

15/02/19

INS. CASE OWNER:

CC 6/AIG1901

LKK:
IDAC:

Surveyor:

MARINS

DOI:

ASSIGNMENT

7/3/19

Date / Time:

7/3/19

Registered in Merimen:

7/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBA 6891P

Claim No.:

Name of Insured:

TECHIAN ENGINEERING

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

7/6/19

Place of Accident:

Is driver the owner?

(YES NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

GBE 9667E

INSRS:
WSP:
Tel:
Liability:
RMKS:Liu's
broINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	GBE 9667E - X	Non-Reporting ltr (1st):	
	GBE 6891P - X	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
12.07.19	EMAIL WSP LIABILITY CLEAR.	Call OI:	ASHER 12.7.19
04.10.19	FILE PASS TO TYPIST TO PREPARE REPORT.	After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: OKS

Repair Cost:

SS 10,800

(9 days)

Reduction:

66 %

Email ☒

Call ☐

FINAL SETTLEMENT

Date/Time: 11.02.20

Confirm with SUSAN

Email ☒

Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

SS 10,800.00

3 VEH CL O.D. 1981

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 880.00

(\$ 80 x 11 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐

LOU only ☒

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 11,682.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 11.02.20

Confirm with: SUSAN

Email ☒

Call ☐

Payee 1:

SS 11,682.00

Name 1:

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
9/3/2020

308/11/13) wef

ASS. REC. BY: Marcus

REF:

A16/
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L1A28U6

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

net 17784

46: +10,800 (RED: +20,968.20 66%)

Veh No:

G3E7663R

Yr Regn:

3, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Toyota hiace

C.C

2982

Colour

white / red

A/C: Insured / Std / NI / NA

Sp. Reading

140240

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDH2015020447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Auston

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

20/6/19

D.O.I.

3/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7663R190620

Estimate

Customer	Page 01 - 03
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 02-07-19
Address: Motor Claims Department	Vehicle No: GBE7663R
78 Shenton Way #07-16	Model/Make: Toyota Hiace
AIG Building Singapore 079120	3.0 DX Diesel Turbo MT 2WD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>body</i>	\$ 1,950.90	
2	Tailgate Inner Lock <i>10/5m</i>	\$ 359.00	
3	Tailgate Outer Handle <i>8m</i>	\$ 137.60	X
4	Tailgate Rubber <i>2m</i>	\$ 426.70	
5	Tailgate Inner Trim Board <i>re/repair</i>	\$ 165.30	
6	Tailgate Inner Trim Board Clips 1 set <i>new</i>	\$ 50.00	SN ✓
7	Tailgate "Corporate" Advertisement & Artwork <i>new</i>	\$ 180.00	SN 1505.~
8	Tailgate Windscreen Glass Moulding <i>NS</i>	\$ 219.00	X
9	Tailgate Windscreen Glass Sealant <i>new</i>	\$ 50.00	SN 405.~
10	Tailgate "70 KM/H" Sticker <i>new</i>	\$ 15.00	SN 105.~
11	Tailgate "8 PAX" Sticker <i>new</i>	\$ 15.00	SN 105.~
12	Tailgate "Toyota" Motif <i>new</i>	\$ 68.10	
13	Tail Lamp 02 pcs (@ \$365.10) <i>n/s cre</i>	\$ 730.20	1pc
14	Tail Lamp Lower Garnish <i>1/5 cre 185</i>	\$ 435.20	
15	Bumper <i>2/5</i>	\$ 465.00	
16	Bumper Clips 1 set <i>new</i>	\$ 48.00	SN ✓
17	<i>1 set</i> Bumper Reverse Sensor <i>shocked</i>	\$ 220.00	SN 2005.~
18	Bumper Inner Bracket 4 pcs (@ 35.80 x 4 = 143.20 <i>but</i>	\$ 760.80	
19	Bumper Side Holder 02 pcs (@ \$139.00) <i>1/1</i>	\$ 278.00	X
20	Exhaust Silencer <i>1/1</i>	\$ 917.60	X
21	Number Plate Outer Garnish <i>1/1</i>	\$ 397.00	X
22	Number Plate and Base <i>1/1</i>	\$ 48.00	SN X
23	End Panel Inner <i>body</i>	\$ 936.20	
24	End Panel Outer <i>body</i>	\$ 566.10	
25	End Panel Top Plate <i>body</i>	\$ 299.50	
26	End Panel Sealant <i>new</i>	\$ 50.00	SN ✓
27	Fender (Body Panel) <i>new</i>	\$ 1,308.10	X
28	Fender Inner Panel <i>new</i>	\$ 1,069.10	X
29	Fender "Corporate" Advertisement & Artwork <i>new</i>	\$ 180.00	SN 1505.~
	Floor Panel Top Wooden Board <i>cre</i>	\$ 650.00	SN 4005.~
	C/F Balance ----> <i>(252)</i>	\$ 12,995.40	

Not Authorized
date
1/5 10,800/
92.
3/7/19



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7663R190620

Estimate

Customer	Page 02 - 03
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 02-07-19
Address: Motor Claims Department	Vehicle No: GBE7663R
78 Shenton Way #07-16	Model/Make: Toyota Hiace
AIG Building Singapore 079120	3.0 DX Diesel Turbo MT 2WD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 12,995.40	
31	Front Bumper <i>De R</i> <i>485.60</i>	\$ 796.80	X
32	Bumper Beam Center <i>R</i>	\$ 217.50	X
33	Bumper Clips 1 set <i>nu</i>	\$ 50.00	X
34	Bumper Bracket <i>11</i>	\$ 178.00	X
35	Bumper Side Holders (@ S\$137.20) <i>11</i>	\$ 274.40	X
36	Bumper Centre Grille <i>11</i>	\$ 155.80	X
37	Bumper Top Beam <i>11</i>	\$ 189.60	X
38	Bumper Carbon "Sticker" Lower <i>nu</i>	\$ 180.00	SN <i>1505.~</i>
39	Grille <i>70.11</i>	\$ 487.70	X
40	Grille Clip 1 set <i>11</i>	\$ 35.00	SN X
41	Grille Chrome <i>(R)</i>	\$ 287.50	X
42	Grille Inner <i>11</i>	\$ 675.10	X
43	Head Lamp 02 pcs (@ S\$930.70) <i>holder era</i>	\$ 1,861.40	X
44	Head Lamp clips 1 set <i>11</i>	\$ 65.00	X
45	Head Lamp Bracket 02 pcs (@ S\$19.70) <i>11</i>	\$ 39.40	SN X
46	Radiator <i>pu1</i>	\$ 2,372.30	X
47	Radiator Fan Motor <i>11</i>	\$ 624.30	X
48	Radiator Fan Blade <i>11</i>	\$ 290.20	X
49	Radiator Fan Cowling <i>11</i>	\$ 587.30	X
50	Radiator Coolant 1 bottles <i>11</i>	\$ 50.00	SN X
51	Aircon Condenser <i>Buy 1 pu1</i>	\$ 1,448.00	X
52	Number Plate and Base <i>Self</i>	\$ 48.00	SN <i>405.~</i>
53	Support Panel <i>11</i>	\$ 766.30	X
54	Brace Panel <i>11</i>	\$ 434.80	X
55	Aircon Condenser <i>Repair</i>	\$ 1,448.00	X
56	Windscreen Glass Moulding <i>11</i>	\$ 303.60	X
57	Windscreen Glass Sealant <i>11</i>	\$ 50.00	SN X
	C/F Balance --->	\$ 26,911.40	

I hereby acknowledge that I have read and understood the terms and conditions of the estimate and I agree to the work to be carried out by the repairer.

Acknowledged by Repairer
Signature: _____



M/s Liu's Brother Auto Engrg Wks

13020.6
257
9764.45
S.N 1150
C.N 2630
13548.45
10836

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7663R190620

Estimate

Customer	Page 03 - 03
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 02-07-19
Address: Motor Claims Department	Vehicle No: GBE7663R
78 Shenton Way #07-16	Model/Make: Toyota Hiace
AIG Building Singapore 079120	3.0 DX Diesel Turbo MT 2WD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 26,911.40	
31	Front Bumper <i>repld</i>	\$ 796.80	X
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	50
	To check all wiring & electrical component for proper function	\$ 80.00	30
	Remove and refix rear bumper reverse sensor	\$ 100.00	50
	Remove & reinstall Rear Windscreen Glass to facilitate repairs	\$ 120.00	120
	Remove & reinstall Front Windscreen Glass to facilitate repairs	\$ 120.00	120 X
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 180.00	100
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	1100
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	1100
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	✓

Total Parts & Labour of estimate for damaged vehicle

\$ 31,768.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBE7663R
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 DX DIESEL TURBO MT 2WD LGV
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2575538
Chassis No.:	KDH2015020447
Maximum Power Output:	-
Open Market Value:	\$29,361.00
Original Registration Date:	21 Mar 2016
First Registration Date:	21 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$1,469.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,036.00
COE Rebate Amount:	\$28,216.00
Total Rebate Amount:	\$28,216.00

The information contained herein is correct as at 03 Jul 2019

OK

Trade the UK100 with
spreads from 0.8



TRADE NOW

re
Sin

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



3.18% P.A. 50 Admin Fees @ GV
Finance 2 Years Warranty \$4500
Down Monthly From \$988
GV Credit Pte Ltd - StarAd



Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

29 vehicles

HIACE

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	HIACE	Any	Any	2016	Any	Any	Any	Available
	Toyota Hiace 3.0M	\$53,800	\$7,430 /yr	28-Sep-2016	2,982 cc	51,000 km	Van	Available
Fuel Type: Diesel 100% Loan At \$832 Monthly! Cheapest In Market! Guaranteed One Of The Best Condition! Original Tip Top Condition With No Repairs Needed! Brand New Paintwork! Smooth Engine & Gearbox! Large Rear Cargo Space For All Your Delivery Needs! High Trade In Value, F... Car (S) Pte Ltd Posted: 03-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace 3.0M DX	\$53,500	\$7,470 /yr	30-Aug-2016	2,982 cc	-	Van	Available
Fuel Type: Diesel Most Durable Van, Low Mileage, Excellent Condition With New Tyres, New Battery Replaced, Well Maintain By Previous Owner. In House/Bank Loan Available, Trade In Are Welcome. Don't Miss Your Chance Call For Viewing Now! Posted: 02-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace 3.0M DX	\$54,800	\$7,780 /yr	18-Jul-2016	2,982 cc	72,235 km	Van	Available
Fuel Type: Diesel Toyota Hiace Manual Rear Aircon, 3 Days Delivery, Super Low Miles, No Need Repairs, \$0 Drive Away, Cash Rebate, High Loan With Lowest Interest Rate Available, Super High Trade In, Call Now! ABWIN Bus Pte Ltd Posted: 02-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace 3.0M	\$46,800	\$7,170 /yr	11-Jan-2016	2,982 cc	87,000 km	Van	Available
Fuel Type: Diesel Loan Available! Accident-Free Unit And Well Maintained Interior Too. All Working Mechanism Is Working As How It Should Be. Reliable Enough For Your Business Needs. Popular Van That Needs No Introduction. Cargo Length At 2.93M, With Height Of 1.56M. Fuel Efficient... Tan Wei Auto Pte Ltd Posted: 02-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
Car Buying	Car Selling	Car Ownership						
Car Aftermarket	On The Move	Lifestyle						
	Toyota Hiace 3.0M	\$54,800	\$7,650 /yr	30-Aug-2016	2,982 cc	-	Van	Available
Fuel Type: Diesel As Good As New, Accident Free! One Owner! Guaranteed Cheapest In Market! Monthly Installment As Low As \$600 Plus! Why Lease When You Can Own Your Vehicle Today With Monthly Installments! Call Us To View Today! Door Step Viewing Available! Car (S) Pte Ltd Posted: 30-Jun-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota Hiace 3.0M DX	\$56,800	\$7,670 /yr	28-Nov-2016	2,982 cc	45,000 km	Van	Available
Fuel Type: Diesel Guaranteed Cheapest In Market! All Business Owners Look Here! It Is A Special Offer Not To Be Missed! High Loan Options Available! Cheapest In Market! Cheaper Than New! New Paintwork! Monthly Installment As Low As \$800+! Why Lease When You Can Own Your V... Car (S) Pte Ltd Posted: 29-Jun-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
Compare	Toyota Hiace 3.0A DX		8,200 /yr	21-Apr-2016	2,982 cc	70,500 km	Van	Available
Fuel Type: Diesel								

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-105650
Date of Request: 02/07/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 02/07/2019
Enquiry By: Susan Low Siew Yian
TP Vehicle No: GBH6891P
Accident Date: 20/06/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	
GST Amount	1.87
Total Amount Due (GST Inclusive)	0.13
	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	08 Jul 2019 14:43	Clim Dtl Modified	Claimant's Name: -> GOLDBELL LEASING PTE LTD. Claimant's ID: -> 199001196N.	[A] Lau Shu Pei
2	08 Jul 2019 14:43	Clim Veh Model Changed	(203266) TOYOTA HIACE 3.0 D DX (M).	[A] Lau Shu Pei
3	08 Jul 2019 14:43	Clim Created	Reg No: GBE7663R. Acct Date: 2019/06/20. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)	[A] Lau Shu Pei
4	08 Jul 2019 14:43	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	08 Jul 2019 14:43	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2019/07/17	[A] Lau Shu Pei
6	08 Jul 2019 14:43	Adj Mandate Set	Approved: 8000.00. Reinsp: Adj decides.	[A] Lau Shu Pei
7	08 Jul 2019 14:43	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	08 Jul 2019 14:43	Label Added	(19): Fastlane.	[A] Lau Shu Pei
9	08 Jul 2019 14:43	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
10	02 Dec 2019 17:56	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
11	02 Dec 2019 17:56	Clim Dtl Modified	JPJ Reg. Date: -> 2000/01/01.	[A] NUR SHAQILAH BTE ABDOL WAHAB
12	02 Dec 2019 17:56	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
13	02 Dec 2019 17:59	Clim Dtl Modified	JPJ Reg. Date: 2000/01/01 -> 2016/03/21.	[A] NUR SHAQILAH BTE ABDOL WAHAB
14	05 Dec 2019 09:05	Adj Mandate Request	Cur. Req: 11682.00: LIABILITY: 100% B: 28 3VEH CC OID LAST	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2205115	09 Jul 2019 09:56:16	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	GBE7663R	GBH6891P	11.77
2364678	02 Dec 2019 17:56:21	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBE7663R	GBH6891P	11.77

2/11/2020

Merimen e-Claims

Print Received Message

This mail is associated with :

***GBE7663R (8462210945SG)**
[GBH6891P]

TP

GOLDBELL LEASING PTE LTD

Jun 20 2019 6:00PM

[TECHIAN ENGINEERING]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/01/2020 10:50 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11682.00) - GBE7663R - Claim Handler: MdNoor, Norsiah

Approved:11682.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jun 2019 Edit Reg		03 Jul 2019 00:00 Edit Adj Rpt	S\$10,800.00 Edit Estimates	S\$10,800.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TECHIAN ENGINEERING, Co. Reg. No.: 52838330B		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBE7663R	Date of Loss:	20/06/2019 18:00 - :59 [38 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8462210945SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	GBH6891P	Policy No. (Claimant):	D-18090757MFCV
		Excess:	
Repairer:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (20/01/2020): Alert - Adj Mandate Approved (S\$11682.00) - GBE7663R - Claim Handler: MdNoor, No...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE7663R (8462210945SG)
[GBH6891P]

TP

GOLDBELL LEASING PTE LTD

Jun 20 2019 6:00PM

[TECHIAN ENGINEERING]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Letters/Correspondences

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page ▼	✓
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Thumbnail Edit Print

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	✓
1	05/12/19 09:03	Odometer Reading	1	Thumbnail Load JPG ✓
2	05/12/19 09:03	General View	1	Load JPG ✓
3	05/12/19 09:03	General View	1	Load JPG ✓
4	05/12/19 09:03	General View	1	Load JPG ✓
5	05/12/19 09:03	General View	1	Load JPG ✓
6	05/12/19 09:03	General View	1	Load JPG ✓
7	05/12/19 09:03	General View	1	Load JPG ✓
8	05/12/19 09:03	General View	1	Load JPG ✓
9	05/12/19 09:03	General View	1	Load JPG ✓
10	05/12/19 09:03	General View	1	Load JPG ✓
11	05/12/19 09:03	General View	1	Load JPG ✓
12	05/12/19 09:03	General View	1	Load JPG ✓
13	05/12/19 09:03	General View	1	Load JPG ✓
14	05/12/19 09:03	General View	1	Load JPG ✓
15	05/12/19 09:03	General View	1	Load JPG ✓
16	05/12/19 09:03	General View	1	Load JPG ✓
17	05/12/19 09:03	General View	1	Load JPG ✓
18	05/12/19 09:03	General View	1	Load JPG ✓
19	05/12/19 09:03	General View	1	Load JPG ✓
20	05/12/19 09:03	General View	1	Load JPG ✓
21	05/12/19 09:03	General View	1	Load JPG ✓
22	05/12/19 09:03	General View	1	Load JPG ✓
23	05/12/19 09:03	General View	1	Load JPG ✓
24	05/12/19 09:03	General View	1	Load JPG ✓
25	05/12/19 09:03	General View	1	Load JPG ✓
26	05/12/19 09:03	General View	1	Load JPG ✓
27	05/12/19 09:03	General View	1	Load JPG ✓
28	05/12/19 09:03	General View	1	Load JPG ✓
29	05/12/19 09:03	General View	1	Load JPG ✓
30	05/12/19 09:03	General View	1	Load JPG ✓
31	05/12/19 09:03	General View	1	Load JPG ✓
32	05/12/19 09:03	General View	1	Load JPG ✓

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	05/12/19 09:03	General View	 Load JPG	✓
34	05/12/19 09:03	General View	 Load JPG	✓
35	05/12/19 09:03	General View	 Load JPG	✓
36	05/12/19 09:03	General View	 Load JPG	✓
37	05/12/19 09:03	General View	 Load JPG	✓
38	05/12/19 09:03	General View	 Load JPG	✓
39	05/12/19 09:03	General View	 Load JPG	✓
40	05/12/19 09:03	General View	 Load JPG	✓
41	05/12/19 09:03	General View	 Load JPG	✓
42	05/12/19 09:03	General View	 Load JPG	✓
43	05/12/19 09:03	General View	 Load JPG	✓
44	05/12/19 09:03	General View	 Load JPG	✓
45	05/12/19 09:03	General View	 Load JPG	✓
46	05/12/19 09:03	General View	 Load JPG	✓
47	05/12/19 09:03	General View	 Load JPG	✓
48	05/12/19 09:03	General View	 Load JPG	✓
49	05/12/19 09:03	General View	 Load JPG	✓
50	05/12/19 09:03	General View	 Load JPG	✓
51	05/12/19 09:03	General View	 Load JPG	✓
52	05/12/19 09:03	General View	 Load JPG	✓
53	05/12/19 09:03	General View	 Load JPG	✓
54	05/12/19 09:03	General View	 Load JPG	✓
55	05/12/19 09:03	General View	 Load JPG	✓
56	05/12/19 09:03	General View	 Load JPG	✓
57	05/12/19 09:03	General View	 Load JPG	✓
58	05/12/19 09:03	General View	 Load JPG	✓
59	05/12/19 09:03	General View	 Load JPG	✓
60	05/12/19 09:03	General View	 Load JPG	✓
61	05/12/19 09:03	General View	 Load JPG	✓
62	05/12/19 09:03	General View	 Load JPG	✓
63	05/12/19 09:03	General View	 Load JPG	✓
64	05/12/19 09:03	General View	 Load JPG	✓
65	05/12/19 09:03	General View	 Load JPG	✓
66	05/12/19 09:03	General View	 Load JPG	✓
67	05/12/19 09:03	General View	 Load JPG	✓
68	05/12/19 09:03	General View	 Load JPG	✓
69	05/12/19 09:03	General View	 Load JPG	✓
70	05/12/19 09:03	General View	 Load JPG	✓
71	05/12/19 09:03	General View	 Load JPG	✓
72	05/12/19 09:03	General View	 Load JPG	✓
73	05/12/19 09:03	General View	 Load JPG	✓
74	05/12/19 09:03	General View	 Load JPG	✓
75	05/12/19 09:03	General View	 Load JPG	✓
76	05/12/19 09:03	General View	 Load JPG	✓
77	05/12/19 09:03	General View	 Load JPG	✓
78	05/12/19 09:03	General View	 Load JPG	✓
79	05/12/19 09:03	General View	 Load JPG	✓
80	05/12/19 09:03	General View	Load JPG	✓

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	05/12/19 09:03	General View	 Load JPG	☒
82	05/12/19 09:03	General View	 Load JPG	☒
83	05/12/19 09:03	General View	 Load JPG	☒
84	05/12/19 09:03	General View	 Load JPG	☒
85	05/12/19 09:03	General View	 Load JPG	☒
86	05/12/19 09:03	General View	 Load JPG	☒
87	05/12/19 09:03	General View	 Load JPG	☒
88	05/12/19 09:03	General View	 Load JPG	☒
89	05/12/19 09:03	General View	 Load JPG	☒
90	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
91	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
92	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
93	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
94	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
95	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
96	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
97	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
98	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
99	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
100	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
101	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
102	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
103	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
104	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
105	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
106	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
107	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
108	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
109	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
110	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
111	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
112	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
113	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
114	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
115	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
116	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
117	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
118	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
119	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
120	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
121	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
122	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
123	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
124	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
125	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
126	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
127	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
128	05/12/19 09:04	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
129	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
130	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
131	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
132	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
133	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
134	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
135	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
136	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
137	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
138	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
139	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
140	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
141	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
142	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
143	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
144	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
145	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
146	05/12/19 09:04	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 19:35	TP ESTIMATE- MARKED	 Load PDF	
2	08/07/19 19:35	TP GIA REPORT.	 Load PDF	
3	12/07/19 11:56	LETTER TO OI	 Load PDF	
4	04/12/19 17:36	GIA SEARCH	 Load PDF	
5	04/12/19 17:36	LOD	 Load PDF	
6	23/03/20 11:14	Authorisation to Act	 Load PDF	
7	23/03/20 11:14	Release Voucher	 Load PDF	
8	23/03/20 11:14	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/07/19 09:52	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBH6891P (Insd veh)	Model:	TOYOTA HIACE 3.0 D DX
	GBE7663R (TP veh)		DIESEL TURBO MT 2WD LGV
Date of Accident:	20/06/2019		(M)

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$			31,768.20	
Final Repair Cost	:	\$			10,800.00	
Loss of Use	:	\$			880.00	11.00 days at \$80.00 per day
Rental (if any)	:	\$				days
LTA / GIA Search Fee	:	\$			2.00	
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$			11,682.00	

Is Third Party Workshop GIA Registered?	[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop :		Agreed Liability _____ 100 _____ (%)			
B) For GIA Registered Workshop :		BOLA Applicable: Yes/ No			BOLA Scenario No: _____
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Liu's Brother Auto Engineering Workshop	: \$	11,682.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

23 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19011785/UES3S2
Date: 23/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBE7663R **Insured Vehicle No :** GBH6891P
 Date of Loss: 20/06/2019 Nature of Claim: TP Claim No: 8462210945SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE7663R**
 Make & Model: TOYOTA HIACE, 3.0 D DX DIESEL TURBO MT 2WD LGV (M) Engine No: 1KD2575538
 Reg. Date: 21/03/2016 (Man. Year: 2015) Chassis No: KDH2015020447
 Colour: White/Red Odometer: 140240 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Austone 6 mm Rear Left Side: Austone 6 mm
 Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,708.20	10,965.45	16,742.75	60.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	2,630.00	1,430.00	35.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,768.20	13,595.45	18,172.75	57.20
Approved Total (Overridden) (S\$)		10,800.00		
Nett Amount (S\$)	31,768.20	10,800.00	20,968.20	66.00
+ Loss of Use (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,682.00		

INSPECTION

Date of Assignment: 03/07/2019
 Date Inspected: 03/07/2019 Inspected At: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)
 Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt
 Singapore 417883, Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE	Badly Dented	1,950.90 F	*1,950.90 FL
2	1	*REAR TAILGATE INNER LOCK	Dented / Jammed	359.00 F	*359.00 FL
3	1	*REAR TAILGATE OUTER HANDLE	Serviceable	137.60 F	*- FL
4	1	*REAR TAILGATE RUBBER	Twisted	426.70 F	*426.70 FL
5	1	*REAR TAILGATE INNER TRIM BOARD	Deformed / Warped	165.30 F	*165.30 FL
6	1	*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
7	1	*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	219.00 F	*- FL
8	1	*REAR TAILGATE TOYOTA MOTIF	Necessary	68.10 F	*68.10 FL
9	1	*REAR TAIL LAMP	N/s Cracked	730.20 F	*365.10 FL
10	1	*REAR TAIL LAMP LOWER GARNISH N/S	Cracked	435.20 F	*185.00 FL
11	1	*REAR BUMPER	Distorted	465.00 F	*465.00 FL
12	1	*SET REAR BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
13	4	*REAR BUMPER INNER BRACKET	Bent	760.80 F	*143.20 FL
14	2	*REAR BUMPER SIDE HOLDER	Not Necessary	278.00 F	*- FL
15	1	*REAR EXHAUST SILENCER	Not Necessary	917.60 F	*- FL
16	1	*REAR NUMBER PLATE OUTER GARNISH	Not Necessary	397.00 F	*- FL
17	1	*REAR END PANEL INNER	Badly Dented	936.20 F	*936.20 FL
18	1	*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
19	1	*REAR END PANEL TOP PLATE	Bent	299.50 F	*299.50 FL
20	1	*REAR FENDER (BODY PANEL)	Repair	1,308.10 F	*- FL
21	1	*REAR FENDER INNER PANEL	Repair	1,069.10 F	*- FL
22	1	*REAR TAILGATE CORPORATE ADVERTISEMENT & ARTWORK	Necessary	180.00 FS	*150.00 FS
23	1	*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
24	1	*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
25	1	*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
26	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
27	1	*REAR NUMBER PLATE AND BASE	Not Necessary	48.00 FS	*- FS
28	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
29	1	*REAR FENDER CORPORATE ADVERTISEMENT & ARTWORK	Necessary	180.00 FS	*150.00 FS
30	1	*REAR FLOOR PANEL TOP WOODEN BOARD	Cracked	650.00 FS	*400.00 FS
31	1	*FRONT BUMPER	Deformed	796.80 F	*485.60 FL
32	1	*FRONT BUMPER BEAM CENTER	Repair	217.50 F	*- FL
33	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
34	1	*FRONT BUMPER BRACKET	Not Necessary	178.00 F	*- FL
35	2	*FRONT BUMPER SIDE HOLDERS	Not Necessary	274.40 F	*- FL
36	1	*FRONT BUMPER CENTRE GRILLE	Not Necessary	155.80 F	*- FL
37	1	*FRONT BUMPER TOP BEAM	Not Necessary	189.60 F	*- FL
38	1	*FRONT GRILLE	Torn	487.70 F	*487.70 FL
39	1	*FRONT GRILLE CHROME	Cracked	287.50 F	*287.50 FL
40	1	*FRONT GRILLE INNER	Not Necessary	675.10 F	*- FL
41	2	*FRONT HEAD LAMP	Holder Cracked	1,861.40 F	*1,861.40 FL
42	1	*SET FRONT HEAD LAMP CLIPS	Not Necessary	65.00 F	*- FL
43	1	*FRONT RADIATOR	Punctured	2,372.30 F	*2,372.30 FL
44	1	*FRONT RADIATOR FAN MOTOR	Not Necessary	624.30 F	*- FL
45	1	*FRONT RADIATOR FAN BLADE	Not Necessary	290.20 F	*- FL
46	1	*FRONT RADIATOR FAN COWLING	Not Necessary	587.30 F	*- FL
47	1	*FRONT AIRCON CONDENSER	Bent / Punctured	1,448.00 F	*1,448.00 FL
48	1	*FRONT SUPPORT PANEL	Repair	766.30 F	*- FL
49	1	*FRONT BRACE PANEL	Not Necessary	434.80 F	*- FL
50	1	*FRONT AIRCON CONDENSER	Repeated	1,448.00 F	*- FL
51	1	*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	303.60 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*FRONT BUMPER CARBON STICKER LOWER	Necessary	180.00 FS	*150.00 FS
53	1	*SET FRONT GRILLE CLIP	Not Necessary	35.00 FS	*- FS
54	2	*FRONT HEAD LAMP BRACKET	Not Necessary	39.40 FS	*- FS
55	1	*BOTTLE FRONT RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
56	1	*FRONT NUMBER PLATE AND BASE	Bent	48.00 FS	*40.00 FS
57	1	*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	50.00 FS	*- FS
58	1	*FRONT BUMPER	Repeated	796.80 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,708.20	14,220.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	3,255.15
Total Parts (\$\$)	27,708.20	10,965.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM.	New	80.00	50.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.	New	80.00	30.00
3	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR.	New	100.00	50.00
4	REMOVE & REINSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS.	New	120.00	120.00
5	REMOVE & REINSTALL FRONT WINDSCREEN GLASS TO FACILITATE REPAIRS.	New	120.00	0.00
6	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES.	New	180.00	100.00
7	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC.	New	1,500.00	1,100.00
8	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.	New	1,800.00	1,100.00
9	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	New	80.00	80.00
Gross Labour Cost (\$\$)			4,060.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >