

Case Details

Case Reference Number : TAX/06/19/2118

Company Type : SMRT Taxis Pte Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-7534-ID

Accident Date and Time : 29/06/2019 07:55 AM

Vehicle Registration Number : SHC4357J

Assigned By : Taxi Claims Manager Team

Vehicle Age(In Months) : 67

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			MIRROR ASSY, LH	1	1,224.90	1,224.90	25.00	918.68	Replace	1	918.68	Replace ▾		
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give ▾		
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace ▾		
Total Spare Part Cost									1,058.00		Surveyor Total		999.23		
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20.00		
Final Spare Part Cost									846.40		Final Sur Total		799.38		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY VIEW MIRROR	180.00	100.00	
Total:			180.00	100.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	60.00	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	

			Recommendation(\$)	Adjustment(\$)	
3	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
Total:			400.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	846.40	799.38
Total Labour Cost	0.00	0.00
Total Spray Painting	180.00	100.00
Other	400.00	80.00
Overall Total	1,426.40	1,179.23
Lump Sum Repair Option	☒	☒
Lump Sum Total	1,450.00	1,200.00
Surveyor Approved Amount		1,200.00
No of Repair Days*	2	1
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	02/07/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: