

ASS. REC. BY:

REF: (S/FCI 19011790/TLS d/3) m2

Special Instruction:

Surveyor TAN H L B ASSIGNMENT (Office)From (Person): May chuan of FCI Date/Time: 3.7.19 3.06pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 5335TB Insured: SHD 3240Mat Workshop m/s Premium Automobile Tel: 67689828
of 55 ubi road 1Policy No: Claim No: D19064259MFSH

Sum Insured: Excess:

Make of Veh: D.O.A 27.6.19
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 3.7.19 3.48pm Person Contacted: kelvin H.O.D. Endorsement: Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SMD 5335 TB-X</u>
	<u>SHD 5335 TB-X</u>
<u>05/07/19 @ 15:24 pm revised PA to may via email.</u>	

Taufik

REF: PC1

ASSIGNMENT

From: 4.1.2019

Estimated Cost:

OD: (1) WET / TP / RES / OD / RES / EVA / INV / MV

To inspect Vehicle No: SMD 5335 B

at Workshop no: Premium

at 24 Benoi Sector

Insured:

Policy No:

Class No:

Sum Insured:

Cover:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

INS	OPS

Est. at Market Value:

EWAG Accident Report Consistent? Yes or No

QAR / PPL Claim Consistent? Yes or No

Est. Repair days Yes or No

Est. Cost % Yes or No

CA / REV / REP / 24 HRS

exp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMD 5335 B

Vt Regn: 2018 Aug

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q2

cc: 999

Colour: white

ABC: Insured / Std / NI / NA

Sp. Decoding: 11956

1/1radio: Insured / Std / NI / NA

Eng No:

CAR:

WAY 227 GA4 JAAS 7670

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Btn / STD A/Btn or 60K16

Tyre Size:

215 / 45

INS / DUH / EXNOVA / GY / FS / LIZA / MIC / OH / SU / PIR / SUMI / TOYO / YOKO or

Front:

6

mm

Rear:

6

mm

L/Ral:

6

mm

L/Ral:

6

mm

D.O.A:

D.O.A:

4/3/19 2345

Survey held at:

Premium Benoi

Des. of Damages: Frl / Rear / OR / NIS / OR / Rooftop or

The OR / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

01/11/19 Confirmed P/P \$ 7,473.40 @ 6 days with Taufik.
(\$ 6,632.60 Red - 47%)

RECEIVED 04 NOV 2019

11/11/2019

Under Time, File Press for:

01/11/19 Type 2

Under Time, File Release for:

2/1

Report Format:

Lump Sum (LBA) (\$ 7,473.40 P/P)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

- ☐ Site Insp (\$)
- ☐ Interview (\$)
- ☐ Tech. Insp (\$)
- ☐ Weekend (\$)

Survey Fee:

Interpretation

2 + 10% of

Phone

Others

TOTAL

4x15 = 60

170 + 60

50

50

26

356



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004259MFSH

Date: 05 July 2019

Our Ref: CS/FCI19011790/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 5335B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/07/2019 at the premises of M/s Premium Automobiles Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 14,106.00</u>
Revised Estimate Amount	: <u>S\$ 7,238.00</u>
"Check" Items Amount	: <u>S\$ 494.00</u>
Total	: <u>S\$</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-06-2019	Our Ref No. D19004259MFSH
Accident Date	27-06-2019	Claim Type. Third Party
Insured Vehicle	SHD3240M	Third Party Vehicle. SMD5335B
Survey Location	55 UBI ROAD 1	
Contact Person.	NG KENJI	
Contact No.	87779612/ 63662323	Fax No. 68411183
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 4 November 2019 9:15 am
To: Boo seng yak; Adrian Ling (LKKAuto); Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Cc: SUR
Subject: RE: FINAL REVISION - SMD5335B - TP MS/FIRST - SURVEYED 4 JUL 19

Dear Mr. Boo,

Finalize amount confirmed.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 23 October 2019 1:39 pm
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SMD5335B - TP MS/FIRST - SURVEYED 4 JUL 19

Hi Taufikh and all,

Revised estimate and some photographs is attached. Please take note that a separate accident repair was done at the same time. Labour rate for Q2 is \$800.00 per day.

Please confirm repair cost of \$7473.40 @ 6 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 23 October 2019 1:39 pm
To: Taufikh (LKKAuto); Adrian Ling (LKKAuto); SUR; Shirley Hiew (LKK Auto); Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SMD5335B - TP MS/FIRST - SURVEYED 4 JUL 19
Attachments: PA08092019 -SMD 5335 B - Audi Q2 1.0 TFSI - RHS - TP (MS FIRST).xls; WhatsApp Image 2019-07-24 at 9.34.10 AM (1).jpeg; WhatsApp Image 2019-07-29 at 3.56.35 PM.jpeg

Hi Taufikh and all,

Revised estimate and some photographs is attached. Please take note that a separate accident repair was done at the same time. Labour rate for Q2 is \$800.00 per day.

Please confirm repair cost of \$7473.40 @ 6 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 5 July 2019 3:24 PM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19004259MFSH/1
Attachments: SMD 5335B - Preli Advise -.pdf

Dear May,

Enclosed preliminary revised of vehicle SMD 5335B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 3 July 2019 3:50 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004259MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 3 July, 2019 3:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004259MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0809/2019/GW
Date : 02-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No. : SHD 3240 M

MS First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Hitachi Capital Asia Pacific PTE LTD
Address : Triple One Somerset
Singapore 238164
Telephone : (HP)+67341222
Type of Claim : Third party Claims
Policy No. : VPX/P2172111
Vehicle No : SMD 5335 B
Model Code : Audi Q2 1.0 TFSI S TRONIC
Model / Year : Aug-18
Engine No : CHZJ 412050
Chassis No : WAUZZZGA4JA087670
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Jun-19
Place of Accident : North Buona Vista Road

LOK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMD 5335 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	xny
2	To remove and transfer rhs front door and rhs rear door's multi-lock systems and power devices. Inspect for damages and renew if necessary.	S/N \$ 560.00	280.
3	To dismantle and instal rear bumper. To renew rhs front door and rhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00	700. 1600 1400. 1600/-
4	To respray rhs front door, door handle and rhs rear door.	\$ 2,500.00	800. x 700. 1500.
5	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,012.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 5335 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - RH	\$ 2,285.00	ld ✓
2	FRONT DOOR ATTACHMENT PARTS - RH	\$ 85.00	? X nn
3	FRONT DOOR CATCH - LH / RH	2 \$ 109.00	? X nn
4	DATA PLATE FOR TYRE PRESSURE	\$ 26.00	ne ✓ 25.70
5	FRONT DOOR COVER - RH	\$ 235.00	at ✓ 234.50
6	REAR DOOR - RH	\$ 2,285.00	Ry
7	REAR OUTER DOOR SEAL - RH	\$ 119.00	X nn
8	BONDING AGENT	\$ 45.00	2 ne ✓ 44.90
9	CLEANING SOLUTION	\$ 65.00	X ne ✓ 64.60
10	APPLICATOR	\$ 7.00	X ne ✓ X NA
11	REAR DOOR ATTACHMENT PARTS	\$ 85.00	X nn
12	REAR DOOR CATCH - LH / RH	2 \$ 109.00	X nn
13	REAR DOOR COVER - RH	\$ 206.00	at ✓
14	REAR WHEEL COVER - LH	\$ 156.00	X nn
15	REAR WHEEL COVER - RH	\$ 156.00	at ✓ 155.50
16	REAR BUMPER SPOILER	\$ 260.00	X nn
17	REAR ALUMINIUM RIM-RH	\$ 548.00	at ✓
18	REAR ALUMINIUM RIM RUBBER VALVE	5 \$ 13.00	ne ✓ 12.40
19	SUNDRIES	\$ 300.00	? ✓ 44.80 ne ✓
TOTAL SPARE PARTS		: \$ 7,094.00	
TOTAL LABOUR CHARGES		: \$ 7,012.00	
GRAND TOTAL		: \$ 14,106.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax



Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanfer 97495749
6 days - w.p.
4/7/19 @ 4pm
Repair before paint.
sup@lucauto.com

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0809/2019/GW
Date : 2-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No. : SHD 3240 M

MS First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Hi Taufikh

6 days exclude 1 Sunday

by 23 Oct 19

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Hitachi Capital Asia Pacific PTE LTD
Address : Triple One Somerset
Singapore 238164
Telephone : (HP)+67341222
Type of Claim : Third party Claims
Policy No. : VPX/P2172111
Vehicle No : SMD 5335 B
Model Code : Audi Q2 1.0 TFSI S TRONIC
Model / Year : Aug-18
Engine No : CHZJ 412050
Chassis No : WAUZZZGA4JA087670
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Jun-19
Place of Accident : North Buona Vista Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMD 5335 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	
2	To remove and transfer rhs front door and rhs rear door's multi-lock systems and power devices. Inspect for damages and renew if necessary.	S/N	\$ 560.00	\$ 280.00
3	To dismantle and instal rear bumper. To renew rhs front door and rhs rear door. Re-organise crash management components. Reinstall all parts removed. (\$800.00 per day)		\$ 3,200.00	\$ 1,600.00
4	To respray rhs front door, door handle and rhs rear door.		\$ 2,500.00	\$ 1,500.00
5	To renew rhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
6	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,012.00</u>	<u>\$ 3,852.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 5335 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - RH	\$ 2,285.00	\$ 2,285.00
2	FRONT DOOR ATTACHMENT PARTS - RH	\$ 85.00	
3	FRONT DOOR CATCH - LH / RH	\$ 109.00	
4	DATA PLATE FOR TYRE PRESSURE	\$ 26.00	\$ 25.70
5	FRONT DOOR COVER - RH	\$ 235.00	\$ 234.50
6	REAR DOOR - RH	\$ 2,285.00	
7	REAR OUTER DOOR SEAL - RH	\$ 119.00	
8	BONDING AGENT	\$ 45.00	\$ 44.90
9	CLEANING SOLUTION	\$ 65.00	\$ 64.60
10	APPLICATOR	\$ 7.00	
11	REAR DOOR ATTACHMENT PARTS	\$ 85.00	
12	REAR DOOR CATCH - LH / RH	\$ 109.00	
13	REAR DOOR COVER - RH	\$ 206.00	\$ 206.00
14	REAR WHEEL COVER - LH	\$ 156.00	
15	REAR WHEEL COVER - RH	\$ 156.00	\$ 155.50
16	REAR BUMPER SPOILER	\$ 260.00	
17	REAR ALUMINIUM RIM-RH	\$ 548.00	\$ 548.00
18	REAR ALUMINIUM RIM RUBBER VALVE	5 \$ 13.00	\$ 12.40
19	SUNDRIES	\$ 300.00	\$ 44.80
TOTAL SPARE PARTS		\$ 7,094.00	\$ 3,621.40
TOTAL LABOUR CHARGES		\$ 7,012.00	\$ 3,852.00
GRAND TOTAL		\$ 14,106.00	\$ 7,473.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011790/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3240M	Veh. Inspected	SMD 5335B
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19004259MFSH	Excess (\$)	0.00
	Assign From	MAY CHUA	Assign Date	03/07/2019
2. Vehicle Particulars & Condition				
	Make & Model	AUDI Q2	c.c	999
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WAUZZZGA4JA087670	Colour	WHITE
	Odometer	11956	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/06/2019	Inspection Date	04/07/2019
	Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 5335B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR-RH (SN)	DENTED	2,285.00	2,285.00
1	FRONT DOOR ATTACHMENT PARTS-RH (SN)	NOT NECESSARY	85.00	-
2	FRONT DOOR CATCH-LH/RH (SN)	NOT NECESSARY	109.00	-
1	DATA PLATE FOR TYRE PRESSURE (SN)	NECESSARY	26.00	25.70
1	FRONT DOOR COVER-RH (SN)	CUT	235.00	234.50
1	REAR DOOR-RH (SN)	TO REPAIR SEE LABOUR	2,285.00	-
1	REAR OUTER DOOR SEAL-RH (SN)	NOT NECESSARY	119.00	-
1	BONDING AGENT (SN)	NECESSARY	45.00	44.90
1	CLEANING SOLUTION (SN)	NECESSARY	65.00	64.60
1	APPLICATOR (SN)	NOT NECESSARY	7.00	-
1	REAR DOOR ATTACHMENT PARTS (SN)	NOT NECESSARY	85.00	-
2	REAR DOOR CATCH-LH/RH (SN)	NOT NECESSARY	109.00	-
1	REAR DOOR COVER-RH (SN)	CUT	206.00	206.00
1	REAR WHEEL COVER-LH (SN)	NOT NECESSARY	156.00	-
1	REAR WHEEL COVER-RH (SN)	CUT	156.00	155.50
1	REAR BUMPER SPOILER (SN)	NOT NECESSARY	260.00	-
1	REAR ALUMINIUM RIM-RH (SN)	CUT	548.00	548.00
5	REAR ALUMINIUM RIM RUBBER VALVE (SN)	NECESSARY	13.00	12.40
1	SUNDRIES (SN)	NECESSARY	300.00	44.80
			7,094.00	3,621.40
LABOUR				
	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	NOT NECESSARY	280.00	-
	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEMS AND POWER DEVICES.INPECT FOR DAMAGES AND RENEW IF NECESSARY.		560.00	280.00

Report Ref No. CS/FCI19011790/T1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REINSTAL REAR BUMPER.TO RENEW RHS FRONT DOOR AND RHS REAR DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF REAR DOOR-RH.		3,200.00	1,600.00
	TO RESPRAY RHS FRONT DOOR,DOOR HANDLE AND RHS REAR DOOR.		2,500.00	1,500.00
	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.		280.00	280.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			7,012.00	3,852.00
GRAND TOTAL			14,106.00	7,473.40

RECOMMENDED COST OF REPAIRS				7,473.40
-----------------------------	--	--	--	----------

Report Ref No. CS/FCI19011790/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES - This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.