



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBJ4161R
Make & Model : NISSAN,NV200 DX 1.6 AUTO,VM20132984
Year of Manufacture : 2019

Estimation No. : E19070001
DOA : 01/07/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>de</i>	1.00	0.00	0.00
2	Rear bumper retainer RH <i>re</i>	1.00	0.00	0.00
3	Rear bumper retainer LH <i>X</i>	1.00	0.00	0.00
4	Rear bumper bracket RH <i>re</i>	1.00	0.00	0.00
5	Rear bumper bracket LH <i>X</i>	1.00	0.00	0.00
6	Rear bumper towing cap <i>X</i>	1.00	0.00	0.00
7	Tail gate <i>bt</i>	1.00	0.00	0.00
8	Tail gate lock <i>X</i>	1.00	0.00	0.00
9	Tail gate lock catch <i>X</i>	1.00	0.00	0.00
10	Tail gate outer handle <i>X</i>	1.00	0.00	0.00
11	Tail gate rubber beading <i>re</i>	1.00	0.00	0.00
12	License lamp garnish <i>X</i>	1.00	0.00	0.00
13	License lamp <i>X</i>	2.00	0.00	0.00
14	Tail gate inner trim <i>X</i>	1.00	0.00	0.00
15	Tail gate wiper motor <i>X</i>	1.00	0.00	0.00
16	Tail gate wiper arm <i>X</i>	1.00	0.00	0.00
17	Tail gate windscreen <i>X</i>	1.00	0.00	0.00
18	Tail gate windscreen moulding <i>re</i>	1.00	0.00	0.00
19	Tail gate emblem - Logo <i>re</i>	1.00	0.00	0.00
20	Tail gate emblem - NV200 <i>re</i>	1.00	0.00	0.00
21	Tail lamp RH <i>bo</i>	1.00	0.00	0.00
22	Tail lamp LH <i>X</i>	1.00	0.00	0.00
23	End panel <i>repair</i>	1.00	0.00	0.00
24	End panel top garnish <i>X</i>	1.00	0.00	0.00
25	Rear fender RH <i>bt</i>	1.00	0.00	0.00
26	Rear fender QTR glass <i>X</i>	1.00	0.00	0.00
27	Rear fender garnish RH <i>X</i>	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBJ4161R
Make & Model : NISSAN,NV200 DX 1.6 AUTO,VM20132984
Year of Manufacture : 2019

Estimation No. : E19070001
DOA : 01/07/2019

No	Description	Qty	U/P	Amt
28	Rear fender sliding door roller set RH X	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

29	Reverse sensor set X	1.00	250.00	250.00
30	Rear bumper clip set m /	1.00	45.00	45.00 30
31	Rear number plate & casing X	1.00	45.00	45.00
32	Tail gate sticker - 70km/h m /	1.00	70.00	70.00 60
33	Tail gate sticker - 6 pax m /	1.00	70.00	70.00 10
34	Tail gate sticker - ar m /	1.00	70.00	70.00 10
35	End panel sealant X	1.00	50.00	50.00
36	Tail gate windscreen sealant m /	1.00	50.00	50.00 40
37	Rear fender QTR glass sealant m /	1.00	50.00	50.00 40

Amt S\$ 700.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 700.00

Section: Labour Items

38	To R&R rear bumper reverse sensor	1.00	80.00	80.00 60
39	To check wiring and lighting system	1.00	80.00	80.00 30
40	To supply under-coating / putty on parts repalced	1.00	80.00	80.00 40
41	To perform anti rust treatment on affected areas	1.00	60.00	60.00 30
42	To R&R tail gate mechanism	1.00	200.00	200.00 80
43	To R&R rear fender QTR glass	1.00	180.00	180.00 60
44	To R&R tail gate windscreen	1.00	250.00	250.00 120
45	To R&R rear trims , garnish assy	1.00	200.00	200.00 60
46	To R&R rear RH sliding door to cut and weld	1.00	200.00	200.00 80
47	To R&R fuel tank to cut and weld	1.00	350.00	350.00 X

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBJ4161R
Make & Model : NISSAN,NV200 DX 1.6 AUTO,VM20132984
Year of : 2019
Manufacture

Estimation No. : E19070001
DOA : 01/07/2019

No	Description	Qty	U/P	Amt
48	To repair , replace and realign damaged areas	1.00	1,400.00	1,400.00 800
49	To spray painting on affected areas	1.00	1,200.00	1,200.00 600
50	To perform water seepage test after repair	1.00	150.00	150.00 30
51	Sundries	1.00	50.00	50.00 20

Amt S\$ 4,480.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 4,480.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Casual
Hp 90010068

7 days

48 p/p

04/07/19 @ 1145

Reg after repair

List Items Subtotal S\$ 0.00

Special Nett Items Subtotal S\$ 700.00

Labour Items Subtotal S\$ 4,480.00

Total S\$ 5,180.00