



VEHICLE REGN.NO. GBA 9110C





























GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



1/38: Chassis Number



2/38: Odometer Reading



3/38: Inspection Photo



4/38: Inspection Photo

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



5/38: Inspection Photo



6/38: Inspection Photo



7/38: Inspection Photo



8/38: Inspection Photo

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



9/38: Inspection Photo



10/38: Inspection Photo



11/38: Inspection Photo



12/38: Inspection Photo

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/38: Inspection Photo



14/38: Inspection Photo




15/38: Inspection Photo



16/38: Inspection Photo

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



17/38: Inspection Photo



18/38: Inspection Photo



19/38: Inspection Photo



20/38: Inspection Photo

GBA9110C [SJN8804C1] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



21/38: Inspection Photo



22/38: Inspection Photo



23/38: Inspection Photo



24/38: Inspection Photo

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



25/38: Inspection Photo



26/38: Photo After Paint



27/38: Photo After Paint



28/38: Photo After Paint

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



29/38: Photo After Paint



30/38: Photo After Paint



31/38: Photo After Paint



32/38: Photo After Paint

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



33/38: Photo After Paint



34/38: Photo After Paint



35/38: Photo After Paint



36/38: Photo After Paint

GBA9110C [SJN8804C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



37/38: Photo After Paint



38/38: Photo After Paint