

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

CHINA

Owner : Yoong Lee Tong

Accident Date : 19-Apr-19

Vehicle No : JTH 2483

Vehicle Model : Yamaha 135 LC

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
2	Front fork tube assys	\$ 2 640.00 <i>not A part</i>
1	Front wheel rim	\$ 2 280.00 <i>new</i>
1	Front rim shaft	\$ 11 45.00 <i>11/800</i>
1	Front rim bearing	\$ 11 38.00 <i>11/800</i>
1	Front brake disc	\$ 11 155.00 <i>4 day</i>
1	Handle-bar	\$ 3 88.00 <i>2/7/19</i>
2	Handle-bar ends	\$ 5 64.00 <i>2/7/19</i>
1	Hand grip (1 set)	\$ 1 55.00 <i>2/7/19</i>
1	Handle-bar inner bracket	\$ 1 68.00 <i>2/7/19</i>
2	Side mirrors	\$ 5 110.00 <i>2/7/19</i>
1	Brake lever	\$ 5 32.00 <i>2/7/19</i>
1	Windshield	\$ 5 38.00 <i>2/7/19</i>
2	Front signals	\$ 0/5 140.00 <i>2/7/19</i>
1	Front signal lower garnish	\$ 1 95.00 <i>2/7/19</i>
1	Headlamp	\$ 1 185.00 <i>2/7/19</i>
1	Fairing assy (1 set)	\$ 1 495.00 <i>2/7/19</i>
1	Front footrest bracket	\$ 1 65.00 <i>2/7/19</i>
2	Front footrest rubbers	\$ 0/5 70.00 <i>2/7/19</i>
1	Gear pedal	\$ 1 42.00 <i>2/7/19</i>
1	Brake pedal	\$ 1 42.00 <i>2/7/19</i>
2	Rear footrests	\$ 0/5 80.00 <i>2/7/19</i>
2	Rear footrest brackets	\$ 0/5 156.00 <i>2/7/19</i>
1	Exhaust assy	\$ 1 485.00 <i>2/7/19</i>
1	Exhaust protector	\$ 5 60.00 <i>2/7/19</i>
1	Exhaust end cap	\$ 5 45.00 <i>2/7/19</i>
1	Rear signal -R/H	\$ 1 60.00 <i>2/7/19</i>
1	Side stand	\$ 1 75.00 <i>2/7/19</i>
1	Main stand	\$ 1 95.00 <i>2/7/19</i>
		\$ 3,803.00
	Less 10%	\$ 380.30
		\$ 3,422.70

c/f: \$ 3,422.70

Special Nett Items

1	Number plate (1 set)	\$	nu	28.00	10
2	Fork oils	\$	ner	30.00	✓
2	Fork oil seals	\$	nu	56.00	✓
1	Steering cone (1 set)	\$	ner	90.00	✓
1	Rear box	\$	nu	250.00	✓
1	Rear box bracket	\$	3.8	100.00	✓
1	Front tyre	\$	11	120.00	x
1	Sticker (1 set)	\$	nu	95.00	✓
		\$		769.00	

<u>S/No.</u>	<u>Labour</u>				
1	To provide towing service.	\$	35	50.00	
2	To check wiring and reset headlamp focusing	\$	11 x	80.00	
3	To provide labour.	\$	250	380.00	
4	To repair body frame.	\$	11 x	350.00	
		\$		860.00	

Grand Total \$ 5,051.70


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: