

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8103J

DATE 2/7/2019 15:58

MAKE :

Like

AXA

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Reflector Lamp (LH)			\$ 30.60
	Rear Fender (LH) X			\$ 2,171.40
	Rear Fender Inner Lining (LH) X			\$ 169.30
	Rear Windscreen Moulding X			\$ 28.30
	Rear Wheel Hub Cap, LH X			\$ 107.10
	SUB TOTAL			\$ 3,741.90
	LESS 20%			\$ 748.38
	DISCOUNTED TOTAL			\$ 2,993.52
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Windscreen Sealant X			\$ 46.00
				\$ 231.70
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 600.00 ²⁰⁰
	Wiring Charge			\$ 30.00 X
	Tuff Kote			\$ 50.00 X
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 X
	Remove/Refix Rear Windscreen Glass			\$ 120.00 X
	Remove/Refix Reverse Sensor			\$ 80.00 X
	Rear Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,510.00
	ESTIMATE TOTAL			\$ 4,735.22

Kalvi 16/6/19
3/7/19 1045L
2 Rys
4/5
Alta Rys

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.