

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 01.07.19

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SJZ9007S
MODEL : VOLKSWAGEN NEW GOLF
DATE OF ACCIDENT : 28.06.19
TIME OF ACCIDENT : 12:45HRS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE Repair	1	\$ 1,401.25	\$ 1,401.25
2	TAILGATE EMBLEM 'GOLF' f	1	\$ 73.00	\$ 73.00
3	TAILGATE EMBLEM 'TSI'	1	\$ 65.25	\$ 65.25
4	TAILGATE TOP LOCK new	1	\$ 537.50	\$ 537.50
5	TAILGATE LOWER LOCK new	1	\$ 40.75	\$ 40.75
6	TAILGATE WEATHESTRIP new cut	1	\$ 275.00	\$ 275.00
7	TAIL LAMP RH new	1	\$ 284.65	\$ 284.65
8	TAIL LAMP LOWER BRACKET new	2	\$ 72.45	\$ 144.90
9	REAR BUMPER (UPPER) Deband	1	\$ 791.25	\$ 791.25
10	REAR BUMPER (LOWER) Deband	1	\$ 372.50	\$ 372.50
11	REAR BUMPER REFLECTOR new	2	\$ 72.35	\$ 144.70
12	REAR BUMPER NUMBER PLATE LAMP new	2	\$ 86.75	\$ 173.50
13	REAR BUMPER TOWING COVER new	1	\$ 24.65	\$ 24.65
14	REAR BUMPER CENTER BEAM cracked	1	\$ 196.40	\$ 196.40
15	REAR BUMPER SIDE BRACKET new	2	\$ 43.25	\$ 86.50
16	REAR BUMPER REINFORCEMENT Bent	1	\$ 403.75	\$ 403.75
17	REAR FENDER INNER TRIM new	2	\$ 241.50	\$ 483.00
18	REAR FENDER INNER COWLING new	2	\$ 127.25	\$ 254.50
19	REAR END PANEL Repair	1	\$ 585.50	\$ 585.50
20	REAR END PANEL TOP GARNISH new	1	\$ 132.75	\$ 132.75
21	REAR FLOOR PANEL TOP BOARD new	1	\$ 269.65	\$ 269.65

2263.65

2037.28

TOTAL PRICE \$ 6,740.95
LESS 10% \$ 674.10
SUB TOTAL PRICE \$ 6,066.86

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE new	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) new	1	\$ 80.00	\$ 80.00
3	TAILLAMP CLIP (SET) new	1	\$ 50.00	\$ 50.00

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SJZ9007S
 MODEL : VOLKSWAGEN NEW GOLF
 DATE OF ACCIDENT : 28.06.19
 TIME OF ACCIDENT : 12:45HRS

4	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
5	REAR FENDER INNER COWLING CLIP (SET) <i>AP</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
6	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>AP</i>	1	\$ 30.00	\$ 30.00	<i>x</i>
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
9	REVERSE SENSOR (SET) <i>day d</i>	1	\$ 220.00	\$ 220.00	<i>200</i>
			TOTAL	\$890.00	

230

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	<i>400</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>x</i>
4	WIRING AND BULB CHECK	\$ 180.00	<i>x</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>x</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>x</i>
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>x</i>
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>x</i>
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>x</i>
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

TOTAL \$4,270.00

ESTIMATE REPORT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

Date: _____

Adrian G
h/s 02/07/19. 2/3: 2.4K.
03 days.
total: 3117.28