

ASS. REC. BY:

REF: CS/FCI190118011 KV d3m2 Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Harry Kao of FCI Date/Time: 3.7.19 3:05 PM

Estimated Cost: Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 3149D Insured: SHA 8610 L

at Workshop m/s Estem Performance Tel: 65662112

of BIK 5033 Amc. Ind Part 2 #01-251

Policy No: Claim No: D19004331MPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 1.7.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.7.19 3:41 PM Person Contacted: Jenny Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SLQ 3149D. X

SHA 8610L Ref CS/MSG19011688/Ptd3 DOA = 1/7/19

10/7/19 Email preli revised to FCI

15/7 81619.25 Cabman (Red 2302.83, 5910)

ASSIGNMENT

From: Date: 9-7-19

Estimated Cost

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 3149D

at Workshop n/s: Esteem Performance

of: 365 Sa ming drive

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Vch:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

RDAC Accident Report:

Consistent? Yes or No

GIA / PR 5000:

Consistent? Yes or No

Est. Repairs:

02

days

Res: Yes or No

Lump Sum:

1.81

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

my?

Vehicle: IN / OUT

Date:

Person Contacted:

Vch No:

SLQ 3149D

Yr Regn:

07 17

Type: ☒ M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pro

C.C.

1798

Colour:

2. P. White

A/C: Insured / Std / NI / NA

Sp/Reading:

115786

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKRB31FU 303561628

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / All or

Tyre Size:

F: P1

195/65R15

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Inl:

7

mm

R/Inl:

7

mm

L/Inl:

7

mm

L/Inl:

7

mm

D.O.A:

1/7/19


D.O.L:

9/7/19

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



RECEIVED 15 JUL 2019

Date / Time

Action / Instruction

Date/Time: 15/7/19



Prel. Report

1)



Final Report

Date/Time: File Return to?

2)

15/7 - typist

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

CWS

Lump Sum / L.B.E (\$)

1619.25

Survey Fee:

Transportation:

3 + 165.34

Photos:

Others:

TOTAL

130

50

50+50

15

295



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004321MFSH

Our ref: CS/FCI19011801/Kvd3

Date : 10/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 3149D


We thank for your instruction on 3/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 9/7/2019 at the premises of M/s ESTEEM PERFORMANCE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,922.08
Revised Estimate Amount	: S\$1,320.08
"Check" Items Amount	: S\$499.18
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-07-2019	Our Ref No. D19004321MFSH
Accident Date	01-07-2019	Claim Type. Third Party
Insured Vehicle	SHA8610L	Third Party Vehicle. SLQ3149D
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	JENNY CHONG	
Contact No.	64841221/ 64847829	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 10 July 2019 12:26 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Henry Kao Cai Jie'
Subject: RE: SURVEY ASSESSMENT - D19004321MFSH/1, SLQ 3149D
Attachments: SLQ 3149D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLQ 3149D
Date of survey: 9/7/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 3 July 2019 3:43 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004321MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 3 July, 2019 3:05 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004321MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLQ 3149 D

Not Authorized

Resurvey B4 paint

Parts	(a) Cost / List Price Items	\$	1,776.10
	Plus/Less 25%	\$	444.03
	Total of Cost / List	\$	1,332.08
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	1,532.08
Labour		\$	2,390.00
Total		\$	3,922.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey the damage, painting.
- To stop damaged surface during resurvey.
- Parts prices are subject to confirmation.
- This cost survey is on a "without prejudice" basis.
- The survey will be conducted on a "without prejudice" basis.
- Survey results will be reviewed and subject to the cost of the insurance claim.

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 9/7/19 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 02 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$ _____
- (e) Signature of surveyor : Le Date: 9/7/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg


Spare Parts

Vehicle No. : SLQ 3149 D
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU303561628

Submit By : JENNY
Year Manufacture : 2017
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		2
7	Rear bumper lower centre garnish	1	\$582.60		✓
8	Rear bumper tow cover	1	\$31.70		X
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. : SLQ 3149 D Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011801/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8610L	Veh. Inspected	SLQ 3149D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004321MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	03/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU303561628	Colour	METALLIC PEARL WHITE	
Odometer	115786	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	PIRELLI	7 mm	
L/H Front Tyre	195/65 R15	PIRELLI	7 mm	
R/H Rear Tyre	195/65 R15	GITI	7 mm	
L/H Rear Tyre	195/65 R15	GITI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2019	Inspection Date	09/07/2019	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 3149D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER LOWER CENTRE GARNISH	DENTED / CUT	582.60	582.60
1	REAR BUMPER TOW COVER	SERVICEABLE	31.70	-
	LESS 25% DISCOUNT		-444.03	-379.75
			1,332.07	1,139.25
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER, TAIL DOOR, END PANEL).		800.00	250.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREAS..(REAR BUMPER, TAIL DOOR, END PANEL).		1,000.00	220.00
	TO CHECK WIRING.		50.00	10.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO TUFF COAT.	NOT NECESSARY	150.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			2,390.00	480.00
GRAND TOTAL			3,922.07	1,619.25
RECOMMENDED COST OF REPAIRS				1,619.25

Report Ref No. CS/FCI19011801/Kvd3n2



Report Ref No. CS/FCI19011801/Kvd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.