

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

03 JUL 2019

E S T I M A T E

Estimate No. : b1 51803
Date Estimated : 03/07/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Wong Kum Cheun
22 Canberra Drive
#04-05

Singapore 768426

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD7227R	D793088	07/10/2016	520iA	0

DESCRIPTION

Replace rear bumper and remove attachment etc

Spray painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

850 1,275.00

934 1,038.00

150 171.00

? 80.00

Total Labour 1: 2,570.00

DESCRIPTION

SET MOUNTS PDC SENSOR REAR

RR BUMPER CARRIER

PROTECTION FOIL L=55MM

ADAPTOR

REAR BUMPER CENTRE GUIDE

REAR BUMPER PRIMED (PDC)

REAR BUMPER TOWING EYE COVER PRIMED

DECOUPLING RING PDC TORQUE CONVERTE

Ultrasonic t

QTY	PRIC	VALUE
1	58.60	58.60
1	772.05	772.05
2	5.35	10.70
1	108.75	108.75
1	61.55	61.55
1	1,571.95	1,571.95
1	47.60	47.60
4	5.05	20.20
4	368.80	1,475.20

Total Parts : 4,126.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 16/07/19 @ 1410 Claim No. _____
Date & Time 16/07/19 @ 1410 Excess S\$ _____
Surveyor's Name Rasue Sign _____
Surveyor's Tel 90014667 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Labour 1 : 2,570.00
Parts : 4,126.60
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 468.76
Grand Total : 7,165.36

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

3 days

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 51803
Date Estimated : 03/07/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Wong Kum Cheun
22 Canberra Drive
#04-05

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 768426

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD7227R	D793088	07/10/2016	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident	850.00		850.00
To spray paint rear bumper	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00
Sundries	80.00		80.00
# Ceramic Protection on Rear Bumper (refer to Customer's receipt)	133.00		133.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PRIMED (PDC)	1,571.95	1.00		1,571.95

SUPPLEMENTARY ITEMS

Total Labour :	2,147.00
Total Parts :	1,571.95
Total Labour & Parts :	3,718.95
Deduction for Excess :	
Total Repair Costs less Excess:	3,718.95
GST @7%:	260.33
Grand Total :	3,979.28

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 51803
Date Estimated : 03/07/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Wong Kum Cheun
22 Canberra Drive
#04-05

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 768426

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD7227R	D793088	07/10/2016	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# Ceramic Protection on Rear Bumper (refer to Customer's receipt) <i>new</i>	133.00		133.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	133.00
Total Parts :	
Total Labour & Parts :	133.00

INVOICE

BILL TO :

Name : Mr. Wong Kum Cheun
Contact Number : 9731 2863

DATE : 11 October 2016

INVOICE : 167032

Vehicle Make/Model/Colour : BMW 520i Grey
Vehicle Registration Number : SKD 7227 R

Payment Mode : CASH / NETS / CREDIT

DESCRIPTION	AMOUNT
Extreme Package	\$ 1,768.00
Discount on Package - 15%	\$ (265.20)
Booking Deposit Paid - Invoice 167017	\$ (200.00)
Upgrade Full Interior Packages	\$ 238.00
Promotion Inclusive Ceramic PRO SEATS Protection Ceramic PRO TAG	
Warranty Number - 2016 3888	
<p>◆ Newly Applied Ceramic PRO Care ◆</p> <p>✓ Do not use Shampoo for the 1st 3 days</p> <p>✓ Keep the surface dry. If surface get wet, Dab the surface dry with a lightly damp Microfiber towel. Do Not use Wiping motion.</p> <p>✓ In event any substances land on the surface, clean up as soon as possible</p> <p>◆ Basic Care for Owners ◆</p> <p>✓ Weekly wash with Quality Shampoo and dry with clean chamois cloth.</p> <p>✓ Remove bird dropping, tree saps as soon as possible. Soften the substances with tissue soaked with water. Gently lift the substances off. Do not rub or use force.</p> <p>✓ Apply Ceramic PRO SPORT after shampoo wash at least once a month.</p> <p>Ceramic PRO Prestige card will be mailed to your residential address provided on warranty registration.</p> <p>* Please register your warranty online to be effective within 14 days http://www.ceramicpro.com.sg/register/</p>	
TOTAL :	\$ 1,540.80
TOTAL DUE AFTER 3% DISCOUNT ON FINAL BILL :	\$ 1,494.58
Parking Rebate :	\$ (9.00)
Total Paid :	\$ 1,485.58

9 Yishun Industrial Street 1 #01-69/70 North Spring Bizhub Singapore 768163

T: +65 6710 7793 | E: info@sgpaintprotection.com



INVOICE

BILL TO :

Name : WONG KUM CHEUN
Contact Number : 9731 2863
Make/Model/Colour : BMW 520I GREY
Licence Plate Number : SKD 7227 R

DATE : 19/07/2019
INVOICE : 1980461

PAYMENT MODE : Nets

DESCRIPTION	UNIT	QTY	AMOUNT (\$)
MS REAR Bumper GOLD W D	138.00	1.00	138.00

parking rebate -5.00

* Update warranty : TR220163888

Amount Due : \$ 133.00

Notes for new application / Re-application / Rejuvenate

Keep the surface dry. Dab the surface dry with a lightly damp Microfiber towel. Wash with quality shampoo and dry with clean chamois/Microfiber towel. Remove any contaminants promptly with proper method. Maintain the Nano-Hairs by applying Ceramic Pro SPORT once every 3 month or surface is losing its hydrophobic. Contact us immediately to avoid unnecessary cost for re-application if there are contaminants that cannot be cleaned off with shampoo. Do not use Shampoo for the Next 3 days. Apply a Layer of Ceramic PRO SPORT after the 3rd day of treatment.

* Please register your warranty online to be effective within 14 days @ <http://www.ceramicpro.com.sg/warranty-register/> Ceramic PRO Prestige card will be mailed to the address provided on warranty registration

Thank You For Your Business !

Ace Gt Pte Ltd | 9 Yishun Industrial Street 1 #01-69/70 North Spring Bizhub Singapore 768163
T: +65 6710 7793 | E: info@sgpaintprotection.com