

ASS. REG. BY:

REF: CS/CT2 190118041 U9d3⁰²

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Tan Kah Long

of CT1

Date/Time: 3.7.19 15.43 P.M

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP 70441

Insured:

GBG 2565 M

at Workshop m/s Automobile Integrated

Tel:

91198371

of 2B Sin Ming Linn #04-147

Policy No: DMCVSR30458518000

Claim No:

SNM 1910203090002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27.7.19

4.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.7.19 4.40 P.M

Person Contacted:

Jacynne

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Inspection: 23 Kaki Bukit Ave 4 #04-01
	YP 70441 - NA/LPC 10011684/r3	ROA - 02/07/2019
	GBG 2565 M: CS/CT2 19012839/TIS/13/2	ROA - 13/07/2019

ASSIGNMENT

From: Date: 4.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YP 7044Y

at Workshop n/s: Automobile Integrated

at 23 Eski Bukit Ave 4 #04-01

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: Contact - 9689 0102 Kelvin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value:

64k

IRAC Accident Report:

Consistent? Yes or No

GIA / IRIS Exam:

Consistent? Yes or No

Est. Repairs:

9

days

Res:

Yes or No

Lump Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

sup 11A29622

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP 7044Y

Yr Regn:

7 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

milf center FEB21 2998

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

126832

T/Radio: Insured / Std / NI / NA

Eng/Mo:

C/Mo:

FEB21EA 21 445

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Jammed / Jammed / Leaked / Burnt or

Brake: Jammed / Jammed / Leaked / Burnt or

Mod: N/S / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

6

Rear:

6/6

R/Bal:

mm

R/Bal:

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

2/7/19

D.O.A:

4/7/19

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rollover or

Rear & L.F.

The U/C / Chassis frame / Body Structure affected due to collision.

15/7/19

2/5 \$10,600 confirmed with Kelvin (Red \$13350.44, 69%)

RECEIVED 7 JUL 2019

Date/Time, File Pass to:

☐

: Prol. Report

1) 17/7/19

☐

: Final Report

Date/Time, File Return to:

2)

Days Of Repair:

9

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

MER-7P

Lump Sum / I.P.S. (\$

10600

Survey Fee:

Transportation:

: 3 + RS, 3

: Photos:

: Other:

: TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019		03 Jul 2019 15:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:									
Main Claimant: SAMMICON T & C PTE. LTD. Co. Reg. No.: 201432343M.									
Vehicle Reg. No.: YP7044Y Date of Loss: 02/07/2019 13:00 - :59									
Claim Type: TP / SNM19D203090C02 Policy/Cover Note No.: DMCVSN30458518000									
Vehicle Reg. No. (Insured): GBG2565M Policy No. (Claimant): A 28991696 MKC									
Excess: S\$500.00									
Repairer: Automobile Integrated Management Pte Ltd (HQ) 28 Sin Ming Lane, #07-147 Midview City, 573972 Bishan - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/07/2019]									
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 3 July, 2019 3:43 PM
To: AIM PTE LTD; assignments
Subject: RE: OUR REF: SNM19D203090/TANKL - GBG2565M - NOA- YP7044Y // Claim TP 02.07.19

WITHOUT PREJUDICE

Dear Jacyne,

We refer to your email of 03.07.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: AIM PTE LTD [mailto:automim.claim@gmail.com]
Sent: Wednesday, 3 July, 2019 3:40 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D203090/TANKL - GBG2565M - NOA- YP7044Y // Claim TP 02.07.19

Hi Kah Leong,

We would like to appoint Marcus Chua as surveyor to conduct this survey. Please let us have the time window and date of surveyor will come down.

Thank you.

Regards,
Jacyne

On Wed, Jul 3, 2019 at 3:31 PM Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com> wrote:

Without Prejudice

Dear Jacyne,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, 3 July, 2019 3:08 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; automim.claim@gmail.com

Subject: OUR REF: SNM19D203090/TANKL - GBG2565M - NOA- YP7044Y // Claim TP 02.07.19

Dear Kah Leong,

Please conduct PRS for YP7044Y.

*** insured non reporting.

Officer-In-Charge – Tan Kah Leong – 63896193 (file with OIC).

Thank you

Lim Shu Min

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: AIM PTE LTD [<mailto:automim.claim@gmail.com>]
Sent: Wednesday, 3 July, 2019 11:30 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: NOA- YP7044Y // Claim TP 02.07.19

Hi,

Please find attached NOA to advise further.

Thank you.

Regards,

Jacyne

AIM

tel: 91198371

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--
AIM
tel: 91198371

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

sgCARMART.COM

Login Sign up

[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Articles](#)
[Forum](#)
[Resources](#)

Advanced Search

Home » Used Cars » Car (S) Pte Ltd » Mitsubishi Fuso Canter FEB21

Mitsubishi Fuso Canter FEB21

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)


Price	\$61,800	Lifespan	13-Mar-2037
Depreciation	\$8,030 /yr View models with similar depre	Reg Date	14-Mar-2017 (7yrs 8mths 8days COE left)
Mileage	N.A.	Manufactured	2016
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$10,354 as of today (change)	OMV	\$35,625
COE	\$13,459	ARF	\$1,782
Engine Cap	2,998 cc	No. of Owners	2
Curb Weight	2,500 kg		
Type of Vehicle	Truck		

Features

Cheapest In The Market!

Accessories

Full Canopy And Checkered Plate.

Description

Cheapest In The Market! Most Popular Canter 14ft Series In Singapore. Maintained By Agent! Still Under Warranty, Full Canopy And Aluminum. No Repairs Needed. Ready For Business, No Waiting Time. Flexible Loan, Trade In Welcome. Do No Miss This Offer, Call Us Now.

Category

Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: 29-Jun-2019 | Last Updated on: 29-Jun-2019

Upfront Payment

[» more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$5,180 (change)	Maximum 90% Loan
1st Installment	\$820	Based on 3.4% interest rate



Price Chart

Click on the point to view the vehicle

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Company	Car (S) Pte Ltd * dealer's pricelist * 119 vehs sold 212 vehs available	
Address	39 Woodlands Close #07-K1, #08-04 Search cars nearby this location	
Location	Mega @ Woodlands	
Office No	63863322	
Contact Person (s)	Bond William Low Song	94389996 91776311 97654355

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2343M

Vehicle Details

Vehicle No.: YP7044Y

Vehicle to be Exported: No

Intended Deregistration Date: 04 Jul 2019

Vehicle Make: MITSUBISHI

Vehicle Model: CANTER FEB21ER4SDEB (CBU)

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 4P10C75501

Chassis No.: FEB21EA21445

Maximum Power Output: -

Open Market Value: \$33,567.00

Original Registration Date: 17 Jul 2017

First Registration Date: 17 Jul 2017

Transfer Count: 0

Actual ARF Paid: \$1,679.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jul 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$36,879.00

COE Rebate Amount: \$29,622.00

Total Rebate Amount: \$29,622.00

The information contained herein is correct as at 04 Jul 2019

OK

not Afford
 2/11
 1/5 #10,600
 taking the Afford
 4/7/18
 9 day.

4/5 # 10,600/



Automobile Integrated Management Pte Ltd
 (Business Reg no. 201605297G)
 Office: 28 Sin Ming Lane #07-147
 Midview City Singapore 573972
 Workshop: 23 Kaki Bukit Ave 4 #04-01 (south wing)
 Singapore 415933
 Email: automim.claim@gmail.com

ESTIMATE

Our Ref: AC2019019/TP/YP7044Y - 02.07.2019

Vehicle number: YP7044Y

Vehicle Made & Model: MITSUBISHI FUSO

Items	Qty	List Items	Amount \$
1	1	Front bumper 1010.33	1,231.55
2	2	Front bumper sides - L/R @ 341.66	683.32
3	2	Front bumper brackets - L/R @ 246.55	493.10
4	1	Front cab panel	1,559.60
5	1	Front cab panel emblem "FUSO"	243.35
6	1	Front corner panel - LH	311.43
7	1	Front chassis crossmember - CTR	641.59
8	1	Front grille	618.32
9	1	Front grille logo	86.50
10	1	Front grille emblem "CANTER"	48.60
11	5	Front grille clips @ 5.50	27.50
12	2	Front headlamps - L/R @ 730.58	1,461.15
13	2	Front signal lamps - L/R @ 299.63	599.26
14	2	Front side lamps - L/R @ 245.96	491.92
15	1	Front side mirror with stay - LH	761.90
16	1	Front wiper panel garnish 383.25	811.53
17	2	Front wiper arms @ 89.60	179.20
18	1 set	Front wiper linkage	481.50
19	1	Front wiper motor	560.93
20	1	Front windscreen rubber	441.53
21	1	Air con blower assy	1,463.32
22	1	Air con cooling coil assy	1,261.52
23	1	Air con heater assy	1,831.31
24	1	Dashboad lower cover - LH	310.35
25	2	Horns @ 89.35	178.70
26	1	Rear tailgate assy 1800.00	2,289.53
27	1	Rear tailgate sticker "FUSO"	272.40
28	4	Rear tailgate hinges @ 89.55	358.20
29	1	Rear tailgate lower member	695.50
30	2	Rear tailgate stopper rubbers @ 28.60	57.20
31	2	Rear taillamps - L/R @ 311.43	622.86
32	2	Rear taillamp brackets - L/R @ 241.50	483.00
33	1	Rear licence lamp	89.90
34	2	Rear sidegates - L/R @ 2655.31	5,310.62

9495.32
 252
 7121.49

Vehicle number: YP7044YVehicle Made & Model: MITSUBISHI FUSO

35 2 Rear sidegate lock hinges - L/R @ 241.20

2 482.40 X
 Sub-total 27,440.59
 Less 25% 6,860.15
 Total List 20,580.44

Special Nett Items

36 1 Rear no. plate
 37 1 Rear sticker "60 KM/H"
 38 1 Rear sticker "22 PAX"
 39 1 Rear step bar
 40 1 set Rear underdrum with bracket assy
 41 2 Rear chassis wooden planks - L/R @ 450
 42 6 Rear chassis "U" bolts - L/R @ 50
 43 1 Rear vertical ~~wooden~~ members
 44 1 set Rear vertical wooden member bolt
 45 1 Front no. plate

3rd 40.00 14
 2nd 10.00 10
 2nd 10.00 10
 3rd 350.00 ✓
 3rd 1,200.00 900
 2 900.00 X
 11 300.00 X
 10/11 2,800.00 2
 11 200.00 X
 3rd 40.00 14
 Total Special Nett 5,850.00

51100

Labour charges

46 To check front & rear electrical wiring
 47 To remove, refix front windscreen
 48 To remove, refix front dashboard
 49 To remove, refix A/C cooling systems
 50 To reinstall & realign rear ^{canopy deck} to assist repair
 51 To straighten, repair & realign chassis frame member
 52 To respray undercoating
 53 To respray painting & etc
 54 Panel beating, cut, weld remove & replacing above parts

120.00 30
 150.00 80
 300.00 200
 250.00 100
 800.00 380
 11 1,200.00 X
 200.00 60
 2,000.00 1500
 2,500.00 1500
 Total Labour 7,520.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$**33,950.44**

LKK Auto Consultants hence notify
 the Responder of the following:
 • To remove, refix front windscreen
 • To remove, refix front dashboard
 • To remove, refix A/C cooling systems
 • To reinstall & realign rear canopy deck to assist repair
 • To straighten, repair & realign chassis frame member
 • To respray undercoating
 • To respray painting & etc
 • Panel beating, cut, weld remove & replacing above parts
 Acknowledged by Repairer:
 Signature:
 Date:

3810.
 13369.46
 202

0695.59

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19011804/UQD3N2

Date: 18/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30458518000
Claimant Vehicle No :	YP7044Y	Insured Vehicle No :	GBG2565M
Date of Loss:	02/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203090C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP7044Y	Engine No:	4P10C75501
Make & Model:	mitsubishi canter, 3.0 D FEB21ER4SDEB (CBU) (M)	Chassis No:	FEB21EA21445
Reg. Date:	17/07/2017 (Man. Year: 2017)	Odometer:	126832 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	26,430.44	9,519.49	16,910.95	63.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,520.00	3,850.00	3,670.00	48.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,950.44	13,369.49	20,580.95	60.62
Approved Total (Overridden) (S\$)		10,600.00		
Nett Amount (S\$)	33,950.44	10,600.00	23,350.44	68.78

INSPECTION

Date of Assignment: 03/07/2019

Date Inspected: 04/07/2019 Inspected At:

23 Kaki Bukit Ave 4 #04-01
Repairer: Automobile Integrated Management Pte Ltd (HQ)
28 Sin Ming Lane, #07-147 Midview City
Singapore 573972

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Jul 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP7044Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,231.55 FL	*1,010.33 FL
2	2		*FRONT BUMPER SIDE-L/R	N/s Deformed/O/s Torn	683.32 FL	*683.32 FL
3	1		*FRONT BUMPER BRACKETS-L/R	N/s Bent	493.10 FL	*246.55 FL
4	1		*FRONT CAB PANEL	Dented/Buckled	1,559.60 FL	*1,559.60 FL
5	1		*FRONT CAB PANEL EMBLEM FUSO	Necessary	243.35 FL	*243.35 FL
6	1		*FRONT CORNER PANEL-LH	Repair	311.43 FL	*- FL
7	1		*FRONT CHASSIS CROSSMEMBER-CTR	Repair	641.59 FL	*- FL
8	1		*FRONT GRILLE	Cracked	618.32 FL	*618.32 FL
9	1		*FRONT GRILLE LOGO	Necessary	86.50 FL	*86.50 FL
10	1		*FRONT GRILLE EMBLEM CANTER	Necessary	48.60 FL	*48.60 FL
11	5		*FRONT GRILLE CLIPS	Necessary	27.50 FL	*27.50 FL
12	1		*FRONT HEADLAMPS-L/R	N/s Cracked	1,461.15 FL	*730.58 FL
13	2		*FRONT SIGNAL LAMPS-L/R	Not Necessary	599.26 FL	*- FL
14	1		*FRONT SIDE LAMPS-L/R	N/s Cracked	491.92 FL	*245.96 FL
15	1		*FRONT SIDE MIRROR WITH STAY-LH	Not Necessary	761.90 FL	*- FL
16	1		*FRONT WIPER PANEL GARNISH	Dented/Warped	811.53 FL	*383.95 FL
17	2		*FRONT WIPER ARMS	Not Necessary	179.20 FL	*- FL
18	1		*SET FRONT WIPER LINKAGE	Not Necessary	481.50 FL	*- FL
19	1		*FRONT WIPER MOTOR	Not Necessary	560.93 FL	*- FL
20	1		*FRONT WINDSCREEN RUBBER	Necessary	441.53 FL	*441.53 FL
21	1		*AIR CON BLOWER ASSY	Not Necessary	1,463.32 FL	*- FL
22	1		*AIR CON COOLING COIL ASSY	Not Necessary	1,261.52 FL	*- FL
23	1		*AIR CON HEATER ASSY	Not Necessary	1,831.31 FL	*- FL
24	1		*DASHBOARD LOWER COVER-LH	Not Necessary	310.35 FL	*- FL
25	2		*HORNS	Not Necessary	178.70 FL	*- FL
26	1		*REAR TAILGATE ASSY	Bent	2,289.53 FL	*1,800.00 FL
27	1		*REAR TAILGATE STICKER FUSO	Necessary	272.40 FL	*272.40 FL
28	4		*REAR TAILGATE HINGES	Repair	358.20 FL	*- FL
29	1		*REAR TAILGATE LOWER MEMBER	Bent	695.50 FL	*695.50 FL
30	2		*REAR TAILGATE STOPPER RUBBERS	Not Necessary	57.20 FL	*- FL
31	1		*REAR TAILLAMPS-L/R }	N/s Cracked	622.86 FL	*311.43 FL
32	2		*REAR TAILLAMP BRACKETS-L/R }		483.00 FL	*- FL
33	1		*REAR LICENCE LAMP	Cracked	89.90 FL	*89.90 FL
34	2		*REAR SIDEGATES-L/R	Repair	5,310.62 FL	*- FL
35	2		*REAR SIDEGATE LOCK HINGES-L/R	Repair	482.40 FL	*- FL
36	1		*REAR NO PLATE	Bent	40.00 FS	*14.00 FS
37	1		*REAR STICKER 60KM/H	Necessary	10.00 FS	*10.00 FS
38	1		*REAR STICKER 22 PAX	Necessary	10.00 FS	*10.00 FS
39	1		*REAR STEP BAR	Bent	350.00 FS	*350.00 FS
40	1		*SET REAR UNDERDRUM WITH BRACKET ASSY	Bent	1,200.00 FS	*900.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	2		*REAR CHASSIS WOODEN PLANKS-L/R	Repair	900.00 FS	*- FS
42	6		*REAR CHASSIS U BOLTS-L/R	Not Necessary	300.00 FS	*- FS
43	1		*REAR VERTICAL MEMBERS	Dented/Twisted	2,800.00 FS	*1,100.00 FS
44	1		*SET REAR VERTICAL WOODEN MEMBER BOLT	Not Necessary	200.00 FS	*- FS
45	1		*FRONT NO PLATE	Bent	40.00 FS	*14.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					33,290.59	11,893.32
- List Item Discount on L Items 25.00/25.00% (\$\$)					6,860.15	2,373.83
Total Parts (\$\$)					26,430.44	9,519.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT & REAR ELECTRICAL WIRNG	New	120.00	30.00
2	TO REMOVE,REFIX FRONT WINDSCREEN	New	150.00	80.00
3	TO REMOVE,REFIX FRONT DASHBOARD	New	300.00	200.00
4	TO REMOVE,REFIX A/C COOLING SYSTEMS	New	250.00	100.00
5	TO REINSTALL & REALIGN REAR CARGO DECK TO ASSIST REPAIR	New	800.00	380.00
6	TO STRAIGHTEN,REPAIR & REALIGN CHASSIS FRAME MEMBER	New	1,200.00	0.00
7	TO RESPRAY UNDERCOATING	New	200.00	60.00
8	TO RESPRAY PAINTING & ETC	New	2,000.00	1,500.00
9	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS	New	2,500.00	1,500.00
Gross Labour Cost (S\$)			7,520.00	3,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >