

22/03/2012

ASS. REC. BY:

REF: CS/FCI 19011808/ Gvcl3 A2

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Hunny kao

of

FCI

Date/Time:

3.7.19 3.06pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLF 349X

Insured:

SHC 7779E

at Workshop m/s

Progressive Car

Tel:

67415336

of

Bllc 3022A Ubi road #01-45

Policy No:

Claim No:

D19004289 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

28.6.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

3.7.19 3.55pm

Person Contacted:

Lily

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLF 349X - CS/MSG 18003239/ Gvcl3 2 D.O.A - 10/02/2018
	SHC 7779E - CS/FCI 19610196/ Dtd3 D.O.A - 01/06/2019
4/7/19	Email preli revised to FCI
15/8/19	@ 4:49pm Ray will finalise with us asap
12/9/19	Final fig \$13,758.48 Confirmed by email (Red 9390.44, 4190)

Sirajus

Ad.

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s Progressive Car Care
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____


(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt.: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 8 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SLF349X Yr Regn: 11 Aug 2016
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda vezel c.c. 1496
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 33458 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: Ru31208154
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 245/40 249
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FAUKEN
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 03-07-19
Survey held at w/s 5pm
Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
\$ 13558.48

RECEIVED 18 SEP 2019

12/9/2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 12/9- typist

Report Format : CWS
Lump Sum / I.B.I. (\$) 13,758.48

Days Of Repair: 8

Resurvey No. of Trip: 4

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + BS - SI

Photos: 580

Other: 558

TOTAL 12/9/19

13x15-195

170 + 195
50
50 + 10 + 50
213
828



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004289MFSH

Our ref: CS/FCI19011808/Gvd3

Date: 4/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LIMITED

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLF 349X


We thank you for your instruction on 3/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/7/2019 at the premises of M/s PROGRESSIVE CAR CARE PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$21,371.24
Revised Estimate Amount	:S\$5,393.12
"Check" Items Amount	:S\$12,034.64
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAI, AMSAE-A

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	02-07-2019	Our Ref No. D19004289MFSH
Accident Date	28-06-2019	Claim Type. Third Party
Insured Vehicle	SHC7779E	Third Party Vehicle. SLF349X
Survey Location	BLK 3022A UBI ROAD #01-45/46	
Contact Person.	LILY LIM	
Contact No.	67415336/ 0	Fax No. 67417208
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (EST. COR \$22,867.23)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE CAR CARE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 4 July 2019 3:26 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Henry Kao Cai Jie'
Subject: RE: SURVEY ASSESSMENT - D19004289MFSH/1, SLF 349X
Attachments: SLF 349X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLF 349X
Date of survey: 3/7/2019
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 3 July 2019 3:41 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004289MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 3 July, 2019 3:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004289MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 12 September 2019 12:49 PM
To: 'Ray'; SUR
Subject: RE: SLF 349X-DOA: 28/6/2019

Dear Ray,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray <ray@procarcare.com.sg>
Sent: Thursday, 12 September 2019 12:46 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SLF 349X-DOA: 28/6/2019

Ok, thank you.

Regards,

Ray Lin

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg



IMPORTANT NOTICE: The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, September 12, 2019 12:35 PM
To: Ray; Guo Qiang (LKKAUTO); SUR
Cc: Wayne; Peiwen; Chermaine
Subject: RE: SLF 349X-DOA: 28/6/2019

Dear Ray,

WITHOUT PREJUDICE

Supplementary labour revised to \$350

Finalise amount \$13,758.48 @ 8 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 11 September 2019 5:29 PM

To: Ray <ray@procarcare.com.sg>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Wayne <wayne@procarcare.com.sg>; Peiwen <peiwen@procarcare.com.sg>; Chermaine <chermaine@procarcare.com.sg>

Subject: RE: SLF 349X-DOA: 28/6/2019

Dear Ray,

WITHOUT PREJUDICE

Supplementary labour revised to \$150

Finalise amount \$13,558.48 @ 8 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray <ray@procarcare.com.sg>

Sent: Tuesday, 20 August 2019 3:52 PM

To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: Wayne <wayne@procarcare.com.sg>; Peiwen <peiwen@procarcare.com.sg>; Chermaine <chermaine@procarcare.com.sg>

Subject: FW: SLF 349X-DOA: 28/6/2019

Hi Guo Qiang/ Veron,

Please refer to finalize

Supp	\$1575.44
Parts	\$7803.04
Sn	\$380.00
Lab	\$4150.00
Total	\$13908.48

Regards,

Ray Lin

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**.
You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses
(@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

Sent: Monday, August 19, 2019 10:05 AM

To: Ray

Subject: RE: SLF 349X-DOA: 28/6/2019

Dear Ray,

Can finalise?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray <ray@procarcare.com.sg>

Sent: Tuesday, 30 July 2019 12:32 PM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Subject: RE: SLF 349X-DOA: 28/6/2019

Will check and revert to you.

Regards,

Ray Lin

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**. You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses (@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Tuesday, July 30, 2019 12:25 PM

To: Ray

Subject: SLF 349X-DOA: 28/6/2019

Dear Ray,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	0592Z
Vehicle No.:	SLF349X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5Z HYBRID CVT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	LEB5908163
Chassis No.:	RU31208154
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$29,576.00
Original Registration Date:	11 Aug 2016
First Registration Date:	11 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$18,407.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2026
PARF Rebate Amount:	\$13,805.00
COE Expiry Date:	10 Aug 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$40,489.00
Total Rebate Amount:	\$54,294.00

The information contained herein is correct as at 03 Jul 2019

OK

ANNEX E

NOTICE OF COMPLIANCE

This is to confirm that Tan Chee Keong NRIC S7430592Z, has reported to the Police on a non-injury traffic accident which occurred along TPE towards SLE direction just before Tampines Link Exit 4, on 28/06/2019 at about 1720hrs involving the following vehicles: SLF 349X, (Informant's vehicle) & SHC 7779E, Citycab (Other party vehicle) and SMJ 7997X (Other party vehicle).

If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with compliance under Sec 84(2) of the Road Traffic Act, Cap 276



Tan Chee Keong
Date: 28/06/2019
Police Post/Unit: Hougang NPP

Name of Issuing Officer: SGT Ong Yu Han



Original - to be issued to informant
Duplicate - to be retained at police post or unit



Time 1720 hrs

Location : TPE heading towards SLE (Before Exit 4 Tampines Link)

On 28/6/2019 @ 1720 hrs, I , Tan Chee Keong bearing NRIC : S7430592Z was driving SLF 349X along TPE heading towards SLE . Somewhere near Tampines Link Exit 4, I noticed vehicle SMJ 7997X driven by Mr Ahmad Hussein (S1313598C) slowing down and braking due to heavy traffic.

I braked my vehicle and so did SMJ 7997X. Both the vehicles were stationary.

Moments later , I was hit from behind by Taxi , SHC 7779E driven by Mr Norman Bin Abu (S1731813F) , causing me to surge ahead and hit the rear end of SMJ 7997X.

All drivers got down , took pictures of the damage and exchange particulars.

I made a police report at Hougang NPC 20 minutes later.

I also visited a GP as I was feeling giddy and had neck and shoulder pains. I was given 3 days MC by the doctor.

I have communicated with Mr Ahmad Hussein and he is willing to be a witness to prove that our vehicles were stationary until being hit by SHC7779E.

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : TAN CHEE KEONG (CHEN ZHIQIANG)
BLK 473D UPPER SERANGOON CRESCENT #15-
SINGAPORE 538473

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
Claim Type: Third Party
Accident Date: 28/06/2019
TP Veh Reg No: SHC 7779 E

Estimate No: EST1504990
Date: 01 Jul 2019
Policy No: P10077042R00
Veh Reg No: SLF349X
Make/Model: HONDA VEZEL 1.5Z
HYBRID CVT ABS
D/AIRBAG 2WD
Chassis No: RU31208154
Engine No: LEB5908163
Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT / Bue ✓	1,100.900	1 PCS	1,100.90 /	
2 REAR BOOT HINGE - LH X	50.8000	1 PC	50.80 X	
3 REAR BOOT HINGE - RH X	50.8000	1 PC	50.80 X	
4 REAR BOOT H LOGO X	24.7000	1 PCS	24.70 X	
5 REAR BOOT VEZEL WORDING	43.0000	1 PCS	43.00 /	
6 REAR BOOT RS WORDING	52.5000	1 PCS	52.50 /	
7 REAR BOOT HYBRID	75.5000	1 PC	75.50 /	
8 REAR BOOT NUMBER PLATE LAMP - LH X	38.5000	1 PCS	38.50 X	
9 REAR BOOT NUMBER PLATE LAMP - RH X	38.5000	1 PCS	38.50 X	
10 REAR BOOT LOCK SENSOR X	0.0000	1 PC	0.0000 X	
11 REAR BOOT REFLECTOR - LH X	413.5000	1 PC	413.50 X	
12 REAR BOOT REFLECTOR - RH X	413.5000	1 PC	413.50 X	
13 REAR BOOT RUBBER	96.8000	1 PC	96.80 /	
14 REAR BOOT TOP LOCK	151.8000	1 PC	151.80 /	
15 REAR BOOT BOTTOM LOCK	32.2000	1 PCS	32.20 X	
16 REAR PANEL	411.9000	1 PCS	411.90 /	
17 REAR PANEL TOP GARNISH	98.2000	1 PCS	98.20 X	
18 REAR FLOOR PANEL MEMBER PN - 21	0.0000	1 PCS	0.0000 /	
19 REAR SPARE TYRE FLOOR PANEL	875.6000	1 PCS	875.60 /	
20 REAR SPARE TYRE BOARD	430.0000	1 PC	430.00 X	
21 REAR BOOT WINDSCREEN MOULDING	158.3000	1 SET	158.30 /	
22 REAR BUMPER - L	195.0000	1 PC	195.00 X	
23 REAR BUMPER	850.0000	1 PC	850.00 /	
24 REAR BUMPER - R	195.0000	1 PC	195.00 X	
25 REAR BUMPER CLIPS	3.9000	10 PC	39.00 /	
26 REAR BUMPER SIDE HOLDER - LH X	17.5000	1 PCS	17.50 X	
27 REAR BUMPER SIDE HOLDER - RH X	17.5000	1 PCS	17.50 X	
28 REAR BUMPER REFLECTORS - LH X	198.5000	1 PC	198.50 X	
29 REAR BUMPER REFLECTORS - RH X	148.5000	1 PC	148.50 X	
30 REAR BUMPER LOWER GARNISH - BLACK	190.0000	1 PCS	190.00 X	
31 REAR FENDER COWLING - RH X	133.0000	1 PCS	133.00 X	
32 REAR WHEEL OUTER WHEEL ARCH GARNISH - LH	210.2000	1 PCS	210.20 X	
33 REAR WHEEL OUTER WHEEL ARCH GARNISH - RH	210.2000	1 PCS	210.20 X	
34 REAR EXHAUST PIPE	726.8000	1 PC	726.80 /	
35 REAR EXHAUST PIPE TOP PLATE	55.0000	1 PCS	55.00 /	
36 REAR EXHAUST PIPE - CENTRE	599.1000	1 PC	599.10 /	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST: 201006949C RCB NO: 201006949C

M/S: TAN CHEE KEONG (CHEN ZHIQIANG)
 BLK 473D UPPER SERANGOON CRESCENT #15-
 SINGAPORE 538473

Estimate No: EST1504990
 Date: 01 Jul 2019
 Policy No: P10077042R00
 Veh Reg No: SLF349X
 Make/Model: HONDA VEZEL 1.5Z
 HYBRID CVT ABS
 D/AIRBAG 2WD

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
 Claim Type: Third Party
 Accident Date: 28/06/2019
 TP Veh Reg No: SHC 7779 E

Chassis No: RU31208154
 Engine No: LEB5908163
 Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price	Amount
			SS	SS
37 REAR EXHAUST PIPE MOUNTING	17.1000	2 PC	17.10	/
38 REAR EXHAUST PIPE CHROME	135.6000	1 PC	135.60	/
39 REAR FLOOR PANEL UNDER LOWER GARNISH	0.0000	1 PC	0.0000	/
40 TAILLAMP ASSY - LH	474.6000	1 PCS	474.60	X
41 TAILLAMP ASSY - RH	474.6000	1 PCS	474.60	X
42 TAILLAMP LOWER RETAINER - LH	0.0000	1 PCS	0.0000	X
43 TAILLAMP LOWER RETAINER - RH	0.0000	1 PCS	0.0000	X
44 HEADLAMP ASSY - LH	1,820.200	1 PCS	1,820.20	/
45 HEADLAMP LOWER RETAINER - LH	35.0000	1 PCS	35.00	/
46 FRONT FENDER OUTER WHEEL ARCH GARNISH - LH	201.5000	1 PCS	201.50	X
47 HEADLAMP ASSY - RH	1,820.200	1 PCS	1,820.20	X
48 HEADLAMP LOWER RETAINER - LH	35.0000	1 PCS	35.00	/
49 FRONT FENDER OUTER WHEEL ARCH GARNISH - LH	201.5000	1 PCS	201.50	X
50 GRILLE TOP GARNISH CLIP	3.9000	12 PCS	46.80	/
51 AIR DUCT CLIPS	4.2000	2 PCS	8.40	/
52 GRILLE LOGO CLIP	5.6000	2 PCS	11.20	/
53 GRILLE BASE	380.6000	1 PCS	380.60	/
54 GRILLE OUTER GARNISH	385.0000	1 PCS	385.00	/
55 GRILLE LOWER CHROME	95.8000	1 PCS	95.80	/
56 GRILLE LOGO	27.4000	1 PCS	27.40	/
57 FRONT BUMPER	801.7000	1 PC	801.70	/
58 FRONT BUMPER CLIPS	3.9000	10 PC	39.00	/
59 FRONT BUMPER SIDE HOLDER - LH	17.0000	1 PC	17.00	/
60 FRONT BUMPER SIDE HOLDER - RH	17.0000	1 PC	17.00	/
61 FRONT BUMPER REINFORCEMENT	360.8000	1 PC	360.80	/
62 FRONT BUMPER LOWER SPOILER, BLACK	450.3000	1 PC	450.30	X
63 FRONT BUMPER FOG LAMP - LH	510.2000	1 PC	510.20	X
64 FRONT BUMPER FOGLAMP COVER - LH	82.6000	1 PCS	82.60	X
65 FRONT BUMPER FOGLAMP - RH	510.2000	1 PCS	510.20	X
66 FRONT BUMPER FOG LAMP COVER - RH	82.6000	1 PC	82.60	X
67 SUPPORT PANEL TOP GARNISH CLIP	3.9000	8 PCS	31.20	/
68 SUPPORT PANEL TOP GARNISH	85.0000	1 PCS	85.00	X
69 SUPPORT PANEL	576.2000	1 PCS	576.20	X
70 CONDENSER	568.7000	1 PC	568.70	X
			18,645.30	
		Less 20%	3,729.06	14,916.24

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : TAN CHEE KEONG (CHEN ZHIQIANG)
BLK 473D UPPER SERANGOON CRESCENT #15-
SINGAPORE 538473

Estimate No: **EST1504990**
Date: 01 Jul 2019
Policy No: P10077042R00
Veh Reg No: **SLF349X**
Make/Model: HONDA VEZEL 1.5Z
HYBRID CVT ABS
D/AIRBAG 2WD

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
Claim Type: Third Party
Accident Date: 28/06/2019
TP Veh Reg No: SHC 7779 E

Chassis No: RU31208154
Engine No: LEB5908163
Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price <u>SS</u>	Amount <u>SS</u>
Special Net				
71 REAR BUMPER SENSOR <i>/ DM</i>	220.0000	1 SET	220.00	
72 GRILLE RS LOGO <i>/ MC</i>	65.0000	1 PCS	65.00	
73 FRONT NUMBER PLATE WITH CASING <i>/ RA</i>	35.0000	1 SET	35.00	
74 REAR NUMBER PLATE WITH CASING <i>X / NN</i>	35.0000	1 PC	35.00	
75 REAR BOOT CAMERA <i>X</i>	450.0000	1 PC	450.00	
76 SEALANT <i>/ MC</i>	20.0000	2 PC	40.00	
77 SPONGE TAPE <i>/ MC</i>	20.0000	1 PCS	20.00	
			865.00	865.00
Labour				
78 TO KNOCK OUT DENTS, REAR BOTH CHASSIS, CUT/WELD REAR PANEL, SUPPORT PANEL, REMOVE, REPLACE ACCIDENT PARTS	2,200.000	1 JOB	2,200.00 <i>1000.00 1900</i>	
79 TO RESPRAY PAINT ON ACCIDENT PORTIONS	2,000.000	1 JOB	2,000.00 <i>1000.00 1800</i>	
80 TO CHECK WIRING	50.0000	1 JOB	50.00 <i>30</i>	
81 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00 <i>40</i>	
82 TO REMOVE, REFIX REAR GARNISH, CUSHION, CARPET & RELATED PARTS	200.0000	1 JOB	200.00 <i>60</i>	
83 TO TUFF-KOTE	120.0000	1 JOB	120.00 <i>60</i>	
84 TO REMOVE, REPLACE REAR EXHAUST PIPE	100.0000	1 JOB	100.00 <i>60</i>	
85 TO REMOVE, REPLACE CENTRE EXHAUST PIPE	100.0000	1 JOB	100.00 <i>✓</i>	
86 TO REMOVE, REPLACE REAR GLASS	120.0000	1 JOB	120.00 <i>100</i>	
87 TO REMOVE, REFIT REAR BOTH UNDERCARRIAGE	400.0000	1 JOB	400.00 <i>X</i>	
88 TO 4 WHEEL ALIGNMENT	100.0000	1 JOB	100.00 <i>X</i>	
89 TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100.0000	1 JOB	100.00 <i>X / NN</i>	
			5,590.00	5,590.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST: 201006949C RCB NO: 201006949C

M/S : TAN CHEE KEONG (CHEN ZHIQIANG)
BLK 473D UPPER SERANGOON CRESCENT #15-
SINGAPORE 538473

Estimate No: EST1504990
Date: 01 Jul 2019
Policy No: P10077042R00
Veh Reg No: SLF349X
Make/Model: HONDA VEZEL 1.5Z
HYBRID CVT ABS
D/AIRBAG 2WD
Chassis No: RU31208154
Engine No: LEB5908163
Reg. Date: 11/08/2016

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
Claim Type: Third Party
Accident Date: 28/06/2019
TP Veh Reg No: SHC 7779 E

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
	23,148.92		Total	SS 21,371.24
			Add GST @ 7%	1,495.99
			Total Amount Payable	SS 22,867.23

TOTAL: SINGAPORE DOLLAR TWENTY TWO THOUSAND EIGHT HUNDRED SIXTY SEVEN AND CENTS TWENTY THREE ONLY

8 Days.

part by part.

before paint photos.

Guo Qiang - 82880282

03/7/19.

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road I #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: TAN CHEE KEONG (CHEN ZHIQIANG)
BLK 473D UPPER SERANGOON CRESCENT #15-
SINGAPORE 538473

Estimate No: EST1504990
Date: 01 Jul 2019
Policy No: P10077042R00
Veh Reg No: SLF349X
Make/Model: HONDA VEZEL 1.5Z
HYBRID CVT ABS
D/AIRBAG 2WD

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
Claim Type: Third Party
Accident Date: 28/06/2019
TP Veh Reg No: SHC 7779 E

Chassis No: RU31208154
Engine No: LEB5908163
Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT / Bue	1,100.900	1 PCS	1,100.90 ✓	
2 REAR BOOT HINGE - LH X	50.8000	1 PC	50.80	
3 REAR BOOT HINGE - RH X	50.8000	1 PC	50.80	
4 REAR BOOT H LOGO X	24.7000	1 PCS	24.70	
5 REAR BOOT VEZEL WORDING	43.0000	1 PCS	43.00 ✓	
6 REAR BOOT RS WORDING	52.5000	1 PCS	52.50 ✓	
7 REAR BOOT HYBRID	75.5000	1 PC	75.50 ✓	
8 REAR BOOT NUMBER PLATE LAMP - LH X	38.5000	1 PCS	38.50	
9 REAR BOOT NUMBER PLATE LAMP - RH X	38.5000	1 PCS	38.50	
10 REAR BOOT LOCK SENSOR X	0.0000	1 PC	0.0000	
11 REAR BOOT REFLECTOR - LH X	413.5000	1 PC	413.50	
12 REAR BOOT REFLECTOR - RH X	413.5000	1 PC	413.50	
13 REAR BOOT RUBBER	96.8000	1 PC	96.80 ✓	
14 REAR BOOT TOP LOCK	151.8000	1 PC	151.80 ✓	
15 REAR BOOT BOTTOM LOCK X	32.2000	1 PCS	32.20	
16 REAR PANEL R ✓	411.9000	1 PCS	411.90 ✓	
17 REAR PANEL TOP GARNISH ?	98.2000	1 PCS	98.20	
18 REAR FLOOR PANEL MEMBER PN - 21 R /	0.0000	1 PCS	0.0000 ✓ 95.00 ✓ 95	
19 REAR SPARE TYRE FLOOR PANEL X	875.6000	1 PCS	875.60 ✓	
20 REAR SPARE TYRE BOARD	430.0000	1 PC	430.00	
21 REAR BOOT WINDSCREEN MOULDING / M.L.	158.3000	1 SET	158.30 ✓	
22 REAR BUMPER - L X	195.0000	1 PC	195.00	
23 REAR BUMPER - R	850.0000	1 PC	850.00 ✓	
24 REAR BUMPER - R X	195.0000	1 PC	195.00	
25 REAR BUMPER CLIPS / M.L.	39.0000	10 PC	39.00 ✓	
26 REAR BUMPER SIDE HOLDER - LH X	17.5000	1 PCS	17.50	
27 REAR BUMPER SIDE HOLDER - RH X	17.5000	1 PCS	17.50	
28 REAR BUMPER REFLECTORS - LH X	198.5000	1 PC	198.50	
29 REAR BUMPER REFLECTORS - RH X	148.5000	1 PC	148.50	
30 REAR BUMPER LOWER GARNISH - BLACK	190.0000	1 PCS	190.00	
31 REAR FENDER COWLING - RH X	133.0000	1 PCS	133.00	
32 REAR WHEEL OUTER WHEEL ARCH GARNISH - LH X	210.2000	1 PCS	210.20	
33 REAR WHEEL OUTER WHEEL ARCH GARNISH - RH X	210.2000	1 PCS	210.20	
34 REAR EXHAUST PIPE	726.8000	1 PC	726.80 ✓	
35 REAR EXHAUST PIPE TOP PLATE	55.0000	1 PCS	55.00 ✓	
36 REAR EXHAUST PIPE - CENTRE	599.1000	1 PC	599.10 ✓ 531.20	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S: TAN CHEE KEONG (CHEN ZHIQIANG)
 BLK 473D UPPER SERANGOON CRESCENT #15-
 SINGAPORE 538473

ATTN: FIRST CAPITAL

Your RefNo: TP 0719-5581
 Claim Type: Third Party
 Accident Date: 28/06/2019
 TP Veh Reg No: SHC 7779 E

Estimate No: EST1504990
 Date: 01 Jul 2019
 Policy No: P10077042R00
 Veh Reg No: SLF349X
 Make/Model: HONDA VEZEL 1.5Z
 HYBRID CVT ABS
 D/AIRBAG 2WD
 Chassis No: RU31208154
 Engine No: LEB5908163
 Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price SS	Amount SS
37 REAR EXHAUST PIPE MOUNTING <i>X</i>	17.1000	2 PC	17.10	
38 REAR EXHAUST PIPE CHROME <i>X</i>	135.6000	1 PC	135.60	
39 REAR FLOOR PANEL UNDER LOWER GARNISH <i>Be</i>	0.0000	1 PC	0.0000	157.80 ✓
40 TAILLAMP ASSY - LH <i>X</i>	474.6000	1 PCS	474.60	
41 TAILLAMP ASSY - RH <i>X</i>	474.6000	1 PCS	474.60	
42 TAILLAMP LOWER RETAINER - LH <i>X</i>	0.0000	1 PCS	0.0000	
43 TAILLAMP LOWER RETAINER - RH <i>X</i>	0.0000	1 PCS	0.0000	
44 HEADLAMP ASSY - LH <i>OLA</i>	1,820.200	1 PCS	1,820.20	
45 HEADLAMP LOWER RETAINER - LH <i>X</i>	35.0000	1 PCS	35.00	
46 FRONT FENDER OUTER WHEEL ARCH GARNISH - LH <i>X</i>	201.5000	1 PCS	201.50	
47 HEADLAMP ASSY - RH <i>X</i>	1,820.200	1 PCS	1,820.20	
48 HEADLAMP LOWER RETAINER - LH <i>X</i>	35.0000	1 PCS	35.00	
49 FRONT FENDER OUTER WHEEL ARCH GARNISH - LH <i>X</i>	201.5000	1 PCS	201.50	
50 GRILLE TOP GARNISH CLIP <i>Mc</i>	3.9000	12 PCS	46.80	
51 AIR DUCT CLIPS <i>Mc</i>	4.2000	2 PCS	8.40	
52 GRILLE LOGO CLIP <i>Mc</i>	5.6000	2 PCS	11.20	
53 GRILLE BASE <i>Mc</i>	380.6000	1 PCS	380.60	
54 GRILLE OUTER GARNISH <i>CRA</i>	385.0000	1 PCS	385.00	
55 GRILLE LOWER CHROME <i>CRA</i>	95.8000	1 PCS	95.80	
56 GRILLE LOGO <i>CRA</i>	27.4000	1 PCS	27.40	
57 FRONT BUMPER <i>Be</i>	801.7000	1 PC	801.70	
58 FRONT BUMPER CLIPS <i>Mc</i>	3.9000	10 PC	39.00	
59 FRONT BUMPER SIDE HOLDER - LH <i>Gre</i>	17.0000	1 PC	17.00	
60 FRONT BUMPER SIDE HOLDER - RH	17.0000	1 PC	17.00	
61 FRONT BUMPER REINFORCEMENT <i>X</i>	360.8000	1 PC	360.80	
62 FRONT BUMPER LOWER SPOILER, BLACK <i>?</i>	450.3000	1 PC	450.30	
63 FRONT BUMPER FOG LAMP - LH <i>X</i>	510.2000	1 PC	510.20	
64 FRONT BUMPER FOG LAMP COVER - LH <i>X</i>	82.6000	1 PCS	82.60	
65 FRONT BUMPER FOG LAMP - RH <i>X</i>	510.2000	1 PCS	510.20	
66 FRONT BUMPER FOG LAMP COVER - RH <i>X</i>	82.6000	1 PC	82.60	
67 SUPPORT PANEL TOP GARNISH CLIP <i>X</i>	3.9000	8 PCS	31.20	
68 SUPPORT PANEL TOP GARNISH <i>X</i>	85.0000	1 PCS	85.00	
69 SUPPORT PANEL <i>X</i>	576.2000	1 PCS	576.20	
70 CONDENSER <i>X</i>	568.7000	1 PC	568.70	
			18,645.30	9753.80
	Less 20%		3,729.06	14,916.24
				7803.04

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : TAN CHEE KEONG (CHEN ZHIQIANG)
BLK 473D UPPER SERANGOON CRESCENT #15-
SINGAPORE 538473

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
Claim Type: Third Party
Accident Date: 28/06/2019
TP Veh Reg No: SHC 7779 E

Estimate No: EST1504990
Date: 01 Jul 2019
Policy No: P10077042R00
Veh Reg No: SLF349X
Make/Model: HONDA VEZEL 1.5Z
HYBRID CVT ABS
D/AIRBAG 2WD
Chassis No: RU31208154
Engine No: LEB5908163
Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price S\$	Amount S\$
Special Net				
71 REAR BUMPER SENSOR / DM	220.0000	1 SET	220.00✓	
72 GRILLE RS LOGO / RBC	65.0000	1 PCS	65.00✓	
73 FRONT NUMBER PLATE WITH CASING / CRA	35.0000	1 SET	35.00✓	
74 REAR NUMBER PLATE WITH CASING X	35.0000	1 PC	35.00	
75 REAR BOOT CAMERA X	450.0000	1 PC	150.00	
76 SEALANT / RBC	20.0000	2 PC	40.00✓	
77 SPONGE TAPE / RBC	20.0000	1 PCS	20.00✓	
			865.00	865.00 380
Labour				
78 TO KNOCK OUT DENTS. REAR BOTH CHASSIS. CUT/WELD REAR PANEL. SUPPORT PANEL. REMOVE. REPLACE ACCIDENT PARTS	2,200.000	1 JOB	2,200.00 1900 (4000?)	
79 TO RESPRAY PAINT ON ACCIDENT PORTIONS	2,000.000	1 JOB	2,000.00 1200 1800	
80 TO CHECK WIRING	50.0000	1 JOB	50.00 30✓	
81 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00 40✓	
82 TO REMOVE. REFIX REAR GARNISH.CUSHION.CARPET & RELATED PARTS	200.0000	1 JOB	200.00 60✓	
83 TO TUFF-KOTE	120.0000	1 JOB	120.00 60✓	
84 TO REMOVE. REPLACE REAR EXHAUST PIPE	100.0000	1 JOB	100.00 60✓	
85 TO REMOVE. REPLACE CENTRE EXHAUST PIPE	100.0000	1 JOB	100.00 7✓	
86 TO REMOVE. REPLACE REAR GLASS	120.0000	1 JOB	120.00 100✓	
87 TO REMOVE. REFIT REAR BOTH UNDERCARRIAGE	400.0000	1 JOB	400.00 X	
88 TO 4 WHEEL ALIGNMENT	100.0000	1 JOB	100.00 X	
89 TO REMOVE. REPLACE CONDENSER AND REFILL GAS	100.0000	1 JOB	100.00 ?	
			5,590.00	5,590.00
				4150

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : TAN CHEE KEONG (CHEN ZHIQIANG)
 BLK 473D UPPER SERANGOON CRESCENT #15-
 SINGAPORE 538473

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
 Claim Type: Third Party
 Accident Date: 28/06/2019
 TP Veh Reg No: SHC 7779 E

Estimate No: EST1504990
 Date: 13 Jul 2019
 Policy No: P10077042R00
 Veh Reg No: SLF349X
 Make/Model: HONDA VEZEL 1.5Z
 HYBRID CVT ABS
 D/AIRBAG 2WD
 Chassis No: RU31208154
 Engine No: LEB5908163
 Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price S\$	Amount S\$
Supplementary Parts to Repair				
List Price				
1 RHR FENDER INNER TRIM	320.8000	1 PCS	320.80	✓
2 GRILLE TOP BRACKET	45.8000	1 PCS	45.80	✓
3 BONNET	892.3000	1 PCS	892.30	✓
4 rear bumper bumper	85.40	✓	1,258.90	1344.70
	Less 20%		251.78	1,007.12
Special Net				
5 REAR BOOT INNER SOUND ROOF INSULATOR & LABOUR CHARGE	500.0000	1 SER	500.00	350
			500.00	500.00
Total				S\$ 1,507.12
GST Amount				S\$ 105.50
Total Amount Payable				S\$ 1,612.62

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SUPP 1575.44

PARTS 7803.04

SN 380.00

LAB. 4150.00

13908.48



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011808/Gvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7779E	Veh. Inspected	SLF 349X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004289MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	03/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU31208154	Colour	WHITE	
Odometer	33458	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 ZR19	FALKEN	6 mm	
L/H Front Tyre	245/40 ZR19	FALKEN	6 mm	
R/H Rear Tyre	245/40 ZR19	FALKEN	6 mm	
L/H Rear Tyre	245/40 ZR19	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/06/2019	Inspection Date	03/07/2019	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 349X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	BUCKLED	1,100.90	1,100.90
1	REAR BOOT HINGE-LH	NOT NECESSARY	50.80	-
1	REAR BOOT HINGE-RH	NOT NECESSARY	50.80	-
1	REAR BOOT H LOGO	NOT NECESSARY	24.70	-
1	REAR BOOT VEZEL WORDING	NECESSARY	43.00	43.00
1	REAR BOOT RS WORDING	NECESSARY	52.50	52.50
1	REAR BOOT HYBRID	NECESSARY	75.50	75.50
1	REAR BOOT NUMBER PLATE LAMP-LH	NOT NECESSARY	38.50	-
1	REAR BOOT NUMBER PLATE LAMP-RH	NOT NECESSARY	38.50	-
1	REAR BOOT LOCK SENSOR (NPA)	NOT NECESSARY	-	-
1	REAR BOOT REFLECTOR-LH	NOT NECESSARY	413.50	-
1	REAR BOOT REFLECTOR-RH	NOT NECESSARY	413.50	-
1	REAR BOOT RUBBER	CUT	96.80	96.80
1	REAR BOOT TOP LOCK	BENT	151.80	151.80
1	REAR BOOT BOTTOM LOCK	NOT NECESSARY	32.20	-
1	REAR PANEL	BUCKLED	411.90	411.90
1	REAR PANEL TOP GARNISH	NOT NECESSARY	98.20	-
1	REAR FLOOR PANEL MEMBER PN-21	BENT	95.00	95.00
1	REAR SPARE TYRE FLOOR PANEL	BUCKLED	875.60	875.60
1	REAR SPARE TYRE BOARD	NOT NECESSARY	430.00	-
1	SET REAR BOOT WINDSCREEN MOULDING	NECESSARY	158.30	158.30
1	REAR BUMPER-L	NOT NECESSARY	195.00	-
1	REAR BUMPER	DEFORMED	850.00	850.00
1	REAR BUMPER-R	NOT NECESSARY	195.00	-
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	REAR BUMPER SIDE HOLDER-LH	NOT NECESSARY	17.50	-
1	REAR BUMPER SIDE HOLDER-RH	NOT NECESSARY	17.50	-
1	REAR BUMPER REFLECTORS-LH	NOT NECESSARY	198.50	-
1	REAR BUMPER REFLECTORS-RH	NOT NECESSARY	148.50	-
1	REAR BUMPER LOWER GARNISH-BLACK	NOT NECESSARY	190.00	-
1	REAR FENDER COWLING-RH	NOT NECESSARY	133.00	-

Report Ref No. CS/FCI19011808/Gvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WHEEL OUTER WHEEL ARCH GARNISH-LH	NOT NECESSARY	210.20	-
1	REAR WHEEL OUTER WHEEL ARCH GARNISH-RH	NOT NECESSARY	210.20	-
1	REAR EXHAUST PIPE	BENT	726.80	726.80
1	REAR EXHAUST PIPE TOP PLATE	BUCKLED	55.00	55.00
1	REAR EXHAUST PIPE-CENTRE	BENT	599.10	599.10
2	REAR EXHAUST PIPE MOUNTING	BENT	17.10	17.10
1	REAR EXHAUST PIPE CHROME	BENT	135.60	135.60
1	REAR FLOOR PANEL UNDER LOWER GARNISH	DEFORMED	157.80	157.80
1	TAILLAMP ASSY-LH	NOT NECESSARY	474.60	-
1	TAILLAMP ASSY-RH	NOT NECESSARY	474.60	-
1	TAILLAMP LOWER RETAINER-LH (NPA)	NOT NECESSARY	-	-
1	TAILLAMP LOWER RETAINER-RH (NPA)	NOT NECESSARY	-	-
1	HEADLAMP ASSY-LH	CRACKED	1,820.20	1,820.20
1	HEADLAMP LOWER RETAINER-LH	CRACKED	35.00	35.00
1	FRONT FENDER OUTER WHEEL ARCH GARNISH-LH	NOT NECESSARY	201.50	-
1	HEADLAMP ASSY-RH	NOT NECESSARY	1,820.20	-
1	HEADLAMP LOWER RETAINER-LH	CRACKED	35.00	35.00
1	FRONT FENDER OUTER WHEEL ARCH GARNISH-LH	NOT NECESSARY	201.50	-
12	GRILLE TOP GARNISH CLIP @\$3.90	NECESSARY	46.80	46.80
2	AIR DUCT CLIPS @\$4.20	NECESSARY	8.40	8.40
2	GRILLE LOGO CLIP @\$5.60	NECESSARY	11.20	11.20
1	GRILLE BASE	CRACKED	380.60	380.60
1	GRILLE OUTER GARNISH	CRACKED	385.00	385.00
1	GRILLE LOWER CHROME	CRACKED	95.80	95.80
1	GRILLE LOGO	CRACKED	27.40	27.40
1	FRONT BUMPER	DEFORMED	801.70	801.70
10	FRONT BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	FRONT BUMPER SIDE HOLDER-LH	DEFORMED	17.00	17.00
1	FRONT BUMPER SIDE HOLDER-RH	DEFORMED	17.00	17.00
1	FRONT BUMPER REINFORCEMENT	BENT	360.80	360.80
1	FRONT BUMPER LOWER SPOILER.BLACK	NOT NECESSARY	450.30	-
1	FRONT BUMPER FOG LAMP-LH	NOT NECESSARY	510.20	-
1	FRONT BUMPER FOG LAMP COVER-LH	NOT NECESSARY	82.60	-

Report Ref No. CS/FCI19011808/Gvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER FOG LAMP-RH	NOT NECESSARY	510.20	-
1	FRONT BUMPER FOG LAMP COVER-RH	NOT NECESSARY	82.60	-
8	SUPPORT PANEL TOP GARNISH CLIP @\$3.90	NECESSARY	31.20	31.20
1	SUPPORT PANEL TOP GARNISH	NOT NECESSARY	85.00	-
1	SUPPORT PANEL	NOT NECESSARY	576.20	-
1	CONDENSER	NOT NECESSARY	568.70	-
1	RHR FENDER INNER TRIM (ADDITIONAL)	CRACKED	320.80	320.80
1	GRILLE TOP BRACKET (ADDITIONAL)	CRACKED	45.80	45.80
1	BONNET (ADDITIONAL)	CRACKED	892.30	892.30
1	REAR BUMPER BUZZER (ADDITIONAL)	DAMAGED	85.40	85.40
	LESS 20% DISCOUNT		-4,048.48	-2,219.62
			16,193.92	8,878.48
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER SENSOR (SN)	DAMAGED	220.00	220.00
1	GRILLE RS LOGO (SN)	NECESSARY	65.00	65.00
1	SET FRONT NUMBER PLATE WITH CASING (SN)	CRACKED	35.00	35.00
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	35.00	-
1	REAR BOOT CAMERA (SN)	NOT NECESSARY	450.00	-
2	SEALANT @\$20.00 (SN)	NECESSARY	40.00	40.00
1	SPONGE TAPE (SN)	NECESSARY	20.00	20.00
			865.00	380.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS,REAR BOTH CHASSIS.CUT/WELD REAR PANEL,SUPPORT PANEL,REMOVE,REPLACE ACCIDENT PARTS.		2,200.00	1,900.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		2,000.00	1,800.00
	TO CHECK WIRING.		50.00	30.00
	TO TRANSFER REAR BUMPER SENSOR.		100.00	40.00
	TO REMOVE,REFIX REAR GARNISH,CUSHION,CARPET & REPLATED PARTS.		200.00	60.00
	TO TUFF-KOTE.		120.00	60.00
	TO REMOVE,REPLACE REAR EXHAUST PIPE.		100.00	60.00
	TO REMOVE,REPLACE CENTRE EXHAUST PIPE.		100.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE REAR GLASS.		120.00	100.00
	TO REMOVE, REFIT REAR BOTH UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	TO 4 WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REMOVE, REPLACE CONDENSER AND REFILL GAS.	NOT NECESSARY	100.00	-
	REAR BOOT INNER SOUND ROOF INSULATOR & LABOUR CHARGE (ADDITIONAL).		500.00	350.00
			6,090.00	4,500.00
	GRAND TOTAL		23,148.92	13,758.48
RECOMMENDED COST OF REPAIRS				13,758.48

Report Ref No. CS/FCI19011808/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.