



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R **08/07/2019**

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAIG.

Vic

Accident date: 02/07/2019

Estimated repair cost for vehicle no: SLP5332H HONDA VEZEL HYBRID 1.5 X A '17

CHASSIS: RU31245542

| S/n | Qty | Items | U/price | Amount |
|-----|-----|--|----------|-----------------------------|
| 1 | 1 | Rear Boot Lid <i>Dented.</i> | | \$ 1100 ✓ |
| 2 | 2 | Rear Boot Lid Hinge <i>? NE</i> | \$68.10 | \$136.20 ✗ |
| 3 | 2 | Rear Boot Lid Shock Absorber <i>NE</i> | \$180.90 | \$361.80 ✗ |
| 4 | 1 | Rear Boot Lid Emblem Logo <i>NE NE</i> | | \$45.10 ✗ |
| 5 | 1 | Rear Boot Lid Vezel Logo <i>? NE</i> | | \$56.30 ✓ |
| 6 | 1 | Rear Boot Lid Hybrid Logo <i>NE</i> | | \$55.00 ✓ |
| 7 | 2 | Rear Boot Lid Side Reflector <i>NE NE</i> | \$284.60 | \$569.20 ✗ |
| 8 | 1 | Rear Boot Lid Number Plate <i>NE NE</i> | | \$50.00 ✗ |
| 9 | 1 | Rear Boot Lid Inner Lock <i>Damaged</i> | | \$185.60 ✓ |
| 10 | 1 | Rear Boot Lid Inner Rubber <i>cut.</i> | | \$135.25 ✗ |
| 11 | 1 | Rear Boot Lid Inner Trim Board <i>NE NE</i> | | \$333.75 ✗ |
| 12 | 1 | Rear Boot Lid Windscreen Seal <i>NE</i> | | \$95.00 ✓ |
| 13 | 2 | Rear Boot Lid Windscreen Moulding <i>NE</i> | \$151.70 | \$303.40 ✓ |
| 14 | 1 | Rear Boot Lid Camera (Special Nett) <i>NE NE</i> | | \$680.00 ✗ |
| 15 | 2 | Rear Tail Lamp <i>NE NE</i> | \$460.50 | \$921.00 ✗ |
| 16 | 1 | Rear Bumper <i>Dented.</i> | | \$863.70 ✓ |
| 17 | 8 | Rear Bumper Clip <i>NE</i> | \$6.50 | \$52.00 30 |
| 18 | 2 | Rear Bumper Side Retainer <i>NE</i> | \$29.20 | \$58.40 ✓ |
| 19 | 2 | Rear Bumper Side Cover <i>NE</i> | \$198.70 | \$397.40 ✗ |
| 20 | 2 | Rear Bumper Side Reflector <i>NE</i> | \$148.40 | \$296.80 ✗ |
| 21 | 1 | Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i> | | \$380.00 200(sw) |
| 22 | 1 | Rear End Panel <i>Repair</i> | | \$595.60 ✗ |
| 23 | 1 | Rear End Panel Top Garnish <i>Dented</i> | | \$132.30 ✓ |
| 24 | 1 | Rear End Panel Lock Sensor <i>? NE</i> | | \$95.80 ✗ |
| 25 | 1 | Rear End Panel Buzz Switch <i>NE NE</i> | | \$85.50 ✗ |
| 26 | 2 | Rear Fender Inner Trim Board <i>NE</i> | \$325.25 | \$650.50 ✗ |
| 27 | 1 | Rear Spare Tyre Panel <i>NE NE</i> | | \$1,230.60 ✗ |
| 28 | 1 | Rear Spare Tyre Panel Top Cover <i>NE NE</i> | | \$390.90 ✗ |

| | | | | | |
|----|---|---|---------|----------|---|
| 29 | 1 | Rear Spare Tyre Panel Top Sponge | | \$285.45 | * |
| 30 | 1 | Rear Spare Tyre Panel & End Panel Sealant | | \$450.00 | * |
| 31 | 1 | Rear Exhaust | | \$828.00 | * |
| 32 | 2 | Rear Exhaust Mounting | \$25.60 | \$51.20 | * |
| 33 | 1 | Rear Center Exhaust | | \$986.00 | * |

3014.95
2411 96

S.N: 200

Subtotal :- \$12,710.75

Labour charges

| | |
|---|---------------------------|
| To remove & refit cushion & trim board | \$380.00 80 |
| To remove & refit reverse sensor | \$100.00 50 |
| To remove & refit rear windscreen | \$120.00 ✓ |
| Gum | \$50.00 ✓ |
| To remove & refit rear & center exhaust | \$380.00 * |
| To remove & refit boot lid camera & windscreen camera | \$380.00 100 |
| To check wiring | \$100.00 30 |
| Towing fee | 1630 \$100.00 * |
| Tuff kote | \$150.00 * |
| Panel beating | \$1,200.00 600 |
| Spray painting | \$1,400.00 600 |
| Subtotal :- | <u>\$4,360.00</u> |

Total:- **\$17,070.75**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 4241 i6.

L/S 34K

04 Days

34K