

DATE: 3. Jul. 2019

VEHICLE NO : SHC8896T

MAKE : HYUNDAI

MODEL : i40

DOA: 2. Jul. 2019

CHINA

MODEL : i40		DOA: 2. Jul. 2019		
Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Fender - LH <i>X repair</i>			\$2,020.10
1	Rear Wheel Cover - LH <i>hatched</i>			\$107.10
1	Rear Wheel Rim - LH <i>X see</i>			\$325.30
1	Rear Bumper <i>X repair</i>			\$553.00
10	Rear Bumper clips <i>X in</i>		\$2.20	\$22.00
1	Rear Door - LH <i>Bulk</i>			\$1,351.10
1	Rocker Cover Garnish - LH <i>X repair</i>			\$341.40
SUB TOTAL				\$4,720.00
LESS 20%				\$944.00
DISCOUNTED TOTAL				\$3,776.00
1	Advertisement - LHR Door <i>me</i>			\$100.00
1	Advertisement - LHR Fender <i>me</i>			\$100.00
1	LHR Door APP sticker <i>me</i>			\$80.00
Labour Charge				
1	Panel Beating			\$400.00
1	Spray Painting Charge			\$750.00
1	Wiring Charge			\$600.00
1	Remove/refix Reverse Sensor			\$50.00
1	Tuff Kote			\$100.00
TOTAL LABOUR				\$1,480.00
ESTIMATE TOTAL				\$5,536.00

LKK Auto Centre is hereby notifying the Repairer that the repair work is to be carried out on a "no fault" basis.

- To the extent possible, the repairer shall use original or equivalent parts.
- To the extent possible, the repairer shall use original or equivalent labour.
- Third party liability insurance cover is required and is subject to final approval from insurance company.
- Supplies and materials used in the repair work are to be supplied by the repairer.

Acknowledged by Repairer
Signature: _____
Date: _____

Kahin Ukk
3/7/19
3 Days
45
Alfa Repair photo

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.