

DATE: 3. Jul. 2019

VEHICLE NO : SHC8896T

MAKE : HYUNDAI

MODEL : i40

DOA: 2. Jul. 2019

CHINA

MODEL : i40		DOA:	2 Jul 2019	
Qty	Parts Description/ Labour	Type	Unit Price	Amount
				\$2,020.10
1	Rear Fender – LH <i>X repair</i>			\$107.10
1	Rear Wheel Cover – LH <i>hand</i>			\$325.30
1	Rear Wheel Rim – LH <i>X see</i>			\$553.00
1	Rear Bumper <i>X repair</i>		\$2.20	\$22.00
10	Rear Bumper clips <i>X m</i>			\$1,351.10
1	Rear Door – LH <i>Bulb</i>			\$341.40
1	Rocker Cover Garnish – LH <i>X repair</i>			
SUB TOTAL				\$4,720.00
LESS 20%				\$944.00
DISCOUNTED TOTAL				\$3,776.00
1	Advertisement – LHR Door <i>me</i>			\$100.00
1	Advertisement – LHR Fender <i>me</i>			\$100.00
1	LHR Door APP sticker <i>me</i>			\$80.00
				\$280.00
Labour Charge				
1	Panel Beating			\$750.00 <i>400</i>
1	Spray Painting Charge			\$600.00 <i>600</i>
1	Wiring Charge			X \$50.00 <i>m</i>
1	Remove/refix Reverse Sensor			X \$100.00 <i>m</i>
1	Tuff Kote			\$80.00 <i>30</i>
TOTAL LABOUR				\$1,480.00
ESTIMATE TOTAL				\$5,536.00

LKK Auto Centre's policy is to notify the Repairer of the damage as follows:

- To allow the Repairer to estimate the cost of repairs.
- To provide the Repairer with a copy of the "basis" basis.
- To provide the Repairer with a copy of the "basis" basis.
- This work is done on a "basis" basis.
- No illegal or unsafe work will be performed and is subject to final approval from insurance company.

Acknowledged by Repairer
Signature:
Date:

Kahin Ullar,
3/7/19 NoL
3 Days
US
All Repair photo

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.