

INSURANCE

Taufman

AG C3/AG 1901224/T4cl3e2

ASSIGNMENT

Form Date: 3.7.2019

Continued Card

OD TP / WVS / TP RES / OD RES / LVA / RVV / MV

To Inspect Vehicle No: SKF 550S

at Workshop no: Premium Automobile

of 24 Reno Sector

Insured

Policy No

Claim No

Form Insured

License: \$01-

Other's Record

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection



Est. or Market Value: \$145K.

HDAC Accident Report: Consistent? Yes or No

CBA / PHI Score: Consistent? Yes or No

Est. Repairs: 22 days Rep: Yes or No

Emp Case: % 3 Val: Yes or No

CA / (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted

Veh No: SKF550S

Y1 Regn: 2017 Sep.

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Andy #5

cc: 1984

Colour: white

ACC: Insured / Std / NI / NA

Up/Boarding: 46387

Lift/dec: Insured / Std / NI / NA

Length

Width

WAY ZZZ FSS JA021889

Gen. Cond: Good / Fair / Poor / Burnt

Steering: border / Jammed / Leaked / Burnt or

Brake: border / Jammed / Leaked / Burnt or

Mod: RR / STD / R/R or

Tyre Size

245/40R18

R:

BS / DUR / EXNOVA / GY / S / LIZA / MG / OH / SU / PR / SUM /

AGYU / YOKO or

Front

Hour

R/Rat: 6 mm

R/Rat: 6 mm

L/Rat: 6 mm

L/Rat: 6 mm

D.O.A.

D.O.I

3/7/19 2:30pm

Survey held at

Premium Bewi

Dir. of Damages: (11) Rear / Q/S / H/S / U/C / Roof/Top or

The U/C / Chassis/frame / Body Structure: affected due to collision

Date / Time

Action / Instruction

SKF 550S - X

RECEIVED 6 MAR 2020

4/7@2:44pm- Revert via menimen

8/7@9:56am inform by Andy authorise repair.

8/7@11:07am- email to premium authorise repair excess \$0 not exceeding \$60,000.

Repair Sam \$60,000. (Red. 62966 (50.510%)

RECEIVED 2 DEC 2019

Initial Time, File Opened

☐ Prel. Report

63 Typst

☒ Final Report

Initial Time, File Returned

2

Days Of Repair: 22

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Report Format: OD

Lump Sum / L.B.E (\$ 60,000+

Survey Fee:

Transportation:

Photocopy:

Others:

TOTAL

200
11
211

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 8 July 2019 11:07 AM
To: Claims Dept; SUR
Subject: RE: OD / 1566843384SG / SKF550S

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKF 550S (Excess \$0/-). NOT EXCEEDING \$60,000/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Friday, 5 July 2019 5:41 PM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD / 1566843384SG / SKF550S

Dear Sir,

Waiting for approval, have email AIG for chaser.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Friday, 5 July 2019 5:38 PM
To: 'Claims Dept' <claims@premiumauto.com.sg>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>; SUR

View Received Message

This mail is associated with :

***SKF550S (1566843384SG)**

OD

Jun 28 2019 12:00AM

[TEO LENG TZE]

Premium Automobiles Pte Ltd - Alexandra

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/07/2019 09:56 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$60000.00) - SKF550S - Claim Handler: Gan, Hunchung

Approved:60000.00;To commence OD repairs. Please re-seek mandate after confirming check items, Check item value too high.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9703D
Vehicle Details	
Vehicle No.:	SKF550S
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CVK044088
Chassis No.:	WAUZZZF55JA021889
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,560.00
Original Registration Date:	20 Sep 2017
First Registration Date:	20 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$42,384.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Sep 2027
PARF Rebate Amount:	\$31,788.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$41,862.00
Total Rebate Amount:	\$73,650.00

The information contained herein is correct as at 04 Jul 2019

OK

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 04 Jul 2019

Preliminary Advice

Vehicle No	: SKF550S	Accident Date	: 28/06/2019
Make	: AUDI A5	Policy No.	: 1700081585
Assignment Date	: 04/07/2019	Excess	: S\$0.00
Date of Inspection	: 03/07/2019	Est. Duration of Repair	: 20.00
Inspection At	: PREMIUM AUTOCARE CENTRE (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	111,576.50
Revised Amount	:S\$	58,728.50
Check Items (Estimated)	:S\$	21,249.00
Total	:S\$	79,977.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	204,900.00
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	73,650.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	131,250.00
Margin for Repair (Pre-Accident Value)	:S\$	71,350.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note on the New car Value and Pre Accident Value.

RETAIL PRICE LIST

Effective as of 28 Jun 2019



MODEL	Power (hp)	Torque (Nm)	Combined Fuel Consumption L/100km	VES (Band)	Retail Price	VES (rebate / surcharge)	Nett Price after VES
AUDI A3 Sportback							
A3 1.0 TFSI S tronic	116	200	4.8	C1	\$124,250	\$10,000	\$134,250
S3 2.0 TFSI qu S tronic	290	380	6.6	C2	\$229,600	\$20,000	\$249,600
AUDI A3 Sedan							
A3 1.0 TFSI S tronic	116	200	4.7	C1	\$126,460	\$10,000	\$136,460
S3 2.0 TFSI qu S tronic	290	380	6.5	C2	\$231,800	\$20,000	\$251,800
AUDI A3 Cabriolet							
A3 1.4 TFSI S tronic	150	250	5.1	B	\$188,639	\$0	\$188,639
AUDI A4 Sedan							
A4 2.0 TFSI S tronic	190	320	5.2	B	\$188,016	\$0	\$188,016
A4 2.0 TFSI qu S tronic (design)	252	370	6.2	C2	\$234,760	\$20,000	\$254,760
S4 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$297,400	\$10,000	\$307,400
AUDI A4 Avant							
A4 2.0 TFSI S tronic (NAV)	190	320	5.4	B	\$199,751	\$0	\$199,751
A4 2.0 TFSI qu S tronic (design)	252	370	6.5	C2	\$244,850	\$20,000	\$264,850
S4 3.0 TFSI qu tiptronic	354	500	8.0	C1	\$306,900	\$10,000	\$316,900
RS 4 2.9 TFSI qu tiptronic	450	600	8.9	C2	\$375,360	\$20,000	\$395,360
AUDI A5 Sportback							
A5 2.0 TFSI S tronic (design)	190	320	5.6	B	\$204,900	\$0	\$204,900
A5 2.0 TFSI qu S tronic (sport)	252	370	6.4	C2	\$251,251	\$20,000	\$271,251
S5 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$304,800	\$10,000	\$314,800
RS 5 2.9 TFSI qu tiptronic	450	600	8.9	C2	\$367,000	\$20,000	\$387,000
AUDI A5 Coupe							
A5 2.0 TFSI S tronic (design)	190	320	5.5	B	\$209,600	\$0	\$209,600
A5 2.0 TFSI qu S tronic (sport)	252	370	6.4	C2	\$256,551	\$20,000	\$276,551
S5 3.0 TFSI qu tiptronic	354	500	7.8	C1	\$312,200	\$10,000	\$322,200
RS 5 2.9 TFSI qu tiptronic	450	600	8.8	C2	\$375,700	\$20,000	\$395,700
AUDI A5 Cabriolet							
A5 2.0 TFSI S tronic (design)	190	320	5.9	B	\$249,321	\$0	\$249,321
A5 2.0 TFSI qu S tronic (sport)	252	370	6.7	B	\$289,500	\$0	\$289,500
S5 3.0 TFSI qu tiptronic	354	500	8.1	C1	\$350,900	\$10,000	\$360,900
AUDI A6 Sedan							
A6 2.0 TFSI S tronic (design)	245	370	7.0	B	\$242,500	\$0	\$242,500
A6 3.0 TFSI qu S tronic	340	500	7.2	C1	\$340,800	\$10,000	\$350,800
AUDI A7 Sportback							
A7 3.0 TFSI qu S tronic	340	500	7.3	C1	\$370,500	\$10,000	\$380,500
AUDI A8							
A8 3.0 TFSI qu tip	340	500	8.2	C2	\$410,999	\$20,000	\$430,999
A8 L 3.0 TFSI qu tip	340	500	8.2	C2	\$427,599	\$20,000	\$447,599
A8 L 4.0 TFSI qu tip	460	660	10.1	C2	\$552,599	\$20,000	\$572,599
AUDI Q2							
Q2 1.0 TFSI S tronic	116	200	5.2	C1	\$130,776	\$10,000	\$140,776
AUDI Q5							
Q5 2.0 TFSI qu S tronic (sport)	252	370	7.4	C1	\$231,200	\$10,000	\$241,200
SQ5 3.0 TFSI qu tiptronic	354	500	8.7	C2	\$299,600	\$20,000	\$319,600
AUDI Q7							
Q7 2.0 TFSI qu tip	252	370	7.4	C1	\$297,800	\$10,000	\$307,800
AUDI Q8							
Q8 3.0 TFSI qu tip	340	500	8.9	C2	\$359,300	\$20,000	\$379,300

Terms and Conditions :

- ✓ Retail price is subject to in-house Financier and Insurance. Price includes 12-months road tax, registration fee and GST but without insurance.
 - ✓ CDE is non guaranteed and subject to B-bids, failing which new terms and conditions shall apply.
 - ✓ Booking deposit for all models is \$520,000/-. Minimum booking deposit for indent order is \$525,000/-. with the exception of RS/RB is \$75,000/-.
 - ✓ All deposits are non-refundable upon cancellation.
 - ✓ In-House utilization of PARF/CDE Rebates for new car registration is within Premium Automobile's discretion.
- All prices and promotions are subject to change without any prior notice.

Premium Automobiles
 Audi Centre Singapore
 281 Alexandra Road Singapore 159938



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Home » Used Cars » Direct Owners » Audi A5 Sportback 2.0A TFSI S-tronic Design

Audi A5 Sportback 2.0A TFSI S-tronic Design

Overview Financial Insurance Accessories Similar Research Photos Map

DIRECT OWNER

Price	\$145,000		
Depreciation	\$15,180 /yr View models with similar degree	Reg Date	29-Aug-2017 (8yrs 1mth 24days COE left)
Mileage	39,000 km (21.1k /yr)	Manufactured	2017
Road Tax	\$1,194 /yr	Transmission	Auto
Dereg Value	\$73,384 as of today (change)	OMV	\$39,560
COE	\$51,000	ARF	\$42,384
Engine Cap	1,984 cc	Power	140.0 kW (187 bhp)
Curb Weight	1,535 kg	No. of Owners	1
Type of Vehicle	Luxury Sedan		



Enlarged Viewing Area

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Contact Person(s) Eugene

Contact No. 94776640

Enquiry [Contact Seller](#)

ESSENTIAL TRANSACTION FORMS

- Indemnity form
- Sales agreement
- Receipt
- Hand-over form
- Ownership Transfer



GET HELP WITH
PAPERWORK

SGCARMART
CONNECT

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Features

2.0 TFSI Engine, 7 Speed S-Tronic Transmission, Paddle Shifters, Auto Brake Hold, Auto Tail Gate. View specs of the Audi A5 Coupe (2017)

Accessories

Front/Rear In Car Dash Camera, Virtual Cockpit. Memory Seat, Power Tailgate. Audi Multi Media Interface With Navi, Reverse Sensors/Camera.

Description

Premium Glass Coating Applied. Weekly Hand-washed And Wax. Single Owner, Reluctant Sale Due To Family Circumstances. Sheltered Basement Parking. Optional Bidded Number Plate. 5 Years Warranty By Agent. 3 Years Free Servicing By Agent. Accident Free. Fully Serviced At Agent. New Condition, Electric/Memory Seats, Reverse Camera, All Around Parking Sensors, Keyless Entry/Start, Knockdown Rear Seat.

Category

PARF Car, Direct Owner Sale

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation
**aid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Compare

» | Last Updated on: 02-Jul-2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/06/2019 12:24
Date Of Accident	28/06/2019 21:45
Exact Location Of Accident	CTE (BRADDEL ROAD) TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF550S
Insured/Policyholder	
Name Of Registered Owner	TEO LENG TZE
NRIC No	S7119703D
Email Address	DNLTEO550@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91163740
Alternative Phone No	OTHERS-91163740

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SPORTBACK 2.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700081585-01
Cover Note Number	

Driver

Name of Driver	TEO LENG TZE
NRIC No	S7119703D
Date Of Birth	14/06/1971
Occupation	INDOOR
Date Of Driving Pass	18/04/1995
Driving Experience	24 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91163740
Fax Number	
Contact Number	OTHERS-91163740
EMail Address	DNLTEO550@YAHOO.COM.SG

Address	BLK 1 ROSEWOOD DRIVE #04-02
Postcode	737934
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TANG GEOK PING GENDER: : FEMALE
Passenger 2	NAME: : ASHLEY TEO JIA YEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT AND ATTACH VIDEO/PIC FOOTAGE LEADING TO THE CHAIN COLLISION. THE OWNER B HIGHLIGHTED THAT AFTER THE ACCIDENT, A GROUP OF MEN APPROACHED FROM NOWHERE TO OFFER ASSISTANCE BY TELLING US TO SEND OVER VEHICLES TO THEIR WORKSHOP TO REPAIR. HOWEVER, WE DIDNT ACCEDE TO THEIR OFFER AS THEY DO NOT LOOK TRUSWORTHY. SUPRISINGLY, ONE OF THE MAN HOPED INTO THE FIRST VEHICLE AND DROVE OFF THE VEHICLE INSTEAD OF THE DRIVER, MR LIONEL HENG ZHEN RON (S8500747E) AND THIS WAS WITNESSED BY MR M/E. FURTHERMORE, THERE WAS A VEHICLE PARKED AT THE SIDE OF CTE WHERE THE ACCIDENT OCCURRED AND ACCORDINGLY TO MR LEE, THE GROUP OF MEN SEEM TO COME FROM THE VEHICLE. IN SUM, IT SEEM TO BE A SET-UP BY SOME PEOPLE CAUSING A CHAIN COLLISION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ2832U
Vehicle Make/Model/Colour	TOYOTA/WISH 1.8/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD ALFIS BIN RASHID
NRIC/Passport Number	S8430951F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJW7888U
Vehicle Make/Model/Colour	MERCEDES BENZ/GLC 250/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKB2042A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIONEL HENG ZHEN RON
NRIC/Passport Number	S8500747E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TEO LENG TZE
Approximate Age	48
Injuries Sustain	
Injured person in which vehicle?	SKF550S
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 1 ROSEWOOD DRIVE #04-02
Postcode	737934

DETAILS OF INJURED PERSON 2

Name	ASHLEY TEO JIA YEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKF550S
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 848 WOODLANDS ST 82 #03-189
Postcode	730848

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Policyholder's Signature
Name: Siti Nur Hafizah
NRIC/FIN No.: SS110762

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report and attach video/pic footage leading to the chain collision.

The owner B highlighted that after the accident, a group of men approached from nowhere to offer assistance by taking us to send our vehicle to their workshop to repair. However, we didn't accede to their offer as they do not look trustworthy. Surprisingly, one of them hopped into the first vehicle and drove off the vehicle instead of the driver Mr Lionel Hey Zhen Pan (S8500747E) and this was witnessed by Mr wife. Furthermore, there was a vehicle parked at the side of the road where the accident occurred and according to Mr Lee, the group of men seem to come from the vehicle. In short, it seems to be a setup by some people causing a chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 28/6/19 1130

Driver's Signature
(If driver is not the policyholder)
Date & Time: 28/6/19 1130

Reporting Centre's Signature
Name: Sh Mui Siu
NRIC/PIN No.: S891962

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190629/2042

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190629/2042

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/06/2019 10:31		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TEO LENG TZE			Address: 1 ROSEWOOD DRIVE 04 ROSEWOOD SINGAPORE 737934		
ID Type / ID No.: NRIC NO / S7119703D			Contact No.: Home/Office: Mobile: 91163740		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 14/06/1971	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: SENIOR MILITARY EXPERT			Driving Licence Information: Class: 2A,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 28/06/2019 21:45	Type of Location: Straight Road
Location: BRADDELL ROAD CENTRAL EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJQ2832U	Car	TOYOTA	WISH 1.8 AUTO	Black		0
SJW7888U	Car	MERCEDES BENZ	GLC250 4MATIC COUPE AUTO	Black		0
SKB2042A	Car	KIA	CERATO FORTE 1.6 SX 6AT ABS D/AB 2WD 4DR	White		0

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190629/2042

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

Report No. T/20190629/2042

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKF550S	Car	AUDI	A5 SB 2.0 TFSI S TRONIC (DESIGN)	White	Seriously Damaged	2

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKF550S	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700081585-01	20/09/2018	19/09/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEO LENG TZE		ID No. S7119703D
Related Vehicle	SKF550S (Car)		Contact No. 91163740
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date Class: 2A,3 Date of Expiry: NIL
Date Treatment	28/06/2019		Date Discharge 29/06/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

ON THE MENTIONED DATE, TIME AND LOCATION,

A SECOND CAR BRAKE, AND I TRIED TO SLOW DOWN BUT THE SECOND CAR CAME TO A FULL HALT AND I WAS NOT ABLE TO AVOID THE COLLISION. A FOURTH VEHICLE FOLLOWED SUIT AND HIT INTO MY CAR.

THATS ALL

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190629/2042

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190629/2042

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
NURBADIY ZULFIKAR BIN SHAWAL

Signature Of Informant:

[Handwritten Signature]

Signature Of Interpreter:
Not applicable

Date/Time:
29/06/2019 10:31

Officer In Charge Of Case:
TP / GIT /
SI THABAGESH JEYATHESH
Contact No.: 65476232

Classification Of Case:

Authentication Stamp
NP168



**SINGAPORE
POLICE FORCE**

Signature: *[Handwritten Signature]*

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0810/2019/TG
Date : 2-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Teo Leng Tze
Address : Blk 1 Rosewood Drive
#04-02
Singapore 737934
Telephone : HP +65 91163740
Type of Claim : Own Damage Claims
Policy No. : 1700081585-01
Vehicle No : **SKF 550 S**
Model Code : Audi A5 Sportback 2.0 TFSI S Tronic
Model / Year : Sep-17
Engine No : CVK 04088
Chassis No : WAUZZZF55JA021889
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Jun-19
Place of Accident : CTE (Braddel Road) Towards Woodlands

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKF 550 S

S/N	Nature of Jobs		Estimated Charges	
1	To tow and recover vehicle from scene of accident.	s/n	N.A	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	s/n	\$ 480.00	✓
3	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and gas.	s/n	\$ 1,400.00	✓
4	To remove center console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining and both curtain air bags.	s/n	\$ 3,600.00	✓
5	To remove and transfer both front door's multi lock system and power window devices. Inspect for damages.	s/n	\$ 560.00	✗
6	To renew front windscreen.	s/n	\$ 480.00	✓
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 6,520.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKF 550 S

S/N	Nature of Jobs	Estimated Charges
7	To dismantle and renew front bumper, bonnet, both front fenders, both headlights and both front doors. Align both front chasis frames to specification of origin. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	8 75 days \$ 10,400.00 3750 4000 ✓
8	To respray front bumper, both front fenders, bonnet, both upper A-pillars, bonnet hinges, engine compartment and both and both front doors. To carry out joint sealant work and stone chip treatment.	RM ✓ LM X \$ 8,900.00 3075 3750
9	To carry out wheel alignment.	s/n \$ 240.00 X ✓
10	To carry out diagnostic check.	s/n \$ 384.00 ✓ ✓
TOTAL LABOUR CHARGES		: <u>\$ 26,444.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,073.00	de / 1658.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	X
3	FRONT BUMPER GRILLE - CENTER	\$ 178.00	? X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	? X
5	FRONT BUMPER SECURING STRIP	\$ 64.00	ne / 50.88
6	FRONT BUMPER SPOILER	\$ 489.00	X
7	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	de / 44.10
8	RADIATOR GRILLE	\$ 2,131.00	ena / 1704.80
9	RADIATOR SUPPORT - LH / RH	\$ 95.00	de / 75.52
10	RADIATOR GRILLE - UPPER	\$ 174.00	ena / 138.80
11	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 431.00	ent / 344.40
12	FRONT BUMPER CARRIER	\$ 733.00	bt / 586
13	FRONT BUMPER BRACKET - LH / RH	\$ 390.00	195 1.2 LH-X RH de / 156
14	HEXAGON NUT	\$ 2.00	ne / X
15	FRONT BUMPER GUIDE SECTION - RH	\$ 33.00	de / 26.08
16	FOAM FILLER PIECE - RH	\$ 16.00	mis / 12.72
17	FRONT BUMPER TOP COVER	\$ 116.00	de / 92.40
18	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	ena / 90.40
19	CAUTION STICKER	\$ 13.00	ne / 9.76
20	AC STICKER	\$ 7.00	ne / 5.12
SUB TOTAL SPARE PARTS		\$ 7,689.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

			Damage Parts & Prices	
S/N	Parts Description		S/NETT	REMARKS
21	FRONT BUMPER LOCK CARRIER - LOWER		\$ 125.00	? 100 de ✓
22	FRONT BUMPER SUPPORT - LH / RH	2	\$ 51.00	? 40.64 de ✓
23	FRONT FENDER - LH / RH	77440 968 1/2	\$ 1,936.00	LH X, RH bt ✓
24	FRONT FENDER CLOSING ELEMENT - LH / RH	53.76 1/2	\$ 135.00	LH X, RH - Pan ✓
25	FRONT FENDER ATTACHMENT PARTS	2	\$ 95.00	LH X, RH - Pan ✓
26	FRONT FENDER BRACKER - LH / RH	25.20 1/2	\$ 63.00	LH X, RH - Pan ✓
27	POP RIVET	24.00 10	\$ 30.00	24 ✓
28	FRONT FENDER SUPPORT - LH / RH	85.60 1/2	\$ 214.00	LH X, RH - Pan ✓
29	FRONT FENDER BRACKET - CENTER LH / RH	35.60 1/2	\$ 89.00	LH X, RH - Pan ✓
30	FRONT WHEEL HOUSING LINER - RH	204.80	\$ 256.00	X de ✓
31	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS		\$ 82.00	X
32	FRONT WHEEL SPOILER - RH		\$ 33.00	X
33	STONE CHIP GUARD - LH / RH		\$ 92.00	X
34	BRACKET FOR TRIM - RH		\$ 22.00	?
35	FRONT FENDER TOP COVER - LONG LH - RH	2	\$ 64.00	?
36	FRONT FENDER TOP COVER - SHORT LH / RH	2	\$ 28.00	? 11.04 de ✓
37	BONNET		\$ 2,602.00	bt ✓ 2081.60
38	RETAINING CLIP FOR BONNET	3	\$ 3.00	de ✓ 2.40
39	CAP NUT	6	\$ 8.00	de ✓ 6.24
40	BONNET ATTACHMENT PARTS		\$ 111.00	de ✓ X nn.
SUB TOTAL SPARE PARTS			\$ 6,039.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
41	BONNET LID HINGE - LH / RH	2 \$ 762.00	? 304.30 bt ✓
42	BONNET IMPACT PROTECTION - CENTER	\$ 25.00	de 19.76
43	BONNET IMPACT PROTECTION - LH / RH	2 \$ 50.00	de 39.66
44	SEAL FOR WATER BOX	\$ 53.00	? X un
45	BONNET ISULATION COVER	\$ 311.00	de 248.30
46	FENDER LEDGE COVER - RH	\$ 66.00	X un
47	GAS STRUT	2 \$ 217.00	X un
48	BONNET LOCK HOOK - LH / RH	45-50 21 \$ 91.00	LH X un, RH bt ✓ 20.45
49	BONNET LID LOCK	2 \$ 391.00	? 312.30 bt ✓
50	FLAT CONNECTOR HOUSING	\$ 12.00	X un
51	BRACKET FOR CONNECTOR HOUSING	\$ 9.00	X un
52	BOWDEN CABLE - CENTER	2 \$ 105.00	X 83.36 dig ✓
53	RETAINING CLIP	2 \$ 3.00	X
54	BONNET RELEASE CABLE CAP	\$ 9.00	X
55	RELEASE LEVER	\$ 12.00	? X
56	LID LOCK CABLE	\$ 67.00	X
57	CABLE TIE	\$ 3.00	X
58	COVER FOR PLENUM CHAMBER	\$ 89.00	X
59	FRONT BUMPER SENSOR	3 \$ 639.00	X
60	SEAL RING	4 \$ 12.00	de 2.96
SUB TOTAL SPARE PARTS		\$ 2,926.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
61	FRONT BUMPER HARNESS		\$ 470.00	X
62	HIGH TONE - HORN		\$ 37.00	X
63	LOW TONE - HORN		\$ 262.00	X
64	SPRING SHACKLE - LH / RH	2	\$ 52.00	X
65	LED HEADLIGHT - LH / RH	576320 7204 1,2	\$ 14,408.00	LH & RH - car
66	LED HEADLIGHT MODULE	554	\$ 693.00	? - photo for dis
67	LED HEADLIGHT CONTROL UNIT	548	\$ 685.00	? photo for dis
68	LED HEADLIGHT HEAT SINK - RH	842 40	\$ 1,053.00	? photo for dis
69	LED HEADLIGHT HOSE	2336	\$ 32.00	new
70	LIFT CYLINDER - RH	144 20	\$ 182.00	dis
71	LIFT CYLINDER PIPE		\$ 78.00	X
72	CORRUGATED PIPE		\$ 35.00	X
73	LIFT CYLINDER BRACKET - RH	10-40	\$ 13.00	dis
74	RADIATOR MOUNTING	742	\$ 928.00	car
75	AC CONDENSER WITH FLUID RESERVOIR	454	\$ 568.00	bt
76	AC PIPE		\$ 152.00	X
77	AC HOSE		\$ 310.00	X
78	AC PRESSURE SENSOR		\$ 180.00	X
79	O RING	2	\$ 3.00	dis
80	AC VALVE		\$ 48.00	X
SUB TOTAL SPARE PARTS		:	\$ 20,189.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
81	RADIATOR	\$	676.00	H ✓ 540.80
82	COOLANT	4 \$	84.00	us ✓ 67.20
83	INTERCOOLER	\$	X535.00	? } X
84	SEAL RING FOR INTERCOOLER	\$	84.00	? } m
85	PRESSURE HOSE	\$	X320.00	? } m
86	COOLING FAN	\$	241.50	Ans ✓ 193.20
87	COOLING FAN CONTROL UNIT	\$	2,107.00	Ans ✓ 1685.60
88	RADIATOR AIR GUIDE - LH / RH	21.76 27.50 14.50 21 \$	✓ de X55.00	LH? RH de
89	RADIATOR SUPPORT COVER - LH / RH	2 \$	de X29.00	LH? RH de
90	RADIATOR AIR GUIDE - UPPER / LOWER	11.28 17.21 \$	de X34.00	LH? RH de
91	INTAKE HOSE - LH / RH	2 \$	nn X67.00	? ?
92	AIR FILTER	Δ 271.20 \$	Δ 339.00	X b de
93	AIR MASS METER	\$	533.00	? X nn
94	ENGINE AIR HOSE	67.84 \$	Δ 85.00	? de
95	FRONT WINDSCREEN	877.40 \$	1,098.00	Ans ✓
96	SPRING CLIP	\$	nn X 20.00	us ✓
97	RAIN SENSOR	102.40 \$	128.00	us ✓
98	PRIMER	29.96 2 \$	38.00	us ✓
99	WATER DEFLECTOR STRIP - LH / RH	48.72 2 \$	Δ 122.00	? out
100	FENDER EMBLEM - LH / RH	115.60 144.50 12 \$	289.00	LH X, RH us ✓
SUB TOTAL SPARE PARTS			\$	6,884.50

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 0550 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
101	FRONT DOOR - LH / RH	2 \$ 5,658.00	Ry
102	FRONT OUTER DOOR SEAL - LH / RH	2 \$ 402.00	X nn
103	BONDING AGENT	2 \$ 90.00	X nn
104	CLEANING SOLUTION	2 \$ 130.00	X } nn
105	APPLICATOR	2 \$ 14.00	X } nn
106	FRONT DOOR CATCH - LH / RH	2 \$ 218.00	X
107	FRONT DOOR TRIM - LH / RH	2 \$ 289.00	X 115.60 nca
108	DATA PLATE FOR TYRE PRESSURE	\$ 35.00	X nn
109	FRONT DOOR WINDOW SLOT SEAL CHROME- LH / RH	2 \$ 728.00	X ? phot 225.60
110	FRONT DOOR CHROME MOULDING - LH / RH	2 \$ 1,148.00	X ? nn
111	AIRBAG UNIT	\$ 3,384.00	act 2707.20
112	AIRBAG UNIT FOR PASSENGER SIDE	\$ 4,019.00	act 3215.20
113	HEXAGON HEAD BOLT	4 \$ 7.00	nn X ne
114	HEAD AIRBAG UNIT - LH / RH	2 \$ 3,416.00	act ? 2732.80
115	CRASH SENSOR FOR AIRBAG	\$ 1,145.00	act 915.60
116	CONTROL UNIT FOR AIRBAG	\$ 1,927.00	act 1541.60
117	BATTERY CONTROL MODULE	\$ 485.00	act 388
118	STEERING WHEEL	1735.20 \$ 2,169.00	act - photo?
119	PAN HEAD BOLTS	\$ 15.00	nn X ne
120	DASHBOARD WITH AIR DUCT	\$ 4,838.00	act 3870.40
SUB TOTAL SPARE PARTS		\$ 30,117.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
121	SEAT BELT WITH TENSIONER - LH / RH	2 \$ 2,010.00	aut 1602
122	MOUNT BRACKET STRIP - RH	2 \$ 8.00	X'm
123	SEAT BELT HEIGHT ADJUSTER	2 \$ aut 322.00	? photo 257.60
124	A-PILLAR TRIM - LH / RH	2 \$ aut 373.00	? photo 299.40
125	B-PILLAR TRIM - LH / RH	2 \$ unx 428.00	? photo
126	FRONT DOOR HANDLE	\$ aut 129.00	? 103.20
127	REAR DOOR HANDLE - LH / RH	2 \$ aut 258.00	? 103.20
128	FRONT NO. PLATE	s/n \$ 40.00	bt 40
129	FRONT WINDSCREEN SEALANT	s/n \$ 200.00	un 200
130	SUNDRIES	\$ 1,000.00	? 572.12 un
TOTAL SPARE PARTS		: \$ 78,612.50	
TOTAL LABOUR CHARGES		: \$ 32,964.00	26444
GRAND TOTAL		\$111,576.50	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

115097 66

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax


10/7/19

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 97495449
Revert, Not Authorised
Ex: to be advise
Resing before paint.
3/7/19 @ 330.
18-20 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9802271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/ODI/0610/2019/TG 9-Jul-19 SM 1 of 1 SKF 550 S AUDI A5 SB 2.0 TFSI	
Quantity	Description		Unit Price	Amount
Labours				
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	\$ 360.00
2	To diamantle and renew rear bumper. Reorganise rear crash management components. Reinstall all parts removed.		\$ 1,200.00	\$ 500.00
3	To respray rear bumper.		\$ 1,000.00	\$ 550.00
4	To carry out diagnostic check.	S/N	\$ 192.00	n/a
4a	To remove and reinstall both front door's trims, attachments, and both wing mirror for respray	S/N	\$ 560.00	\$ 560.00
			\$ 3,312.00	\$ 1,970.00
Parts				
1	REAR BUMPER		\$ 2,311.00	\$ 1,848.40
2	REAR BUMPER FIXING PARTS		\$ 150.00	\$ 150.00
3	REAR KICK SENSOR SECURING STRIP		\$ 203.00	\$ 162.40
4	REAR BUMPER CHROME TRIM		\$ 928.00	\$ 742.40
5	REAR REINFORCEMENT BEAM		\$ 819.00	
6	REAR BUMPER GUIDE - UPPER LH/RH	2	\$ 40.00	
7	REAR BUMPER GUIDE LOCK PIN - LH/RH	2	\$ 5.00	
8	REAR REVERSE SENSOR	2	\$ 462.00	
9	REAR REVERSE SENSOR SEAL RING SET		\$ 12.00	
10	OUTER TEMP. SENSOR BRACKET		\$ 17.00	\$ 13.04
11	FRONT FENDER COVER - LH		\$ 16.00	\$ 12.72
12	HEADLIGHT COMPENSATING PIECE	2	\$ 72.00	\$ 57.60
13	INTAKE AIR DUCT		\$ 48.00	\$ 37.76
14	INTAKE AIR DUCT - RH		\$ 19.00	\$ 15.20
Materials			\$ 5,102.00	\$ 2,889.52
Labour			\$ 3,312.00	\$ 1,970.00
Total			\$ 8,414.00	\$ 4,859.52

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0810/2019/TG 26-Jul-19 Glory Tan 1 OF 1 SKF 550 S Audi A5 Sportback 2.0 TFSI S Tronic
Quantity	Description	Unit Price	Amount
Parts			
1	Defroster nozzle for windscreen dashboard top cover	\$ 153.00	\$ 122.40
2	D-pillar trim LHS	\$ 187.00	\$ 149.20
3	D-pillar trim RHS	\$ 187.00	\$ 149.20
4	Round connector hsg with cable	\$ 241.00	\$ 192.80
5	Flatcontact housing with cable	\$ 174.00	\$ 138.80
6	Butt connector, watertight	\$ 96.00	\$ 76.80
7	Front fender inner top cover RHS	\$ 66.00	\$ 25.44
8	Roof liner	\$ 1,872.00	\$ 1,497.00
		\$ 2,976.00	\$ 2,351.64
TOTAL		\$ 2,976.00	\$ 2,351.64

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0810/2019/TG
Date : 2-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian, Taufikh
You recommended 20 days
We took 22 days - ok - jb - 10 Oct 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Teo Leng Tze
Address : Blk 1 Rosewood Drive
#04-02
Singapore 737934
Telephone : HP +65 91163740
Type of Claim : Own Damage Claims
Policy No. : 1700081585-01
Vehicle No : **SKF 550 S**
Model Code : Audi A5 Sportback 2.0 TFSI S Tronic
Model / Year : Sep-17
Engine No : CVK 04088
Chassis No : WAUZZZF55JA021889
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Jun-19
Place of Accident : CTE (Braddel Road) Towards Woodlands

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKF 550 S

S/N	Nature of Jobs		Estimated Charges	
1	To tow and recover vehicle from scene of accident.	s/n	N.A	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	s/n	\$ 480.00	\$ 480.00
3	To remove and renew aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and gas.	s/n	\$ 1,400.00	\$ 1,400.00
4	To remove center console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining and both curtain air bags.	s/n	\$ 3,600.00	\$ 3,600.00
5	To remove and transfer both front door's multi lock system and power window devices. Inspect for damages.	s/n	\$ 560.00	
6	To renew front windscreen.	s/n	\$ 480.00	\$ 480.00
SUB TOTAL LABOUR CHARGES		:	\$ 6,520.00	\$ 5,960.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKF 550 S

S/N	Nature of Jobs	Estimated Charges	
		<i>c/f</i>	\$ 5,960.00
7	To dismantle and renew front bumper, bonnet, both front fenders, both headlights and both front doors. Align both front chasis frames to specification of origin. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 10,400.00	\$ 4,000.00
8	To respray <i>front bumper, both front fenders, bonnet, both upper A-pillars</i> , bonnet hinges, engine compartment and both and <i>both front doors</i> . To carry out joint sealant work and stone chip treatment.	\$ 8,900.00	\$ 3,850.00
9	To carry out wheel alignment.	s/n \$ 240.00	\$ 240.00
9a	Added labour charges - see attached	\$ 3,312.00	\$ 1,970.00
10	To carry out diagnostic check.	s/n \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 29,756.00 \$ 16,404.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,073.00	\$ 1,658.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	
3	FRONT BUMPER GRILLE - CENTER	\$ 178.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	
5	FRONT BUMPER SECURING STRIP	\$ 64.00	\$ 50.88
6	FRONT BUMPER SPOILER	\$ 489.00	
7	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	\$ 44.40
8	RADIATOR GRILLE	\$ 2,131.00	\$ 1,704.80
9	RADIATOR SUPPORT - LH / RH	\$ 95.00	\$ 75.52
10	RADIATOR GRILLE - UPPER	\$ 174.00	\$ 138.80
11	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 431.00	\$ 344.40
12	FRONT BUMPER CARRIER	\$ 733.00	\$ 586.00
13	FRONT BUMPER BRACKET - LH / RH	2 \$ 390.00	\$ 156.00
14	HEXAGON NUT	4 \$ 2.00	
15	FRONT BUMPER GUIDE SECTION - RH	\$ 33.00	\$ 26.08
16	FOAM FILLER PIECE - RH	\$ 16.00	\$ 12.72
17	FRONT BUMPER TOP COVER	\$ 116.00	\$ 92.40
18	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	\$ 90.40
19	CAUTION STICKER	\$ 13.00	\$ 9.76
20	AC STICKER	\$ 7.00	\$ 5.12
SUB TOTAL SPARE PARTS		\$ 7,689.00	\$ 4,995.68

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	4,995.68
21	FRONT BUMPER LOCK CARRIER - LOWER		\$ 125.00	\$ 100.00
22	FRONT BUMPER SUPPORT - LH / RH	2	\$ 51.00	\$ 40.64
23	FRONT FENDER - LH / RH	2	\$ 1,936.00	\$ 774.40
24	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 135.00	\$ 53.76
25	FRONT FENDER ATTACHMENT PARTS	2	\$ 95.00	
26	FRONT FENDER BRACKER - LH / RH	2	\$ 63.00	\$ 25.20
27	POP RIVET	10	\$ 30.00	\$ 24.00
28	FRONT FENDER SUPPORT - LH / RH	2	\$ 214.00	\$ 85.60
29	FRONT FENDER BRACKET - CENTER LH / RH	2	\$ 89.00	\$ 35.60
30	FRONT WHEEL HOUSING LINER - RH		\$ 256.00	\$ 204.80
31	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS		\$ 82.00	
32	FRONT WHEEL SPOILER - RH		\$ 33.00	
33	STONE CHIP GUARD - LH / RH		\$ 92.00	
34	BRACKET FOR TRIM - RH		\$ 22.00	
35	FRONT FENDER TOP COVER - LONG LH - RH		\$ 64.00	
36	FRONT FENDER TOP COVER - SHORT LH / RH		\$ 28.00	\$ 11.04
37	BONNET		\$ 2,602.00	\$ 2,081.60
38	RETAINING CLIP FOR BONNET	3	\$ 3.00	\$ 2.40
39	CAP NUT	6	\$ 8.00	\$ 6.24
40	BONNET ATTACHMENT PARTS		\$ 111.00	
	SUB TOTAL SPARE PARTS		\$ 6,039.00	\$ 8,440.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT		
				\$	8,440.96
41	BONNET LID HINGE - LH / RH	2	\$ 762.00	\$	304.80
42	BONNET IMPACT PROTECTION - CENTER		\$ 25.00	\$	19.76
43	BONNET IMPACT PROTECTION - LH / RH	2	\$ 50.00	\$	39.68
44	SEAL FOR WATER BOX		\$ 53.00		
45	BONNET ISULATION COVER		\$ 311.00	\$	248.80
46	FENDER LEDGE COVER - RH		\$ 66.00		
47	GAS STRUT	2	\$ 217.00		
48	BONNET LOCK HOOK - LH / RH	2	\$ 91.00	\$	72.48
49	BONNET LID LOCK	2	\$ 391.00	\$	312.80
50	FLAT CONNECTOR HOUSING		\$ 12.00		
51	BRACKET FOR CONNECTOR HOUSING		\$ 9.00		
52	BOWDEN CABLE - CENTER	2	\$ 105.00	\$	83.36
53	RETAINING CLIP	2	\$ 3.00		
54	BONNET RELEASE CABLE CAP		\$ 9.00		
55	RELEASE LEVER		\$ 12.00		
56	LID LOCK CABLE		\$ 67.00		
57	CABLE TIE		\$ 3.00		
58	COVER FOR PLENUM CHAMBER		\$ 89.00		
59	FRONT BUMPER SENSOR	3	\$ 639.00		
60	SEAL RING	4	\$ 12.00	\$	8.96
	SUB TOTAL SPARE PARTS	:	\$ 2,926.00	\$	9,531.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		\$	9,531.60
61	FRONT BUMPER HARNESS	\$ 470.00	
62	HIGH TONE - HORN	\$ 37.00	
63	LOW TONE - HORN	\$ 262.00	
64	SPRING SHACKLE - LH / RH	2 \$ 52.00	
65	LED HEADLIGHT - LH / RH	2 \$ 14,408.00	\$ 5,763.20
66	LED HEADLIGHT MODULE	\$ 693.00	\$ 554.00
67	LED HEADLIGHT CONTROL UNIT	\$ 685.00	\$ 548.00
68	LED HEADLIGHT HEAT SINK - RH	\$ 1,053.00	\$ 842.40
69	LED HEADLIGHT HOSE	\$ 32.00	\$ 25.36
70	LIFT CYLINDER - RH	\$ 182.00	\$ 144.80
71	LIFT CYLINDER PIPE	\$ 78.00	
72	CORRUGATED PIPE	\$ 35.00	
73	LIFT CYLINDER BRACKET - RH	\$ 13.00	\$ 10.40
74	RADIATOR MOUNTING	\$ 928.00	\$ 742.00
75	AC CONDENSER WITH FLUID RESERVOIR	\$ 568.00	\$ 454.00
76	AC PIPE	\$ 152.00	
77	AC HOSE	\$ 310.00	
78	AC PRESSURE SENSOR	\$ 180.00	
79	O RING	\$ 3.00	\$ 2.00
80	AC VALVE	\$ 48.00	
	SUB TOTAL SPARE PARTS	\$ 20,189.00	\$ 18,617.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	18,617.76
81	RADIATOR		\$ 676.00	\$ 540.80
82	COOLANT	4	\$ 84.00	\$ 67.20
83	INTERCOOLER		\$ 535.00	
84	SEAL RING FOR INTERCOOLER		\$ 84.00	
85	PRESSURE HOSE		\$ 320.00	
86	COOLING FAN		\$ 241.50	\$ 193.20
87	COOLING FAN CONTROL UNIT		\$ 2,107.00	\$ 1,685.60
88	RADIATOR AIR GUIDE - LH / RH	2	\$ 55.00	\$ 21.76
89	RADIATOR SUPPORT COVER - LH / RH	2	\$ 29.00	
90	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 34.00	\$ 11.28
91	INTAKE HOSE - LH / RH	2	\$ 67.00	
92	AIR FILTER		\$ 339.00	\$ 271.20
93	AIR MASS METER		\$ 533.00	
94	ENGINE AIR HOSE		\$ 85.00	\$ 67.84
95	FRONT WINDSCREEN		\$ 1,098.00	\$ 878.40
96	SPRING CLIP		\$ 20.00	
97	RAIN SENSOR		\$ 128.00	\$ 102.40
98	PRIMER	2	\$ 38.00	\$ 29.76
99	WATER DEFLECTOR STRIP - LH / RH	2	\$ 122.00	\$ 48.72
100	FENDER EMBLEM - LH / RH	2	\$ 289.00	\$ 115.60
	SUB TOTAL SPARE PARTS	:	\$ 6,884.50	\$ 22,651.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 0550 S

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT	\$	
				\$	22,651.52
101	FRONT DOOR - LH / RH	2	\$	5,658.00	
102	FRONT OUTER DOOR SEAL - LH / RH	2	\$	402.00	
103	BONDING AGENT	2	\$	90.00	
104	CLEANING SOLUTION	2	\$	130.00	
105	APPLICATOR	2	\$	14.00	
106	FRONT DOOR CATCH - LH / RH	2	\$	218.00	
107	FRONT DOOR TRIM - LH / RH	2	\$	289.00	\$ 115.60
108	DATA PLATE FOR TYRE PRESSURE		\$	35.00	
109	FRONT DOOR WINDOW SLOT SEAL CHROME- LH / RH	2	\$	728.00	\$ 225.60
110	FRONT DOOR CHROME MOULDING - LH / RH	2	\$	1,148.00	
111	AIRBAG UNIT		\$	3,384.00	\$ 2,707.20
112	AIRBAG UNIT FOR PASSENGER SIDE		\$	4,019.00	\$ 3,215.20
113	HEXAGON HEAD BOLT	4	\$	7.00	
114	HEAD AIRBAG UNIT - LH / RH	2	\$	3,416.00	\$ 2,732.80
115	CRASH SENSOR FOR AIRBAG		\$	1,145.00	\$ 915.60
116	CONTROL UNIT FOR AIRBAG		\$	1,927.00	\$ 1,541.60
117	BATTERY CONTROL MODULE		\$	485.00	\$ 388.00
118	STEERING WHEEL		\$	2,169.00	\$ 1,735.20
119	PAN HEAD BOLTS		\$	15.00	
120	DASHBOARD WITH AIR DUCT		\$	4,838.00	\$ 3,870.40
	SUB TOTAL SPARE PARTS		\$	30,117.00	\$ 40,098.72

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKF 550 S

S/N	Parts Description		Damage Parts & Prices		REMARKS
			S/NETT		
		<i>c/f</i>		\$	40,098.72
121	SEAT BELT WITH TENSIONER - LH / RH	2	\$ 2,010.00	\$	1,608.00
122	MOUNT BRACKET STRIP - RH	2	\$ 8.00		
123	SEAT BELT HEIGHT ADJUSTER	2	\$ 322.00	\$	257.60
124	A-PILLAR TRIM - LH / RH	2	\$ 373.00	\$	298.40
125	B-PILLAR TRIM - LH / RH	2	\$ 428.00		
126	FRONT DOOR HANDLE		\$ 129.00	\$	103.20
127	REAR DOOR HANDLE - LH / RH	2	\$ 258.00	\$	103.20
128	FRONT NO. PLATE	s/n	\$ 40.00	\$	40.00
129	FRONT WINDSCREEN SEALANT	s/n	\$ 200.00	\$	200.00
130	<i>Added parts - see attached</i>		\$ 2,976.00	\$	2,351.64
131	<i>Added parts - see attached</i>		\$ 5,102.00	\$	2,889.52
133	SUNDRIES		\$ 1,000.00	\$	572.12
TOTAL SPARE PARTS		:	\$ 86,690.50	\$	48,522.40
TOTAL LABOUR CHARGES		:	\$ 36,276.00	\$	16,404.00
GRAND TOTAL			\$ 122,966.50	\$	64,926.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.


Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Work Order: 00710
V: WAUZZZF55JA021889
Technician: way
Sens: SKF550S
Odometer: 46386
Date: 22.7.19 21:54

Audi : A5 : 2016- (F5) : Standard Suspension (1BA)



• One or more values are not within specification. Tire wear, handling and safety problems may result.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0810/2019/TG

26-Jul-19

Glory Tan

1 OF 1

SKF 550 S

Audi A5 Sportback 2.0 TFSI S Tr

Quantity Description

Unit Price Amount

Parts

1	Defroster nozzle for windscreen dashboard top cover	\$ 153.00	Ans 122.40
2	D-pillar trim LHS	\$ 187.00	Ans 149.20
3	D-pillar trim RHS	\$ 187.00	Ans 149.20
4	Round connector hsg with cable	\$ 241.00	Ans 192.80
5	Flatcontact housing with cable	\$ 174.00	Ans 138.80
6	Butt connector, watertight	\$ 96.00	Ans 76.80
7	Front fender inner top cover RHS	\$ 66.00	Ans 25.44

\$ 1,104.00 854.64

TOTAL \$ 1,104.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-VV

AIG Asia Pacific Insurance Pte Ltd
7B Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/00/0610/2019/TG
9-Jul-19
SM
1 of 1
SKF 550 S
AUDI A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00
2	To dismantled and renew rear bumper. Reorganise rear crash management components. Reinstall all parts removed.		\$ 1,200.00
3	To respray rear bumper.		\$ 1,000.00
4	To carry out diagnostic check.	S/N	\$ 192.00
Parts			
1	REAR BUMPER <i>de</i>		\$ 2,311.00
2	REAR BUMPER FIXING PARTS <i>X</i>		\$ 150.00
3	REAR KICK SENSOR SECURING STRIP <i>see photo</i>		\$ 203.00
4	REAR BUMPER CHROME TRIM <i>see</i>		\$ 928.00
5	REAR REINFORCEMENT BEAM <i>?</i>		\$ 819.00
6	REAR BUMPER GUIDE - UPPER LH/RH <i>?</i>	2	\$ 40.00
7	REAR BUMPER GUIDE LOCK PIN - LH/RH <i>?</i>	2	\$ 5.00
8	REAR REVERSE SENSOR <i>X</i>	2	\$ 462.00
9	REAR REVERSE SENSOR SEAL RING SET <i>see</i>		\$ 12.00
10	OUTER TEMP. SENSOR BRACKET <i>see</i>		\$ 17.00
11	FRONT FENDER COVER - LH <i>see</i>		\$ 16.00
12	HEADLIGHT COMPENSATING PIECE <i>see</i>	2	\$ 72.00
13	INTAKE AIR DUCT <i>see</i>		\$ 48.00
14	INTAKE AIR DUCT - RH <i>see</i>		\$ 19.00
GRAND TOTAL			\$ 7,854.00

Russul
12/07/19

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKF 550 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0810/2019/NH

4TH March 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKF 550 S, Audi A5 SB 2.0 TFSI S-TRONIC.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SKF 550 S**, claimant, **Mr. Teo Leng Tze**, please find the related document per attached.

1. A copy of the Original invoice no. 85014925 – S\$ 64,200.00.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.


Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKF 550 S

Premium Automobiles Pte Ltd



Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408699
Main Telephone 6366 2323
Main Telefax 6541 1183

Customer Service

Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:29

Company Reg.No.199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014925 Date : 29/02/2020 Order: SKF05505 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKF05505 (V 35074)

Regn Date: 20/09/2017

Mileage: 60685

WIP No : 58778

Model: A5 SPORTBACK 2.0 TFSI S tronic

Chassis: WAUZZZF55JA021889

Engine: CVK D44088

DEPT: U

You have been assisted by: UB-Siti Marsilla (137)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LIMIT repair basis as agreed	60,000.00	1.00	60,000.00

Parts 0.00
Labour 0.00
Sublet 60,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 60,000.00

7% GST 4,200.00

Grand Total 64,200.00



29/2

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKF 550 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0810/2019/EH
1ST Aug 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A5 Sportback 2.0 tfsi s Tronic
Vehicle Chassis No. : WAUZZZF55JA021889
Vehicle Regn No. : **SKF 550 S**
Vehicle Mileage : 46,000 KM
Vehicle Owner : Mr. Teo Leng Tze
Certificate No : 1700081585-01
Own Damage Excess : NA
Accident Date : 28/06/2019
Place : CTE (Braddel Road) Towards Woodlands
Repair Cost : \$ 64,200.00
WIP No. : 58778
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


1700 hrs
2/8/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019		04 Jul 2019 11:38 Edit Adj Rpt	S\$60,000.00 Edit Estimates	S\$60,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TEO LENG TZE, ID: S7119703D, Tel: +6591163740, Email: DNLTEO550@YAHOO.COM.SG								
Vehicle Reg. No.:	SKF550S	Date of Loss:	28/06/2019 00:00 - :59 [21 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1566843384SG	Policy/Cover Note No.:	1700081585 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2, 159938 Alexandra - Tel: 63882233								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/07/2019]								
Driver/Custodian:	TEO LENG TZE (48 / Male) , NRIC: S7119703D, Tel: +6591163740 Email: DNLTEO550@YAHOO.COM.SG								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (04/12/2019): Alert - Adj Mandate Approved (S\$60000.00) - SKF550S - Claim Handler: Gan, Hunchu... - AIG_SG (08/07/2019): Alert - Adj Mandate Approved (S\$60000.00) - SKF550S - Claim Handler: Gan, Hunchu... - AIG_SG (04/07/2019): Alert - Adj Mandate Maintained - SKF550S - Claim Handler: Gan, Hunchung									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKF550S (1566843384SG)

OD

Jun 28 2019 12:00AM

[TEO LENG TZE]

Premium Automobiles Pte Ltd - Alexandra

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video														1 per page		☐	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)												Thumbnail	Print		
1	29/06/19 13:42	Video - Accident (Linked Accident Report Documents)												Load MP4			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	04/07/19 16:05	Video - Accident												Load MP4			
Assessment Reports														1 per page		☐	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	04/07/19 14:40	Adjuster Immediate Advice												Load HTM			
Photos/Images														3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	04/07/19 14:18	General View												Load JPG	☒		
2	04/07/19 14:18	General View												Load JPG	☒		
3	04/07/19 14:18	General View												Load JPG	☒		
4	04/07/19 14:18	General View												Load JPG	☒		
5	04/07/19 14:19	General View												Load JPG	☒		
6	04/07/19 14:19	General View												Load JPG	☒		
7	04/07/19 14:19	General View												Load JPG	☒		
8	04/07/19 14:19	General View												Load JPG	☒		
9	04/07/19 14:19	General View												Load JPG	☒		
10	04/07/19 14:19	General View												Load JPG	☒		
11	04/07/19 14:19	General View												Load JPG	☒		
12	04/07/19 14:19	General View												Load JPG	☒		
13	04/07/19 14:19	General View												Load JPG	☒		
14	04/07/19 14:19	General View												Load JPG	☒		
15	04/07/19 14:19	General View												Load JPG	☒		
16	04/07/19 14:19	General View												Load JPG	☒		
17	04/07/19 14:19	General View												Load JPG	☒		
18	04/07/19 14:19	General View												Load JPG	☒		
19	04/07/19 14:19	General View												Load JPG	☒		
20	04/07/19 14:19	General View												Load JPG	☒		
21	04/07/19 14:19	General View												Load JPG	☒		
22	04/07/19 14:19	General View												Load JPG	☒		
23	04/07/19 14:19	General View												Load JPG	☒		
24	04/07/19 14:19	General View												Load JPG	☒		
25	04/07/19 14:19	General View												Load JPG	☒		
26	04/07/19 14:19	General View												Load JPG	☒		
27	04/07/19 14:19	General View												Load JPG	☒		
28	04/07/19 14:19	General View												Load JPG	☒		
29	04/07/19 14:19	General View												Load JPG	☒		
30	04/07/19 14:19	General View												Load JPG			

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
31	04/07/19 14:19	General View	 Load JPG	☒
32	04/07/19 14:19	General View	 Load JPG	☒
33	04/07/19 14:19	General View	 Load JPG	☒
34	04/07/19 14:19	General View	 Load JPG	☒
35	04/07/19 14:19	General View	 Load JPG	☒
36	04/07/19 14:19	General View	 Load JPG	☒
37	04/07/19 14:19	General View	 Load JPG	☒
38	04/07/19 14:19	General View	 Load JPG	☒
39	04/07/19 14:19	General View	 Load JPG	☒
40	04/07/19 14:19	General View	 Load JPG	☒
41	04/07/19 14:19	General View	 Load JPG	☒
42	04/07/19 14:19	General View	 Load JPG	☒
43	04/07/19 14:19	General View	 Load JPG	☒
44	04/07/19 14:19	General View	 Load JPG	☒
45	04/07/19 14:19	General View	 Load JPG	☒
46	04/07/19 14:19	General View	 Load JPG	☒
47	04/07/19 14:19	General View	 Load JPG	☒
48	04/07/19 14:19	General View	 Load JPG	☒
49	04/07/19 14:19	General View	 Load JPG	☒
50	04/07/19 14:19	General View	 Load JPG	☒
51	04/07/19 14:19	General View	 Load JPG	☒
52	04/07/19 14:19	General View	 Load JPG	☒
53	04/07/19 14:19	General View	 Load JPG	☒
54	04/07/19 14:19	General View	 Load JPG	☒
55	04/07/19 14:19	General View	 Load JPG	☒
56	04/07/19 14:19	General View	 Load JPG	☒
57	04/07/19 14:19	General View	 Load JPG	☒
58	04/07/19 14:19	General View	 Load JPG	☒
59	04/07/19 14:19	General View	 Load JPG	☒
60	04/07/19 14:19	General View	 Load JPG	☒
61	04/07/19 14:19	General View	 Load JPG	☒
62	04/07/19 14:19	General View	 Load JPG	☒
63	04/07/19 14:19	General View	 Load JPG	☒
64	04/07/19 14:19	General View	 Load JPG	☒
65	04/07/19 14:19	General View	 Load JPG	☒
66	04/07/19 14:19	General View	 Load JPG	☒
67	04/07/19 14:19	General View	 Load JPG	☒
68	04/07/19 14:19	General View	 Load JPG	☒
69	04/07/19 14:19	General View	 Load JPG	☒
70	04/07/19 14:19	General View	 Load JPG	☒
71	04/07/19 14:19	General View	 Load JPG	☒
72	04/07/19 14:19	General View	 Load JPG	☒
73	04/07/19 14:19	General View	 Load JPG	☒
74	04/07/19 14:19	General View	 Load JPG	☒
75	04/07/19 14:19	General View	 Load JPG	☒
76	04/07/19 14:19	General View	 Load JPG	☒
77	04/07/19 14:19	General View	 Load JPG	☒
78	04/07/19 14:19	General View	 Load JPG	☒
79	04/07/19 14:19	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
80	04/07/19 14:19	General View	 Load JPG	☒
81	04/07/19 14:19	General View	 Load JPG	☒
82	04/07/19 14:19	General View	 Load JPG	☒
83	04/07/19 14:19	General View	 Load JPG	☒
84	04/07/19 14:19	General View	 Load JPG	☒
85	04/07/19 14:19	General View	 Load JPG	☒
86	04/07/19 14:19	General View	 Load JPG	☒
87	04/07/19 14:19	General View	 Load JPG	☒
88	04/07/19 14:19	General View	 Load JPG	☒
89	04/07/19 14:19	General View	 Load JPG	☒
90	04/07/19 14:19	General View	 Load JPG	☒
91	04/07/19 14:19	General View	 Load JPG	☒
92	04/07/19 14:19	General View	 Load JPG	☒
93	04/07/19 14:19	General View	 Load JPG	☒
94	04/07/19 14:19	General View	 Load JPG	☒
95	04/07/19 14:19	General View	 Load JPG	☒
96	04/07/19 14:19	General View	 Load JPG	☒
97	04/07/19 14:19	General View	 Load JPG	☒
98	04/07/19 14:19	General View	 Load JPG	☒
99	04/07/19 14:19	General View	 Load JPG	☒
100	04/07/19 14:19	General View	 Load JPG	☒
101	04/07/19 14:19	General View	 Load JPG	☒
102	04/07/19 14:19	General View	 Load JPG	☒
103	04/07/19 14:19	General View	 Load JPG	☒
104	04/07/19 14:19	General View	 Load JPG	☒
105	04/07/19 14:19	General View	 Load JPG	☒
106	04/07/19 14:19	General View	 Load JPG	☒
107	04/07/19 14:19	General View	 Load JPG	☒
108	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
109	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
110	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
111	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
112	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
113	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
114	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
115	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
116	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
117	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
118	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
119	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
120	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
121	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
122	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
123	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
124	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
125	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
126	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
127	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
128	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
129	04/12/19 10:19	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
130	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
131	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
132	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
133	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
134	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
135	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
136	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
137	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
138	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
139	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
140	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
141	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
142	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
143	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
144	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
145	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
146	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
147	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
148	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
149	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
150	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
151	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
152	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
153	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
154	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
155	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
156	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
157	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
158	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
159	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
160	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
161	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
162	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
163	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
164	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
165	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
166	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
167	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
168	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
169	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
170	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
171	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
172	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
173	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
174	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
175	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
176	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
177	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
178	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
179	04/12/19 10:19	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
180	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
181	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
182	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
183	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
184	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
185	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
186	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
187	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
188	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
189	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
190	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
191	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
192	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
193	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
194	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
195	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
196	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
197	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
198	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
199	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
200	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
201	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
202	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
203	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
204	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
205	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
206	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
207	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
208	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
209	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
210	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
211	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
212	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
213	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
214	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
215	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
216	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
217	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
218	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
219	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
220	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
221	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
222	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
223	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
224	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
225	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
226	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
227	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
228	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
229	04/12/19 10:19	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
230	04/12/19 10:19	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/19 14:14	SG CAR MART	 Load PDF	
2	04/07/19 14:14	ESTIMATE	 Load PDF	
3	04/07/19 14:14	Police Report	 Load PDF	
4	04/07/19 14:14	Singapore Accident Statement	 Load PDF	
5	04/07/19 14:14	NEW CAR PRICE	 Load PDF	
6	04/07/19 14:16	CI AND DRIVING LICENSE	 Load PDF	
7	04/07/19 14:41	LTA	 Load PDF	
8	06/03/20 17:43	Workshop Invoice	 Load PDF	
9	06/03/20 17:43	Discharge Voucher	 Load PDF	
10	06/03/20 17:44	Supplementary	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/06/19 13:42	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/19 01:28	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/06/19 13:43	Accident Photo	 Load JPG	☒
2	29/06/19 13:43	Accident Photo	 Load JPG	☒
3	29/06/19 13:43	Accident Photo	 Load JPG	☒
4	29/06/19 13:43	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/06/19 13:38	Sketch Plan	 Load JPG	☒
2	29/06/19 13:39	Accident Sketch Plan	 Load JPG	☒
3	29/06/19 13:44	POLICE REPORT	 Load JPG	☒
4	29/06/19 13:44	POLICE REPORT	 Load JPG	☒
5	29/06/19 13:44	POLICE REPORT	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19011824/T1TD3E2

Date: 06/03/2020

REFERENCE

Insured/Claimant:	TEO LENG TZE	Policy No:	1700081585	
Date of Loss:	28/06/2019	Nature of Claim:	OD	Claim No: 1566843384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF550S	Engine No:	CVK044088
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF55JA021889
Reg. Date:	20/09/2017 (Man. Year: 2017)	Odometer:	46387 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	85,341.66	48,522.40	36,819.26	43.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	29,756.00	16,404.00	13,352.00	44.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	115,097.66	64,926.40	50,171.26	43.59
Approved Total (Overridden) (S\$)		60,000.00		
(S\$)	115,097.66	60,000.00	55,097.66	47.87
+ GST 7.00/7.00% (S\$)	8,056.84	4,200.00	3,856.84	47.87
Nett Amount (S\$)	123,154.50	64,200.00	58,954.50	47.87

INSPECTION

Date of Assignment:	04/07/2019		
Date Inspected:	03/07/2019	Inspected At:	Premium Autocare Centre (Benoi) 24 Benoi Sector Singapore 629857
Estimated Period of Repair:	22.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,073.00 FS	*1,658.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	368.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	178.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	207.00 FS	*- FS
5	1		*FRONT BUMPER SECURING STRIP	Necessary	64.00 FS	*50.88 FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	489.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	56.00 FS	*44.40 FS
8	1		*RADIATOR GRILLE	Cracked	2,131.00 FS	*1,704.80 FS
9	2		*RADIATOR SUPPORT - LH / RH	Distorted	95.00 FS	*75.52 FS
10	1		*RADIATOR GRILLE - UPPER	Cracked	174.00 FS	*138.80 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	431.00 FS	*344.40 FS
12	1		*FRONT BUMPER CARRIER	Bent	733.00 FS	*586.00 FS
13	1		*FRONT BUMPER BRACKET - LH / RH	N/SNotNecessary/O/SDeformed	390.00 FS	*156.00 FS
14	4		*HEXAGON NUT	Not Necessary	2.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Deformed	33.00 FS	*26.08 FS
16	1		*FOAM FILLER PIECE - RH	Missing	16.00 FS	*12.72 FS
17	1		*FRONT BUMPER TOP COVER	Deformed	116.00 FS	*92.40 FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	113.00 FS	*90.40 FS
19	1		*CAUTION STICKER	Necessary	13.00 FS	*9.76 FS
20	1		*AC STICKER	Necessary	7.00 FS	*5.12 FS
21	1		*FRONT BUMPER LOCK CARRIER - LOWER	Distorted	125.00 FS	*100.00 FS
22	2		*FRONT BUMPER SUPPORT - LH / RH	Deformed	51.00 FS	*40.64 FS
23	1		*FRONT FENDER - LH / RH	N/SNotNecessary/O/SBent	1,936.00 FS	*774.40 FS
24	1		*FRONT FENDER CLOSING ELEMENT - LH / RH	N/S Not Necessary / O/S Bent	135.00 FS	*53.76 FS
25	2		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	95.00 FS	*- FS
26	1		*FRONT FENDER BRACKET - LH / RH	N/S Not Necessary / O/S Bent	63.00 FS	*25.20 FS
27	10		*POP RIVET	Necessary	30.00 FS	*24.00 FS
28	1		*FRONT FENDER SUPPORT - LH / RH	N/S Not Necessary / O/S Bent	214.00 FS	*85.60 FS
29	1		*FRONT FENDER BRACKET - CENTER LH / RH	N/S Not Necessary / O/S Bent	89.00 FS	*35.60 FS
30	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	256.00 FS	*204.80 FS
31	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
32	1		*FRONT WHEEL SPOILER - RH	Not Necessary	33.00 FS	*- FS
33	1		*STONE CHIP GUARD - LH / RH	Not Necessary	92.00 FS	*- FS
34	1		*BRACKET FOR TRIM - RH	Not Necessary	22.00 FS	*- FS
35	2		*FRONT FENDER TOP COVER - LONG LH - RH	Not Necessary	64.00 FS	*- FS
36	2		*FRONT FENDER TOP COVER - SHORT LH / RH	Necessary	28.00 FS	*11.04 FS
37	1		*BONNET	Bent	2,602.00 FS	*2,081.60 FS
38	3		*RETAINING CLIP FOR BONNET	Necessary	3.00 FS	*2.40 FS
39	6		*CAP NUT	Necessary	8.00 FS	*6.24 FS
40	1		*BONNET ATTACHMENT PARTS	Not Necessary	111.00 FS	*- FS
41	2		*BONNET LID HINGE - LH / RH	Bent	762.00 FS	*304.80 FS
42	1			Deformed	25.00 FS	*19.76 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*BONNET IMPACT PROTECTION - CENTER			
43	2		*BONNET IMPACT PROTECTION - LH / RH	Deformed	50.00 FS	*39.68 FS
44	1		*SEAL FOR WATER BOX	Not Necessary	53.00 FS	*- FS
45	1		*BONNET INSULATION COVER	Deformed	311.00 FS	*248.80 FS
46	1		*FENDER LEDGE COVER - RH	Not Necessary	66.00 FS	*- FS
47	2		*GAS STRUT	Not Necessary	217.00 FS	*- FS
48	1		*BONNET LOCK HOOK - LH / RH	N/SNotNecessary/O/SBent	91.00 FS	*72.48 FS
49	2		*BONNET LID LOCK	Bent	391.00 FS	*312.80 FS
50	1		*FLAT CONNECTOR HOUSING	Not Necessary	12.00 FS	*- FS
51	1		*BRACKET FOR CONNECTOR HOUSING	Not Necessary	9.00 FS	*- FS
52	2		*BOWDEN CABLE - CENTER	Distorted	105.00 FS	*83.36 FS
53	2		*RETAINING CLIP	Not Necessary	3.00 FS	*- FS
54	1		*BONNET RELEASE CABLE CAP	Not Necessary	9.00 FS	*- FS
55	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
56	1		*LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
57	1		*CABLE TIE	Not Necessary	3.00 FS	*- FS
58	1		*COVER FOR PLENUM CHAMBER	Not Necessary	89.00 FS	*- FS
59	3		*FRONT BUMPER SENSOR	Not Necessary	639.00 FS	*- FS
60	4		*SEAL RING	Necessary	12.00 FS	*8.96 FS
61	1		*FRONT BUMPER HARNESS	Not Necessary	470.00 FS	*- FS
62	1		*HIGH TONE - HORN	Not Necessary	37.00 FS	*- FS
63	1		*LOW TONE - HORN	Not Necessary	262.00 FS	*- FS
64	2		*SPRING SHACKLE - LH / RH	Not Necessary	52.00 FS	*- FS
65	1		*LED HEADLIGHT - LH / RH	N/SNotNecessary/O/SCracked	14,408.00 FS	*5,763.20 FS
66	1		*LED HEADLIGHT MODULE	Distorted	693.00 FS	*554.00 FS
67	1		*LED HEADLIGHT CONTROL UNIT	Distorted	685.00 FS	*548.00 FS
68	1		*LED HEADLIGHT HEAT SINK - RH	Distorted	1,053.00 FS	*842.40 FS
69	1		*LED HEADLIGHT HOSE	Necessary	32.00 FS	*25.36 FS
70	1		*LIFT CYLINDER - RH	Distorted	182.00 FS	*144.80 FS
71	1		*LIFT CYLINDER PIPE	Not Necessary	78.00 FS	*- FS
72	1		*CORRUGATED PIPE	Not Necessary	35.00 FS	*- FS
73	1		*RADIATOR MOUNTING	Cracked	928.00 FS	*742.00 FS
74	1		*AC CONDENSER WITH FLUID RESERVOIR	Bent	568.00 FS	*454.00 FS
75	1		*AC PIPE	Not Necessary	152.00 FS	*- FS
76	1		*AC HOSE	Not Necessary	310.00 FS	*- FS
77	1		*AC PRESSURE SENSOR	Not Necessary	180.00 FS	*- FS
78	1		*O RING	Necessary	3.00 FS	*2.00 FS
79	1		*AC VALVE	Not Necessary	48.00 FS	*- FS
80	1		*RADIATOR	Bent	676.00 FS	*540.80 FS
81	4		*COOLANT	Necessary	84.00 FS	*67.20 FS
82	1		*INTERCOOLER	Not Necessary	535.00 FS	*- FS
83	1		*SEAL RING FOR INTERCOOLER	Not Necessary	84.00 FS	*- FS
84	1		*PRESSURE HOSE	Not Necessary	320.00 FS	*- FS
85	1		*COOLING FAN	Cracked	241.50 FS	*193.20 FS
86	1		*COOLING FAN CONTROL UNIT	Distorted	2,107.00 FS	*1,685.60 FS
87	1		*RADIATOR AIR GUIDE - LH / RH	N/SNotNecessary/O/SDeformed	55.00 FS	*21.76 FS
88	2		*RADIATOR SUPPORT COVER - LH / RH	Not Necessary	29.00 FS	*- FS
89	1		*RADIATOR AIR GUIDE - UPPER / LOWER	N/S Not Necessary /O/SDeformed	34.00 FS	*11.28 FS
90	2		*INTAKE HOSE - LH / RH	Not Necessary	67.00 FS	*- FS
91	1		*AIR FILTER	Deformed	339.00 FS	*271.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
92	1		*AIR MASS METER	Not Necessary	533.00 FS	*- FS
93	1		*ENGINE AIR HOSE	Distorted	85.00 FS	*67.84 FS
94	1		*FRONT WINDSCREEN	Cracked	1,098.00 FS	*878.40 FS
95	1		*SPRING CLIP	Not Necessary	20.00 FS	*- FS
96	1		*RAIN SENSOR	Necessary	128.00 FS	*102.40 FS
97	2		*PRIMER	Necessary	38.00 FS	*29.76 FS
98	2		*WATER DEFLECTOR STRIP - LH / RH	Cut	122.00 FS	*48.72 FS
99	1		*FENDER EMBLEM - LH / RH	N/SNotNecessary/O/SNecessary	289.00 FS	*115.60 FS
100	2		*FRONT DOOR - LH / RH	Repair	5,658.00 FS	*- FS
101	2		*FRONT OUTER DOOR SEAL - LH / RH	Not Necessary	402.00 FS	*- FS
102	2		*BONDING AGENT	Not Necessary	90.00 FS	*- FS
103	2		*CLEANING SOLUTION	Not Necessary	130.00 FS	*- FS
104	2		*APPLICATOR	Not Necessary	14.00 FS	*- FS
105	2		*FRONT DOOR CATCH - LH / RH	Not Necessary	218.00 FS	*- FS
106	2		*FRONT DOOR TRIM - LH / RH	Necessary	289.00 FS	*115.60 FS
107	1		*DATA PLATE FOR TYRE PRESSURE	Not Necessary	35.00 FS	*- FS
108	2		*FRONT DOOR WINDOW SLOT SEAL CHROME - LH / RH	Necessary	728.00 FS	*225.60 FS
109	2		*FRONT DOOR CHROME MOULDING - LH / RH	Not Necessary	1,148.00 FS	*- FS
110	1		*AIR BAG UNIT	Activated	3,384.00 FS	*2,707.20 FS
111	1		*AIRBAG UNIT FOR PASSENGER SIDE	Cut	4,019.00 FS	*3,215.20 FS
112	4		*HEXAGON HEAD BOLT	Not Necessary	7.00 FS	*- FS
113	2		*HEAD AIRBAG UNIT - LH / RH	Activated	3,416.00 FS	*2,732.80 FS
114	1		*CRASH SENSOR FOR AIRBAG	Activated	1,145.00 FS	*915.60 FS
115	1		*CONTROL UNIT FOR AIRBAG	Activated	1,927.00 FS	*1,541.60 FS
116	1		*BATTERY CONTROL MODULE	Activated	485.00 FS	*388.00 FS
117	1		*STEERING WHEEL	Activated	2,169.00 FS	*1,735.20 FS
118	1		*PAN HEAD BOLTS	Not Necessary	15.00 FS	*- FS
119	1		*DASHBOARD WITH AIR DUCT	Activated	4,838.00 FS	*3,870.40 FS
120	2		*SEAT BELT WITH TENSIONER - LH / RH	Activated	2,010.00 FS	*1,608.00 FS
121	2		*MOUNT BRACKET STRIP - RH	Not Necessary	8.00 FS	*- FS
122	2		*SEAT BELT HEIGHT ADJUSTER	Activated	322.00 FS	*257.60 FS
123	2		*A-PILLAR TRIM - LH / RH	Deformed	373.00 FS	*298.40 FS
124	2		*B-PILLAR TRIM - LH / RH	Not Necessary	428.00 FS	*- FS
125	1		*FRONT DOOR HANDLE	Distorted	129.00 FS	*103.20 FS
126	2		*REAR DOOR HANDLE - LH / RH	Distorted	258.00 FS	*103.20 FS
127	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
128	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
129	1		*SUNDRIES	Necessary	1,000.00 FS	*572.12 FS
130	1		*REAR BUMPER	Deformed	1,848.40 FS	*1,848.40 FS
131	1		*REAR BUMPER FIXING PARTS	Not Necessary	150.00 FS	*- FS
132	1		*REAR KICK SENSOR SECURING STRIP	Necessary	162.40 FS	*162.40 FS
133	1		*REAR BUMPER CHROME TRIM	Scratched	742.40 FS	*742.40 FS
134	1		*REAR REINFORCEMENT BEAM	Not Necessary	819.00 FS	*- FS
135	2		*REAR BUMPER GUIDE - UPPER LH / RH	Not Necessary	40.00 FS	*- FS
136	2		*REAR BUMPER GUIDE LOCK PIN - LH / RH	Not Necessary	5.00 FS	*- FS
137	2		*REAR REVERSE SENSOR	Not Necessary	462.00 FS	*- FS
138	1		*SET REAR REVERSE SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
139	1		*OUTER TEMP SENSOR BRACKET	Cracked	13.04 FS	*13.04 FS
140	1		*FRONT FENDER COVER - LH	Cracked	12.72 FS	*12.72 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
141	2		*HEADLIGHT COMPENSATING PIECE	Distorted	57.60 FS	*57.60 FS
142	1		*INTAKE AIR DUCT	Cracked	37.76 FS	*37.76 FS
143	1		*INTAKE AIR DUCT - RH	Cracked	15.20 FS	*15.20 FS
144	1		*DEFROSTER NOZZLE FOR WINDSCREEN DASHBOARD TOP COVER	Cracked	122.40 FS	*122.40 FS
145	1		*D-PILLAR TRIM LHS	Deformed	149.20 FS	*149.20 FS
146	1		*D-PILLAR TRIM RHS	Deformed	149.20 FS	*149.20 FS
147	1		*ROUND CONNECTOR HSG WITH CABLE	Distorted	192.80 FS	*192.80 FS
148	1		*FLATCONTACT HOUSING WITH CABLE	Distorted	138.80 FS	*138.80 FS
149	1		*BUTT CONNECTOR, WATERTIGHT	Distorted	76.80 FS	*76.80 FS
150	1		*FRONT FENDER INNER TOP COVER RHS	Deformed	25.44 FS	*25.44 FS
151	1		*ROOF LINER	Deformed	1,497.00 FS	*1,497.00 FS
152	1		*LIFT CYLINDER BRACKET - RH	Distorted	13.00 FS	*10.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 85,341.66 48,522.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND GAS	New	1,400.00	1,400.00
3	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS	New	3,600.00	3,600.00
4	TO REMOVE AND TRANSFER BOTH FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	0.00
5	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS AND BOTH FRONT DOORS. ALIGN BOTH FRONT CHASIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	10,400.00	4,000.00
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, BOTH UPPER A-PILLARS, BONNET HINGES, ENGINE COMPARTMENT AND BOTH AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	8,900.00	3,850.00
8	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	240.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
10	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
11	TO DISMANTLE AND RENEW REAR BUMPER. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
12	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
13	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
14	TO REMOVE AND REINSTALL BOTH FRONT DOORS TRIMS, ATTACHMENTS, AND BOTH WING MIRROR FOR RESPRAY	New	560.00	560.00
Gross Labour Cost (S\$)			29,756.00	16,404.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >