

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 24 Jul 2019

Preliminary Advice

Insured Vehicle No : SMC1031J

TP Vehicle No : SLB7383X

Make : TOYOTA VELLFIRE 2.5Z A

Date of Inspection : 04/07/2019

Inspection At : Supreme Auto Service Pte Ltd (HQ)
176 Sin Ming Drive #02-01, Sin Ming Autocare
Singapore 575721

Accident Date : 02/07/2019

Assignment Date : 03/07/2019

Est. Duration of Repair : 2 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,003.48
Revised Amount	:S\$	4,651.87
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,651.87

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.