

22/03/2002

ASS. REC. BY:

REF: CS/CT1 19011830/R1+d302

Special Instruction:

Survivor: RASU

ASSIGNMENT (Office)

From (Person): Chu So chow

of CT1

Date/Time: 4.7.19 9.09 a.m.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKW 4897B

Insured: GBH 43412

at Workshop m/s Sng Ah Tee

Tel: 62686183

of Blk 3 Pioneer Road NDAU #01-18

Policy No: DMCVSN 1872119011

Claim No: SNM 1901183086

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30.6.19

CA / REV / REP. / REV 24 HRS

Date/Time: 4.7.19 10.10 a.m.

Person Contacted:

Janice

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 4897B - X

GBH 43412 - X

27/11

Confirm final figure \$749.43, (Red: 265.11 : 35%).

(00/11/13)

ASS. REC. BY:

REF

0494F

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKW 4897B**
 at Workshop m/s **SNA A4 TEE**
 of **PIONEER ROAD NORTH**
 Insured: **CTI**

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKW 4897B** Yr Regn: **2015 / OCT**
 Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **Honda Vezel 1.5 A** C.C. **1496**
 Colour: **Grey** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **05 0881** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **Ru 11103588**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **In order** / Jammed / Leaked / Burnt orBrake: **In order** / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **6** mmR/Bal. **6** mmL/Bal. **6** mmL/Bal. **6** mmD.O.A. **30/06/17**D.O.I. **11/07/17**

Survey held at

Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 NOV 2019

[Signature]
 27/11/2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **6**1) *[Signature]* Typist☒ : Final ReportResurvey No. of Trip: **1**

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: **TP**Lump Sum / I.B. (\$) **2749.43****220****220**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019 Sendback Est	02 Jul 2019 17:49 S\$3,104.54	04 Jul 2019 09:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	N/A, ID: N/A								
Main Claimant:	GOH JOW SHYAN MATTHEW, ID: S7720494F								
Vehicle Reg. No.:	SKW4897B	Date of Loss:	30/06/2019 11:00 - :59 [44 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203086-(PRS) CHONGBS	Policy/Cover Note No.:	DMCVSN18172119011 Coverage: 28/05/2019 - 27/05/2020						
Vehicle Reg. No. (Insured):	GBH4341Z	Policy No. (Claimant):	DMPCSN3102241802						
		Excess:	S\$0.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chee So Chow - 6389 6176]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/07/2019]								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 27 November 2019 10:28 AM
To: Sharon Sng
Subject: RE: SKW4897B - FINALISE & BEFORE PAINT/ITEMS

Dear Sharon,

Confirm final figure at \$2,749.43, 6days.

Please submit your documents directly to China Taiping

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Tuesday, 26 November 2019 3:55 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: FW: SKW4897B - FINALISE & BEFORE PAINT/ITEMS

From: Sharon Sng
Sent: Monday, November 18, 2019 4:40 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: SKW4897B - FINALISE & BEFORE PAINT/ITEMS

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/07/2019 09:57
Date Of Accident	30/06/2019 11:30
Exact Location Of Accident	AYE(CITY) NEAR CLEMENTI AVE 2 EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKW4897B
Insured/Policyholder	
Name Of Registered Owner	GOH JOW SHYAN MATTHEW
NRIC No	S7720494F
Email Address	MATTHEWGJS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98389947
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3102241802
Cover Note Number	
Driver	
Name of Driver	GOH JOW SHYAN MATTHEW
NRIC No	S7720494F
Date Of Birth	22/07/1977
Occupation	INDOOR
Date Of Driving Pass	02/08/1996
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	+65-98389947
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	MATTHEWGJS@GMAIL.COM

Address	677B JURONG WEST ST64 #06-301
Postcode	642677
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : ADMOND TAN GENDER: : MALE
Passenger 2	NAME: : SEM CHI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 30/06/2019 AT AROUND 1130HRS, I AS TRAVELLING ALONG AYE TOWARDS CITY DIRECTION. WHILE DRIVING NEAR THE EXIT OF CLEMENTI AVE 2, THE TRAFFIC IS SLOW AS THERE IS ROADWORK AHEAD BUT WHEN I SLOW DOWN TO MAKE STOP OF MY VEHICLE AS IN FRONT VEHICLE HAD STOP. SUDDENLY I FELT AN IMPACT ON MY REAR THEN I WENT DOWN TO CHECK AND FOUND THAT VEHICLE B HAD HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH4341Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMAD FAHMI BIN ZAHARI
NRIC/Passport Number	S9742529I
Contact Number	87523972



Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN

Hand-drawn sketch plan on grid paper showing a road layout. A vertical road is labeled 'Ave (city) near Clement Ave 2 Int.' with two boxes labeled 'A' and 'B' indicating specific locations. To the right, two circled numbers are written: '④ SW4897B.' and '⑤ AB143412.'

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Accident Circumstances.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☐ Claim own policy
☒ Claim third party
☐ Claim OD / TP at other works hop
☐ For record purpose
Policy No. DMCP3102241802
Insurer China Veh.No. SW4897B

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0494F
Vehicle Details	
Vehicle No.:	SKW4897B
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B4023583
Chassis No.:	RU11103588
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,047.00
Original Registration Date:	30 Oct 2015
First Registration Date:	30 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$9,047.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2025
PARF Rebate Amount:	\$6,785.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$35,026.00
Total Rebate Amount:	\$41,811.00

The information contained herein is correct as at 01 Jul 2019

OK

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
Assessment number: SKW4897B-TP-CHINA
Version: 1810
Date calculated: 02/07/2019 5:39 PM

Full Report
Registration: SKW4897B
Printed: 02/07/2019 5:39 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	30/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL/HR-V RU1/5
Sub Model:	BASE MODEL
Model Sheet Number:	35 VE 01
Registration:	SKW4897B

VIN number:

Odometer:

Model Specs

FROM MODEL 2015	REARVIEW CAMERA	REAR PARKING SYSTEM	1496CCM 97KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SKW4897B-TP-CHINA
 Version: 1810
 Date calculated: 02/07/2019 5:39 PM

Full Report
 Registration: SKW4897B
 Printed: 02/07/2019 5:39 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
7141A0	R + R LEFT OUTER TAILLAMP		1.0	4.20
8131A8	R + R LEFT REAR WHEELHOUSE SHELL		3.0	12.60
7141A5	R + R RIGHT OUTER TAILLAMP		1.0	4.20
8131A9	R + R RIGHT REAR WHEELHOUSE SHELL		3.0	12.60
8111A5 ZAX	RENEW REAR BUMPER		8.0	33.60
	INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.			
823100 ZAX	RENEW TAILGATE		33.0	138.60
	INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
8231C2)	R + R MANUFACTURER BADGE		1.0	4.20
NO NUMBER	RENEW REAR PANEL		42.0	176.40
8571C8)	R + R L/R SIDE PANEL TRIM		2.0	8.40
8571C9)	R + R R/R SIDE PANEL TRIM		2.0	8.40

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SKW4897B-TP-CHINA
 Version: 1810
 Date calculated: 02/07/2019 5:39 PM

Full Report
 Registration: SKW4897B
 Printed: 02/07/2019 5:39 PM

Code	Description	WU	Price SGD
NO NUMBER	CALIBRATE CAMERA	6.0	25.20
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	10.20	102.0
	Total of Labour		428.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR PANEL NEW PART PAINTING	19.0
	L/R INN PARKING SENS NEW PART PAINT K1R	3.0
	R/R INN PARKING SENS NEW PART PAINT K1R	3.0
	L/R BUMPER CORNER SURFACE PAINT PLAST.	4.0
	R/R BUMPER CORNER SURFACE PAINT PLAST.	4.0
	BOOTLID/TAILGATE SURFACE PAINT	9.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	20.90
2671	L/R INN PARKING SENS NEW PART PAINT K1R	0.49
2672	R/R INN PARKING SENS NEW PART PAINT K1R	0.49
2587	L/R BUMPER CORNER SURFACE PAINT PLAST.	7.69
2588	R/R BUMPER CORNER SURFACE PAINT PLAST.	7.69
2931	BOOTLID/TAILGATE SURFACE PAINT	28.88

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		42.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	72.0	302.40

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SKW4897B-TP-CHINA

Version: 1810

Date calculated: 02/07/2019 5:39 PM

Pr

Material Cost - Paint

New Part Painting

New Part Painting - Plastic K1R

Surface-/Blend Paint

Surface Painting Plastic

Material-constant Metal Preparation

Material-constant Plastic

Total

Spare Parts

Code	Description	Part Number	Supplier
2583	REAR BUMPER	71501T8NT50	de /
2619	L/R OUT BUMPER BRKT	71598T7A000	ne /
2620	R/R OUT BUMPER BRKT	71593T7A000	ne /
2671	L/R INN PARKING SENS	39680TV0E01C5	x
2672	R/R INN PARKING SENS	39680TV0E11ZN	x
2711	REAR PANEL	66100T8NT00ZZ	? (photo) /
2931	BOOTLID/TAILGATE	68100T8NQ10ZZ	bt /
2977	BOOT/TAILGATE LOCK	74800T7AJ02	jam /
3015	MANUFACTURER BADGE	75701T5A000	ne /
3017	BADGE MODEL	75722T7WA01	x sue
3160	REAR SCREEN BOND KIT	KNGKWI2	ne x sue
3161	LWR REAR SCREEN SEAL	73226SZW000	ne /
3163	REAR SCREEN FIX SET	USE SINGLE PARTS	x
3165	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161	ne /
3167	L/R WINDOW SEAL	73254T7JH01	ne /
3168	R/R WINDOW SEAL	73214T7JH01	ne /
3170	CHECK	91502S70003	x
3171	CHECK	91501S70003	x
3173	CHECK	91536SS0J01	x
3283	L/R INNER LAMP	34155T7SA01	cm /
3284	R/R INNER LAMP	34150T7SA01	cm /
3296	R/R REFLECTOR	33505T7AJ01	x
4907	INNER TAILGATE TRIM	84431T8NT01ZA	? x sue
4985	END PANEL TRIM	84640T8NT01ZA	? x sue
4994	BOOT FLOOR PANEL CVR	84521T8NT01ZA	repair
1001	REAR END PANEL	RUBBER	? /

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings

Subtotal

Fixed Sundry Parts Price

180*+

10*+

10*+

280*+

600*+

75*+

12*+

15*+

15*+

15*+

15*+

120*+

120*+

35*+

=

1,502*+

1,502*+

100*+

=

1,602*+

0*c

180*+

40*+

60*+

=

280*+

0*c

436*8+

319*2+

111*43+

=

867*4*

0*c

1,602*+

280*+

867*43+

=

2,749*43*

10

1,850.00

100.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:
 Assessment number: SKW4897B-TP-CHINA
 Version: 1810
 Date calculated: 02/07/2019 5:39 PM

Full Report
 Registration: SKW4897B
 Printed: 02/07/2019 5:39 PM

Total **1,950.00**

Extras

Code	Description	Price SGD
1000	R/R BUMPER REVERSE SENSOR	180.00*
1002	RR WINDSCREEN SEALANT	40.00*
1003	ANTI RUST COATING -	100.00*
	Total Extras	320.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	1,850.00	1502
Total Parts	100.00	1,950.00
Labour Time Base 10 WU/h		
Total 102.0 WU X 42.00 SGD/h	428.40	436.80
Total of Labour		428.40
Total Of Extras		320.00
Paint Work Time Base 10 WU/h		
Labour Cost 72.0 WU X 42.00 SGD/h	302.40	319.20
Material Cost	103.74	111.43
Total Paint Including Material		406.14
Repair Cost Excludes GST		3,104.54
GST (+7.0%)		217.32
Repair Cost Included GST		3,321.86

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: SKW4897B-TP-CHINA
Date calculated: 18/11/2019 4:36 PM

Full Report
Registration: SKW4897B
Printed: 18/11/2019 4:36 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SNG AH TEE	Currency:	SGD
Claim Reference:		Date of Incident:	30/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL/HR-V RU1/5
Sub Model:	BASE MODEL
Model Sheet Number:	35 VE 01
Registration:	SKW4897B
VIN number:	
Odometer:	

Model Specs

FROM MODEL 2015	REARVIEW CAMERA	REAR PARKING SYSTEM	1496CCM 97KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Code	Description	WU	Price SGD
7141A0	R + R LEFT OUTER TAILLAMP	1.0	4.20
8131A8	R + R LEFT REAR WHEELHOUSE SHELL	3.0	12.60
7141A5	R + R RIGHT OUTER TAILLAMP	1.0	4.20
8131A9	R + R RIGHT REAR WHEELHOUSE SHELL	3.0	12.60
8111A5 ZAX	RENEW REAR BUMPER INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.	8.0	33.60
823100 ZAX	RENEW TAILGATE INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	33.0	138.60
8231C2)	R + R MANUFACTURER BADGE	1.0	4.20
NO NUMBER	RENEW REAR PANEL	42.0	176.40
8131B2	R + R LOWER COVER	2.0	8.40
8571C8)	R + R L/R SIDE PANEL TRIM	2.0	8.40
8571C9)	R + R R/R SIDE PANEL TRIM	2.0	8.40
NO NUMBER	CALIBRATE CAMERA	6.0	25.20
Labour Cost		Hrs	WU
Panel / Mechanical Labour		10.40	104.0
Total of Labour			436.80

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR PANEL NEW PART PAINTING	19.0	
	L/R INN PARKING SENS NEW PART PAINT K1R	3.0	
	R/R INN PARKING SENS NEW PART PAINT K1R	3.0	
	L/R BUMPER CORNER SURFACE PAINT PLAST.	4.0	
	R/R BUMPER CORNER SURFACE PAINT PLAST.	4.0	
	TAILGATE TRIM SURFACE PAINT PLAST.	4.0	
	BOOTLID/TAILGATE SURFACE PAINT	9.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	20.90
2671	L/R INN PARKING SENS NEW PART PAINT K1R	0.49
2672	R/R INN PARKING SENS NEW PART PAINT K1R	0.49
2587	L/R BUMPER CORNER SURFACE PAINT PLAST.	7.69
2588	R/R BUMPER CORNER SURFACE PAINT PLAST.	7.69
2593	TAILGATE TRIM SURFACE PAINT PLAST.	7.69
2931	BOOTLID/TAILGATE SURFACE PAINT	28.88

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			46.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	7.60	76.0	319.20

Material Cost - Paint				Price SGD
New Part Painting				20.90
New Part Painting - Plastic K1R				0.98
Surface-/Blend Paint				28.88
Surface Painting Plastic				23.07
Material-constant Metal Preparation				28.60
Material-constant Plastic				9.00
Total				111.43

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	71501T8NT50		180.00
2619	L/R OUT BUMPER BRKT	71598T7A000		10.00
2620	R/R OUT BUMPER BRKT	71593T7A000		10.00
2671	L/R INN PARKING SENS	39680TV0E01C5		0.00
2672	R/R INN PARKING SENS	39680TV0E11ZN		0.00
2711	REAR PANEL	66100T8NT00ZZ		280.00
2931	BOOTLID/TAILGATE	68100T8NQ10ZZ		600.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02		75.00
3015	MANUFACTURER BADGE	75701T5A000		12.00
3160	REAR SCREEN BOND KIT	KNGKWI2		0.00
3161	LWR REAR SCREEN SEAL	73226SZW000		15.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3165	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161		15.00
3167	L/R WINDOW SEAL	73254T7JH01		15.00
3168	R/R WINDOW SEAL	73214T7JH01		15.00
3170	CHECK	91502S70003		0.00
3171	CHECK	91501S70003		0.00
3173	CHECK	91536SS0J01		0.00
3283	L/R INNER LAMP	34155T7SA01		120.00
3284	R/R INNER LAMP	34150T7SA01		120.00
4985	END PANEL TRIM	84640T8NT01ZA		35.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	1,502.00
u: Used parts	Fixed Sundry Parts Price	100.00
	Total	1,602.00

Extras

Code	Description	Price SGD
1000	R/R BUMPER REVERSE SENSOR	180.00*
1002	RR WINDSCREEN SEALANT	40.00*
1003	ANTI RUST COATING -	60.00*

Code	Description	Price SGD
	Total Extras	280.00

Final Calculation

	SGD	SGD
Parts	1,502.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,602.00
Labour Time Base 10 WU/h		
Total 104.0 WU X 42.00 SGD/h	436.80	
Total of Labour		436.80
Total Of Extras		280.00
Paint Work Time Base 10 WU/h		
Labour Cost 76.0 WU X 42.00 SGD/h	319.20	
Material Cost	111.43	
Total Paint Including Material		430.63
Repair Cost Excludes GST		2,749.43
GST (+7.0%)		192.46
Repair Cost Included GST		2,941.89

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019 Sendback Est	02 Jul 2019 17:49 S\$3,104.54	04 Jul 2019 09:09 Edit Adj Rpt	S\$2,749.43 Edit Estimates	S\$2,749.43 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: N/A , ID: N/A									
Main Claimant: GOH JOW SHYAN MATTHEW , ID: S7720494F									
Vehicle Reg. No.: SKW4897B		Date of Loss: 30/06/2019 11:00 - :59 [44 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D203086-(PRS)CHONGBS		Policy/Cover Note No.: DMCVSN18172119011 Coverage: 28/05/2019 - 27/05/2020							
Vehicle Reg. No. (Insured): GBH4341Z		Policy No. (Claimant): DMPCSN3102241802							
		Excess: S\$0.00							
Repairer: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chee So Chow - 6389 6176]									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKW4897B (SNM19D203086-(PRS)CHONGBS)
[GBH4341Z]

TP





























GOH JOW SHYAN MATTHEW

Jun 30 2019 11:00AM
















[N/A]














Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	01/07/19 15:07	Accident Statement	Load HTM	
2	01/07/19 15:29	Addendum Sheet	Load TIF	
3	01/07/19 15:29	Accident Statement Addm. #1	Load HTM	
4	02/07/19 17:49	Repairer Estimates	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
17	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
18	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
19	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
20	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
21	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
22	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
23	01/07/19 15:26	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/19 11:15	General View	Load JPG	<input checked="" type="checkbox"/>
2	27/11/19 11:15	General View	Load JPG	<input checked="" type="checkbox"/>
3	27/11/19 11:15	General View	Load JPG	<input checked="" type="checkbox"/>
4	27/11/19 11:15	General View	Load JPG	<input checked="" type="checkbox"/>
5	27/11/19 11:15	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
6	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/11/19 11:15	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	27/11/19 11:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	01/07/19 15:27	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	01/07/19 15:27	CI,IC,DL [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	01/07/19 15:07	Accident Statement	 Load HTM	
2	01/07/19 15:29	Addendum Sheet	 Load TIF	
3	01/07/19 15:29	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	01/07/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	01/07/19 15:26	Accident Photo	 Load JPG	

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print	
						<input checked="" type="checkbox"/>
13	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
14	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
15	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
16	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
17	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
18	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
19	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
20	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
21	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
22	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
23	01/07/19 15:26	Accident Photo		Load JPG		<input checked="" type="checkbox"/>
Documentation					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print	
1	01/07/19 15:27	Sketch Plan		Load TIF		
2	01/07/19 15:27	CI,IC,DL		Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011830/R1TD3E2

Date: 05/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18172119011		
Claimant Vehicle No :	SKW4897B	Insured Vehicle No :	GBH4341Z		
Date of Loss:	30/06/2019	Nature of Claim:	TP	Claim No:	SNM19D203086-(PRS) CHONGBS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW4897B		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4023583
Reg. Date:	30/10/2015 (Man. Year: 2015)	Chassis No:	RU11103588
Colour:	Grey	Odometer:	50881 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,950.00	1,602.00	348.00	17.85
Miscellaneous Items	320.00	280.00	40.00	12.50
Paintwork Materials	103.74	111.43	-7.69	-7.41
Labour	428.40	436.80	-8.40	-1.96
Paintwork Labour	302.40	319.20	-16.80	-5.56
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,104.54	2,749.43	355.11	11.44
+ GST 7.00/7.00% (S\$)	217.32	192.46	24.86	11.44
Nett Amount (S\$)	3,321.86	2,941.89	379.97	11.44

INSPECTION

Date of Assignment:	04/07/2019 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	11/07/2019 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW4897B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		1,950.00 F	*1,602.00 F
F=Franchise part.						
				Total Parts (S\$)	1,950.00	1,602.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	TOTAL PAINT / MATERIAL	103.74	111.43
<u>Miscellaneous Items</u>				
2	1	SPARE PARTS SPECIAL NETT	320.00	280.00
Sub Total (S\$)			423.74	391.43

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK	New	302.40	319.20
<u>Labour Items</u>				
2	TOTAL PANEL / MECHANICAL	New	428.40	436.80
Gross Labour Cost (S\$)			730.80	756.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North,
#01-18,
628457

Claim Reference:

Assessment number: SKW4897B-TP-CHINA

Version: 1810

Date calculated: 02/07/2019 5:39 PM

Full Report

Registration: SKW4897B

Printed: 02/07/2019 5:39 PM

Material Cost - Paint

New Part Painting	Price SGD
New Part Painting - Plastic K1R	20.90
Surface-/Blend Paint	0.98
Surface Painting Plastic	28.88
Material-constant Metal Preparation	15.38
Material-constant Plastic	28.60
Total	9.00
	103.74

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	71501T8NT50	de /	✓ 180.00
2619	L/R OUT BUMPER BRKT	71598T7A000	ne /	✓ 10.00
2620	R/R OUT BUMPER BRKT	71593T7A000	ne /	✓ 10.00
2671	L/R INN PARKING SENS	39680TV0E01C5	x	0.00
2672	R/R INN PARKING SENS	39680TV0E11ZN	x	0.00
2711	REAR PANEL	66100T8NT00ZZ	? (photo) / bt -	✓ 280.00
2931	BOOTLID/TAILGATE	68100T8NQ10ZZ	bt -	✓ 600.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02	jam	✓ 75.00
3015	MANUFACTURER BADGE	75701T5A000	ne /	✓ 12.00
3017	BADGE MODEL	75722T7WA01	x sue	✓ 28.00
3160	REAR SCREEN BOND KIT	KNGKWI2	ne xnn	✓ 0.00
3161	LWR REAR SCREEN SEAL	73226SZW000	ne /	✓ 15.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS	x	
3165	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161	ne /	✓ 15.00
3167	L/R WINDOW SEAL	73254T7JH01	ne /	✓ 15.00
3168	R/R WINDOW SEAL	73214T7JH01	ne /	✓ 15.00
3170	CHECK	91502S70003	x	0.00
3171	CHECK	91501S70003	x	0.00
3173	CHECK	91536SS0J01	x	0.00
3283	L/R INNER LAMP	34155T7SA01	crn /	✓ 120.00
3284	R/R INNER LAMP	34150T7SA01	crn /	✓ 120.00
3296	R/R REFLECTOR	33505T7AJ01	x	✓ 35.00
4907	INNER TAILGATE TRIM	84431T8NT01ZA	? x sue	✓ 110.00
4985	END PANEL TRIM	84640T8NT01ZA	? x sue	✓ 35.00
4994	BOOT FLOOR PANEL CVR	84521T8NT01ZA	repair	✓ 130.00
1001	REAR END PANEL	RUBBER	? /	45.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,850.00
u: Used parts	Fixed Sundry Parts Price			100.00