

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SCG 0100 Y

S/N	Nature of Jobs		Estimated Charges	Surveyor's Reccomendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and healight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$	2,450.00	\$ 1,000.00
3	To respray front bumper and rhs front fender.	\$	2,000.00	\$ 1,100.00
4	To renew rhs front rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,282.00</u>	<u>\$ 2,932.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCG 100 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 35.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - RH	\$ 270.00	
5	FRONT BUMPER COVER TRIM - RH	\$ 148.00	
6	FRONT BUMPER ADAPTER - RH	\$ 34.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 171.00	
8	FRONT FENDER - RH	\$ 778.00	\$ 622.00
9	FRONT FENDER RIVET	5 \$ 15.00	\$ 12.00
10	FRONT FENDER ATTACHMENT PARTS	\$ 65.00	
11	FRONT FENDER BRACKET - RH	\$ 35.00	
12	FRONT FENDER BRACE - RH	\$ 88.00	\$ 69.84
13	FRONT WHEEL HOUSING LINER - RH	\$ 158.00	
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 81.00	
15	FRONT HEADLIGHT - RH	\$ 5,029.00	
16	ALUMINIUM RIM	\$ 666.00	\$ 532.40
17	RUBBER VALVE	4 \$ 13.00	
18	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 10,374.00	\$ 2,700.24
TOTAL LABOUR CHARGES		\$ 5,282.00	\$ 2,932.00
GRAND TOTAL		\$ 15,656.00	\$ 5,632.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SCG 100 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0815/2019/KK

17 Sep 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SCG 100 Y, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SCG 100 Y**, claimant, **Mr Aw Ming Zhe, Alvin**, please find the related document per attached.

1. A copy of the Original invoice no. 85014251 – S\$ 5,384.50.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SCG 100 Y

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 1183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9628 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:58

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014251	Account: A0006 (T 0)		
		Date : 16/09/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
		Order : SCG0100Y			
		Term : 30			
Regn No: SCG0100Y (V 40863)		Regn Date: 27/12/2018	Mileage: 11367	WIP No.: 58748	
Model: A3 SEDAN 1.0 TFSI 8VMANG		Chassis: WAUZZZ8V0K1012760	Engine: CHZ C25985	Dept: U	
You have been assisted by :- UB-Tony Foong (33)					
		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888	-600.00	1.00	-600.00
S	BODYWORK	Insurance Excess/Liability M:	360.00	1.00	360.00
S	BODYWORK	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY M:	1000.00	1.00	1,000.00
S	BODYWORK	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED M:	1100.00	1.00	1,100.00
S	BODYWORK	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER M:	280.00	1.00	280.00
S	BODYWORK	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT M:	192.00	1.00	192.00
X	A8V5821106A	TO CARRY OUT DIAGNOSTIC CHECK			
X	A8V5807065R GRU	FENDER Less 020%	1.00	777.50	622.00
X	A8V0601025DC	COVER Less 020%	1.00	1830.00	1,464.00
X	A8V0821136A	(A) (SK) RIM 16" C4E 1 Less 020%	1.00	665.50	532.40
X	AN 0161857	SUPPORT Less 020%	1.00	87.30	69.84
		POP-RIVET Less 020%	5.00	3.00	12.00
Parts 2,700.24		Sub-Total		5,032.24	
Labour 0.00		7% GST		352.26	
Sublet 2,932.00		Grand Total		5,384.50	
Menus 0.00					
Lubricant 0.00					



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SCG 100 Y

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0815/2019/EH
1ST Aug 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A3 Sedan 1.0 TSFI
Vehicle Chassis No. : WAUZZZ8V0K1012760
Vehicle Regn No. : **SCG 100 Y**
Vehicle Mileage : 11367KM
Vehicle Owner : Mr. Aw Ming Zhe, Alvin
Certificate No : 1900009652
Own Damage Excess : \$642.00 (Including 7% GST)
Accident Date : 28/06/2019
Place : Along 70 Shrewsbury Road
Repair Cost : \$ 5,384.50
WIP No. : 58748
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


09.30am
3/8/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2019		04 Jul 2019 13:39 Edit Adj Rpt	S\$5,632.24 Edit Estimates	S\$5,632.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **AW MING ZHE, ALVIN**, ID: S8847865G

Vehicle Reg. No.: **SCG100Y**

Claim Type: **OD / 8450551692SG**

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Chan, Yoke Shi**] yokeshi.chan@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 15/07/2019]**

Driver/Custodian: LIM SO CHENG (66 / Female) , NRIC: S0145337H, Tel: +6597982558 Email: PEGGYLIMSC@GMAIL.COM

[Created by insurer]

Date of Loss: 28/06/2019 00:00 - :59
[6 Months and 1 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.: 1900009652 (Comprehensive)

Excess: S\$600.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (04/07/2019): **SCG100Y / OD / 28/06/2019 / Coverage & Excess update**

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCG100Y (8450551692SG)

OD

Jun 28 2019 12:00AM

[AW MING ZHE, ALVIN]

Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/07/19 14:56	General View		Load JPG	
2	04/07/19 14:56	General View		Load JPG	
3	04/07/19 14:56	General View		Load JPG	
4	04/07/19 14:56	General View		Load JPG	
5	04/07/19 14:56	General View		Load JPG	
6	04/07/19 14:56	General View		Load JPG	
7	04/07/19 14:56	General View		Load JPG	
8	04/07/19 14:56	General View		Load JPG	
9	04/07/19 14:56	General View		Load JPG	
10	04/07/19 14:56	General View		Load JPG	
11	04/07/19 14:56	General View		Load JPG	
12	04/07/19 14:56	General View		Load JPG	
13	04/07/19 14:56	General View		Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/07/19 10:40	DL AND CI		Load PDF	
2	24/09/19 10:53	DISCHARGE VOUCHER		Load PDF	
3	24/09/19 10:53	WORKSHOP INVOICE		Load PDF	

Linked Accident Report Documents

					View		View In Browser ▾	
Assessment Reports					1 per page ▾		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)				Thumbnail	Print	
1	29/06/19 10:20	Accident Statement				Load HTM		
2	29/06/19 10:40	Addendum Sheet				Load JPG	☒	
3	29/06/19 10:41	Accident Statement Addm. #1				Load HTM		
Photos/Images					3 per page ▾		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)				Thumbnail	Print	
1	29/06/19 10:18	Accident Photo				Load JPG	☒	
2	29/06/19 10:18	Accident Photo				Load JPG	☒	
3	29/06/19 10:18	Accident Photo				Load JPG	☒	
4	29/06/19 10:18	Accident Photo				Load JPG	☒	
5	29/06/19 10:18	Accident Photo				Load JPG	☒	
6	29/06/19 10:18	Accident Photo				Load JPG	☒	
7	29/06/19 10:18	Accident Photo				Load JPG	☒	
8	29/06/19 10:18	Accident Photo				Load JPG	☒	
9	29/06/19 10:18	Accident Photo				Load JPG	☒	
10	29/06/19 10:18	Accident Photo				Load JPG	☒	
Documentation					1 per page ▾		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)				Thumbnail	Print	

Assessment Reports			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/06/19 10:16	Sketch Plan	 Load JPG	✓
2	29/06/19 10:16	Sketch Plan #2	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19011838/ATD3S2

Date: 24/09/2019

REFERENCE

Insured/Claimant:	AW MING ZHE, ALVIN	Policy No:	1900009652	
Date of Loss:	28/06/2019	Nature of Claim:	OD	Claim No: 8450551692SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCG100Y		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZC25985
Reg. Date:	27/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V0K1012760
Colour:	Red	Odometer:	9919 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,374.00	2,700.24	7,673.76	73.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	2,932.00	2,350.00	44.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,656.00	5,632.24	10,023.76	64.03
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	15,056.00	5,032.24	10,023.76	66.58
+ GST 7.00/7.00% (S\$)	1,053.92	352.26	701.66	66.58
Nett Amount (S\$)	16,109.92	5,384.50	10,725.42	66.58

INSPECTION

Date of Assignment:	04/07/2019		
Date Inspected:	03/07/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	35.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	488.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	270.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM - RH	Not Necessary	148.00 FS	*- FS
7	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	34.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	171.00 FS	*- FS
9	1		*FRONT FENDER - RH	Dented	778.00 FS	*622.00 FS
10	5		*FRONT FENDER RIVET	Necessary	15.00 FS	*12.00 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
12	1		*FRONT FENDER BRACKET - RH	Not Necessary	35.00 FS	*- FS
13	1		*FRONT FENDER BRACE - RH	Bent	88.00 FS	*69.84 FS
14	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	158.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
16	1		*FRONT HEADLIGHT - RH	Not Necessary	5,029.00 FS	*- FS
17	1		*ALUMINIUM RIM	Cut	666.00 FS	*532.40 FS
18	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **10,374.00** **2,700.24**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,450.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	New	2,000.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			5,282.00	2,932.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >