新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20 Singapore 159761

Tel: 6278 2482 Fax: 6271 9802 Email: sinhuplee@gmail.com Reg. No. 083995/00E

1 July 2019

Attn: Motor Claim Department AIG Asia Pacific Insurance Pte. Ltd AIG Building 78 Shenton Way #07-16 Singapore 079120

Lim Puay Tiang c/o Sin Hup Lee Service Co. Block 1005 Bukit Merah Lane 2 #01-20 Singapore 159761

Dear Sir/Ms,

Re: Road Traffic Accident on 21 June 2019 at 20 Marlene Avenue, involving vehicle EE747T / SMF1410H

Quotation for Repair Vehicle No: SMF1410H, Honda Civic (Third Party Claim)

Quai	ntity	List Item					
	1	Front Grille		1	,	· Ś	173.80 000
	1	Front Grille Logo				\$	36.70 per
	1	Front Grille Chrome				Ś	247.40 Cres
	1	Front Grille Garnish			ř.	Ś	149.30 cm
	1	Front Grille Top Cover			,	Ś	38.20 de
1	10	Front Grille Clip				\$	39.00 nei
	2	Head Lamp LH + PH				LH-cra/s	1,171.40 RH-X
	1	Head Lamp Chrome LH	1			\$	195.60 Cut
	1	Head Lamp Lower Bracket LH +RH				\$	de ~ 38.80 77.60
	1 .	Head Lamp Clip				. \$	3.50 ner
	1	Support Side Garnish LH galle.				\$	59.70 de
	1	Front Bumper	Carl Coll			\$	597.90 de/
	1	Front Bumper Garnish				\$	96.30

1	Front Bumper Reinforcement		\$	345.90 ≺
1 .	Front Bumper Bracket LH		\$	38.90 M
1	Front Bumper Side Bracket LH		\$	29.40 10
1	Front Bumper Side Garnish LH		\$	57.50 at
1	Front Bumper Lower Grille		\$	72.40 ×
10	Front Bumper Clip		\$	39.00 per
		-	\$	3,430.70
	the state of the s	Less 20%	\$	686.14
			\$	2,744.56
	S/NETT ITEM			45 bt/
1	Front No Plate	and the second second	\$	50,00
	4,			
	Labour			. 300
1	To cut-weld and repair Front Fender LH, Bonnet, Support		\$	500.00
	Panel and re-fix damaged parts, straighten and realign			
	affected areas.			
	the property of the second			400.
2	To spray Bonnet, Front Fender LH, Support Panel, Front		\$	680.00
	Bumper and affected area		* *	
				100.
3	To programme and focus Head Lamp for function		\$	180.00
	Francisco and local field samp for failed in		*	
		Total	\$	A 15A 56
		Amount	Þ	4,154.56
		-		

Kindly arrange your surveyor to survey my vehicle. We look forward to hear from you soon. Thank you.

Yours Faithfully Mr Wong 81122116

LKK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Date: WP'
3/7/190 1045
Lumpsum
Resury after repoir
taufilme Ilhantonon
3 days.