

22/03/2012

ASS. REC. BY:

REF: CS/C71 19 011846/000372

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Ong Chin Bait of C71 Date/Time: 4.7.19 14.18pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: GQ 787BR Insured: GBG 9965X

at Workshop m/s Automobile Hub Enterprise Tel: 97864483

of 1 Kaki Bukit Ave 5 #2-11

Policy No: DMCVSN 4713518011 Claim No: SNM 19D 20204002

Sum Insured: Excess:

Make of Veh: D.O.A. 1.7.2019
(Client's Record) myp

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.7.19 249p.m Person Contacted: Ah Siong Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GQ 787BR - NA / AIG 16 009854 / h4 D.O.A - 28/06/2016
	GBG 9965X - NA / C71 19006984 / Y D.O.A - 12/04/2019

(08/11/13) wef

ASS. REC. BY: *M. J. S.*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

3000

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

3 Val.: Yes or No

0387W

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn:

c.c

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Rear

R/Bal.

L/Bal.

D.O.I.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

RECEIVED 12 JUL 2019

11/7/19 4/5 \$5000 confirmed with AH X-ray (Ref 16, 219, 769)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019		04 Jul 2019 14:18 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by insurer]	
Insured:		TURNON ENGINEERING PTE LTD, Co. Reg. No.: 199906608H							
Main Claimant:		POMEX PTE LTD, Co. Reg. No.: 199900387W							
Vehicle Reg. No.:		GQ7878R				Date of Loss:		01/07/2019 14:00 - :59 [64 Months and 6 Days From LTA Reg Date (Man Yr)]	
Claim Type:		TP / SNM19D202040C02				Policy/Cover Note No.:		DMCVSN17713518011 (Comprehensive)	
Vehicle Reg. No. (Insured):		GBG9965X				Policy No. (Claimant):			
						Excess:		\$50.00	
Repairer:		Automobile Hub Enterprise () 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/07/2019]							
Adj Asg. Remarks:		please assign Mr Marcus Chua for SJE. thank you							
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SGCARMART.COM

Login Sign up

[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Articles](#)
[Forum](#)
[Resources](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Honda Civic 1.8.



Well Maintained And
Appreciated By Owner.
Direct Owner StarAd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SYTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category Sort by Date Posted 20 results/page

15 vehicles

toyota dyna

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota dyna		Any	Any	2014	Any	Any	Any	Available
	Toyota Dyna	150 3.0M	\$44,000	\$8,140 /yr	28-Nov-2014	2,982 cc	153,500 km	Truck	Available
Fuel Type: Diesel First Hand Owner. The Vehicle Is Used Only For Transportation Of Dry Goods. Clean And No Odour. Slight Bump On The Front. No Othe...									
Posted: 05-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$38,800	\$7,420 /yr	26-Sep-2014	2,982 cc	103,109 km	Truck	Available
Fuel Type: Diesel Best Selling Brand In Town, Road Tax Until 09/19, New Paint, 100% Loan Available, High Trade In Available. Call Our Sales Consultant F...									
ABWIN (1994) Pte Ltd									
Posted: 05-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$38,200	\$7,340 /yr	16-Sep-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel One Owner.Vehicle In Showroom Condition, No Repair Needed, Low Down Payment, Flexible Loan Plan Available.;									
Posted: 04-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$37,800	\$7,100 /yr	30-Oct-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel This 10 Ft Lorry Need No Introduction. Most Sought In The Market. Previous Owner Selling Due To Vehicle Under Utilize. Monthly Only \$...									
ABWIN Bus Pte Ltd									
Posted: 02-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	A Maximum of Power and Longevity Powerful sound! Excellent condition, enquiries welcome at 92777497 Find out more!								
	Toyota Dyna	150 3.0M	\$41,800	\$7,860 /yr	27-Oct-2014	2,982 cc	82,245 km	Truck	Available
Fuel Type: Diesel Under Utilised Lorry For Sale! Toyota Barneo Agent Full Service Records. Smooth Manual Transmission, No Further Repairs Needed. Gre...									
Ezy-1 Pte Ltd									
Posted: 02-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$40,800	\$7,550 /yr	28-Nov-2014	2,982 cc	118,000 km	Truck	Available
Fuel Type: Diesel 1 Owner Only! Well Maintained, Excellent Condition! In House Loan Available. Call For More Enquiries!;									
Posted: 02-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$41,800	\$7,850 /yr	30-Oct-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel Free Insurance!Most Popular 10 Feet Commercial Vehicles In The Market. 1 Owner With. Tip Top Condition. We Do 100% Loan And Driv...									
Qife Auto Pte Ltd									
Posted: 01-Jul-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M	\$38,800	\$7,680 /yr	23-Jul-2014	2,982 cc	-	Truck	Available
Fuel Type: Diesel									

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0387W
Vehicle Details	
Vehicle No.:	GQ7878R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2367848
Chassis No.:	JTFAT35Y10K202773
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	25 Feb 2014
First Registration Date:	25 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,287.00
COE Rebate Amount:	\$14,974.00
Total Rebate Amount:	\$14,974.00

The information contained herein is correct as at 05 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/07/2019 18:00
Date Of Accident 01/07/2019 14:45
Exact Location Of Accident KAKI BUKIT AVE 3
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GQ7878R
Name Of Registered Owner POMEX PTE LTD
Co Reg No 199900387W
Email Address INFO@POMEX.COM.SG
Mobile Phone No (LOCAL) +65-96333143
Alternative Phone No OFFICE-96333143

Manufacturer TOYOTA
Model DYNA
Exact Purpose for which vehicle was being used at time of accident WORK USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number VCA/P2081228
Cover Note Number

Name of Driver LIM TIONG HAI
NRIC No S1331537Z
Date Of Birth 03/05/1958
Occupation INDOOR
Date Of Driving Pass 16/08/1977
Driving Experience 41 YEARS AND 10 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96333143
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 404B FERNVALE LANE #14-143
Postcode 792404
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (including Driver) 1

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 60 HOUGANG AVE 9, POSTCODE: 538775, COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED


Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG9965X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

Notes to police report:

DISCUSSION

www.dunlop-tyres.com



1998

Author's Address: Department of Psychology, University of Illinois at Chicago, Chicago, IL 60607-7131, USA.
E-mail: shawn@uic.edu


Repair Estimate

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Make/Model: TOYOTA DYNA
Engine/Chassis No.: JTFAT35Y10K202773
Date of accident:
Damaged area: Rear

Date: 02/07/2019
Claim Type: TP
VRN: GQ7878R



U/S @ 5000/-
6 day.
not Allowed
5/7/19
Zuhair Attorneys

List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tail gate 1888.50 body rd	1	\$ 1,997.00	\$ 1,997.00	
2	Tail gate hinge 11	4	\$ 68.00	\$ 272.00	X
3	Tail gate stopper N/S 70.00	2	\$ 63.00	\$ 126.00	100
4	Tail gate stopper bracket 300	2	\$ 153.00	\$ 306.00	
5	Tail gate lower panel 300	1	\$ 958.00	\$ 958.00	
6	Tail lamp panel 265x22530 200	2	\$ 383.00	\$ 766.00	
7	Tail lamp 320.10x22640.20 200	2	\$ 373.00	\$ 746.00	
8	Rear licence plate lamp 11	2	\$ 77.00	\$ 154.00	X
9	Side gate 2	2	\$ 2,216.00	\$ 4,432.00	X
10	Side gate lock 300	2	\$ 186.00	\$ 372.00	
11	Rear spare tyre carrier 11	1	\$ 486.00	\$ 486.00	X
12	Tail gate hinge pin 11	4	\$ 134.00	\$ 536.00	X
13	Tail gate lock 200	2	\$ 276.00	\$ 552.00	X
14	Tail gate lower member 200	1	\$ 1,714.00	\$ 1,714.00	X
15	Tail gate lower member hook 200	2	\$ 158.00	\$ 316.00	X
16	Exhaust silencer 2	1	\$ 782.00	\$ 782.00	X
17	Exhaust hanger 11	1	\$ 66.00	\$ 66.00	X
18	Rear floor panel 200	1	\$ 1,487.00	\$ 1,487.00	X
19	Side gate hinge pin 11	12	\$ 153.00	\$ 1,836.00	X
20	Rear licence plate base panel 185 300	1	\$ 270.00	\$ 270.00	
21	Rear tailgate "Toyota" sticker 200	1	\$ 150.00	\$ 150.00	
Subtotal				\$ 18,324.00	
List discount				25.00%	
Total				\$ 13,743.00	

5092.70
25%
3819.52

Nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear floor panel inner top aluminium board 200	1	\$ 1,500.00	\$ 1,500.00	X
2	Rear floor panel inner top aluminium board rivet- set 100	1	\$ 120.00	\$ 120.00	50
3	Rear number plate lamp bulb 11	2	\$ 10.00	\$ 20.00	X
4	Rear tailgate lower panel step bracket 11	2	\$ 300.00	\$ 600.00	X
Subtotal				\$ 2,240.00	
Nett discount				10.00%	
Total				\$ 2,016.00	

Repair Estimate

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear number plate <i>best</i>	1	\$ 55.00	\$	55.00
2	Rear tailgate "4 pax" sticker <i>ru</i>	1	\$ 15.00	\$	15.00
3	Rear tailgate "70km/h" sticker <i>ru</i>	1	\$ 15.00	\$	15.00
4	Rear tailgate "DYNA" sticker <i>ru</i>	1	\$ 15.00	\$	15.00
5	<i>1x4 Rear reverse sensor</i> <i>shotel</i>	<i>1/14</i>	\$ 380.00	\$	760.00
6	Sundries <i>11</i>	1	\$ 50.00	\$	50.00
Total				\$	910.00

14
10
10
✓
2005.~
X

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	<i>4</i>	\$ 1,600.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	<i>0.25</i>	\$ 50.00
3	To remove and replace, straighten and readjust exhaust pipe.	<i>0.51</i>	\$ 100.00
4	To align rear cargo frame and to conduct chassis alignment on Car-O-Liner.	<i>1</i>	\$ 1,000.00
5	Supply spray paint material and necessary items to respray tailgate, both side gates, floor panel and other affected area / panel.	<i>1</i>	\$ 1,600.00
6	To rust proof all affected portions after repair.	<i>1</i>	\$ 200.00
Total labour			\$ 4,550.00
Estimate Grand Total			\$ 21,219.00

1200
20
60
any X
880
11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19011846/UVD3N2

Date: 15/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17713518011	
Claimant Vehicle No :	GQ7878R	Insured Vehicle No :	GBG9965X	
Date of Loss:	01/07/2019	Nature of Claim:	TP	Claim No: SNM19D202040C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GQ7878R		
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Engine No:	1KD2367848
Reg. Date:	25/02/2014 (Man. Year: 2014)	Chassis No:	JTFAT35Y10K202773
Colour:	Silver	Odometer:	162454 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155R12 (D)
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,669.00	4,113.52	12,555.48	75.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	2,160.00	2,390.00	52.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,219.00	6,273.52	14,945.48	70.43
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	21,219.00	5,000.00	16,219.00	76.44

INSPECTION

Date of Assignment:	04/07/2019	
Date Inspected:	05/07/2019	Inspected At: Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Jul 2019)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GQ7878R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Badly Dented	1,997.00 FL	*1,888.50 FL
2	4		*TAIL GATE HINGE	Not Necessary	272.00 FL	*- FL
3	1		*TAIL GATE STOPPER	N/s Torn	126.00 FL	*63.00 FL
4	2		*TAIL GATE STOPPER BRACKET	Bent	306.00 FL	*306.00 FL
5	1		*TAIL GATE LOWER PANEL	Bent	958.00 FL	*958.00 FL
6	2		*TAIL LAMP PANEL	Bent	766.00 FL	*530.00 FL
7	2		*TAIL LAMP	Cracked	746.00 FL	*640.20 FL
8	2		*REAR LICENCE PLATE LAMP	Not Necessary	154.00 FL	*- FL
9	2		*SIDE GATE	Repair	4,432.00 FL	*- FL
10	2		*SIDE GATE LOCK	Bent	372.00 FL	*372.00 FL
11	1		*REAR SPARE TYRE CARRIER	Not Necessary	486.00 FL	*- FL
12	4		*TAIL GATE HINGE PIN	Not Necessary	536.00 FL	*- FL
13	2		*TAIL GATE LOCK	Repeated	552.00 FL	*- FL
14	1		*TAIL GATE LOWER MEMBER	Repeated	1,714.00 FL	*- FL
15	2		*TAIL GATE LOWER MEMBER HOOK	Not Necessary	316.00 FL	*- FL
16	1		*EXHAUST SILENCER	Repair	782.00 FL	*- FL
17	1		*EXHAUST HANGER	Not Necessary	66.00 FL	*- FL
18	1		*REAR FLOOR PANEL	Repair	1,487.00 FL	*- FL
19	12		*SIDE GATE HINGE PIN	Not Necessary	1,836.00 FL	*- FL
20	1		*REAR LICENCE PLATE BASE PANEL	Bent	270.00 FL	*185.00 FL
21	1		*REAR TAILGATE TOYOTA STICKER	Necessary	150.00 FL	*150.00 FL
22	1		*REAR FLOOR PANEL INNER TOP ALUMINIUM BOARD	Repair	1,500.00 FN	*- FN
23	1		*SET REAR FLOOR PANEL INNER TOP ALUMINIUM BOARD RIVET	Necessary	120.00 FN	*50.00 FN
24	2		*REAR NUMBER PLATE LAMP BULB	Not Necessary	20.00 FN	*- FN
25	2		*REAR TAILGATE LOWER PANEL STEP BRACKET	Not Necessary	600.00 FN	*- FN
26	1		*REAR NUMBER PLATE	Bent	55.00 FS	*14.00 FS
27	1		*REAR TAILGATE 4 PAX STICKER	Necessary	15.00 FS	*10.00 FS
28	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
29	1		*REAR TAILGATE DYNA STICKER	Necessary	15.00 FS	*15.00 FS
30	1		*SET REAR REVERSE SENSOR	Shorted	760.00 FS	*200.00 FS
31	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$) 21,474.00 5,391.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					4,581.00	1,273.18
- Nett Item Discount on N Items 10.00/10.00% (S\$)					224.00	5.00
Total Parts (S\$)					16,669.00	4,113.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,600.00	1,200.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAIL LAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE AND REPLACE,STRAIGHTEN AND READJUST EXHAUST PIPE	New	100.00	60.00
4	TO ALIGN REAR CARGO FRAME AND TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER	New	1,000.00	0.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE,BOTH SIDE GATES,FLOOR PANEL AND OTHER AFFECTED AREA/PANEL	New	1,600.00	880.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	200.00	0.00
Gross Labour Cost (\$\$)			4,550.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >