

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9360K**AAD1907-026**

Not Authored
Runny B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 JUL 2019**SHD 9360K**

JTDKB3FU403079878

TOYOTA

PRIUS

1.7.19

AXA

17/5/2019

		PART
1	1	FRONT BUMPER
2	1	BRACKET, FRONT BUMPER EXTENSION MOUNTING
3	1	COVER, FRONT BUMPER HOLE, LH
4	1	REINFORCEMENT, FRONT BUMPER
5	1	ABSORBER, FRONT BUMPER, LOWER
6	1	ABSORBER, FRONT BUMPER ENERGY
7	1	FRONT BUMPER SIDE RETAINER LH
8	1	FRONT BUMPER SUPPORT
9	1	EXTENSION, FRONT BUMPER LH
10	1	FRONT BUMPER SUPPORT
11	1	FRONT LED LAMP (LOWER) LH
12	1	FRONT HEADLAMP LH
13	1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
14	1	MOTOR, HEADLAMP LEVELING, LH
15	1	FRONT FENDER LH
16	1	EXTENSION, FRONT FENDER, LH
17	1	COVER SUB-ASSY, FRONT PILLAR, UPR LH
18	1	LINER, FRONT FENDER, LH
19	1	FRONT FENDER EMBLEM LH
20	1	SEAL, FENDER APRON MUDGUARD, LH
21	1	FRONT BONNET
22	1	FRONT LOWER ARM
23	1	SHAFT ASSY, FRONT DRIVE, LH
24	1	KNUCKLE, STEERING, LH
25	1	LINK ASSY, FRONT STABILIZER, LH
26	1	BAR, STABILIZER, FRONT
27	1	ABSORBER ASSY, SHOCK, FRONT LH
28	1	GRILLE, RADIATOR, LOWER NO.1

		LIST
\$	<i>Bu lrm</i>	499.90 ✓
\$	<i>SL</i>	101.20 X
\$	<i>SL</i>	29.00 X
\$	<i>SL</i>	696.40 X
\$	<i>SL</i>	130.20 X
\$	<i>SL</i>	78.10 X
\$	<i>SL</i>	112.70 ✓
\$	<i>SL</i>	81.70 X
\$	<i>SL</i>	117.80 X
\$	<i>SL</i>	81.70 X
\$		907.75 ?
\$	<i>SL</i>	2,909.04 ✓
\$	<i>SL</i>	492.30 X
\$	<i>SL</i>	413.10 X
\$	<i>SL</i>	945.30 X
\$	<i>SL</i>	48.80 X
\$	<i>SL</i>	98.30 X
\$	<i>SL</i>	200.70 X
\$	<i>SL</i>	86.50 ✓
\$	<i>SL</i>	50.90
\$	<i>SL</i>	950.50
\$	<i>SL</i>	631.90
\$	<i>SL</i>	1,186.20
\$	<i>SL</i>	562.30
\$	<i>SL</i>	199.00
\$	<i>SL</i>	360.30
\$	<i>SL</i>	401.80
\$	<i>SL</i>	167.90

Trans-cab Auto Services Pte Ltd

AAD1907-026

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9360K

TOTAL	\$	12,541.29
25%	\$	3,135.32
	\$	9,405.97

Special Nett

1	1	FRONT WHEEL RIM	\$	<i>pn</i>	1,570.55	X
2	1	FRONT WHEEL RIM COVER	\$	<i>pn</i>	175.80	X
3	1	CLIP, FRONT FENDER LINER	\$	<i>nn</i>	22.00	X
TOTAL			\$		1,768.35	

TOTAL PARTS	\$	11,174.32
--------------------	-----------	------------------

LABOUR

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *2cp*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 *4cp*

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *2cp*

To transfer of Front Bonnet fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1907-026

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9360K

To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na 380.00 X
TOTAL	\$	14,760.00
Over All Total	\$	25,934.32

(PART-BY-PART) Repair Days~~20 days~~

2 1/2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: