

DING AUTOMOTIVE PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

02/07/2019 18:03

JOB-NO: 50111791

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA9759K TRANS: AUTO
MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHC851CVKU164382
ENGINE: G4LEKU296066

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,100.00	0.00	1,100.00		Y	700
2 RUST PROOFING	1.00	80.00	0.00	80.00		Y	30
3 SUNDRIES	1.00	50.00	0.00	50.00		Y	30
4 R&R FRONT DOOR COMPONENTS LH	1.00	100.00	0.00	100.00		Y	60
5 R&R REAR DOOR COMPONENTS LH	1.00	100.00	0.00	100.00		Y	x nn
6 TO CALIBRATE POWER WINDOW (AUTO POSITION)	1.00	180.00	0.00	180.00		Y	180
7 DIAGNOSTIC (CLEAR FAULT CODE)	1.00	200.00	0.00	200.00		Y	100
8 RESPRAY FRONT FENDER LH	1.00	250.00	0.00	250.00		Y	200
9 RESPRAY FRONT DOOR LH	1.00	250.00	0.00	250.00		Y	200
10 RESPRAY REAR DOOR LH	1.00	250.00	0.00	250.00		Y	200
11 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	200
12 RESPRAY FRONT WINDSCREEN PILLAR LH	1.00	250.00	0.00	250.00		Y	100
TOTAL:		3,060.00	0.00	3,060.00			1900
<u>MATERIALS</u>							
1 FRONT FENDER LH	1.00	659.50	131.90	527.60	L	Y	bt
2 FRONT FENDER EMBLEM LOGO LH	1.00	36.50	7.30	29.20	L	Y	new
3 FRONT FENDER QTR GARNISH LH	1.00	65.12	13.02	52.10	L	Y	new
4 SIDE MIRROR LH	1.00	1,054.60	210.92	843.68	L	Y	Rx
5 FRONT DOOR LH	1.00	2,256.83	451.37	1,805.46	L	Y	bt
6 FRONT DOOR OUTER HANDLE LH	1.00	168.90	33.78	135.12	L	Y	new
7 FRONT DOOR OUTER MOULDING LH	1.00	87.65	17.53	70.12	L	Y	new
8 FRONT DOOR OUTER HANDLE PAD LH	1.00	20.88	4.18	16.70	L	Y	IX nn
9 REAR DOOR LH	1.00	2,201.00	440.20	1,760.80	L	Y	Rx
10 TAIL LAMP LH	1.00	903.22	180.64	722.58	L	Y	new
11 REPAIR FRONT WINDSCREEN PILLAR LH	1.00	0.00	0.00	0.00	S	Y	Rx
12 FRONT DOOR STICKER-COMFORT DELGRO LH	1.00	100.00	0.00	100.00	S	Y	new
13 REAR DOOR STICKER-COMFORT DELGRO LOGO LH	1.00	100.00	0.00	100.00	S	Y	new
14 REAR DOOR STICKER-BOOK NOW & APP STORE LH	1.00	80.00	0.00	80.00	S	Y	new
15 REPAIR REAR FENDER LH	1.00	0.00	0.00	0.00	S	Y	Rx
16 TAIL LAMP HOLD CLIP LH	1.00	15.00	0.00	15.00	S	Y	new
TOTAL:		7,749.20	490.84	6,258.36			
TOTAL PARTS & LABOUR:		10,809.20	1,490.84	9,318.36			3637.18

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
EXCESS/LOADING:\$\$		0.00					
No. Of Day:		5					
RE-SURVEY: BEFORE/AFTER PAINTING							
PART-BY-PART OR LUMP SUM: \$\$							
DATE OF SURVEY:		4 / 7 / 19		930am			
SURVEYED BY:		Tanfer					
CONTACT NO:		97445749		FAX NO:			
NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED							
DAuto002							
Ding Auto User 2							
ESTIMATOR							
STA AUTOCENTRE							
TEL: FAX:							

tanfer@khanh.com
-wp-

3637.18
1900
\$5537.18 #
5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: