



Reg No : 196700086Z
T Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1199

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/IC1111 Document No 0 Document Date 17/07/2019	Mr Palaniappan S/O Palaniappan K 277A Compassvale Link #02-316 Singapore 541277 Mobile: 91074366

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
8	MWYNKT	S3	NSP170R 08/01/2019	SMH0159E	0	18586	67/DS/SMH0159E
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
HFZ28H3600061663	2NRX415083	60	Sam San Joi	02/07/2019 13.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SHC3074G ACC DATE:02/07/2019 DRIVE IN:02/07/2019 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS				183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				164.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				164.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE				80.00
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				328.00
7	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				462.00
8	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				480.00
9	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH A TRIMMING TO ASSIST REPAIR				328.00
10	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				164.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4023734

PLEASE TEAR ALONG PERFORATED LINE

4023734

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/07/2019
TIME 14:26

VEHICLE NO SMH0159E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Reg No : 196700086Z
T Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIII1	Mr Palaniappan S/O Palaniappan K 277A Compassvale Link #02-316 Singapore 541277 Mobile: 91074366
	Document No 0	
	Document Date 17/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
8	MWYNKT	S3	NSP170R 08/01/2019	SMH0159E	0	18586	67/DS/SMH0159E
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
HFZ28H3600061663	2NRX415083	60	Sam San Joi	02/07/2019 13.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS	686		1312	2952.00
2	B	STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS			1076 - 2090	
2	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREA	538			
		EAS				
3	1	S52159-OU919 COVER, RR BUMPER, L	1.00	316.10		316.10
4	2	S52156-OD100 SUPPORT, RR BUMPER S	1.00	73.60		73.60
5	3	S52155-OD110 SUPPORT, RR BUMPER S	1.00	73.60		73.60
6	4	S52161-OK040 CLIPS	10.00	4.10		41.00
7	5	S52151-OD010 EXTENSION, RR BUMPER	1.00	190.00		190.00
8	6	S58307-OD320 PANEL SUB-ASSY, BODY	1.00	433.60		433.60
9	7	S58302-OD010 PANEL SUB-ASSY, LWR	1.00	696.30		696.30
10	8	S64716-OD170 CO COVER, DECK TRIM, RR	1.00	154.10		154.10
11	9	S67005-OD360 PANEL SUB-ASSY, BACK	1.00	1131.90		1131.90
12	0	S67881-OD130 WEATHERSTRIP, BACK D	1.00	372.30		372.30
13	1	S68105-OD261 GLASS SUB-ASSY, BACK	1.00	1009.20		1009.20
14	2	S69350-OD240 LOCK ASSY, BACK DOOR	1.00	467.60		467.60
15	3	S69430-OD090 STRIKER ASSY, BACK D	1.00	25.70		25.70
16	4	T90975-02086 FRONT BONNET EMBLEM,	1.00	72.20		72.20
17	5	S75442-OD300 PLATE, BACK DOOR NAM	1.00	35.50		35.50
18	6	S75441-OD070 PLATE, BACK DOOR NAM	1.00	53.20		53.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4023735

4023735

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/07/2019
TIME 14:26

VEHICLE NO SMH0159E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



Reg No : 196700086Z
T Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no: 6631 1198

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIIII1	Mr Palaniappan S/O Palaniappan K 277A Compassvale Link #02-316 Singapore 541277 Mobile: 91074366
	Document No	
	0	
	Document Date	
	17/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
8	MWYNKT	S3	NSP170R 08/01/2019	SMH0159E	0	18586	67/DS/SMH0159E
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
HFZ28H3600061663	2NRX415083	60	Sam San Joi	02/07/2019 13.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	7	T04562-12010 <i>Rev</i> FRT W/SCREEN DAM KIT,	1.00	104.60		104.60
10	8	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
11	9	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
12	0	SPC507-OD014 24 BACK SENSOR (1G3, GRAY ME)	1.00	172.40		172.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	11,443.08	
	Please acknowledge receipt of vehicle	Parts	5,838.90	GST 7.00%	801.02
		Labour	4,941.00		
		Materials	663.18	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00	Amount Due	12,244.10

4023736

PLEASE TEAR ALONG PERFORATED LINE

4023736

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/07/2019
TIME 14:26

VEHICLE NO SMH0159E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors