

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLN2472S

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	REPAIR FLOOR PAN (SUPP)	250.00	✓
2 ZZ/002	RESPRAY FLOOR PAN (SUPP)	200.00	X
TOTAL LABOUR CHARGES		450.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN2472S

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 COVER EXH R (SUPP)	59024FJ000				72.00 <i>de</i>
2 MUD GUARD R LH (SUPP)	59122FJ012				64.80 <i>ck</i>
3 LENS & BODY-FOG LIGHT, REAR (SUPP)	84913FG420				102.00 <i>CRA</i>
SUB TOTAL		0.00	0.00	0.00	238.80
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	71.64
GRAND TOTAL		0.00	0.00	0.00	167.16
OVERALL TOTAL		167.16			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLN2472S

TOTAL LABOUR CHARGES	450.00
TOTAL SPARE PARTS CHARGES	167.16
GRAND TOTAL	617.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/035/2019
DATE : 03-JUL-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : HO CHYE YIN, KATHERINE (HE CAIYING, KATHERINE)
ADDRESS : 83 HILLVIEW AVENUE
#07-01
S(669583)
TELEPHONE NO : 9694 7308

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100508384-01
VEHICLE NO : SLN2472S
MODEL CODE : GP3FKDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : F816Y558994
CHASSIS NO : JF1GP3KC5HG204275
MILEAGE : 1 KM
DATE IN : 03/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI
ACCIDENT DATE : 03/07/2019

Print Date : 23/07/2019
Print Time : 16:16:06

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLN2472S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG DATE:03/07/2019 TIME:0710HRS LOCATION:HOLLAND ROAD		
3	ZZ/002	REPAIR/REPLACE RR BUMPER, TAILGATE, ENDPANEL, RR RH FENDER, RR LH FENDER AND FLOORPAN	1500.00	1250.00
4	ZZ/003	RESPRAY RR BUMPER, ENDPANEL, TAILGATE, RR RH FENDER, RR LH FENDER AND FLOOR PAN	1200.00	800.00
5	ZZ/004	REMOVE/REFIX REAR U/CARR RH, LH AND CENTRE FRAME	684.00	.00
6	ZZ/005	REMOVE/REFIX EXHAUST TO FACILITATE REPAIR	114.00	114.00
7	ZZ/006	CONDUCT WATER SEEPAGE TEST AFTER REPAIR	85.00	.00
8	ZZ/007	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	95.00	95.00
9	ZZ/008	CONDUCT 4 WHEEL ALIGNMENT AFTER REPAIR	171.00	.00
10	ZZ/009	REMOVE/REFIX RR CARPET, SEAT, GARNISH & TRIM TO FACILITATE REPAIR	456.00	456.00
11	ZZ/011	REMOVE/REFIX FUEL TANK TO FACILITATE REPAIR	171.00	.00
12	ZZ/012	CONDUCT REAR LIGHTING TEST	28.00	28.00
13	ZZ/013	CONDUCT REAR ANTI RUST COATING AFTER REPAIR TO REAR PORTION	290.00	.00
14	ZZ/014	TO SUPPLY/INSTALL REVERSE SENSOR 2 EYES	300.00	300.00
15	ZZ/015	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	145.00	145.00
16	ZZ/016	SUNDRIES	100.00	20.00
17	ZZ/10	REMOVE/INSTALL REAR WINDSCREEN	237.00	237.00
TOTAL LABOUR CHARGES			5576.00	3445.00

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN2472S

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST	REMARKS
			NETT	LIST	S/NETT		
1	GASKET RM	44011AE010				16.00	OK
2	EXH PIPE ASSY R	608C/N 44200FJ110				684.00	OK
3	MUFFLER AY	44300FJ040				576.00	OK
4	FLOOR PAN R	CKD-XV 52129FJ0009P				540.00	X
5	SKIRT COMPL R 5D	52401FJ0209P				244.80	OK
6	BUMPER FACE REAR XV	57704FJ041				594.00	OK
7	BRKT RRH BUMP CORN	57707FJ080				28.80	OK
8	BRKT RLH BUMP CORN	57707FJ090				28.80	OK
9	BRKT RRH BUMP	57707FJ160				14.40	OK
10	BRKT RLH BUMP	57707FJ170				14.40	OK
11	BRKT BUMP R LWR	57707FJ201				14.40	OK
12	BEAM COMPL R EU	57711FJ0239P				259.20	OK
13	COVER-REAR BUMPER	57731FG010B7				14.40	OK
14	CVR RRH BUMP	57731FJ080				28.80	X
15	CVR RLH BUMP	57731FJ090				28.80	OK
16	COVER EXH R (SUPP)	59024FJ000				72.00	OK <i>de✓</i>
17	MUD GUARD R LH (SUPP)	59122FJ012				64.80	OK <i>de✓</i>
18	PANEL COMPL R GAT	60809FJ0509P				756.00	OK
19	GLASS ASSY R G	63019FJ040				1020.60	OK
20	LATCH&ACT ASSY RG	63032FG112				176.40	X
21	BUFFER(R G SIDE) RH	63112AL000				3.20	OK
22	BUFFER(R G SIDE) LH	63112AL010				3.20	OK
23	HANDLE R/G	63160FE010				10.80	X
24	STRIKER R/G	63264AG100				21.60	X
25	DAM RUBBER R WIND	65245SC000				21.60	OK

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN24725

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 REFLEX AY RH	84281FG000			21.60	X
27 RELFLEX ASSY LH	84281FG010			21.60	OK
28 LENS & BODY COMPL	84912FJ361			377.40	X
29 LENS & BODY COMPL	84912FJ371			377.40	OK
30 LENS & BODY-FOG LIGHT, REAR (SUPP)	84913FG420			102.00	OK <i>Cur</i>
31 GARNISH AY RG	91111FJ190NN			162.00	X
32 LETTER MARK-REAR	93079FJ060			68.00	OK
33 LETTER MARK-REAR	93079FJ100			40.80	OK
34 REAR NUMBER PLATE	WM002			45.00	X
SUB TOTAL					
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	5069.20
		0.00	0.00	0.00	1520.76
GRAND TOTAL					
		0.00	0.00	0.00	3548.44
OVERALL TOTAL					
		3548.44			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLN2472S

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	5069.20
LESS 30 %	-1520.76
S/LIST AMOUNT	3548.44
TOTAL LABOUR CHARGES	3445.00
TOTAL SPARE PARTS CHARGES	3548.44
TOTAL CHARGES	6993.44
ADD 7 % GST	489.54
GRAND TOTAL	7482.98



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
T (65) 6417 0333 F (65) 6252 5655
W www.motorimage.net

Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured: HO CHYE YIN, KATHERINE
Address of Insured: APT 83 HILLVIEW AVENUE #07-01 S(669583)
Name of Repairs: MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP
Address of Repairs: NO.25 LENG KEE ROAD SINGAPORE 159097
Place of Accident: HOLLAND ROAD
Date of Accident: 03/07/2019 Vehicle No: SLN2472S
Policy No: 2100508384-02 Claim No: _____


I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of AIG ASIA PACIFIC INS P/L settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.

I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:



Company's Chop & Signature

INSURED:

[Signature] S7322840I
IC No. & Signature/Company's Chop

SAYEDINAH ALI

Name

HO CHYE YIN, KATHERINE

Name

17/07/2019

Date

17/07/2019

Date

CERTIFIED
TRUE COPY

motorimage



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535
25 Leng Kee Road Singapore 159097
Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: M191549

**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**

DATE REC'D: 05-Jul-2019

SERVICE ADVISOR: SAYED

JOB No.: M188573

MILEAGE: 27004

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: XV 1.6I-S AWD CVT
ENGINE No.: FB16Y558994
CHASSIS No.: JF1GP3KC5HG204275
REGISTRATION No.: SLN2472S

ITEMS	CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	ODCLAI	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)	
2	REMARK	CONDUCT OD CLAIM AIG DATE:03/07/2019 TIME:0710HRS LOCATION:HOLLAND ROAD	
3	REMARK	REPAIR/REPLACE RR BUMPER,TAILGATE,ENDPANEL,RR RH FENDER,RR LH FENDER AND FLOORPAN	1,250.00
4	REMARK	RESPRAY RR BUMPER,ENDPANEL,TAILGATE,RR RH FENDER, RR LH FENDER AND FLOOR PAN	800.00
5	REMARK	REMOVE/REFIX EXHAUST TO FACILITATE REPAIR	
6	REMARK	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	114.00
7	REMARK	REMOVE/REFIX RR CARPET,SEAT,GARNISH & TRIM TO FACILITATE REPAIR	95.00 456.00
8	REMARK	CONDUCT REAR LIGHTING TEST	
9	REMARK	TO SUPPLY/INSTALL REVERSE SENSOR 2 EYES	28.00
10	REMARK	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	300.00
11	REMARK	SUNDRIES	145.00
12	REMARK	REMOVE/INSTALL REAR WINDSCREEN	20.00
13	INS01	FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	237.00
14	INS02		
15	INS03	STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
16	INS04		
17	INS05	INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM THE OWNER IS REQUIRED.	
18	INS06		
19	INS07	CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	

**CERTIFIED
TRUE COPY**

**Motor Image Enterprises Pte Ltd**

19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net

**TAX INVOICE**

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211

MODEL: XV 1.6I-S AWD CVT
ENGINE No.: FB16Y558994
CHASSIS No.: JF1GP3KC5HG204275
REGISTRATION No.: SLN2472S

Sales: INSURANCE CUSTOMER

Invoice No: M191549

For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.

DATE REC'D: 05-Jul-2019

SERVICE ADVISOR: SAYED

JOB No.: M188573

MILEAGE: 27004

ID:

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
20 INS08	NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO.	
21 INS09	APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
	TOTAL(LABOUR)	3,445.00
1	GASKET RM (SUPP)	
2	44011AE010(Qty : 1 @ 16.00 each(Discount 30.00%))	11.20
3	EXH PIPE ASSY R 608C/N	
4	44200FJ110(Qty : 1 @ 684.00 each(Discount 30.00%))	478.80
5	MUFFLER AY (SUPP)	
6	44300FJ040(Qty : 1 @ 576.00 each(Discount 30.00%))	403.20
7	SKIRT COMPL R 5D	
8	52401FJ0209P(Qty : 1 @ 244.35 each(Discount 30.00%))	171.05
9	BUMPER FACE REAR XV	
10	57704FJ041(Qty : 1 @ 594.00 each(Discount 30.00%))	415.80
11	BRKT RRH BUMP CORN	
12	57707FJ080(Qty : 1 @ 28.80 each(Discount 30.00%))	20.16
13	BRKT RLH BUMP CORN	
14	57707FJ090(Qty : 1 @ 28.80 each(Discount 30.00%))	20.16
15	BRKT RRH BUMP	
16	57707FJ160(Qty : 1 @ 14.40 each(Discount 30.00%))	10.08
17	BRKT RLH BUMP	
18	57707FJ170(Qty : 1 @ 14.40 each(Discount 30.00%))	10.08
19	BRKT BUMP R LWR	
20	57707FJ201(Qty : 1 @ 14.40 each(Discount 30.00%))	10.08
21	BEAM COMPL R EU	
22	57711FJ0239P(Qty : 1 @ 259.20 each(Discount 30.00%))	181.44
23	COVER-REAR BUMPER	
24		10.08

CERTIFIED
TRUE COPY

**Motor Image Enterprises Pte Ltd**

19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net

**TAX INVOICE**

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: XV 1.6I-S AWD CVT
ENGINE No.: FB16Y558994
CHASSIS No.: JF1GP3KC5HG204275
REGISTRATION No.: SLN2472S

Sales: INSURANCE CUSTOMER
Invoice No: M191549
**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**
DATE REC'D: 05-Jul-2019
SERVICE ADVISOR: SAYED
JOB No.: M188573
MILEAGE: 27004
ID:

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
13	57731FG010B7(Qty : 1 @ 14.40 each(Discount 30.00%)) CVR RLH BUMP	20.16
14	57731FJ090(Qty : 1 @ 28.80 each(Discount 30.00%)) COVER EXH R (SUPP)	50.40
15	59024FJ000(Qty : 1 @ 72.00 each(Discount 30.00%)) MUD GUARD R LH	45.36
16	59122FJ012(Qty : 1 @ 64.80 each(Discount 30.00%)) PANEL COMPL R GAT	529.20
17	60809FJ0509P(Qty : 1 @ 756.00 each(Discount 30.00%)) GLASS ASSY R G	714.42
18	63019FJ040(Qty : 1 @ 1020.60 each(Discount 30.00%)) BUFFER(R G SIDE) RH	2.24
19	63112AL000(Qty : 1 @ 3.20 each(Discount 30.00%)) BUFFER(R G SIDE) LH	2.24
20	63112AL010(Qty : 1 @ 3.20 each(Discount 30.00%)) DAM RUBBER R WIND	15.12
21	65245SC000(Qty : 1 @ 21.60 each(Discount 30.00%)) RELFLX ASSY LH	15.12
22	84281FG010(Qty : 1 @ 21.60 each(Discount 30.00%)) LENS & BODY COMPL (SUPP)	264.18
23	84912FJ370(Qty : 1 @ 377.40 each(Discount 30.00%)) LENS & BODY-FOG LIGHT,REAR	71.40
24	84913FG420(Qty : 1 @ 102.00 each(Discount 30.00%)) LETTER MARK-REAR	47.60
25	93079FJ060(Qty : 1 @ 68.00 each(Discount 30.00%)) LETTER MARK-REAR	28.56
	93079FJ100(Qty : 1 @ 40.80 each(Discount 30.00%)) TOTAL(SPARE PARTS)	3,548.13

Subtotal 6,993.13
GST(7%) 489.52
TOTAL \$7,482.65

**CERTIFIED
TRUE COPY**

DATE : 31-Oct-2019

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2019 09:49		04 Jul 2019 16:14 Edit Adj Rpt	\$6,993.12 Edit Estimates	\$6,993.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
[Created by insurer]									
Insured:	HO CHYE YIN KATHERINE, ID: S7322840I, Tel: +6596947308, Email: jinglebee03@yahoo.com.sg								
Vehicle Reg. No.:	SLN2472S	Date of Loss:	03/07/2019 07:00 - :59 [26 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 0702142908SG	Policy/Cover Note No.:	2100508384 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Yap, Weijoe] Weijoe.Yap@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/07/2019]								
Driver/Custodian:	HO CHYE YIN KATHERINE (46 / Female), NRIC: S7322840I, Tel: +6596947308 Email: jinglebee03@yahoo.com.sg								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
- AIG_SG (30/10/2019): Alert - Adj Mandate Approved (S\$6993.14) - SLN2472S - Claim Handler: Yap, Weijoe - AIG_SG (01/08/2019): Alert - Adj Mandate Maintained - SLN2472S - Claim Handler: Yap, Weijoe - AIG_SG (05/07/2019): Alert - Adj Mandate Approved (S\$6276.46) - SLN2472S - Claim Handler: Yap, Weijoe									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN2472S (0702142908SG)
OD
Jul 3 2019 7:00AM
[HO CHYE YIN KATHERINE]
Motor Image Enterprises Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

Video

No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	03/07/19 11:56	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
2	03/07/19 11:56	Video - Accident [Linked Accident Report Documents]	Load MP4	☐

Assessment Reports

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/19 09:52	Adjuster Immediate Advice	Load HTM	☐
2	31/07/19 09:44	Adjuster Immediate Advice	Load HTM	☐

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/19 09:45	Odometer Reading	Load JPG	☒
2	05/07/19 09:45	Chassis Number	Load JPG	☒
3	05/07/19 09:46	General View	Load JPG	☒
4	05/07/19 09:46	General View	Load JPG	☒
5	05/07/19 09:46	General View	Load JPG	☒
6	05/07/19 09:46	General View	Load JPG	☒
7	05/07/19 09:46	General View	Load JPG	☒
8	05/07/19 09:46	General View	Load JPG	☒
9	05/07/19 09:46	General View	Load JPG	☒
10	05/07/19 09:46	General View	Load JPG	☒
11	05/07/19 09:46	General View	Load JPG	☒
12	05/07/19 09:46	General View	Load JPG	☒
13	05/07/19 09:46	General View	Load JPG	☒
14	05/07/19 09:46	General View	Load JPG	☒
15	05/07/19 09:46	General View	Load JPG	☒
16	05/07/19 09:46	General View	Load JPG	☒
17	05/07/19 09:46	General View	Load JPG	☒
18	05/07/19 09:46	General View	Load JPG	☒
19	05/07/19 09:46	General View	Load JPG	☒
20	05/07/19 09:46	General View	Load JPG	☒
21	05/07/19 09:46	General View	Load JPG	☒
22	05/07/19 09:46	General View	Load JPG	☒
23	05/07/19 09:46	General View	Load JPG	☒
24	05/07/19 09:46	General View	Load JPG	☒
25	05/07/19 09:46	General View	Load JPG	☒
26	05/07/19 09:46	General View	Load JPG	☒
27	05/07/19 09:46	General View	Load JPG	☒
28	05/07/19 09:46	General View	Load JPG	☒
29	05/07/19 09:46	General View	Load JPG	☒
30	05/07/19 09:46	General View	Load JPG	☒
31	05/07/19 09:46	General View	Load JPG	☒
32	05/07/19 09:46	General View	Load JPG	☒

Video			1 per page	
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
33	05/07/19 09:46	General View	 Load JPG	☒
34	05/07/19 09:46	General View	 Load JPG	☒
35	05/07/19 09:46	General View	 Load JPG	☒
36	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
37	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
38	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
39	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
40	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
41	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
42	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
43	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
44	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
45	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
46	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
47	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
48	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
49	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
50	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
51	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
52	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
53	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
54	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
55	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
56	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
57	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
58	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
59	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
60	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
61	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
62	31/07/19 09:40	Reinspection Photo	 Load JPG	☒
63	30/10/19 17:36	Reinspection Photo	 Load JPG	☒
64	30/10/19 17:36	Reinspection Photo	 Load JPG	☒
65	30/10/19 17:36	Reinspection Photo	 Load JPG	☒
66	30/10/19 17:36	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/19 09:45	Singapore Accident Statement	 Load PDF	
2	05/07/19 09:45	Certificate of Insurance	 Load PDF	
3	05/07/19 09:45	Driver's Driving License	 Load PDF	
4	05/07/19 09:45	ESTIMATE	 Load PDF	
5	31/07/19 09:38	REVISED ESTIMATE	 Load PDF	
6	31/07/19 09:38	SUPPLEMENTARY LIST	 Load PDF	
7	01/11/19 10:11	DISCHARGE VOUCHER	 Load PDF	
8	01/11/19 10:11	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	1 per page	
1	03/07/19 11:56	Video - Accident	 Load MP4	
2	03/07/19 11:56	Video - Accident	 Load MP4	
Assessment Reports			1 per page	
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print

Video				1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		Thumbnail	Print
1	03/07/19 11:58	Accident Statement		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		Thumbnail	Print
1	03/07/19 11:55	Accident Photo		Load JPG	☒
2	03/07/19 11:55	Accident Photo		Load JPG	☒
3	03/07/19 11:55	Accident Photo		Load JPG	☒
4	03/07/19 11:55	Accident Photo		Load JPG	☒
5	03/07/19 11:55	Accident Photo		Load JPG	☒
6	03/07/19 11:55	Accident Photo		Load JPG	☒
7	03/07/19 11:55	Accident Photo		Load JPG	☒
8	03/07/19 11:55	Accident Photo		Load JPG	☒
9	03/07/19 11:55	Accident Photo		Load JPG	☒
10	03/07/19 11:55	Accident Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		Thumbnail	Print
1	03/07/19 11:54	Accident Sketch Plan		Load TIF	
2	03/07/19 11:54	Common Statement		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#) [Save](#) [Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19011856/T1QD3S2
Date: 01/11/2019

REFERENCE

Insured/Claimant: HO CHYE YIN KATHERINE Policy No: 2100508384
Date of Loss: 03/07/2019 Nature of Claim: OD Claim No: 0702142908SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN2472S**
Make & Model: SUBARU XV, 1.6 I-S AWD CVT (A) Engine No: FB16Y558994
Reg. Date: 27/04/2017 (Man. Year: 2016) Chassis No: JF1GP3KC5HG204275
Colour: Blue Odometer: 26983 km
Engine Capacity: 1600 cc
Market Value/New Car Price: S\$76,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,930.46	3,868.12	1,062.34	21.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,626.00	3,125.00	2,501.00	44.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,556.46	6,993.12	3,563.34	33.76
+ GST 7.00/7.00% (S\$)	738.95	489.52	249.43	33.75
Nett Amount (S\$)	11,295.41	7,482.64	3,812.77	33.76

INSPECTION

Date of Assignment: 04/07/2019

Date Inspected: 04/07/2019 Inspected At:

Motor Image Enterprises Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$6,993.13

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GASKET RM	Necessary	16.00 FL	*16.00 FL
2	1		*EXH PIPE ASSY R	Bent	684.00 FL	*684.00 FL
3	1		*MUFFLER AY	Bent	576.00 FL	*576.00 FL
4	1		*FLOOR PAN R	Not Necessary	540.00 FL	*- FL
5	1		*SKIRT COMPL R 5D	Bent	244.80 FL	*244.35 FL
6	1		*BUMPER FACE REAR XV	Deformed	594.00 FL	*594.00 FL
7	1		*BRKT RRH BUMP CORN	Deformed	28.80 FL	*28.80 FL
8	1		*BRKT RLH BUMP CORN	Deformed	28.80 FL	*28.80 FL
9	1		*BRKT RRH BUMP	Necessary	14.40 FL	*14.40 FL
10	1		*BRKT RLH BUMP	Necessary	14.40 FL	*14.40 FL
11	1		*BKRT BUMP R LWR	Necessary	14.40 FL	*14.40 FL
12	1		*BEAM COMPL R EU	Bent	259.20 FL	*259.20 FL
13	1		*COVER - REAR BUMPER	Missing	14.40 FL	*14.40 FL
14	1		*CVR RRH BUMP	Not Necessary	28.80 FL	*- FL
15	1		*CVR RLH BUMP	Deformed	28.80 FL	*28.80 FL
16	1		*PANEL COMPL R GAT	Bent	756.00 FL	*756.00 FL
17	1		*GLASS ASSY R G	Necessary	1,020.60 FL	*1,020.60 FL
18	1		*LATCH & ACT ASSY RG	Not Necessary	176.40 FL	*- FL
19	1		*BUFFER (R G SIDE) RH	Necessary	3.20 FL	*3.20 FL
20	1		*BUFFER (R G SIDE) LH	Necessary	3.20 FL	*3.20 FL
21	1		*HANDLE R/G	Not Necessary	10.80 FL	*- FL
22	1		*STRIKER R/G	Not Necessary	21.60 FL	*- FL
23	1		*DAM RUBBER R WIND	Necessary	21.60 FL	*21.60 FL
24	1		*REFLEX AY RH	Not Necessary	21.60 FL	*- FL
25	1		*REFLEX ASSY LH	Cracked	21.60 FL	*21.60 FL
26	1		*LENS & BODY COMPL	Not Necessary	377.40 FL	*- FL
27	1		*LENS & BODY COMPL	Cracked	377.40 FL	*377.40 FL
28	1		*GARNISH AY RG	Not Necessary	162.00 FL	*- FL
29	1		*LETTER MARK - REAR	Necessary	68.00 FL	*68.00 FL
30	1		*LETTER MARK - REAR	Necessary	40.80 FL	*40.80 FL
31	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
32	1		*REVERSE SENSOR 2 EYES	Not Working	300.00 FS	*300.00 FS
33	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
34	1		*COVER EXH R	Deformed	72.00 FL	*72.00 FL
35	1		*MUD GUARD R LH	Deformed	64.80 FL	*64.80 FL
36	1		*LENS & BODY - FOG LIGHT, REAR	Cracked	102.00 FL	*102.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,852.80	5,388.75
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,922.34	1,520.63
Total Parts (\$\$)	4,930.46	3,868.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE RR BUMPER, TAILGATE, END PANEL, RR RH FENDER, RR LH FENDER AND FLOOR PAN.	New	1,500.00	1,000.00
2	RESPRAY RR BUMPER, END PANEL, TAILGATE, RR RH FENDER, RR LH FENDER AND FLOOR PAN.	New	1,200.00	800.00
3	REMOVE / REFIX REAR U/CARR RH, LH AND CENTRE FRAME.	New	684.00	0.00
4	REMOVE / REFIX EXHAUST TO FACILITATE REPAIR.	New	114.00	114.00
5	CONDUCT WATER SEEPAGE TEST AFTER REPAIR.	New	85.00	0.00
6	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.	New	95.00	95.00
7	CONDUCT 4 WHEEL ALIGNMENT AFTER REPAIR.	New	171.00	0.00
8	REMOVE / REFIX RR CARPET, SEAT, GARNISH & TRIM TO FACILITATE REPAIR.	New	456.00	456.00
9	REMOVE / REFIX FUEL TANK TO FACILITATE REPAIR.	New	171.00	0.00
10	CONDUCT REAR LIGHTING TEST.	New	28.00	28.00
11	CONDUCT REAR ANTI RUST COATING AFTER REPAIR TO REAR PORTION.	New	290.00	0.00
12	SUPPLY / INSTALL REAR WINDSCREEN TINTED FILM.	New	145.00	145.00
13	REMOVE / INSTALL REAR WINDSCREEN.	New	237.00	237.00
14	REPAIR FLOOR PAN.	New	250.00	250.00
15	RESPRAY FLOOR PAN.	New	200.00	0.00
Gross Labour Cost (\$\$)			5,626.00	3,125.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >