2,219.29

Estimate Report

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12 Singapore 737856 Tel: 62562281 Fax: Email: YTMG

INSURER: AXA INSURANCE SINGAPORE PTE LTD

This claim is handled by: Sky Toh T C

PARTICULARS OF CLAIM				
Claim Type:	TP	Ref. No:	YTMG/TP/1907/002	2
Policy No:	5109039451	Date of Loss:	28/06/2019	
Vehicle Reg. No.:	SGV9575A	Driveable?	no	
Driver Age:	23/02/1988	Third Party Vehicle No.:	SFR9228K	
Any Injuries?	no	Contact No:	86666007	
Insured/Claimant:	XU ZHUOHUA	Driver:	XU ZHUOHUA	
Make/Model:	Honda, Stream	Vehicle Reg. Date:	29/06/2007	
Vehicle Colour:		Engine Number:		
Chassis No:	RN61037828	Odometer:		
Total Loss?		Est. Duration of Repair(Day)	
Description of Accident/loss Remarks:	COLLISION - HEAD T	O REAR		
Present Location:	Yew Tee Automobile	Tech Pte Ltd (Mega)-YTMG		
COST OF CLAIMS				Amoun
Parts				804.10
Miscellaneous Items				250.00
Labour				510.00
Paintwork Labour				510.00
Towing				0.00
		Gross Total(S\$)):	2,074.10
		GST 7.00%(S\$)		145.19
			-	

Nett Amount(S\$):

				_
RFP	AIR	DET	IIA	S

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	0.00	440.00	+10.00	484.00
2	1	REAR BUMPER SIDE RETAINER RH /	0.00	12.00	+10.00	13.20
3	1	REAR BUMPER BRACKET RH	0.00	15.00	+10.00	16.50
4	1	REAR TAILLAMP RH / CRA	0.00	264.00	+10.00	290.40
5	1	REAR FENDER RH	0.00	0.00	0.00	0.00

Total Parts (S\$)	804.10

Estima	ates of IVIIS	cellaneous Items				
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	0.00	30.00	0.00	30.00
2	1	REAR BUMPER SENSORS	0.00	220.00	0.00	220.00

Sub Total (S\$)	250.00

No.	Qty	Particulars	Rate	Amount	%Disc	After
	ary	1 di dodidi 3	Nate	Amount	/0D130	Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 /
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 2
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	400.00	400.00	0.00	400.00 20

Gross Labour Cost (S\$) 510.00

No.	Qty	Particulars	Rate	Amount	%Disc	After
	,	- and and	Nate	Amount	70D13C	Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 X
2	1	To Apply Undercoating On The Repaired and	20.00	20.00	0.00	20.00/
		Replaced Panels For Rust Protection.				
3	1	To Spray painting on the Replaced and Repair	450.00	450.00	0.00	450.00
		Parts, Prepare Spray Such as Masking Tape				200
		the unaffected areas with paper, Cleaning and				,
		Sanding of Surfaces, Final Polishing and				
		Waxing are also available.				

Steve CLKK) 8311 8813 Steve ching IKK outh . rom WIL ATUL

< END OF ESTIMATES >

Gross Labour Cost SNKK Auto Consultants hence notify 510.00

- the Repairer of the following:
- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to contimation
- Third party survey is on a "Valmout Prejudice" basis
- No illegal modification(s)
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

Date: