Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12 Singapore 737856 Tel: 62562281 Fax: Email: YTMG

INSURER: AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type: TP Ref. No: YTMG/TP/1907/002

Policy No: 5109039451 Date of Loss: 28/06/2019

Vehicle Reg. No.: SGV9575A Driveable? no

Driver Age: 23/02/1988 Third Party Vehicle No.: SFR9228K
Any Injuries? no Contact No: 86666007
Insured/Claimant: XU ZHUOHUA Driver: XU ZHUOHUA

Make/Model: Honda, Stream Vehicle Reg. Date: 29/06/2007

Vehicle Colour: Engine Number:

Chassis No: RN61037828 Odometer:

Total Loss? Est. Duration of Repair(Day)

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS		Amount
Parts		804.10
Miscellaneous Items		250.00
Labour		510.00
Paintwork Labour		510.00
Towing	<u> </u>	0.00
	Gross Total(S\$):	2,074.10
	GST 7.00%(S\$):	145.19
	Nett Amount(S\$):	2,219.29

This claim is handled by: Sky Toh T C

Estimate Report 07/03/2019

REPAIR DETAILS

Estima	ates On Pa	rts				
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	0.00	440.00	+10.00	484.00
2	1	REAR BUMPER SIDE RETAINER RH	0.00	12.00	+10.00	13.20
3	1	REAR BUMPER BRACKET RH	0.00	15.00	+10.00	16.50
4	1	REAR TAILLAMP RH	0.00	264.00	+10.00	290.40
5	1	REAR FENDER RH	0.00	0.00	0.00	0.00

Total Parts (S\$)	804.10

Estima	Estimates of Miscellaneous Items						
No.	Qty	Particulars	Rate	Amount	%Disc	After	
						Disc	
1	1	REAR BUMPER CLIPS	0.00	30.00	0.00	30.00	
2	1	REAR BUMPER SENSORS	0.00	220.00	0.00	220.00	

Sub Total (S\$) 250.00

Estimates On Labour							
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc	
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00	
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00	
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	400.00	400.00	0.00	400.00	

Gross Labour Cost	(S \$	510.00

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	20.00	20.00	0.00	20.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	450.00	450.00	0.00	450.00
		Gross Labour	Cost (S\$)			510.00

< END OF ESTIMATES >