



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLZ6093M
Make & Model : HONDA,STREAM 1.8L AT
SUNROOF,JHMRN68609C200093
Year of Manufacture : 2009

Estimation No. : E19070005
DOA : 02/07/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>de</i> ✓	1.00	574.90	574.90
2	Rear bumper retainer (LH) X	1.00	89.90	89.90
3	Rear bumper retainer (RH) X	1.00	89.90	89.90
4	Rear bumper towing cap <i>M.S</i> ✓	1.00	38.00	38.00
5	Tailgate <i>bt</i> ✓	1.00	990.00	990.00
6	Tailgate lock <i>bt</i> ✓	1.00	187.00	187.00
7	Tailgate lock catch X	1.00	103.00	103.00
8	Tailgate lock switch X	1.00	0.00	0.00
9	Tailgate damper (LH) X	1.00	138.00	138.00
10	Tailgate damper (RH) X	1.00	138.00	138.00
11	Tailgate hinge (LH) X	1.00	65.00	65.00
12	Tailgate hinge (RH) X	1.00	65.00	65.00
13	Tailgate rubber beading <i>m</i> ✓	1.00	150.00	150.00
14	License lamp garnish X	1.00	192.00	192.00
15	License lamp (LH) X	1.00	112.00	112.00
16	License lamp (RH) X	1.00	112.00	112.00
17	Tailgate inner trim board ?	1.00	245.00	245.00
18	Tailgate inner side garnish (LH) X	1.00	63.80	63.80
19	Tailgate inner side garnish (RH) X	1.00	63.80	63.80
20	Tailgate inner centre garnish X	1.00	265.00	265.00
21	Tailgate inner pull handle X	1.00	92.00	92.00
22	Tailgate wiper motor X	1.00	296.00	296.00
23	Tailgate wiper arm X	1.00	120.00	120.00
24	Third brake lamp X	1.00	153.00	153.00
25	Rear windscreen X	1.00	920.00	920.00
26	Rear bumper bracket (LH) <i>m</i> ✓	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLZ6093M
Make & Model : HONDA,STREAM 1.8L AT
SUNROOF,JHMRN68609C200093
Year of Manufacture : 2009

Estimation No. : E19070005
DOA : 02/07/2019

No	Description	Qty	U/P	Amt
27	Rear bumper bracket (RH) X	1.00	0.00	0.00
28	Rear windscreen moulding ~✓	1.00	238.00	238.00
29	Tail lamp (LH) X	1.00	390.00	390.00
30	Tail lamp (RH) X	1.00	390.00	390.00
31	Tail lamp inner panel (LH) X	1.00	185.00	185.00
32	Tail lamp inner panel (RH) X	1.00	185.00	185.00
33	End panel repair ?	1.00	381.00	381.00
34	End panel top garnish ?	1.00	186.00	186.00
35	Rear floor panel X	1.00	1,045.50	1,045.50
36	Rear floor panel top board X	1.00	322.00	322.00
37	Spare tyre bracket X	1.00	167.00	167.00
38	Rear fender inner trim (LH) X	1.00	197.00	197.00
39	Rear fender inner trim (RH) X	1.00	197.00	197.00
40	Rear exhaust muffler X	1.00	694.00	694.00
41	Rear exhaust heat shield X	1.00	292.20	292.20
42	Exhaust mid pipe X	1.00	583.50	583.50

Amt	S\$
	10,716.50
Discount (0.00%)	S\$ 0.00
Subtotal	S\$
	10,716.50

Section: Special Nett Items

43	Tailgate emblem - Logo X	1.00	120.00	120.00
44	Reverse sensor set ~✓	1.00	500.00	500.00 200
45	Reverse camera X	1.00	50.00	50.00
46	Rear number plate & casing X	1.00	45.00	45.00
47	Rear bumper clip set ~✓	1.00	30.00	30.00 ✓
48	Tail lamp clip set X	1.00	45.00	45.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLZ6093M
Make & Model : HONDA,STREAM 1.8L AT
SUNROOF,JHMRN68609C200093
Year of Manufacture : 2009

Estimation No. : E19070005
DOA : 02/07/2019

No	Description	Qty	U/P	Amt
49	Tailgate inner trim board clip set <i>m</i>	1.00	30.00	30.00 ✓
50	End panel top garnish clip set <i>m</i>	1.00	30.00	30.00 ✓
51	Rear windscreen tinted <i>X</i>	1.00	200.00	200.00
52	Rear windscreen sealant <i>m</i>	1.00	50.00	50.00 40
53	End panel sealant <i>X</i>	1.00	50.00	50.00
54	Rear floor panel sealant <i>X</i>	1.00	50.00	50.00
55	Rear floor panel insulator matt <i>X</i>	1.00	280.00	280.00
56	Rear fender inner trim clip set (LH) <i>X</i>	1.00	45.00	45.00
57	Rear fender inner trim clip set (RH) <i>X</i>	1.00	45.00	45.00
58	Tailgate sticker <i>m</i>	1.00	180.00	180.00 30

Amt S\$ 1,750.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,750.00

Section: Labour Items

59	To R&R rear bumper reverse sensor	1.00	60.00	60.00 ✓
60	To check wiring & lighting system	1.00	80.00	80.00 <i>X</i>
61	To perform anti rust treatment on affected areas	1.00	60.00	60.00 40
62	To supply undercoating / putty on parts replaced	1.00	80.00	80.00 30
63	To R&R rear exhaust assy	1.00	200.00	200.00 <i>X</i>
64	To R&R rear windscreen	1.00	200.00	200.00 120
65	To R&R tailgate mechanism	1.00	180.00	180.00 60
66	To R&R rear trims,garnish and seats assy	1.00	260.00	260.00 60
67	To repair,replace & realign damaged areas	1.00	1,400.00	1,400.00 500
68	To spray painting on affected areas	1.00	1,200.00	1,200.00 600
69	To perform water seepage test after repair	1.00	150.00	150.00 30
70	Sundries	1.00	50.00	50.00 20

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLZ6093M
Make & Model : HONDA, STREAM 1.8L AT
SUNROOF, JHMRN68609C200093
Year of Manufacture : 2009

Estimation No. : E19070005
DOA : 02/07/2019

No	Description	Qty	U/P	Amt
				Amt S\$ 3,920.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,920.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 900 10068
5 days
4/3
04/07/19 @ 1200
Resurvey after repair

List Items Subtotal S\$ 10,716.50
Special Nett Items S\$ 1,750.00
Subtotal
Labour Items Subtotal S\$ 3,920.00
Total S\$ 16,386.50