

ASS. REC. BY:

REF: CS/CT119011864/Avd372

Special Instruction:

Supervisor: Adrian

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 4/7/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 8774 C Insured: SKL 7348 H

at Workshop m/s N-SI Automotive Tel: 68420051

of 2 Kaki Bukit Ave 2 #01-17.

Policy No: Claim No: SNM190203005

Sum Insured: Excess:

Make of Veh: D.O.A. 27/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4/7 Person Contacted: Zi Ting Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

GBD 8774 C - NA/INC19011438/24 DOA: 27/6/2019.

SKL 7348 H - CG/CT119011678/Kda3 DOA: 27/6/2019.

16/9/19

Adrian confirmed LS \$ 8600 (Red 10,901.46, 5670)

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: G8D8774C Yr Regn: 2015 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2982Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 168673 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KD142010168264Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/80R15R: 195/80R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 02/07/19Survey held at NSIDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chian

RECEIVED 17 SEP 2019

MV: 47KPV: 30.5KNett: 16.51K

Date/Time, File Pass to?

Date/Time, File Return to?

1) 17/9 - typist

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report: _____

Final Report: _____

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 4 July 2019 10:20 AM
To: Chio Ziting
Cc: assignments
Subject: RE: gbd8774c & skl7348h - notice to insurer to conduct pre repair inspection within 3 working dayss / our ref: snm19d203005

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Monday, 1 July, 2019 3:49 PM

To: 'Chio Ziting' <ziting@n51.com.sg>

Subject: RE: gbd8774c & skl7348h - notice to insurer to conduct pre repair inspection within 3 working dayss / our ref: snm19d203005

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

Yeh In - Adrian

From: Chio Ziting [mailto:ziting@n51.com.sg]
Sent: Monday, 1 July, 2019 3:47 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: gbd8774c & skl7348h - notice to insurer to conduct pre repair inspection within 3 working dayss / our ref: snm19d203005


Dear Sir / Madam,

We appoint your surveyor Mr Adrian Ling - LKK

Please see attached.

Thank you.

Regards,
Zi Ting
N-51 Automotive Pte Ltd
Office: 6842 0051
Fax: 6741 0510
www.n51.com.sg



On Fri, Jun 28, 2019 at 11:14 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



SAVE \$\$ ON UR CAR

INSURANCE RENEWAL

Compare
10+ Insurers

CLICK HERE >



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A



3.18% P.A \$0 Admin Fees At GV
Finance. 2 Years Warranty.
Monthly From \$558.
GV Credit Pte Ltd StarAd



HIN LUNG AUTO

HoBee Group

30 years
of car sale

One Stop Car Hub

Finance, Insurance, Workshop
New and Used Cars

Browse by Category

Save Search

Print

< Back (1 2) Next >

Sort by Date Posted

20 results/page

22 vehicles

Search

Hiace

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Hiace

Any

Any

2015

Any

Any

Any

Available



Toyota Hiace 3.0M

\$43,888

\$7,960 /yr

07-Jan-2015

2,982 cc

46,000 km

Van

Available

Fuel Type: Diesel

Super Low Mileage 46k Km, 1 Owner, Excellent Mechanical Condition. Well Maintained, Factory Condition No Modifications, Always Parked Under Shelter. Very Well Priced. Contact For Fast Deal Via Whatsapp Or SMS;

DIRECT OWNER

Posted: 24-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 3.0A GL

\$53,800

\$9,630 /yr

02-Feb-2015

2,982 cc

133,900 km

Bus

Available

Fuel Type: Diesel

2015 Toyota Hiace 3.0GL, Power Doors, 14 Seaters, New Paint.;

Think One Automobile & Trading

Posted: 04-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M

\$44,800

\$7,900 /yr

06-Mar-2015

2,982 cc

90,000 km

Van

Available

Fuel Type: Diesel

1 Owner Only! Super And Reliable Toyota Hiace Van Turbo Manual! Well Maintained By Previous Owner, High Loan And High Trade In Available! Drive Off With No Worries. Door Step Viewing Can Be Arrange.;

QiFei Auto Pte Ltd

Posted: 26-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M

\$45,800

\$8,010 /yr

23-Mar-2015

2,982 cc

-

Van

Available

Fuel Type: Diesel

1 Owner! Low Mileage! New Paint Work! Engine And Gearbox Tip Top Condition 1 Month Warranty.nice And Clean Interior! High Loan Available! Trade In Welcome! See To Believe! Call Us Now To Arrange Door Step View!;

Net Link Partners Pte Ltd

Posted: 22-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Car Buying >

Car Selling >

Car Ownership >

Car Aftermarket >

On The Move >

Lifestyle >

Buying a pre-owned car, but
Unsure of its Condition?
Get, STA Car Evaluation



Toyota Hiace Commuter 3.0A GL

\$58,500

\$10,200 /yr

28-Mar-2015

2,982 cc

348,945 km

Bus

Available

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 26-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 3.0A

\$59,800

\$10,300 /yr

24-Apr-2015

2,982 cc

-

Bus

Available

Fuel Type: Diesel

One Owner Only! Immaculate Condition! Servicing Done Regularly! 13 Seater With Rear Aircon, GL Model With Auto Sliding Door! Don't Miss Out On This Beauty! Call Our Friendly Salesperson Now To Arrange A Viewing! View To Offer!;

Net Link Partners Pte Ltd

Posted: 01-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

SHORTLISTED HISTORY

Toyota Hiace 3.0M

\$54,800

\$9,350 /yr

14-May-2015

2,982 cc

-

Van

Available

Fuel Type: Diesel

Best Selling Brand In Singapore, Reliable And Easy Maintain, Most Nominated Choice Of The Vehicle For Businesses. Well Maintained,

Compare



Wear And Tear Replaced, No Further Repairs Required, We Provide High Loan And High Trade In. 100% Loan Also Available. Call Us For...

ABWIN (1994) Pte Ltd

☆ Posted: 17-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace 3.0M \$44,800 \$7,570 /yr 03-Jun-2015 2,982 cc - Van Available

Fuel Type: Diesel

6/15 Toyota Hiace Van, Stainless Steel - Ideal For Catering, One Owner Only, Come With An In-car Camera, Loan/Trade In Welcome.;

Think One Automobile & Trading

☆ Posted: 03-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace Commuter 3.0A GL \$58,800 \$9,820 /yr 29-Jun-2015 2,982 cc - Bus Available

Fuel Type: Diesel

Reliable Euro 5 Engine, Trade In/Finance/Insurance/Workshop! Full Loan At \$1211 Monthly, 85% Loan Of Car Price At \$998 Monthly. Welcome To Call For Enquiry And Viewing Appointment.;

Think One Automobile & Trading

☆ Posted: 25-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace 3.0M DX \$47,800 \$7,870 /yr 31-Jul-2015 2,982 cc - Van Available

Fuel Type: Diesel

1 Owner Only, High COE Amount, Very Well Maintain By Previous Owner, Interior And Exterior Good Condition, 4 Almost New Tyres, Easy Loan, Low Interest, View To Believe! Call Fast Before Gone.;

SG Motor Link Pte Ltd

☆ Posted: 01-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Find the right car through consignment.

Purchase pre-loved, owner consigned cars at affordable prices through our dedicated consignment agents. Arrange a test drive today.

Find out more!



☐ Toyota Hiace 3.0M \$52,000 \$8,490 /yr 18-Aug-2015 2,982 cc - Van Available

Fuel Type: Diesel

Toyota Hiace Van Turbo 5 Dr Manual, Registered 18 Aug 2015, Pearl Colour, White Capacity, 2982cc, COE Value Of \$50,584, ARF Value Of \$1,376. One Owner.;

☆ Posted: 30-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace 3.0A DX \$51,000 \$8,320 /yr 20-Aug-2015 2,982 cc - Bus Available

Fuel Type: Diesel

Reliable 12 Seaters Passenger Mini Bus! Easy Maintain, Tip Top Condition, Serviced Regularly By Agent.;

☆ Posted: 18-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace 3.0M \$47,800 \$7,790 /yr 21-Aug-2015 2,982 cc 67,000 km Van Available

Fuel Type: Petrol

This Van Is Definitely For You! Pristine Condition With No Repair Needed! This Is Definitely The Genuine Workhorse To Work For You! Low Maintenance With High Productivity! Flexible Loan Packages With Up To 100% Loan Available! Instalment As Low As \$756/Mth.Loo...

Car (S) Pte Ltd

☆ Posted: 03-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace 3.0M \$48,800 \$7,930 /yr 28-Aug-2015 2,982 cc - Van Available

Fuel Type: Diesel

Super & Reliable Toyota Hiace Van Turbo 5DR Manual 1 Owner Only! Well Maintained By Previous Owner, A1 Condition High Loan & High Trade-In Available, Drive Off With No Worries. DoorStep Viewing Can Be Arrange.;

ABWIN (1994) Pte Ltd

☆ Posted: 30-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace Commuter 3.0A GL \$61,000 \$9,740 /yr 08-Oct-2015 2,982 cc 180,000 km Bus Available

Fuel Type: Diesel

Car Register On Oct 2015, Accident-Free.;

☆ Posted: 24-May-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



☐ Toyota Hiace 3.0M \$47,888 \$7,620 /yr 14-Oct-2015 2,982 cc 90,000 km Van Available

Fuel Type: Diesel

Voted The Most Reliable & Cost Efficient Van! Single Owner Unit! Fully Maintained & Serviced By Agent! Viewing Strictly Via Appointment Only. Call Our Experience Sales Executives To Avoid Disappointment.;

☆ Posted: 03-May-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

SHORTLISTED RESTORE

Compare

☐ Toyota Hiace 3.0M \$47,800 \$7,540 /yr 04-Nov-2015 2,982 cc - Van Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Business
Owner ID:	4793E
Vehicle Details	
Vehicle No.:	GBD8774C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 DX A
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2524170
Chassis No.:	KDH2010168264
Maximum Power Output:	-
Open Market Value:	\$29,544.00
Original Registration Date:	02 Jul 2015
First Registration Date:	02 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$1,478.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$50,900.00
COE Rebate Amount:	\$30,497.00
Total Rebate Amount:	\$30,497.00

The information contained herein is correct as at 04 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/06/2019 16:50
Date Of Accident	27/06/2019 14:10
Exact Location Of Accident	UPP CHANGI RD NORTH TWDS LOYANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD8774C
Insured/Policyholder	
Name Of Registered Owner	LFY SERVICES
Co Reg No	52994793E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62590212
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE 3.0 DX A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072387015-03
Cover Note Number	
Driver	
Name of Driver	MOHAMMAD FAROSS BIN HASHIM
NRIC No	S7832721I
Date Of Birth	26/10/1978
Occupation	OUTDOOR
Date Of Driving Pass	04/01/2000
Driving Experience	19 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82018124
Fax Number	
Contact Number	OFFICE-82018124
Email Address	NOEMAIL

Address	BLK 307C ANG MO KIO AVENUE 1 #03-447
Postcode	563307
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL7348H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAJAN RAJGOPAL
NRIC/Passport Number	
Contact Number	91863226
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLQ9262U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	MOHAMMAD FAROSS BIN HASHIM
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	GBD8774C
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (POPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Upper Chang Rd North towards Laying on the right lane of a 2-lanes road. Somewhere after Japanese School, I stopped completely due to traffic red light ahead. Out of the sudden, I felt an impact on the rear portion of my vehicle. After the impact, I alighted and realised that (C) hit into (B) and (B) hit into my vehicle.

A - GBD 87746

B - SKL 734841

C - SLQ 9262U

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LFY SERVICES
158 BISHAN ST 1 #02-128
SINGAPORE 570158

Contact : 62590012 82018124

TP China.
Veron

ESTIMATE

Repair Code : CLM15357
Date in : 27/06/2019
Vehicle Num. : GBD8774C
Model : TOYOTA HIACE 3.0 DX A
Chassis/Eng# : KDH2010168264/1KD2524170

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER LOWER BRACKET Bent	4	45.10	180.40 ✓
REAR BUMPER SIDE BRACKET L/R none	2	30.00	60.00 X
REAR BUMPER SIDE RETAINER L/R Nec	2	66.10	132.20 ✓
REAR BUMPER STEP BRACKET Bent.	1	299.80	299.80 ✓
REAR END PANEL 'INNER' Distorted	1	1144.00	78x 1144.00 ✓
REAR END PANEL 'OUTER' Distorted	1	581.80	581.80 ✓
REAR END PANEL INNER TOP MOULDING Bent	1	198.10	198.10 ✓
REAR END PANEL SIDE GUIDE RUBBER STOPPER L/R none	2	68.10	136.20 +
REAR END PANEL SIDE PANEL RH Bent.	1	315.10	315.10 ✓
REAR EXHAUST GASKET	1	61.10	61.10 +
REAR EXHAUST RUBBER MOUNTING } none	1	48.60	48.60 +
REAR EXHAUST SILENCER PIPE Rep's	1	980.20	980.20 +
REAR NUMBER PLATE L/R none	2	96.10	192.20 +
REAR TAILGATE Distorted.	1	2205.30	1755 2205.30 ✓
REAR TAILGATE 'HIACE' STICKER Nec	1	58.00	58.00 ✓
REAR TAILGATE DAMPER L/R } Not	2	299.60	599.20 +
REAR TAILGATE HINGE L/R } Nec	2	68.90	137.80 X
REAR TAILGATE INNER CARDBOARD Deformed	1	444.10	444.10 ✓

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

LFY SERVICES

158 BISHAN ST 1 #02-128

SINGAPORE 570158

Contact : 62590012 82018124

ESTIMATE

Repair Code : CLM15357

Date in : 27/06/2019

Vehicle Num. : GBD8774C

Model : TOYOTA HIACE 3.0 DX A

Chassis/Eng# : KDH2010168264/1KD2524170

REAR TAILGATE MECHANISM LOCK <i>Jammed</i>	1	263.00	263.00 ✓
REAR TAILGATE MECHANISM LOCK STRIKER <i>new</i>	1	40.10	40.10 X
REAR TAILGATE OUTER GARNISH <i>changed</i>	1	261.60	261.60 ✓
REAR TAILGATE REMOTE CONTORL LOCK <i>Damaged</i>	1	485.80	485.80 ✓
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	28.50	57.00 ✓
REAR TAILGATE WEATHER STRIP <i>lt</i>	1	299.15	299.15 ✓
REAR TAILLAMP BACK RUBBER GASKET L/R <i>NCC</i>	2	25.80	51.60 ✓
REAR TAILLAMP L/R <i>cracked</i>	2	354.80	709.60 ✓
Subtotal before discount			9,941.95
Percentage discount 25%			2,485.49
Sub-total 1			7,456.46
FLOOR PANEL TOP TRIM CARPET <i>Not NCC</i>	1	800.00	800.00 X
REAR BUMPER <i>Distorted</i>	1	2900.00	2,900.00 1500
REAR BUMPER CENTER FIBER MOULDING <i>cracked</i>	1	800.00	800.00 600
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 30
REAR END PANEL TOP CLIPS - SET <i>new</i>	1	30.00	30.00 20
REAR NUMBER PLATE <i>2 Not</i>	1	25.00	25.00 X
REAR NUMBER PLATE HOLDER <i>new</i>	1	50.00	50.00 X

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LFY SERVICES
 158 BISHAN ST 1 #02-128
 SINGAPORE 570158

Contact : 62590012 82018124

ESTIMATE

Repair Code : CLM15357

Date in : 27/06/2019

Vehicle Num. : GBD8774C

Model : TOYOTA HIACE 3.0 DX A

Chassis/Eng# : KDH2010168264/1KD2524170

REAR TAILGAT OUTER GARNISH FIBER MOULDING <i>NEU</i>	1	400.00	400.00 X
REAR TAILGATE '70KM/H' STICKER <i>NEU</i>	1	15.00	15.00 ✓
REAR TAILGATE '8PAX' STICKER <i>NEU</i>	1	15.00	15.00 ✓
REAR TAILGATE 'MTS M-TECHSPORTS' EMBLEM <i>NEU</i>	1	150.00	150.00 70
REAR TAILGATE EMBLEM <i>NEU</i>	1	80.00	80.00 60
REAR TAILGATE FIBER NUMBER PLATE GARNISH <i>lit</i>	1	800.00	800.00 400
REAR TAILGATE INNER CARDBOARD CLIPS - SET <i>NEU</i>	1	50.00	50.00 30
REAR TAILGATE INNER SOUND PROOF INSULATOR <i>NEU</i>	1	600.00	600.00 X
REAR TAILGATE OUTER CARDBOARD CLIPS - SET <i>NEU</i>	1	30.00	30.00 X
REAR TAILGATE REVERSE CAMERA <i>NEU</i> <i>3040</i>	1	500.00	500.00 ✓
REAR TAILGATE WINDSCREEN GLASS SEALANT <i>NEU</i>	1	80.00	80.00 60
REAR TAILLAMP CLIPS L/R - SET <i>NEU</i>	2	30.00	60.00 20
REAR TAILLAMP LOWER GARNISH CLIPS L/R - SET <i>NEU</i>	2	30.00	60.00 20
REAR TAILLAMP LOWER GARNISH L/R <i>torn</i>	2	300.00	600.00 200
Subtotal before discount			8,095.00
Percentage discount 0%			0.00
Sub-total 2			8,095.00
Parts-total			15,551.46

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LFY SERVICES
158 BISHAN ST 1 #02-128
SINGAPORE 570158

Contact : 62590012 82018124

ESTIMATE

Repair Code : CLM15357

Date in : 27/06/2019

Vehicle Num. : GBD8774C

Model : TOYOTA HIACE 3.0 DX A

Chassis/Eng# : KDH2010168264/1KD2524170

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

~~50.00~~ 30

~~150.00~~ 120

~~150.00~~ 80

~~1,500.00~~ 1000

~~120.00~~ X

~~1,800.00~~ 1200

~~100.00~~ 80

~~80.00~~ ✓

3,950.00

19,501.46

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 10744.43

H/s: 8.6K

09 Days

8.6K

09 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19011864/AVD3N2

Date: 24/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN13524418055
Claimant Vehicle No :	GBD8774C	Insured Vehicle No :	SKL7348H
Date of Loss:	27/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D203005C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD8774C	Engine No:	1KD2524170
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2010168264
Reg. Date:	02/07/2015 (Man. Year: 2015)	Odometer:	168673 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80R15	Rear Tyre Size:	195/80R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,551.46	8,154.44	7,397.02	47.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	2,590.00	1,360.00	34.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,501.46	10,744.44	8,757.02	44.90
Approved Total (Overridden) (\$\$)		8,600.00		
(\$\$)	19,501.46	8,600.00	10,901.46	55.90
+ GST 7.00/7.00% (\$\$)	1,365.10	602.00	763.10	55.90
Nett Amount (\$\$)	20,866.56	9,202.00	11,664.56	55.90

INSPECTION

Date of Assignment: 05/07/2019

Date Inspected: 04/07/2019 Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
KAKI BUKIT AUTOHUB 2 KAKI
BVUKIT AVE 2 #01-18
Singapore 417921

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Sep 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8774C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*REAR BUMPER LOWER BRACKET	Bent	180.40 FL	*180.40 FL
2	2		*REAR BUMPER SIDE BRACKET L/R	Not Necessary	60.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	132.20 FL	*132.20 FL
4	1		*REAR BUMPER STEP BRACKET	Bent	299.80 FL	*299.80 FL
5	1		*REAR END PANEL INNER	Distorted	1,144.00 FL	*784.00 FL
6	1		*REAR END PANEL OUTER	Distorted	581.80 FL	*581.80 FL
7	1		*REAR END PANEL INNER TOP MOULDING	Bent	198.10 FL	*198.10 FL
8	2		*REAR END PANEL SIDE GUIDE RUBBER STOPPER L/R	Not Necessary	136.20 FL	*- FL
9	1		*REAR END PANEL SIDE PANEL RH	Dented	315.10 FL	*315.10 FL
10	1		*REAR EXHAUST GASKET	Not Necessary	61.10 FL	*- FL
11	1		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	48.60 FL	*- FL
12	1		*REAR EXHAUST SILENCER PIPE	Repair	980.20 FL	*- FL
13	2		*REAR NUMBER PLATE L/R	Not Necessary	192.20 FL	*- FL
14	1		*REAR TAILGATE	Distorted	2,205.30 FL	*1,755.00 FL
15	1		*REAR TAILGATE HIACE STICKER	Necessary	58.00 FL	*58.00 FL
16	2		*REAR TAILGATE DAMPER L/R	Not Necessary	599.20 FL	*- FL
17	2		*REAR TAILGATE HINGE L/R	Not Necessary	137.80 FL	*- FL
18	1		*REAR TAILGATE INNER CARDBOARD	Deformed	444.10 FL	*444.10 FL
19	1		*REAR TAILGATE MECHANISM LOCK	Jammed	263.00 FL	*263.00 FL
20	1		*REAR TAILGATE MECHANISM LOCK STRIKER	Not Necessary	40.10 FL	*- FL
21	1		*REAR TAILGATE OUTER GARNISH	Deformed	261.60 FL	*261.60 FL
22	1		*REAR TAILGATE REMOTE CONTROL LOCK	Damaged	485.80 FL	*485.80 FL
23	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	57.00 FL	*- FL
24	1		*REAR TAILGATE WEATHER STRIP	Cut	299.15 FL	*299.15 FL
25	1		*FLOOR PANEL TOP TRIM CARPET	Not Necessary	800.00 FS	*- FS
26	1		*REAR BUMPER	Distorted	2,900.00 FS	*1,500.00 FS
27	1		*REAR BUMPER CENTER FIBER MOULDING	Cracked	800.00 FS	*600.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*SET REAR END PANEL TOP CLIPS	Necessary	30.00 FS	*20.00 FS
30	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
31	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
32	1		*REAR TAILGATE OUTER GARNISH FIBER MOULDING	Not Necessary	400.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
34	1		*REAR TAILGATE 8PAX STICKER	Necessary	15.00 FS	*15.00 FS
35	1		*REAR TAILGATE MTS M-TECHSPORTS EMBLEM	Necessary	150.00 FS	*70.00 FS
36	1		*REAR TAILGATE EMBLEM	Necessary	80.00 FS	*60.00 FS
37	1		*REAR TAILGATE FIBER NUMBER PLATE GARNISH	Cut	800.00 FS	*400.00 FS
38	1		*SET REAR TAILGATE INNER CARDBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*REAR TAILGATE INNER SOUND PROOF INSULATOR	Not Necessary	600.00 FS	*- FS
40	1		*SET REAR TAILGATE OUTER CARDBOARD CLIPS	Not Necessary	30.00 FS	*- FS
41	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
42	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
43	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*20.00 FS
44	2		*SET REAR TAILLAMP LOWER GARNISH CLIPS L/R	Necessary	60.00 FS	*20.00 FS
45	2		*REAR TAILLAMP LOWER GARNISH L/R	Torn	600.00 FS	*200.00 FS
46	2		*REAR TAILLAMP BACK RUBBER GASKET L/R	Necessary	51.60 FL	*51.60 FL
47	2		*REAR TAILLAMP L/R	Cracked	709.60 FL	*709.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,036.95	9,859.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,485.49	1,704.81
Total Parts (\$\$)	15,551.46	8,154.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING (TO FR)	New	50.00	30.00
2	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	150.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	1,000.00
5	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	0.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,800.00	1,200.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	80.00
8	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			3,950.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >