

Trans-cab Auto Services Pte Ltd

AAD1907-024

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9963X*Not Authored*
HLB 89201

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 JUL 2019

SHD 9963X

VF1ABL15AUC278147

RENAULT

LATITUDE

29.6.19

AXA

5/6/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	2,844.66
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	ROCKER PANEL CENTER RH	\$	990.25
1	BOOT REFLECTOR LAMP RH	\$	493.35
1	FENDER PANEL REAR RH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR RH	\$	671.45
1	WHEELARCH REAR RH	\$	543.47
1	BUMPER COVER REAR	\$	1,108.46
1	BUMPER LOWER REAR	\$	768.84
1	BUMPER BRACKET CTR REAR	\$	113.47
1	BUMPER BRACKET SIDE RH REAR	\$	135.97
1	BUMPER RETAINER RH REAR	\$	44.99
1	BUMPER REFLECTOR RH	\$	43.61
1	BUMPER BEAM REAR	\$	777.52
1	BUMPER BEAM BRACKET RH REAR	\$	225.95
1	TAILLAMP RH	\$	552.55
1	TAILLAMP PANEL RH	\$	986.70
TOTAL		\$	16,276.66
10%		\$	1,627.67
		\$	14,649.00

*X***Special Nett**

1	REAR DOOR STICKER '6555-3333'	\$	80.00	<i>60.00</i>
1	FENDER INNER TRIM CLIP RH	\$	28.00	<i>X</i>
1	TAILLAMP CLIP RH	\$	5.00	<i>X</i>
1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	<i>X</i>
2	REAR WINDSCREEN SEALANT	\$	80.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1907-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9963X

1	WINDSCREEN MOULDING	\$	nn	100.00	}	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
1	REAR RIGHT TYRE	\$	sh	300.00		
1	REAR RIGHT TYRE RIM	\$	sh	380.00		
1SET	PARKING AID	\$	sh	700.00		
1SET	REAR BUMPER CLIP	\$	nn	66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00		
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00		
1SET	BUMPER RETAINER CLIP RH RR	\$	nn	20.00		
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00		
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00		
1	EXHAUST MOUNTING REAR	\$	nn	17.82		
TOTAL		\$		2,042.82		
TOTAL PARTS		\$		16,691.82		

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	2001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	sh	380.00 X
To check steering geometry and computer wheel alignment	\$	sh	220.00 X
To rust-proofing of the affected areas.	\$	sh	170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	sh	170.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	sh	380.00 X

Trans-cab Auto Services Pte Ltd**AAD1907-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9963X

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>6601</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	<i>X</i>
TOTAL	\$	12,350.00	
Over All Total	\$	29,041.82	

LUMP SUM (REPAIR DAY)~~15 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: