

22/03/2002

ASS. REC. BY:

REF: CS/SMO190118721 GC d3⁵²

Special Instruction:

Surveyor:

GA

ASSIGNMENT (Office)

From (Person): Ruth (hua) Get. Tiang of SMO

Date/Time: 4.7.19 1517PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 2274K

Insured:

SKX 28466

at Workshop m/s: Heng Lok Automobile

Tel:

96601347

of 160 Sin ming Drive, #05-17

Policy No: DIBMT PR01018746

Claim No: CMTD1903201

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3.7.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.7.19 4.35PM

Person Contacted:

Han Wei

Vehicle IN/OUT

| Date/Time | Action/Instruction (X) Estimate |
|-----------|---------------------------------|
| | SLB 2274K - X |
| | SKX 28466 - X |
| | Dismantle: 10/7/2019 |
| | After repair: 15/7/2019 |
| | |
| | |
| | |

ASS. REC. BY:

REF SMO

PKS

ASSIGNMENT

From:

Date:

9.7.19

Veh No:

SLB 2274K

Yr Regn:

30 Mar 2016

Estimated Cost:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLB 2274K

Make:

Mazda 5

C.C.

1998

at Workshop n/s: Hap Let Automob. ll

Colour:

Black

A/C:

Insured / Std / NI / NA

of 160 sn mng Drive #105-17

Sp. Reading:

69132

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JM6CW 1071G 0123342

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)

Tyre Size:

F:

205/55R16

R:

11

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

5 days

Res.: Yes or No

D.O.A.

D.O.I.

09-07-19

Lum Sum:

%

3 Val: Yes or No

Survey held at

WKS

4:15 pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

5

1)

☐

Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

3 + RS, \$

Photos

Others

TOTAL

Report Format:

PRE

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 04 Jul 2019 | | 04 Jul 2019 15:17 Assign | | | | New Assignment Cancel Case |

| | | | | | | | | | |
|--|----------|--|------------|-------------------------------|---------|------------------------------------|--------------|--|-------|
| Main | | Reference | | Claim Details | | Documents | | Show All | |
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | | KOH KAY GUAN ALLAN, ID: S7904592F, Tel: +6596649672, Email: NOEMAIL | | | | | | | |
| Main Claimant: | | UNKNOWN3201 | | | | | | | |
| Vehicle Reg. No.: | | SLB2274K | | Date of Loss: | | 03/07/2019 07:00 - :59 | | | |
| Claim Type: | | TP / CMTD1903201 | | Policy/Cover Note No.: | | D18MTPV01018746 (Comprehensive) | | | |
| Vehicle Reg. No. (Insured): | | SKX2846G | | Policy No. (Claimant): | | Excess: | | | |
| Repairer: | | Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743 | | | | | | | |
| Handling Insurer: | | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153] | | | | | | | |
| Adjuster: | | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/07/2019] | | | | | | | |
| Driver/Custodian (Insured): | | KOH KAY GUAN ALLAN (40 / Male), NRIC: S7904592F, Tel: +6596649672 Email: NOEMAIL | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | | | | | View All Compose Case Mail | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | | | | | | | | |
| View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---------------------------|
| Date Of Report | 05/07/2019 14:26 |
| Date Of Accident | 03/07/2019 07:15 |
| Exact Location Of Accident | TPE TOWARDS SLE AT 11.5KM |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|-----------------------|
| Vehicle Registration Number | SLB2274K |
| Insured/Policyholder | |
| Name Of Registered Owner | TAN CHOON YONG |
| NRIC No | S1713814F |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97102914 |
| Alternative Phone No | OTHERS-97102914 |
| Vehicle Particulars | |
| Manufacturer | MAZDA |
| Model | 5 |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | LONPAC INSURANCE BHD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | Z19VP05022560 |
| Cover Note Number | |
| Driver | |
| Name of Driver | TAN CHOON YONG |
| NRIC No | S1713814F |
| Date Of Birth | 22/10/1965 |
| Occupation | INDOOR |
| Date Of Driving Pass | 30/11/1990 |
| Driving Experience | 28 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97102914 |
| Fax Number | |
| Contact Number | OTHERS-97102914 |
| Email Address | NOEMAIL |

| | |
|---|--|
| Address | BLK 338B ANCHORVALE CRESCENT #13-57 |
| Postcode | 542338 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 3 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SKX2846G |
| Vehicle Make/Model/Colour | HONDA |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SJX7447D |
|-----------------------------|----------|

Vehicle Make/Model/Colour

HIONDA FIX

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Person Ling Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

- (A) SLB 2274R
- (B) SKX 2846G
- (C) SJX 7447D

TPE towards SLE (At 11.5km)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03/07/19 @ about 7.15am, I am travelling along TPE towards SLE. There cars ahead of me (11.5km) slow down and stopped. I too slow down and stopped with safe keeping distance from the car ahead of me. When suddenly, I felt an impact on my rear portion when I got down, I found myself in a 3 car chain collision and I am the first vehicle. I felt my rear portion twice impact before I got down.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------|--|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 3814F |
| Vehicle No.: | SLB2274K |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 09 Jul 2019 |
| Vehicle Make: | MAZDA |
| Vehicle Model: | MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF |
| Primary Colour: | Black |
| Manufacturing Year: | 2016 |
| Engine No.: | PE10311646 |
| Chassis No.: | JM6CW1071G0123342 |
| Maximum Power Output: | 111.0 kW (148 bhp) |
| Open Market Value: | \$19,191.00 |
| Original Registration Date: | 30 Mar 2016 |
| First Registration Date: | 30 Mar 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$19,191.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Mar 2026 |
| PARF Rebate Amount: | \$14,393.00 |
| COE Expiry Date: | 29 Mar 2026 |
| COE Category: | E - Open Category |
| COE Period(Years): | 10 |
| QP Paid: | \$46,667.00 |
| COE Rebate Amount: | \$31,251.00 |
| Total Rebate Amount: | \$45,644.00 |

The information contained herein is correct as at 09 Jul 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|--|--|------------|---|
| Main | 04 Jul 2019 | | 04 Jul 2019 15:17 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

| | | | |
|-----------------------------|---|------------------------|---|
| Insured: | KOH KAY GUAN ALLAN, ID: S7904592F, Tel: +6596649672, Email: NOEMAIL | | |
| Main Claimant: | TAN CHOON YONG, ID: S1713814F | | |
| Vehicle Reg. No.: | SLB2274K | Date of Loss: | 03/07/2019 07:00 - :59 [39 Months and 3 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / CMTD1903201 | Policy/Cover Note No.: | D18MTPV01018746 (Comprehensive) |
| Vehicle Reg. No. (Insured): | SKX2846G | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743 | | |
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/07/2019] | | |
| Driver/Custodian (Insured): | KOH KAY GUAN ALLAN (40 / Male), NRIC: S7904592F, Tel: +6596649672 Email: NOEMAIL | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*SLB2274K (CMTD1903201)
[SKX2846G]
TP
TAN CHOON YONG
Jul 3 2019 7:00AM
[KOH KAY GUAN ALLAN]
Hiap Lek Automobile Trading

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#) [View in Browser](#) ▼




Photos/Images

3 per page ▼



| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
|----|-----------------|-----------------------------------|--|-----------|-------|
| 1 | 12/07/19 17:23 | General View | | Load JPG | |
| 2 | 12/07/19 17:23 | General View | | Load JPG | |
| 3 | 12/07/19 17:23 | General View | | Load JPG | |
| 4 | 12/07/19 17:23 | General View | | Load JPG | |
| 5 | 12/07/19 17:23 | General View | | Load JPG | |
| 6 | 12/07/19 17:23 | General View | | Load JPG | |
| 7 | 12/07/19 17:23 | General View | | Load JPG | |
| 8 | 12/07/19 17:23 | General View | | Load JPG | |
| 9 | 12/07/19 17:23 | General View | | Load JPG | |
| 10 | 12/07/19 17:23 | General View | | Load JPG | |
| 11 | 12/07/19 17:23 | General View | | Load JPG | |
| 12 | 12/07/19 17:23 | General View | | Load JPG | |
| 13 | 12/07/19 17:23 | General View | | Load JPG | |
| 14 | 12/07/19 17:23 | General View | | Load JPG | |
| 15 | 12/07/19 17:23 | General View | | Load JPG | |
| 16 | 12/07/19 17:23 | General View | | Load JPG | |
| 17 | 12/07/19 17:23 | General View | | Load JPG | |
| 18 | 12/07/19 17:23 | General View | | Load JPG | |
| 19 | 12/07/19 17:23 | General View | | Load JPG | |
| 20 | 12/07/19 17:23 | General View | | Load JPG | |
| 21 | 12/07/19 17:23 | General View | | Load JPG | |
| 22 | 12/07/19 17:23 | General View | | Load JPG | |
| 23 | 12/07/19 17:23 | General View | | Load JPG | |
| 24 | 12/07/19 17:23 | General View | | Load JPG | |
| 25 | 12/07/19 17:23 | General View | | Load JPG | |
| 26 | 12/07/19 17:23 | General View | | Load JPG | |
| 27 | 12/07/19 17:23 | General View | | Load JPG | |
| 28 | 12/07/19 17:23 | General View | | Load JPG | |
| 29 | 12/07/19 17:23 | General View | | Load JPG | |
| 30 | 12/07/19 17:23 | General View | | Load JPG | |
| 31 | 12/07/19 17:23 | General View | | Load JPG | |
| 32 | 12/07/19 17:23 | General View | | Load JPG | |
| 33 | 12/07/19 17:23 | General View | | Load JPG | |
| 34 | 12/07/19 17:23 | General View | | Load JPG | |
| 35 | 12/07/19 17:23 | General View | | Load JPG | |

| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 36 | 12/07/19 17:23 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 12/07/19 17:23 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 12/07/19 17:23 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 12/07/19 17:23 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 22/07/19 17:58 | Photographs of Damaged Parts | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 84 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 99 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 100 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 22/07/19 17:58 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 111 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 112 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 113 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 114 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 115 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 116 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 117 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 118 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 119 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 120 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 121 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 122 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 123 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 124 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 125 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 126 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 127 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 128 | 22/07/19 17:59 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 129 | 22/07/19 18:01 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 130 | 22/07/19 18:01 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 131 | 22/07/19 18:01 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page ▼ | ✓ |
|---------------|-----------------|--|--------------|-------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 132 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 133 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 134 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 135 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 136 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 137 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 138 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 139 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 140 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 141 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 142 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 143 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 144 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 145 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 146 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 147 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 148 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 149 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 150 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 151 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 152 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 153 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| 154 | 22/07/19 18:01 | Photo After Spray | 1 Load JPG | ✓ |
| Documentation | | | 1 per page ▼ | ✓ |
| No | Finalized On | Sompo Insurance Singapore Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 04/07/19 15:16 | PRI - NOT AGREED LKK | 1 Load HTM | |

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19011872/GCD3S2

Date: 30/07/2019

REFERENCE

| | | | |
|-----------------------|-------------------------------------|----------------------|-----------------|
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. | Policy No: | D18MTPV01018746 |
| Claimant Vehicle No : | SLB2274K | Insured Vehicle No : | SKX2846G |
| Date of Loss: | 03/07/2019 | Nature of Claim: | TP |
| | | Claim No: | CMTD1903201 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|----------------------------------|-------------|-------------------|
| Reg No: | SLB2274K | Engine No: | PE10311646 |
| Make & Model: | MAZDA 5, 2.0 SP.6EAT SUNROOF (A) | Chassis No: | JM6CW1071G0123342 |
| Reg. Date: | 30/03/2016 (Man. Year: 2016) | Odometer: | 69132 km |
| Colour: | Black | | |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55R16 | Rear Tyre Size: | 205/55R16 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 04/07/2019 | |
| Date Inspected: | 09/07/2019 | Inspected At: Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity Singapore 575722 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source:

Parts: N/A MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB2274K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >