

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0821/2019/DY/TG
Date : 3-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Dinesh Gang
Address : Blk 5 Tanjong Rhu Road
#09-03
Singapore 436882
Telephone : HP +65 91737346
Type of Claim : Own Damage Claims
Policy No. : 1800078078
Vehicle No : **SFB 1399 L**
Model Code : Audi A4 SEDAN 2.0 TFSI
Model / Year : 10/7/2018
Engine No : CVK 064183
Chassis No : WAUZZZF42JN015094
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jun-19
Place of Accident : Merging From Holland Rd > Holland Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle.SFB 1399 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00	\$ 00
3	To respray front bumper.	\$ 1,050.00	\$ 00
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>3,122.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFB 1399 L

S/N Parts Description		Damaged Parts & Prices S/Nett	
1	FRONT BUMPER <i>rehd</i>	\$	1,999.00 ✓
2	FRONT BUMPER FIXING PARTS <i>MC</i>	\$	258.00 +
3	FRONT BUMPER GRILLE <i>MC</i>	\$	178.00 +
4	FRONT BUMPER GRILLE CLOSING ELEMENT - LOWER CENTRE <i>MC</i>	\$	191.00 +
5	FRONT GRILLE AIR GUIDE - LH <i>MC</i>	\$	56.00 +
6	FRONT RADIATOR GRILLE <i>rehd</i>	\$	1,227.00 ✓
7	FRONT RADIATOR AIR GUIDE - LH <i>MC</i>	\$	123.00 +
8	FRONT BUMPER CARRIER ?	\$	733.00 ?
9	FRONT BUMPER CARRIER FOAM FILLER PIECE ?	\$	113.00 ?
10	FRONT BUMPER COVER <i>MC</i>	\$	116.00 +
11	CAUTION STICKER <i>MC</i>	\$	13.00 +
12	FRONT BUMPER CARRIER CLOSNG BRACKET <i>MC</i>	\$	207.00 +
13	CAUTION SIGN <i>MC</i>	\$	13.00 +
14	AC STICKER <i>MC</i>	\$	7.00 +
15	FRONT BUMPER COVER BRACKET <i>MC</i>	\$	125.00 +
16	FRONT BUMPER COVER SUPPORT - LH / RH <i>2</i>	2 \$	52.00 +
17	FRONT PARKING SENSOR <i>2</i>	2 \$	462.00 +
18	PARKING SENSOR SEAL RING <i>MC</i>	4 \$	12.00 +
19	HORN- HIGH TONE <i>MC</i>	\$	37.00 +
20	SPRING SHACKLE - LH <i>2</i>	\$	26.00 +
SUB TOTAL SPARE PARTS		\$	5,948.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFB 1399 L

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
21	FRONT LED HEADLIGHT - LH <i>me u</i>	\$ 7,087.00	<i>x</i>
22	FRONT HEADLIGHT LIFT CYLINDER - LH <i>me u</i>	\$ 192.00	<i>x</i>
23	RADIATOR AIR DUCT - OUTER <i>2</i>	\$ 25.00	<i>x</i>
24	RADIATOR AIR DUCT - INNER <i>me u</i>	\$ 11.00	<i>x</i>
25	RADIATOR AIR GUIDE - UPPER	\$ 15.00	<i>x</i>
26	RADIATOR AIR GUIDE - LOWER	\$ 19.00	<i>x</i>
TOTAL SPARE PARTS		\$ 13,297.00	
TOTAL LABOUR CHARGES		\$ 3,122.00	
GRAND TOTAL		\$ 16,419.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 04/07/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repair, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant