

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : **EQ INSURANCE COMPANY LTD**

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTMG/TP/1907/001
Policy No:	5102278012	Date of Loss:	29/06/2019
Vehicle Reg. No.:	SLR2451G	Driveable?	no
Driver Age:	25/09/1960	Third Party Vehicle No.:	SKZ7165U
Any Injuries?	no	Contact No:	90603548
Insured/Claimant:	SAM NG NETWORK	Driver:	NG YEOW MENG

Make/Model:	Mitsubishi, Attrage	Vehicle Reg. Date:	07/08/2017
Vehicle Colour:	Blue	Engine Number:	3A92UGB6003
Chassis No:	MMBSTA13AHH006376	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	2,747.70
Miscellaneous Items	495.00
Labour	840.00
Paintwork Labour	605.00
Towing	0.00
Gross Total(S\$):	4,687.70
GST 7.00%(S\$):	328.14
Nett Amount(S\$):	5,015.84

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER	0.00	660.00	-10.00	594.00
2	1	FRONT BUMPER SIDE RETAINER RH	0.00	18.00	-10.00	16.20
3	1	FRONT BUMPER BRACKET RH	0.00	25.00	-10.00	22.50
4	1	FRONT FOG LAMP GARNISH RH	0.00	120.00	-10.00	108.00
5	1	FRONT FOG LAMP CHROME RH	0.00	150.00	-10.00	135.00
6	1	FRONT HEADLAMP RH	0.00	544.00	-10.00	489.60
7	1	FRONT HEADLAMP LOWER BRACKET RH	0.00	70.00	-10.00	63.00
8	1	FRONT FENDER RH	0.00	0.00	0.00	0.00
9	1	FRONT WHEEL HUB RH	0.00	230.00	-10.00	207.00
10	1	FRONT KNUCKLE ARM RH	0.00	329.00	-10.00	296.10
11	1	FRONT KNUCKLE ARM BEARING RH	0.00	130.00	-10.00	117.00
12	1	FRONT LOWER ARM RH	0.00	304.00	-10.00	273.60
13	1	FRONT SHOCK ABSORBER RH	0.00	428.00	-10.00	385.20
14	1	FRONT STABILIZER BAR LINK RH	0.00	45.00	-10.00	40.50

Total Parts (\$\$) 2,747.70

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS	0.00	45.00	0.00	45.00
2	1	FRONT WHEEL RIM RH	0.00	450.00	0.00	450.00

Sub Total (\$\$) 495.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80.00
3	1	To Dismantle and Refit Front Undercarriage.	180.00	180.00	0.00	180.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	550.00	550.00	0.00	550.00

Gross Labour Cost (\$\$) 840.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and	480.00	480.00	0.00	480.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Sanding of Surfaces, Final Polishing and Waxing are also available.				

Gross Labour Cost (S\$) 605.00

< END OF ESTIMATES >

NAZ LKK

8/7/19 1315

826 215

2 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO

NAZ Naz@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: