Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12 Singapore 737856 Tel: 62562281 Fax: Email: YTMG

INSURER: EQ INSURANCE COMPANY LTD

PARTICULARS OF CLAIM

Claim Type: TP Ref. No: YTMG/TP/1907/001

Policy No: 5102278012 Date of Loss: 29/06/2019

Vehicle Reg. No.: SLR2451G Driveable? no

Driver Age: 25/09/1960 Third Party Vehicle No.: SKZ7165U Any Injuries? Contact No: 90603548

Insured/Claimant: SAM NG NETWORK Driver: NG YEOW MENG

Make/Model: Mitsubishi, Attrage Vehicle Reg. Date: 07/08/2017
Vehicle Colour: Blue Engine Number: 3A92UGB6003

Chassis No: MMBSTA13AHH006376 Odometer:

Total Loss? NO Est. Duration of Repair(Day)

Description of Accident/loss HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS		Amount
Parts		2,747.70
Miscellaneous Items		495.00
Labour		840.00
Paintwork Labour		605.00
Towing		0.00
	Gross Total(S\$):	4,687.70
	GST 7.00%(S\$):	328.14
	Nett Amount(S\$):	5,015.84

This claim is handled by: Sky Toh T C

Estimate Report 07/03/2019

REPAIR DETAILS

Estima	ates On Pa	rts				
No.	Qty	Particulars	Rate	Amount	%Disc	After
	_					Disc
1	1	FRONT BUMPER	0.00	660.00	-10.00	594.00
_2	1	FRONT BUMPER SIDE RETAINER RH	0.00	18.00	-10.00	16.20
3	1	FRONT BUMPER BRACKET RH	0.00	25.00	-10.00	22.50
4	1	FRONT FOG LAMP GARNISH RH	0.00	120.00	-10.00	108.00
5	1	FRONT FOG LAMP CHROME RH	0.00	150.00	-10.00	135.00
6	1	FRONT HEADLAMP RH	0.00	544.00	-10.00	489.60
7	1	FRONT HEADLAMP LOWER BRACKET RH	0.00	70.00	-10.00	63.00
8	1	FRONT FENDER RH	0.00	0.00	0.00	0.00
9	1	FRONT WHEEL HUB RH	0.00	230.00	-10.00	207.00
10	1	FRONT KNUCKLE ARM RH	0.00	329.00	-10.00	296.10
11	1	FRONT KNUCKLE ARM BEARING RH	0.00	130.00	-10.00	117.00
12	1	FRONT LOWER ARM RH	0.00	304.00	-10.00	273.60
13	1	FRONT SHOCK ABSORBER RH	0.00	428.00	-10.00	385.20
14	_ 1	FRONT STABILIZER BAR LINK RH	0.00	45.00	-10.00	40.50

Total Parts (S\$)	2,747.70

Estima	Estimates of Miscellaneous Items							
No.	Qty	Particulars	Rate	Amount	%Disc	After		
						Disc		
1	1	FRONT BUMPER CLIPS	0.00	45.00	0.00	45.00		
2	1	FRONT WHEEL RIM RH	0.00	450.00	0.00	450.00		

Sub Total (S\$) 495.00

Estim	Estimates On Labour							
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc		
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00		
2	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80.00		
3	1	To Dismantle and Refit Front Undercarriage.	180.00	180.00	0.00	180.00		
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	550.00	550.00	0.00	550.00		

Gross Labour Cost (S\$) 840.00

Estimates On Paint Work Labour							
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc	
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00	
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00	
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00	
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and	480.00	480.00	0.00	480.00	

No.	Qty	int Work Labour Particulars	Rate	Amount	%Disc	After Disc
	-	Sanding of Surfaces, Final Polishing and				
		Waxing are also available.				
			_			
		Gross Labour Cost	(S\$) __			605.00

< END OF ESTIMATES >