

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

KIM HIN AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30541

Date : 04-Jul-2019


PAGE : 1

Your Reference : V0020325

Accident Date : 03-Jul-2019

Our Ref : 190369 / SANDRA

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10
SOUTH TOWER
Singapore 048583



C/S Rep & ulc

5 days

Fax 62564315

Ex 8600

ESTIMATED COST OF REPAIR FOR SUBARU LEGACY 2.5I-S CVT (2016) SLJ828J

1 pc rear bumper	Bul/wr	350.00	c	✓
1 pc o/s rear bumper side retainer		25.00	c	?
10 pcs rear bumper clips	@ S\$ 2.00	20.00	c	✓
1 pc o/s rear fender	R	600.00	c	X
1 pc rear windscreen glass moulding	nn	50.00	c	X
1 pc o/s rear rim	nd	500.00	c	✓
1 pc o/s rear shock absorber		230.00	c	?
1 pc o/s rear shock absorber mounting		45.00	c	?
1 pc o/s rear shock absorber stopper		20.00	c	?
1 pc o/s rear shock absorber cover	sn	20.00	c	X
1 pc o/s rear knuckle arm		180.00	c	?
1 pc o/s rear knuckle arm bearing		140.00	c	?
1 pc o/s rear lower arm		100.00	c	?
1 pc o/s rear trailing arm		110.00	c	?
1 pc o/s rear lateral link		100.00	c	?
1 pc o/s rear upper arm		330.00	c	?
1 pc o/s rear stablizer bar linkage	sn	50.00	c	X
		2,870.00		
Add 10% :		287.00		
		3,157.00		
1 pc rear windscreen glass sealant	nn	40.00	sn	X
1 pc rear windscreen glass damping seal	nn	20.00	sn	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

SIN MING AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Page : 2

No. : 30541

Your Reference : V0020325

Our Ref : 190369

1 pc o/s rear tyre

602 320.00 sn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

700.00 500

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 60

To remove and refit rear windscreen
glass and conduct water leak test

nn 100.00 X

To dismantle and check rear under-
carriage. To replace affected
portions.

120.00 7

To conduct rear wheel alignment
test.

100.00 60

To putty and respray on affected
portions.

650.00 400

Total : S\$ 5,327.00

Singapore Dollars Five Thousand Three Hundred
and Twenty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.