

INS CASE OWNER:

CC 4, MG 190 11893, Uka3/VI DMC

Surveyor: MAPPEN DOI: 4/17/19 Date/Time: 4/17/19
Registered in Merimen: 4/17/19

Pre-assign / CCU / FEE:

SMJ 83194



Insured Vehicle No. : _____ Claim No. : _____
Name of Insured : ONG TIAO YOUNG KENNETH Policy No. : _____
Insured Tel No. : _____ HP: _____ Make / Model : _____
Excess Sec II :SS _____ D.O.A: 3/17/2019 Place of Accident : _____
Is driver the owner? () YES / NO () Nature of Accident : _____
If NO, Driver Name / Age : _____ OI GIA REPORT: () YES / NO () TP GIA REPORT: () YES / NO
Driver Tel No. : _____ (V/L:) YES / NO () Insured Liability : _____ % Final ? Yes / No

SKX 8756T



INSRS: _____
WSP: Impertum
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>28/5/19</u> <u>chancha</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>	
Pipal Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>	
Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>	
Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>	
LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>	
Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>	
PIR:	<input type="checkbox"/> <input type="checkbox"/>	
Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>	
LOD:	<input type="checkbox"/> <input type="checkbox"/>	
Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>	
Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>	
Others:	<input type="checkbox"/> <input type="checkbox"/>	

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
Repair Cost: L15 \$S 12,000 (12 days) Reduction: 49 % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % _____ (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____
Repair Cost: \$S _____
Loss of Rental (LOR): \$S _____ (_____ days)
Loss of Use (LOU): \$S _____ (\$ _____ x _____ days)
Loss of Income (LOI): \$S _____ (\$ _____ x _____ days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
GIA/LTA Search: \$S _____
Medical: \$S _____
Disbursement: \$S _____ (e.g. Tow/ Independent)
Legal Cost: \$S _____
Total: \$S _____ Global Sum \$S: _____
1) Claim status: Normal Reject/Private Settle
2) Report Format: WP
3) Survey fee: R250

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S _____ Name 1: _____
Payee 2: (Strike if N.A.) \$S _____ Name 2: _____
Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: SKX8756T
 at Workshop m/s: 1000
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKX8756T Yr Regn: 12-15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI

Make: Honda vezel c.c. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 86489 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: R411106164
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____
 R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u>	mm	R/Bal. <u>6</u>	mm
L/Bal. <u>6</u>	mm	L/Bal. <u>6</u>	mm
D.O.A. <u>3/7/19</u>		D.O.I. <u>4/7/19</u>	

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
None
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 606.
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS L1A 43369
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction
6/15/19 4:45 pm Rep 9/c. ref 16631
4/5 \$12,000 lawyer case
(Ref \$11,601.76 / 49%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____ Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)
 Report Format : _____
 Lump Sum / I.B.I: (\$ _____)
 TOTAL _____

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

3 July 2019

Vehicle No.: SKX 8756 T

Model: Honda Vezel

*not allowed
d/s = 12000
4/7/19
12 day
weight change*

QTY	List Items	DESCRIPTION	AMT S\$
1	Rear windscreen moulding	all	\$ 121.80 ✓
1	Rear tailgate	body ID	\$ 1,287.60 ✓
2	Rear tailgate dampers	1A	\$ 331.60 X
1	Rear tailgate inner trim board	TOP1	\$ 225.00 ✓
2	Rear tailgate lamps	285	\$ 570.00 IPC
1	Rear tailgate lock	3ent	\$ 269.50 ✓
1	Rear tailgate rubber	1W	\$ 227.00 ✓
1	Rear tailgate "VEZEL" emblem	all	\$ 56.20 ✓
2	Rear tailgate number plate lamps	11	\$ 97.00 X
1	Rear tailgate number plate garnish	one	\$ 185.50 ✓
2	Rear taillamps	180.50	\$ 1,390.00 IPC
1	Rear end panel	517.00	\$ 585.80 ✓
1	Rear end panel inner garnish	1W	\$ 160.50 ✓
1	Rear keyless sensor (1 set)	one	\$ 189.50 ✓
1	Rear bumper	DD	\$ 950.60 ✓
2	Rear bumpers - side	225.30	\$ 450.60 IPC
2	Rear bumper brackets	11	\$ 97.00 X
2	Rear bumper reflectors	151.00	\$ 303.80 IPC
2	Rear bumper side retainers	11	\$ 101.80 X
1	Rear floor board	one	\$ 187.60 X
1	Rear floor panel	body ID/one	\$ 1,145.70 ✓
1	Rear floor sponge tray board	TOP1	\$ 197.80 ✓
1	Rear exhaust silencer	1	\$ 840.30 X
2	Rear exhaust mountings	11	\$ 49.00 X
2	Rear fender inner trim boards	265.00	\$ 530.00 IPC
1	Rear fender wheel arch garnish -R/H	TOP1	\$ 300.70 ✓
1	Front bonnet	1	\$ 1,151.70 X
1	Front bonnet lock	11	\$ 145.00 X
2	Front bonnet side rubbers	11	\$ 156.60 X
2	Front bonnet seals	11	\$ 96.00 X
2	Front headlamps	1759.10 x 2 = 3518.20	\$ 3,569.00 ✓
2	Front headlamp lower brackets	one	\$ 150.60 ✓
1	Front grille	one	\$ 285.00 ✓
1	Front grille top outer garnish	562	\$ 195.30 ✓
1	Front grille logo	all	\$ 45.70 ✓
1	Front grille chrome moulding	142.50	\$ 285.00 IPC
1	Front bumper	26/00	\$ 1,085.40 ✓
2	Front bumper fog lamps	327.70	\$ 655.40 IPC
			\$ 18,672.60

11/7/19

vezel Price Range Depreciation 2015 Vehicle Type Submit Advanced Search

Home > Used Cars > ST Carz Pte Ltd > Honda Vezel 1.5A X

Honda Vezel 1.5A X

Overview Financial Insurance Accessories Similar Research Photos Map



Price Chart

Summary

Price	\$62,800	Reg Date	18-Dec-2015 (6yrs 5mths 12days COE left)
Depreciation	\$8,990 /yr <small>View models with similar depre</small>	Manufactured	2015
Mileage	43,330 km (12.2k /yr)	Transmission	Auto
Road Tax	\$682 /yr	DMV	\$19,541
Derog Value	\$43,957 as of today (change)	ARF	\$9,541
COE	\$56,989	Power	96.0 kW (128 bhp)
Engine Cap	1,496 cc	No. of Owners	1
Curb Weight	1,190 kg		
Type of Vehicle	SUV		

Features

Powerful 1.5L I-VTEC Engine Producing 128Bhp, Earth Dream Technology, Keyless Entry/Start/Auto Brake Hold, Cruise Control, Electric Park Brake. View specs of the Honda Vezel (2014)

Accessories

2 Tone Leather Upholstery Seats, Pioneer DVD Player With Reverse Camera, 18" S/Rims, Fog Lamps, v-kool Solar Films, Smart Entry Push Start/Stop.

Description

New Arrival! 1 Owner Since New! Not Grab And Go-Jek Unit! 6 Months Warranty Provided! Excellent Condition! Very Well Maintained By Previous Owner! View To Believe! Bank Loan Or In-house Loan Available! Trade In Most Welcome! Call/SMS/WhatsApp Our Friendly Sales Consultant Today To Arrange For Viewing And Test Drive!

Category

MPV Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 03-Jul-2019 | Last Updated on: 03-Jul-2019

Upfront Payment		more Financial info
Transfer Fee	\$25	
Down Payment	\$18,840 (change)	Maximum 70% Loan

Click on the point to view the vehicle.

Shortlist Compare Add note
Report Error More Actions

Seller Information

Company	ST Carz Pte Ltd = dealer's pricelist = 46 vehs sold 21 vehs available	
Address	210 Turf Club Road Lot 848/50 Search cars nearby this location	
Location	Car Mall @ The Grandstand	
Office No	64654747	
Contact Person(s)	Ryan Chris Liao Harry Yee	90778009 83565566 82289729

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more

vezel Price Range Deprecation 2015 Vehicle Type Submit Advanced Search

Home > Used Cars > Direct Owners > Honda Vezel 1.5A X

Honda Vezel 1.5A X

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$64,900	Reg Date	11-Dec-2015 (6yrs 5mths 5days COE left)
Depreciation	\$9,370 /yr <small>View models with similar depre</small>	Manufactured	2015
Mileage	47,000 km (13.2k /yr)	Transmission	Auto
Road Tax	\$682 /yr	OMV	\$19,087
Dereg Value	\$43,507 as of today (change)	ARF	\$9,087
COE	\$56,989	Power	96.0 kW (128 bhp)
Engine Cap	1,496 cc	No. of Owners	2
Curb Weight	1,190 kg		
Type of Vehicle	SUV		



Features

1.5L 4 Cylinder Inline DOHC I-VTEC Engine, CVT (A) Transmission, Keyless Entry/Engine Start, 8 Airbags, Auto Headlights, Cruise Control, Brake Hold. View specs of the Honda Vezel

Accessories

Pioneer Touch Screen Infotainment System With DVD And Bluetooth. Executive Brown Leather Seats.

Description

Well Maintained. 3 Years Old. Low Mileage. Only Used For Daily Commute To And From Office At CBD.

Category

PA&F Car, Direct Owner Sale

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 02-Jul-2019 | Last Updated on: 02-Jul-2019

Upfront Payment

> more Financial info

Transfer Fee	\$25	
Down Payment	\$19,470 (change)	Maximum 70% Loan
1st Instalment	\$703	Based on 2.99% interest rate

Compare



Shortlist Compare Add note
Report Error More Actions

Seller Information

Contact Person(s) Mr Chong
Contact No. 96587671
Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

- Indemnity form
- Receipt
- Ownership Transfer
- Sales agreement
- Hand-over form

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 4257D

Vehicle Details

Vehicle No.: SKX8756T
 Vehicle to be Exported: No
 Intended Deregistration Date: 04 Jul 2019
 Vehicle Make: HONDA
 Vehicle Model: VEZEL 1.5X CVT
 Primary Colour: Blue
 Manufacturing Year: 2015
 Engine No.: L15B4026155
 Chassis No.: RU11106164
 Maximum Power Output: 96.0 kW (128 bhp)
 Open Market Value: \$19,413.00
 Original Registration Date: 30 Dec 2015
 First Registration Date: 30 Dec 2015
 Transfer Count: 0
 Actual ARF Paid: \$9,413.00 *4706*

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 29 Dec 2025
 PARF Rebate Amount: \$7,059.00

Intended COE Rebate Details

COE Expiry Date: 29 Dec 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Period(Years): 10
 QP Paid: \$56,001.00
 COE Rebate Amount: \$36,310.00
Total Rebate Amount: \$43,369.00

The information contained herein is correct as at 04 Jul 2019

OK

PRE-REPAIR INSPECTION REQUEST – SKX8756Tvs SMJ8319Y (OI) on D.O.A.: 03/07/2019

From: Hor, Yinnul
To: 'asagments@kkauto.com'; Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Manessa; Azlan, Sykazairina; Chan, Yoke Shi; Lim, Sheng Yang; Mithosingh, Ashweenjeetkaur; Subramanian, Divyashri; Tan
Sent: Thursday, 4 July 2019 10:04:45 AM
Attachments: [PRE-REPAIR.pdf](#)

Hi,

Please refer to the enclosed request from IMPERIUM AUTOMOTIVE.
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rai (Vivian)
AIG
Claim Advisor @ Singapore PSC, Claims Operations - Auto
Yinnul.Hor@aig.com | www.aig.com

P. SHAWN
T. 3.31p.m
V: lh
E: ✓

From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]
Sent: Thursday, July 04, 2019 9:51 AM
To: Hor, Yinnul
Subject: [EXTERNAL] ACCIDENT INVOLVING SKX8756T, SMJ8319Y AND OTHERS ON 3 JULY 2019.

This message is from an external sender; be cautious with links and attachments.

Your ref: SMJ8319Y
Our ref: JEQ/SKX8756T/IMP

Dear Sir,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

Mr. Marcus Chua- LKK Auto Consultants Pte Ltd.

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

IMPERIUM AUTOMOTIVE
25 Kaki Bukit Road 4 #01-49,
Synergy@KB
Singapore 417800
Tel:9748 9940 Fax: 6346 7213
Mr. Shawn Tan

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com
To: alfred_ng@juseq.com.sg
Cc: Andy-SY.Fong@aig.com; Lee-Ying.Chin@aig.com; Baljit.Kaur@aig.com; NoorManessa.AbuKassim@aig.com; Sykazairina.Azlan@aig.com; YokeShi.Chen@aig.com; ShengYang.Lim@aig.com; Ashweenjeetkaur.Mithosingh@aig.com
Subject: aigenory@ PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMJ8319Y AND SKX8756T ON 03/07/2019
Date: Thu, 4 Jul 2019 01:00:26 +0000
Without Prejudice

Your Reference : JEQ/SKX8756T/IMP
Our Reference : SMJ8319Y

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kint	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formiteam Adjusters Pte Ltd
Ng You Han	Formiteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formiteam Adjusters Pte Ltd
Chow Bo Xiong	Formiteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formiteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Gao Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adnan Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasid	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Mr. Yin Hui (Yinhuai)

AIG

Chief Adjuster II, Singapore PRCI Claims Department – Auto

Youf.Hui@aig.com www.aig.sg

From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]
Sent: Wednesday, July 03, 2019 2:52 PM
To: Hor, Yinrul
Subject: [EXTERNAL] NOTICE OF ACCIDENT

This message is from an external sender; be cautious with links and attachments.

Your ref: SMJ8319Y
 Our ref: JEQ/SKX8756T/IMP

Dear Yinrul,

Kindly refer to our attachment for your necessary actions.

With Regards

Alfred Ng
 Executive
 On behalf of Mr Michael Yap
 M/s JusEquity Law Corporation
 No. 171 Chin Swee Road
 #02-01/02/06 Singapore 169877
 Tel : 6536 9339
 Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone (65) 6536 9339,

Fax : (65) 6536 5368 (Litigation & Conveyancing)

Email : claims@juseq.com.sg

website : www.juseq.com.sg

Our Ref: JEQ/SKX8756T/IMP (zl)

Your Ref: SMJ8319Y

3 July 2019

ONG TIOW YOONG KENNETH
(WANG ZHURONG KENNETH)
138C Lorong 1A Toa Payoh #10 – 36
Singapore 313138

By Post Only

AIG ASIA PACIFIC INSURANCE PTE LTD
Singapore

By Fax: 6835 7416 Only

Dear Sir

ACCIDENT INVOLVING SKX8756T & SMJ8319Y ON 03.07.2019

We act for the owner of vehicle no. SKX8756T.

We hereby notify you of a road traffic accident on 3 July 2019 at about 0800 hrs, along Adam Road involving our client's vehicle and vehicle registration no. SMJ8319Y driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jul 2019 Edit Reg		04 Jul 2019 00:00 Edit Adj Rpt	S\$12,000.00 Edit Estimates	S\$12,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	ONG TIOW YOONG KENNETH , ID: S7104023B								
Main Claimant:	WONG CHEE BENG , ID: S1524257D								
Vehicle Reg. No.:	SKX8756T	Date of Loss:	03/07/2019 07:00 - :59 [42 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3563534392SG	Policy/Cover Note No.:	1900078820 (Comprehensive) Coverage: 22/03/2019 - 21/03/2020						
Vehicle Reg. No. (Insured):	SMJ8319Y	Policy No. (Claimant):	D18MPC0003377						
		Excess:							
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/07/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKX8756T (3563534392SG)**
[SMJ8319Y]
TP
WONG CHEE BENG
Jul 3 2019 7:00AM
[ONG TIOW YOONG KENNETH]
Imperium Automotive - Kaki Bukit

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
2	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
3	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
4	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
5	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
6	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
7	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
8	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
9	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
10	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
11	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
12	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
13	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
14	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
15	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
16	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
17	28/08/19 12:04	General View							Load JPG	<input checked="" type="checkbox"/>		
18	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
19	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
20	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
21	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
22	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
23	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
24	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
25	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
26	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
27	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
28	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
29	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
30	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
31	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
32	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
33	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
34	28/08/19 12:04	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
35	28/08/19 12:05	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
36	28/08/19 12:05	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		
37	28/08/19 12:05	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	28/08/19 12:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	28/08/19 12:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/19 20:03	ACKNOWLEDGEMENT EMAIL TO AIG DD 04.07.2019	 Load PDF	
2	04/07/19 20:03	EMAIL FROM AIG DD 04.07.2019	 Load PDF	
3	04/07/19 20:03	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/07/19 09:26	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011893/UKA3Q2

Date: 29/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900078820	
Claimant Vehicle No: SKX8756T	Insured Vehicle No: SMJ8319Y	
Date of Loss: 03/07/2019	Nature of Claim: TP	Claim No: 3563534392SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX8756T		
Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)	Engine No: L15B4026155	
Reg. Date: 30/12/2015 (Man. Year: 2015)	Chassis No: RU11106164	
Colour: Blue	Odometer: 86489 km	
Engine Capacity: 1496 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,071.76	11,583.68	7,488.08	39.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	3,420.00	1,110.00	24.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,601.76	15,003.68	8,598.08	36.43
Approved Total (Overridden) (S\$)		12,000.00		
Nett Amount (S\$)	23,601.76	12,000.00	11,601.76	49.16
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	04/07/2019	
Date Inspected:	04/07/2019 Inspected At:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	121.80 FL	*121.80 FL
2	1		*REAR TAILGATE	Badly Dented	1,287.60 FL	*903.20 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	331.60 FL	*- FL
4	1		*REAR TAILGATE INNER TRIM BOARD	Torn	225.00 FL	*225.00 FL
5	1		*REAR TAILGATE LAMPS	O/S Cracked	570.00 FL	*285.00 FL
6	1		*REAR TAILGATE LOCK	Bent	269.50 FL	*269.50 FL
7	1		*REAR TAILGATE RUBBER	Twisted	227.00 FL	*227.00 FL
8	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
9	2		*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	97.00 FL	*- FL
10	1		*REAR TAILGATE NUMBER PLATE GARNISH	Cracked	185.50 FL	*185.50 FL
11	1		*REAR TAILLAMPS	O/S Cracked	1,390.00 FL	*560.50 FL
12	1		*REAR END PANEL	Badly Dented	585.80 FL	*517.00 FL
13	1		*REAR END PANEL INNER GARNISH	Twisted	160.50 FL	*160.50 FL
14	1		*SET REAR KEYLESS SENSOR	Cracked	189.50 FL	*189.50 FL
15	1		*REAR BUMPER	Dented	950.60 FL	*762.00 FL
16	1		*REAR BUMPER -SIDE	O/S Deformed	450.60 FL	*225.30 FL
17	2		*REAR BUMPER BRACKETS	Not Necessary	97.00 FL	*- FL
18	1		*REAR BUMPER REFLECTORS	O/S Cracked	303.80 FL	*151.00 FL
19	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	101.80 FL	*- FL
20	1		*REAR FLOOR BOARD	Serviceable	187.60 FL	*- FL
21	1		*REAR FLOOR PANEL	Badly Dented / Buckled	1,145.70 FL	*1,145.70 FL
22	1		*REAR FLOOR SPONGE TRAY BOARD	Torn	197.80 FL	*197.80 FL
23	1		*REAR EXHAUST SILENCER	Repair	840.30 FL	*- FL
24	2		*REAR EXHAUST MOUNTINGS	Not Necessary	49.00 FL	*- FL
25	1		*REAR FENDER INNER TRIM BOARDS	O/S Deformed / Torn	530.00 FL	*265.00 FL
26	1		*REAR FENDER WHEEL ARCH GARNISH -R/H	Torn	300.70 FL	*300.70 FL
27	1		*FRONT BONNET	Repair	1,151.70 FL	*- FL
28	1		*FRONT BONNET LOCK	Not Necessary	145.00 FL	*- FL
29	2		*FRONT BONNET SIDE RUBBERS	Not Necessary	156.60 FL	*- FL
30	2		*FRONT BONNET SEALS	Not Necessary	96.00 FL	*- FL
31	2		*FRONT HEADLAMPS	Cracked	3,569.00 FL	*3,518.20 FL
32	2		*FRONT HEADLAMP LOWER BRACKETS	Cracked	150.60 FL	*150.60 FL
33	1		*FRONT GRILLE	Cracked	285.00 FL	*285.00 FL
34	1		*FRONT GRILLE TOP OUTER GARNISH	Scratched	195.30 FL	*195.30 FL
35	1		*FRONT GRILLE LOGO	Necessary	45.70 FL	*45.70 FL
36	1		*FRONT GRILLE CHROME MOULDING	N/S Scratched	285.00 FL	*142.50 FL
37	1		*FRONT BUMPER	Deformed / Dented	1,085.40 FL	*762.00 FL
38	1		*FRONT BUMPER FOG LAMPS	O/S Cracked	655.40 FL	*327.70 FL
39	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	90.40 FL	*- FL
40	1		*FRONT BUMPER LOWER GRILLE	Twisted	185.00 FL	*185.00 FL
41	1		*REAR BUMPER REINFORCEMENT	Bent	321.40 FL	*321.40 FL
42	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	120.60 FL	*- FL
43	1		*REAR BUMPER TOW HOOK COVER	Cut	48.00 FL	*48.00 FL
44	1		*FRONT SUPPORT PANEL	Repair	576.00 FL	*- FL
45	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	90.30 FL	*- FL
46	2		*FRONT SUPPORT PANEL SIDE GARNISHES	Not Necessary	141.00 FL	*- FL
47	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	135.00 FL	*- FL
48	1		*HORN	Not Necessary	80.00 FL	*- FL
49	1		*AIR CON CONDENSER	Not Necessary	748.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*RADIATOR SIDE GARNISHES	Not Necessary	131.40 FL	*- FL
51	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
52	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
53	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
54	1		*REAR BUMPER LOWER TRAY	Distorted	480.00 FS	*350.00 FS
55	1		*REAR REVERSE SENSOR BUZZER	Not Necessary	150.00 FS	*- FS
56	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
57	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
58	1		*FRONT BUMPER LOWER SPOILER	Deformed	750.00 FS	*680.00 FS
59	1		*FRONT NUMBER PLATE WITH HOLDER	Cracked	50.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (S\$)	23,339.70	14,129.60
- List Item Discount on L Items 20.00/20.00% (S\$)	4,267.94	2,545.92
Total Parts (S\$)	19,071.76	11,583.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE,REFIT AIR-CON CONDENSER AND CONDUCT LEAKAGE TEST	New	120.00	0.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
8	TO APPLY TUFF KOTE	New	250.00	100.00
9	PANEL BEATING	New	1,800.00	1,500.00
10	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	1,500.00
Gross Labour Cost (S\$)			4,530.00	3,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >