

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0820/2019/DY/TG
Date : 3-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Merry Gunawan
Address : 11 Nanthan Road
#23-03
Singapore 248732
Telephone : HP +65 96688927
Type of Claim : Own Damage Claims
Policy No. : 1700056957-01
Vehicle No : **SDM 8858 Z**
Model Code : Audi Q5 SPORT 2.0 TFSI qu
Model / Year : 27/9/2017
Engine No : DAX 012912
Chassis No : WAUZZZF3H2048510
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jun-19
Place of Accident : At traffic light along Maxwell Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDM 8858 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper and both headlights. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,400.00 ✓ 850	500 ✓ Bumper : 550. 850
3	To respray front bumper, front bumper spoiler and both front wheel arch trims. ✓	\$ 2,800.00 ✓	Arch : 280 x 2 = 400.
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓ 850.
TOTAL LABOUR CHARGES		: <u>\$ 5,872.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDM 8858 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair torn</i>	\$ 2,364.00	+ 1891.20
2	FRONT BUMPER FIXING PARTS	\$ 244.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH	\$ 67.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	\$ 202.00	+
5	FRONT BUMPER GRILLE - CENTER	\$ 129.00	+
6	FRONT BUMPER SPOILER	\$ 685.00	+
7	FRONT BUMPER UNDERRUN BAR - SILVER	\$ 431.00	+
8	FRONT BUMPER CLOSING ELEMENT LOWER	\$ 156.00	+
9	RADIATOR GRILLE <i>Cracked</i>	\$ 3,258.00	✓ 266.40
10	"QUATTRO" EMBLEM <i>new</i>	\$ 87.00	✓ 69.28
11	RADIATOR GRILLE CLOSING ELEMENT <i>Not new.</i>	\$ 222.00	? X 414.80
12	FRONT BUMPER AIR GUIDE GRILLE LH / RH <i>LH cracked</i>	\$ 1,037.00	518.50
13	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH <i>LH cracked</i>	\$ 165.00	82.50 65.84
14	FRONT BUMPER LOCKING CLIP <i>new</i>	\$ 15.00	+
15	FRONT BUMPER CARRIER <i>new Bent</i>	\$ 831.00	+ 664.40
16	FOAM FILLER PIECE <i>new cracked.</i>	\$ 259.00	+ 207.20
17	FRONT BUMPER TOP COVER <i>new</i>	\$ 116.00	+
18	"CAUTION SIGN" STICKER	\$ 13.00	+
19	"AIR COND " STICKER	\$ 18.00	+
20	HORN - LOW TONE FOR LEFT	\$ 178.00	+
TOTAL SPARE PARTS		\$ 10,477.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDM 8858 Z

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remark
21	HORN - HIGH TONE FOR RIGHT	2	\$	178.00	+
22	FRONT PARKING AID SENSOR - INNER	2	\$	462.00	+
23	FRONT PARKING AID SENSOR - OUTER		\$	231.00	+
24	SEAL RING	4	\$	12.00	+
25	FRONT WHEEL HOUSING LINER - LH		\$	246.00	+
26	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS		\$	35.00	+
27	FRONT WHEEL SPOILER - LH		\$	146.00	+
28	FRONT WHEEL COVER - LH / RH		\$	1,153.00	922.40
29	FRONT HEADLIGHT MOUNTING - LH / RH	2	\$	214.00	+
30	FRONT HEADLIGHT - LH / RH	2	\$	14,454.00	+
31	FRONT HEADLIGHT LIFT CYLINDER - LH / RH	2	\$	255.00	+
32	FRONT RADIATOR AIR GUIDE - LH / RH	2	\$	100.00	+
33	FRONT RADIATOR AIR GUIDE - CENTER		\$	37.00	+
34	FRONT RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	85.00	+
35	FRONT NO. PLATE	S/N	\$	40.00	40
36	SUNDRIES		\$	400.00	23.76
TOTAL SPARE PARTS			\$	28,525.00	
TOTAL LABOUR CHARGES			\$	5,872.00	
GRAND TOTAL			\$	34,397.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 04/07/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant