

ASS REC. BY:

REF: CS1 MSG 19011901 / AG vcl302

Special Instruction:

Survivor: Adrian ASSIGNMENT (Office)

From (Person): Jasmine LOK Hai Kwei of MSIG Date/Time: 5.7.19 9:57am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 9828H Insured: YIN 25842

at Workshop m/s Hiep Hong Motor Tel: 67459623

of 2 Kaki Bukit Ave 2 # 02-13

Policy No: A29127138M KC Claim No: 598770

Sum Insured: Excess:

Make of Veh: D.O.A. 4.7.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5.7.19 10:04am Person Contacted: Ah Kat Vehicle: IN / OUT


Date/Time	Action/Instruction (✓) Estimate
	SLR 9828H - NAIT MT 19011833/13 12.01 - 04/07/2019
	YIN 25842 - X
5/7/19	Informed Jasmine pending workshop est by merimen
26/7/19	Adrian confirmed LS \$4000 (Real 4855, 55/9)
26/7/19	Send preli revised via merimen

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLR9828H
 at Workshop n/s Hiap Hong
 of 2 Kaki Bukit Ave 2 #02-13
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : **Yes or No**
 GIA / PR Seen: _____ Consistent? : **Yes or No**
 Est. Repairs: _____ days Res.: **Yes or No**
 Lum Sum: _____ % 3 Val.: **Yes or No**
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

N/S	O/S

Veh No: SLR9828H Yr Regn: 2015 Oct.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Altis c.c. 1598
 Colour: White A/C: **Insured / Std / NI / NA**
 Sp. Reading: 45680 T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: M2053REH104542074
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 05/07/19
 Survey held at Hiap Hong
 Des. of Damages: **Frnt / Rear / O/S / N/S / U/C / Rooftop** or
Rear o/s., Frnt o/s.
 The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	<u>TPMS16</u>
	RECEIVED 29 JUL 2019
	 <u>26/7/2019</u>

Date/Time, File Pass to? : **Preli. Report**
 : **Final Report**
 1) _____
 Date/Time, File Return to?
 2) 26/7 - typist
 Report Format: merimen
 Long Form / Short L/S \$4000+
 Days Of Repair: 6
 Resurvey No. of Trip: 2
 Artd Fee: : Site Insp (\$) : Interview (\$) : Tech. Insp (\$) : Wash and
 Survey Fee: 190
 Transportation: _____
 Photos: _____
 Other: 11
 P/S: 161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2019 16:19		05 Jul 2019 09:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	NTT TRANSPORT PTE LTD, Co. Reg. No.: 200008686D								
Main Claimant:	KM CONSTRUCTION CO (S) PTE. LTD., Co. Reg. No.: 199908291C								
Vehicle Reg. No.:	SLR9828H	Date of Loss:	04/07/2019 10:00 - :59 [44 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598770	Policy/Cover Note No.:	A29127138MKC (Comprehensive) Coverage: 28/05/2019 - 27/05/2020						
Vehicle Reg. No. (Insured):	YN2584Z	Policy No. (Claimant):	Excess:						
Repairer:	Hiap Hong Motor Repair (HQ) 2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 67459633								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/07/2019]								
Driver/Custodian (Insured):	CHANDRAN A/L MARATHAMUTHU (/ Male) , NRIC: G7652828X Email:								
Adj Asg. Remarks:	on WP. Liab: Dispute. Agree on SJE. Assign: Adrian Ling from LKK Auto Consultants. Contact: 6745 9633.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

Attn: Jasmine Lok Kheng Kwei **Date:** 26 Jul 2019

Preliminary Advice

Insured Vehicle No : YN2584Z	Accident Date : 04/07/2019
TP Vehicle No : SLR9828H	Assignment Date : 05/07/2019
Make : TOYOTA COROLLA ALTIS	Est. Duration of Repair : 6
Date of Inspection : 5/7/2019	
Inspection At : HIAP HONG MOTOR REPAIR	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s and front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,855.00
Revised Amount	:S\$	4,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,000.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SLR9828H (598770)**
[YN2584Z]

TP
KM CONSTRUCTION CO (S) PTE. LTD.
Jul 4 2019 10:00AM
[NTT TRANSPORT PTE LTD]
Hiap Hong Motor Repair

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 05/07/2019 17:50 PM.
To MSIG_JLKK
Subject TP SURVEY SLR 9828H

Dear Jasmine,

Please be informed that we have inspected the vehicle SLR 9828H on 5/7/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Friday, 5 July 2019 9:14 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

Importance: High

ACCIDENT ON 4TH JULY 2019 @ 10:30 HRS INVOLVING MOTOR-VEHICLES NOS. SLR9828H & YN2584Z ALONG KAKI BUKIT INDUSTRIAL TERRACE TWDS LOYANG (Your Ref: YN2584Z) (Our Ref: TSC.SLR9828H.Accid.2019(HH)-ak)

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Tng Soon Chye [<mailto:tsclex@singnet.com.sg>]
Sent: Thursday, 4 July, 2019 6:16 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>; Helene Phua <helene_phua@sg.msig-asia.com>
Subject: ACCIDENT ON 4TH JULY 2019 @ 10:30 HRS INVOLVING MOTOR-VEHICLES NOS. SLR9828H & YN2584Z ALONG KAKI BUKIT INDUSTRIAL TERRACE TWDS LOYANG (Your Ref: YN2584Z) (Our Ref: TSC.SLR9828H.Accid.2019(HH)-ak)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

IMMEDIATE ATTENTION

Dear Sirs,

We refer to your fax dated 4th July 2019 to us.

Our client instructs that he agrees to the appointment of Adrian Ling of M/s LKK Auto Consultants Pte Ltd as a single joint expert for the pre-repair inspection of the vehicle **SLR9828H** at the workshop, **Hiap Hong Motor Repair**, situated at **2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921 (tel: 6745 9633)**.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Thank You & Best Regards,

M/s Tng Soon Chye & Co
150 South Bridge Road
#02-19
Fook Hai Building
Singapore 058727

Confidentiality: This e-mail and its attachments are intended for the above named only and may be confidential. If they have come to you in error you must take no action based on them, nor must you copy or show them to anyone; please reply to this e-mail and highlight the error. The firm reserves the right to monitor all incoming and outgoing e-mail.

Security Warning: Please note that this e-mail has been created in the knowledge that Internet e-mail is not a 100% secure communications medium. We advise that you understand and observe this lack of security when e-mailing us.

Viruses: Although we have taken steps to ensure that this e-mail and attachments are free from any virus, we advise that in keeping with good computing practice the recipient should ensure they are actually virus free

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 04/07/2019 11:48
 Date Of Accident 04/07/2019 10:30
 Exact Location Of Accident KAKI BUKIT INDUSTRIAL TERRACE TWDS LOYANG
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR9828H
 Insured/Policyholder
 Name Of Registered Owner KM CONSTRUCTION CO(S)PTE.LTD.
 Co Reg No -
 Email Address INFO@KMCONSTRUCTION-CS.COM
 Mobile Phone No
 Alternative Phone No OFFICE-67412404

Vehicle Particulars

Manufacturer TOYOTA
 Model ALTIS
 Exact Purpose for which vehicle was being used at time of accident WORKING
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number MU010441
 Cover Note Number

Driver

Name of Driver FOXALL MICHAEL JOHN
 Passport No/FIN G3455993M
 Date Of Birth 26/05/1987
 Occupation OUTDOOR
 Date Of Driving Pass 15/08/2018
 Driving Experience 0 YEAR AND 10 MONTH
 Gender MALE
 Mobile Number (LOCAL) +65-94566509
 Fax Number
 Contact Number
 EMail Address MICHAEL.FOXALL@KMCONSTRUCTION-CS.COM

Address 45 WOO MON CHEW ROAD
 Postcode 455122
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING FROM KAKI BUKIT INDUSTRIAL TERRACE TWDS LOYANG. WHEN I WANTED TO MAKE A LEFT TURN AHEAD THERE WAS VEH PARKED SO I HAVE TO STOP AT THE JUNC TO GIVE WAY FOR THE VEH B. WHILE VEH B MAKING A RIGHT TURN HIS LEFT SIDE PORTION OF HIS VEH HIT ONTO MY REAR RIGHT SIDE PORTION OF MY VEH. I TRY TO BREAK FREE MY VEH AND MY FRT RIGHT SIDE PORTION HIT ONTO THE KERB.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN2584Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver CHANDRAN A/L MARATHAMUTHU
 NRIC/Passport Number 4 01799583
 Contact Number 82458145
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

04 July 19


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls refer to the statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: _____
Date & Time: _____



Driver's Signature: *pmocuw*
(If driver is not the policyholder)
Date & Time: _____

04 July 19

Reporting Centre Personnel's Signature: *sfur*
Name: _____
NRIC/FIN No.: 04107119

SCR9828H.

-PMSIG.
Verion.

Toyota Altis 1598cc.

MROS3REN104542074.

Rear Bumper	tom	564.10 ✓
Rear Bumper Clips.	m	30 ✓
Rear Bumper Side Holder RH	Other	94 ✓
Taillamp RH	could	495.30 ✓
Taillamp Lower Bracket RH	m	58 X
Taillamp Sponge Gasket.	m	20. X
Taillamp Panel RH.	Broken.	388.20 ✓
Bootlid.	Dented	755 ✓
Bootlid Weatherstripe.	m	175.10 X
Bootlid Reflector.	could	381.90 ✓
Toyota Logo.	?	66.10 ✓
Corolla Wording	✓	58.60 ✓
Altis Wording.	✓	55.40 ✓
Rear RH Fender.	Distorted	977.70 ✓
Rear RH Fender Inner Trim.	14 m	379.50. X
Rear RH Fender Lower Trim Clips.	10	30. ✓

SLR9828H.

Reer Windscreen Moulding? ~~Net~~ 86.10 ✓
 Reer Windscreen Sealant 60(SN) ✓
 Reer RH Wheel Rim HP M850(SN) X

Panel Beating.	1200	900
Spony Painting.	1200	700
Wiring.	150	30
To underscul.	150	60
To remove upholstery.	150	80
To remove reverse sensor.	100	50
To transfer bootlid fittings.	150	60
To remove reer windscreen.	180	120
To perform wheel alignment.	150	X

List: 3982.40

Len 25%: 2986.80

S.N: 60

Labour: 2000

total: 5046.80

4/5: HK.

06 Days.


 26/7/19

8855

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2019 16:19		05 Jul 2019 09:57 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NTT TRANSPORT PTE LTD, Co. Reg. No.: 200008686D								
Main Claimant:	KM CONSTRUCTION CO (S) PTE. LTD., Co. Reg. No.: 199908291C								
Vehicle Reg. No.:	SLR9828H	Date of Loss:	04/07/2019 10:00 - :59 [44 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598770	Policy/Cover Note No.:	A29127138MKC (Comprehensive) Coverage: 28/05/2019 - 27/05/2020						
Vehicle Reg. No. (Insured):	YN2584Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Hiap Hong Motor Repair (HQ) 2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 67459633								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/08/2019]								
Driver/Custodian (Insured):	CHANDRAN A/L MARATHAMUTHU (/ Male) , NRIC: G7652828X Email:								
Adj Asg. Remarks:	on WP. Liab: Dispute. Agree on SJE. Assign: Adrian Ling from LKK Auto Consultants. Contact: 6745 9633.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR9828H (598770)
 [YN2584Z]
 TP
 KM CONSTRUCTION CO (S) PTE. LTD.
 Jul 4 2019 10:00AM
 [NTT TRANSPORT PTE LTD]
 Hiap Hong Motor Repair

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	26/07/19 11:56	Adjuster Immediate Advice					Load HTM			
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
2	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
3	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
4	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
5	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
6	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
7	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
8	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
9	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
10	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
11	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
12	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
13	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
14	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
15	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
16	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
17	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
18	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
19	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
20	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
21	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
22	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
23	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
24	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
25	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
26	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
27	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
28	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
29	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
30	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
31	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
32	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
33	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		
34	26/07/19 11:26	General View					Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/19 11:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/07/19 11:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/07/19 16:21	OI YN2584Z E-FILE REPORT	 Load PDF	
2	04/07/19 16:21	TP SLR9828H E-FILE REPORT	 Load PDF	
3	04/07/19 16:21	PRI from Tng Soon Chye & Co.	 Load PDF	
4	05/07/19 09:48	Agree on SJE	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail Print
1	05/07/19 09:52	Survey Request - Manual Assigned		Load PDF
2	05/07/19 09:54	Manual Assigned - Jason instruction		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011901/AGVD3E2

Date: 01/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29127138MKC
 Claimant Vehicle No: SLR9828H Insured Vehicle No: YN2584Z
 Date of Loss: 04/07/2019 Nature of Claim: TP Claim No: 598770

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR9828H**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZRY232603
 Reg. Date: 14/10/2015 (Man. Year: 2015) Chassis No: MR053REH104542074
 Colour: White Odometer: 45680 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,525.00	3,046.80	2,478.20	44.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,000.00	1,330.00	39.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,855.00	5,046.80	3,808.20	43.01
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	8,855.00	4,000.00	4,855.00	54.83

INSPECTION

Date of Assignment: 05/07/2019
 Date Inspected: 05/07/2019 Inspected At: Hiap Hong Motor Repair (HQ)
 2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit
 Autohub
 Singapore 417921
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR9828H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	564.10 F	*564.10 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER RH	Necessary	94.00 F	*94.00 FL
4	1		*TAILLAMP RH	Cracked	495.30 F	*495.30 FL
5	1		*TAILLAMP LOWER BRACKET RH	Not Necessary	58.00 F	*- FL
6	1		*TAILLAMP SPONGE GASKET	Not Necessary	20.00 F	*- FL
7	1		*TAILLAMP PANEL RH	Buckled	388.20 F	*388.20 FL
8	1		*BOOTLID	Dented	755.00 F	*755.00 FL
9	1		*BOOTLID WEATHERSTRIPE	Not Necessary	175.10 F	*- FL
10	1		*BOOTLID REFLECTOR	Cracked	381.90 F	*381.90 FL
11	1		*TOYOTA LOGO	Necessary	66.10 F	*66.10 FL
12	1		*COROLLA WORDING	Necessary	58.60 F	*58.60 FL
13	1		*ALTIS WORDING	Necessary	55.40 F	*55.40 FL
14	1		*REAR RH FENDER	Distorted	977.70 F	*977.70 FL
15	1		*REAR RH FENDER INNER TRIM	Not Necessary	379.50 F	*- FL
16	1		*REAR RH FENDER INNER TRIM CLIPS	Necessary	30.00 F	*30.00 FL
17	1		*REAR WINDSCREEN MOULDING	Necessary	86.10 F	*86.10 FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
19	1		*REAR RH WHEEL RIM	Not Necessary	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,525.00	4,042.40
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	995.60
Total Parts (S\$)	5,525.00	3,046.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	900.00
2	SPRAY PAINTING	New	1,200.00	700.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
8	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
9	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (S\$)			3,330.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >