

INDIA INTERNATIONAL INSURANCE
 64, Cecil St.
 Singapore 049711

Vehicle number	FBG2555S
Make / Model	YAHAMA/R1
Chassis number	
Accident date	30 June 2019
Reference	1907-09

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT FENDER repair	210.00
1	FRONT RH SIDE FAIRING cra /	950.00
1	FRONT HEADLAMP cra / (photo)	1350.00
1	FRONT HEADLAMP FAIRING cra /	1400.00
1	FRONT SILDER at /	250.00
1	REAR SILDER at /	140.00
1	ENGINE CLTUCH OIL PAN COVER cra X	310.00
1	RH PILLION FOOTREST cra /	250.00
1	HANDLE BAR bt /	610.00
1 SET	WING MIRROR sca - (1pc) RH	210.00
		5680.00
	Less 10 %	568.00
	Subtotal	5112.00
	Balance C/F	5112.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	5112.00
1	GEAR SHIT SHAFT OIL SEAL cra /	120.00
1	FORK OIL SEAL cra /	150.00
1	FORK OIL cra /	50.00
1	FRONT NUMBER PLATE X	80.00
1	FRONT RH SIGNAL sca /	120.00
1 SET	CLTUCH LEVER ASSY X	900.00
1 SET	BALANCER ds - RH (1pc)	250.00
1 SET	HANDLE BAR GRIP RH (1pc) at /	210.00
1	FRONT FORK ASSY repair	4500.00
1	RH BRAKE BOOTREST BRACKET ASSY (AFTER MARKET) bt /	690.00
1	AIR DUCT COVER (CARBON FIBER) cra /	760.00
1	RH LOWER GARNISH COVER (CARBON FIBER) cra /	1200.00
1	ENGINE CLUTCH OIL COVER (CARBON FIRBER) cra /	450.00
1	ENGINE OIL COVER (CARBON FIBER) X	710.00
1	SWING ARM COVER (CARBON FIBER) X	550.00
1	REAR EXHSUST ASSY (AFTER MARKET) bt /	5500.00
	Subtotal	16240.00
	Balance C/F	21352.00

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	21352.00
1	REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	600.00 300
2	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	380.00 150
3	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	250.00 150
4	SPRAY PAINTING	500.00 250
	Subtotal	1730.00
	Grand total	23082.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Passul
Hp 900/100/18
4 days
4s
04/07/19 @ 1710
Ready after repair