

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900208
Date: 04 Jul 2019
Veh Reg No: SLZ7134Y
Make/Model: HONDA FIT 1.3GF CVT
Chasis No: GK31316502
Reg. Date:
Your Ref No: SLN8808T

Claim Type: Third Party
Accident Date: 02/07/2019
TP Veh Reg No: SLN8808T

Ashes.

Estimate Repair Cost to Vehicle No :SLZ7134Y

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR FENDER RH <i>Buckled</i>	749.60	—
2	1 PC REAR FENDER COWLING <i>new</i>	89.40	+
3	1 PC REAR FENDER RH SIDE RUBBER <i>new</i>	197.80	+
4	1 PC REAR FENDER TRIM RH <i>Rehnd</i>	284.30	—
5	1 PC TAIL LAMP - RH <i>crackd</i>	396.90	—
6	1 PC TAIL LAMP PANEL RH <i>Dented</i>	146.10	—
7	1 PC BOOT LID <i>Dented</i>	881.20	—
8	1 PC BOOT LID LOGO	54.90	—
9	1 PC BOOT LID "FIT" EMBLEM <i>free</i>	48.60	—
10	1 PC BOOTLID TRIM <i>new</i>	187.10	+
11	1 PC BOOT LID RUBBER <i>new</i>	167.50	—
12	1 PC REAR WINDSCREEN RUBBER <i>new</i>	81.40	—
13	1 PC BOOT LID LOCK <i>new</i>	200.70	+
14	1 PC REAR PANEL <i>Dented</i>	384.40	—
15	1 PC REAR PANEL TRIM <i>Rehnd</i>	104.80	—
16	1 PC REAR BUMPER <i>Distorted.</i>	697.70	588.60
17	1 PC REAR BUMPER SIDE RETAINER RH <i>new</i>	38.90	—
18	1 PC REAR BUMPER BLACK GARNISH <i>lt</i>	86.80	—
	<i>1pc "ventilation garnish" crackd</i>	96.70	—
		4,798.10	
		Less 20%	959.62
			3,838.48
Special Net			
19	1 SET REAR FENDER COWLING CLIPS RH <i>new</i>	30.00	+
20	1 PC REAR RH FENDER QUARTER GLASS SEAL	60.00	30
21	1 PC REAR RH FENDER QUARTER GLASS SEALANT	60.00	30
22	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	48.00	30
23	1 SET BOOTLID TRIM CLIPS <i>new</i>	48.00	+
24	1 PC REAR WINDSCREEN SEAL	60.00	30
25	1 PC REAR WINDSCREEN SEALANT	60.00	30
26	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00	10
27	1 SET REAR BUMPER CLIPS <i>new</i>	48.00	30

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900208
Date: 04 Jul 2019
Veh Reg No: SLZ7134Y
Make/Model: HONDA FIT 1.3GF CVT
Chasis No: GK31316502
Reg. Date:
Your Ref No: SLN8808T

Claim Type: Third Party
Accident Date: 02/07/2019
TP Veh Reg No: SLN8808T

Estimate Repair Cost to Vehicle No :SLZ7134Y

Quantity	Description	List Price	Amount
28	1 SET REVERSE SENSORS <i>Damaged.</i>	SS 250.00 <i>390.</i>	SS <i>200</i>
		704.00	704.00
	Labour		
29	1 TO CHECK WIRING	50.00 <i>30.</i>	
30	1 TO REMOVE AND REFIT QUARTER GLASS	100.00 <i>60</i>	
31	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
32	1 TO REMOVE AND REFIT REAR CUSHION	180.00 <i>80</i>	
33	1 TO REPLACE THIRD BRAKE LIGHT	80.00 <i>30.</i>	
34	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 <i>50</i>	
35	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00 <i>50</i>	
36	1 TO SPRAY UNDERSEAL	180.00 <i>80.</i>	
37	1 (REAR) TO SPRAY PAINTING	1,400.00 <i>1000</i>	
38	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 <i>1200</i>	
		3,770.00	3,770.00
	Total		S\$ 8,312.48
	Add GST @ 7%		581.87
	Total Amount Payable		S\$ 8,894.35

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED NINETY FOUR AND CENTS THIRTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK which may be required after work has begun.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian Ly
2/3 04/07/19.
09 Amp.
total 6378.56
C/S: 511C