

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SDU 8228A

TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739
 ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 04/07/2019
 TP Veh Reg No: SLV5424U

Estimate No: ES1991745/YISHUN
 Date: 5 Jul 2019
 Policy No: 5080429442-03
 Veh Reg No: SDU8228A
 Make/Model: NISSAN ALMERA 1.5
 5MT AIRBAG 2WD 4DR
 Chassis No: MNTBBAN17Z0005591
 Engine No: HR15929322D
 Reg. Date: 30/05/2016

Not Withheld

Recovery Bypassing

6 days

61 Lm & 4400

Estimate Repair Cost to Vehicle No :SDU8228A

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR BUMPER	518.80	1 PC	518.80	—
2 REAR BUMPER RH SIDE RETAINER	31.10	1 PC	31.10	—
3 REAR BUMPER CLIPS	4.40	6 PCS	26.40	—
4 REAR BUMPER RH BRACKET	86.60	1 PC	86.60	—
5 REAR BOOT	846.00	1 PC	846.00	—
6 REAR BOOT EMBLEM "ALMERA"	59.70	1 PC	59.70	—
7 REAR BOOT LOGO	53.50	1 PC	53.50	—
8 REAR BOOT INNER LOCK	64.50	1 PC	64.50	—
9 REAR BOOT INNER RUBBER	103.90	1 PC	103.90	—
10 REAR BOOT HINGES	87.60	2 PCS	175.20	x
11 REAR BOOT INNER SPONGE CLIPS	6.00	4 PCS	24.00	—
12 TAILLAMPS	264.40	2 PCS	528.80	264.40
13 RH TAILLAMP INNER BRACKET BEAM	31.10	1 PC	31.10	—
14 REAR CENTRE PANEL	458.20	1 PC	458.20	—
15 REAR CENTRE PANEL INNER TOP GARNISH	112.20	1 PC	112.20	—
16 REAR RH FENDER INNER GARNISH	356.70	1 PC	356.70	x
17 REAR SPARE TYRE TOP BOARD	250.00	1 PC	250.00	—
18 REAR RH FENDER	784.50	1 PC	784.50	x
19 REAR WINDSCREEN GLASS MOULDING	115.80	1 PC	115.80	x
			4,627.00	
		Less 10%	462.70	4,164.30
Special Net				
20 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	40.00
Labour				
21 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	x
22 PANEL BEATING	1,200.00	1 LA	1,200.00	900
23 PUTTY & RESPRAY ON REAR BOTH FENDERS, REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BOOT, HINGES, REAR BUMPER & REAR AFFECTED AREAS	1,200.00	1 LA	1,200.00	900
24 REMOVE & REFIX REAR SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC	120.00	1 LA	120.00	90
25 RUSTPROOFING	90.00	1 LA	90.00	30
			2,730.00	2,730.00
		Total		S\$ 6,934.30
		Add GST @ 7%		485.40
		Total Amount Payable		S\$ 7,419.70

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE