

XXXX (LXX)
Monday
8-7-19

Kw



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 699535.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLH 6305 Y

Finalised

Parts	(a) Cost / List Price Items	\$ 1550.70	1,776.10
	Plus/Less 25%	\$ 387.68	444.03
	Total of Cost / List	\$ 1163.02	1,332.08
	(b) Nett Price Items		
	Less		
	Total of Nett item		
	(c) Special Nett Items	\$ 200.00	200.00
	Total Parts Cost	\$ 1363.02	1,532.08
	Labour	\$ 480.00	2,590.00
	Total	\$ 1843.02	4,122.08

Not Authorized
Resurvey Required

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	Kennery	
Company	:	CKK	
Survey conducted on	:	8/7/19	at 11:45
<u>Remarks By Surveyor</u>			
(a)	The repair of this vehicle is authorized / is not authorized until further notice.		
(b)	Recommended Days of Repair	:	02 day(s)
(c)	Resurvey	:	Required / Not Required
(d)	Excess	:	\$
(e)	Signature of surveyor	:	De Date: 8/7/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :

SLH 6305 Y

Submit By :

Carmen Lim

Make & Model :

TOYOTA PRIUS

Year Manufacture :

2016

Chassis No. :

JTDKB3FU503536729

Engine No. :

Cost / List


S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper <i>Bu</i>	1	\$497.50		✓
2	Rear bumper clip <i>Na</i>	10	\$40.00		✓
3	Rear bumper side retainer LH <i>Se</i>	1	\$112.70		X
4	Rear bumper side retainer RH <i>Se</i>	1	\$112.70		X
5	Rear bumper reinforcement <i>BT</i>	1	\$398.90		(2)
6	Rear bumper lower garnish centre <i>De</i>	1	\$582.60		(2)
7	Rear bumper tow cover <i>MT</i>	1	\$31.70		✓
8	Reverse sensor <i>Re</i>	1	\$200.00	S.N	✓
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

1830.70

200 S-N



Vehicle No. : SLH 6305 Y Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.