



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLH 6305 Y

Parts	(a) Cost / List Price Items	\$	1,776.10
	Plus/Less 25%	\$	444.03
	<b>Total of Cost / List</b>	<b>\$</b>	<b>1,332.08</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	200.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>1,532.08</b>
<b>Labour</b>		<b>\$</b>	<b>2,590.00</b>
<b>Total</b>		<b>\$</b>	<b>4,122.08</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Date: 8/7/19



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLH 6305 Y**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU503536729**

Submit By : **Carmen Lim**  
Year Manufacture : **2016**  
Engine No. :  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper Bu	1	\$497.50		✓
2	Rear bumper clip Ma	10	\$40.00		✓
3	Rear bumper side retainer LH Lu	1	\$112.70		X
4	Rear bumper side retainer RH Lu	1	\$112.70		X
5	Rear bumper reinforcement	1	\$398.90		7
6	Rear bumper lower garnish centre	1	\$582.60		7
7	Rear bumper tow cover Ma	1	\$31.70		✓
8	Reverse sensor Re	1	\$200.00	S.N	✓
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLH 6305 Y** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, FRONT BUMPER)	\$1,000.00	2001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, FRONT BUMPER)	\$1,000.00	2201
3	To check wiring	\$50.00	101
4	To remove & refit reverse sensor	\$120.00	501
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To tuff coat. <i>nn</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.