

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GX7603E

Spare Parts

No.	Qty	List Items
1	1	Rear bumper
2	2	Rear bumper side retainer
3	1	Rear bumper inner reinforcement
4	1 set	Rear bumper clips
5	2	Taillamp
6	1	Rear tailgate
7	1	Rear tailgate centre "NISSAN" logo
8	1	Rear tailgate outer handle garnish
9	1	Rear tailgate wiper arm
10	1	Rear tailgate wiper motor
11	1	Rear tailgate weatherstrip
12	1 set	Rear tailgate inner trim board clips
13	1	Rear end panel

Bumper	660.60	✓
\$ CM	36.20	✓
\$ B	262.60	✓
\$ M	40.00	✓
Niss mg GM	461.60	✓ 230.80
BT / warts	1,916.20	✓
\$ M	59.70	✓
\$ M	466.30	X
\$ M	79.60	X
\$ M	568.10	X
\$ M	180.80	X
\$ M	60.00	✓
\$ B	242.10	✓
\$	5,033.80	
Less 10%	\$ 503.38	
Total :	\$ 4,530.42	

Special Nett Items

14	1	Rear tailgate LH "70km/h" sticker
15	1 set	Rear windscreen sealant
16	1 set	Reverse sensor

\$ M	12.00	✓
\$ M	50.00	405m
\$ SM	250.00	2005m
Total :	\$ 312.00	

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.
2	To putty and spray Spray Paintings charges.
3	To check wirings and lightings.
4	To remove, refit rear windscreen.
5	To remove, refit rear tailgate fittings.
6	To apply anti rust treatment

\$	1,000.00	600
\$	1,000.00	4500
\$	40.00	200
\$	140.00	1200
\$	80.00	600
\$	100.00	300
Total :	\$ 2,360.00	

Total Parts and Labour : \$ 7,202.42

Not Withstand

1/10/2008 83750h

Presony After Point

4day

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: