

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GX7603E

Spare Parts

No.	Qty	List Items			
1	1	Rear bumper	Bumper	660.60	✓
2	2	Rear bumper side retainer	\$	36.20	✓
3	1	Rear bumper inner reinforcement	\$	262.60	✓
4	1 set	Rear bumper clips	\$	40.00	✓
5	2	Taillamp	2x 5M	461.60	✓
6	1	Rear tailgate	BT 1 way	1,916.20	✓
7	1	Rear tailgate centre "NISSAN" logo	\$	59.70	✓
8	1	Rear tailgate outer handle garnish	\$	466.30	X
9	1	Rear tailgate wiper arm	\$	79.60	X
10	1	Rear tailgate wiper motor	\$	568.10	4?
11	1	Rear tailgate weatherstrip	\$	180.80	X
12	1 set	Rear tailgate inner trim board clips	\$	60.00	✓
13	1	Rear end panel	\$	242.10	✓
			\$	5,033.80	
			Less 10%	\$ 503.38	
			Total :	\$ 4,530.42	

Special Nett Items

14	1	Rear tailgate LH "70km/h" sticker	\$	12.00	✓
15	1 set	Rear windscreen sealant	\$	50.00	40sm
16	1 set	Reverse sensor	\$	250.00	20sm
			Total :	\$ 312.00	

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,000.00	✓
2	To putty and spray Spray Paintings charges.	\$	1,000.00	4500
3	To check wirings and lightings.	\$	40.00	200
4	To remove, refit rear windscreen.	\$	140.00	1200
5	To remove, refit rear tailgate fittings.	\$	80.00	600
6	To apply anti rust treatment	\$	100.00	300
Total :		\$	2,360.00	

Total Parts and Labour : \$ 7,202.42

Not withair
 1/1mp & ?
 Presury After Paint
 4day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: