

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation
 DATE : 08.07.2019
 VEH NO : SFG9191P
 MODEL : Toyota Alphard
 D O A : 04.07.2019
 YR REF : SKV8663M

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SFG9191P (TOYOTA ALPHARD)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO</u>	<u>LIST ITEMS</u>		
1	Front Bumper <i>dehd</i>	1	1,909.50 ✓
2	Front Bumper Clips <i>re</i>	1	30.00 ✓
3	Front Bumper Side Holders - RH <i>re</i>	1	43.80 ✓
4	Front Bumper Sensor - RH <i>dehd</i>	1	381.80 ✓
5	Front Bumper Sponge <i>dehd</i>	1	69.80 ✓
6	Front Bumper Reinforcement <i>re</i>	1	447.10 +
7	Front Bumper Undercover <i>dehd</i>	1	245.90 ✓
8	Front Bumper Fog Lamp - RH <i>cauld</i>	1	279.30 ✓
9	Front Bumper Fog Lamp Cover - RH <i>re</i>	1	82.50 +
10	Front Bumper Fog Lamp Chrome Moulding - RH <i>re</i>	1	45.90 +
11	Front Fender - RH <i>re</i>	1	819.10 +
12	Front Fender Inner Shield - RH <i>re</i>	1	249.40 +
13	Front Fender Inner Shield Clips - RH <i>re</i>	1	30.00 +
14	Head Lamp - RH <i>cauld</i>	1	3,668.40 ✓
15	Front Grille <i>re</i>	1	1,335.80 X.
			9,641.30
			(2,410.33)
			\$ 7,230.98
	Total Parts		\$ 7,230.98

LABOUR CHARGE

- | | | | |
|---|--|----|-------------------|
| 1 | To knocking & pull out front portion & renew above parts | \$ | 500.00 <i>800</i> |
| 2 | To putty & spray up paint works | \$ | 600.00 <i>450</i> |

RE: ESTIMATE FOR ACCIDENT REPAIR SFG9191P (TOYOTA ALPHARD)

3	To check wiring	\$	50.00 ³⁰
4	To remove front bumper sensor	\$	100.00 ⁶⁰
Total Labour		\$	1,250.00
Grand Total		\$	8,480.98

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 5813.62
L/S: 4650.
04 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: