



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### General Details

Involving 1 2017 SUBARU LEVORG 1.6 GT-S (SMD5703Y)

Date of Loss 8 March 2019

Time of Loss 4.00

Loss Description SMD5703Y (INSD) PARKED AND HIT

Comment

### Workshop Details

Total Rebate Amount

Nett Loss Amount \$49,562.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion   
\*



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

SMD5703Y

Purchase Date

dd/mm/yyyy

Registration State

SINGAPORE

Registration Date \*

14/10/2017

Mileage

32737

Age of Vehicle

1

CATEGORY

POLICY INFORMATION

ASSESSMENT INFORMATION

Manufacturing Year

2017

2017

Make

SUBARU

SUBARU

Model

LEVORG 1.6 GT-S

LEVORG 1.6GT-S AWD

Type



### Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY INFORMATION

Driver Name

CHOO BENG HOOI

Date of Birth

11 April 1974

dd/mm/yy

Age

45

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type of Paint		
Chassis No	JF1VM4K55JG006440	JF1VM4K55JG006440
Engine No	FB16CB05085	FB16CB05085
Engine Capacity		1600
Sum Insured	0	0
Market Value	0	109000

CATEGORY	ENQUIRY INFORMATION	
Education Qualification	Other	
Driving Experience	15	
Driver License #		
License Type		
License Issue Date		dd/mm/yy 
License Expiration Date		dd/mm/yy 
Address	BLK 693C WOODLANDS AVENUE 6, #07-757, 733693, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text"/>
Marital status	Married	<input type="text"/>
Identification #	S7481123Z	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

05/07/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Un  
named Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

## Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/45ZR18

Rear Tyre Size

225/45ZR18

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS

**<< Assessment Details**

General &amp; Workshop Details   Vehicle &amp; Driver Details   Vehicle Condition   Taxes &amp; Ratio   Parts &amp; Labour   Miscellaneous   Summary

## Parts





	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FRONT BUMPER (WCP) (10%)	Deformed	0	550	No					550	Reviewing	
<input type="checkbox"/>		0	1		FRT BUMPER GRILLE	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		L/F BUMPER GUIDE	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		L/F BUMPER COVER (WCP) (10%)	Missing	0	59.4	No					59.4	Reviewing	
<input type="checkbox"/>		0	1		L/F INN BUMPER BRKT (WCP) (10%)	Necessary	0	39.6	No					39.6	Reviewing	
<input type="checkbox"/>		0	1		FRT BUMPER SUPPORT	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		FRT BUMPER CLAMP KIT (WCP) (10%)	Necessary	0	22	No					22	Reviewing	
<input type="checkbox"/>		0	1		CLIP FASTENING (NPA)	Serviceable	0	0	No					0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		CLIP FASTENING (NPA)	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		L/F INNER SENSOR (NPA)	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		R/F INNER SENSOR (NPA)	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		L/F OUT PARK AID SEN (NPA)	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		R/F OUT PARK AID SEN (NPA)	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		FRT PARKING AID SET (NPA)	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Damaged	0	3113	No				3113	3113	Reviewing	
<input type="checkbox"/>		0	1		H/LAMP WASHER VALVE (WCP) (10%)	Cracked	0	49.5	No				49.5	49.5	Reviewing	
<input type="checkbox"/>		0	1		L/H-LAMP WASHER LID (WCP) (10%)	Missing	0	59.4	No				59.4	59.4	Reviewing	
<input type="checkbox"/>		0	1		L/F FOG LAMP	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		L/F UPPER WING	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		L/F WING CLAMP KIT	Serviceable	0	0	No				0	0	Deny	

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
	0	1		L/F WHEELHOUSE COVER	Serviceable	0	0	No					0	Deny	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		42.0 WU X 45.00 SGD/H	0	103.5	0	0	Reviewing		
	0		LABOUR COST 85.0 WU X 45.00 SGD/H	0	382.5	0	0	Reviewing		
	0		MATERIAL COST	0	141.66	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	AIRCON GAS	Reviewing		50	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Estimated Claim Amount \$0.00

Adjusted Claim Amount \$4,170.56

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$3,892.90

Labour

\$0.00

\$627.66

Miscellaneous

\$0.00

\$50.00

Excess

-\$400.00

[Submit for Review](#)