

ASS. REC. BY:

REF: CS/MSG 196119401 RHF3

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Muhd Ashid B Madi of MSG Date/Time: 5-7-19 15:59 p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 8913 Insured: XD 7699H

at Workshop m/s Woon Meng Motor Tel: 63161131 63161151

of 50 BUKIT BATOK STREET 23, #01-06

Policy No: 29611451 MCC Claim No: 598813

Sum Insured: Excess:

Make of Veh: D.O.A. 2-7-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5-7-19 4:06 p.m. Person Contacted: Hung H.O.D. Endorsement:

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	XE 8913 - X
	XD 7699H - X
	lump sum \$9,650/- (red: 12686.21; 56%)



 27/12/2019

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *XE 8913*
 at Workshop m/s: *Woon menh*
 of: *50, Baker Barron St 23 #01-06*
 Insured: *MSH*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Soon: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *XE 8913* Yr Regn: *2015 / July*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer or

Make: *SCANIA P400 LA4X2M32 c.c 12742*
 Colour: *WHITE* A/C: Insured / Std / NI / NA
 Sp. Reading: *157464* T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: *452P4X2000 5392368*

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: Inorder / ☒ Jammed / Leaked / Burnt orBrake: Inorder / ☒ Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: *295/80R22.5*
 R: *295/80R22.5*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *GOODYEAR*

Front	Rear
R/Bal. <i>8</i> mm	R/Bal. <i>8/8</i> mm
L/Bal. <i>8</i> mm	L/Bal. <i>8/8</i> mm
D.O.A. <i>02/07/19</i>	D.O.I. <i>09/07/19</i>

Survey held at *Woon menh*Des. of Damages: ☒ Front / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 30 DEC 2019

Date/Time, File Pass to?

1) *27/12 Typist*

Date/Time, File Return to?

2)

Report Format: *TP*Lump Sum / I.B.I. (\$) *9650f*Days Of Repair: *8*Resurvey No. of Trip: *1*Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)Survey Fee: *200*

Transportation:

3 + RS, St

Photos

Others *0*

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019		05 Jul 2019 15:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		HENG LIM TRANSPORT PTE LTD, Co. Reg. No.: 199602304E [Created by insurer]							
Main Claimant:		OCTOGON LOGISTICS PTE. LTD., Co. Reg. No.: 201505427D							
Vehicle Reg. No.:	XE891J	Date of Loss:	02/07/2019 11:00 - :59 [47 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598813	Policy/Cover Note No.:	28611451MKC (Comprehensive) Coverage: 20/09/2018 - 19/09/2019						
Vehicle Reg. No. (Insured):	XD7699H	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/07/2019]								
Driver/Custodian (Insured):	SONG XIANGJIA (), NRIC: G2786579N, Tel: +6596476993 Email:								
Adj Asg. Remarks:	on WP. URGENT. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: 63161131 / 63161151.								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All	Search Tasks	Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2019 15:32
Date Of Accident	02/07/2019 10:55
Exact Location Of Accident	AYE TOWARDS TUAS CRESCENT (BEFORE EXIT 22)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE891J
Insured/Policyholder	
Name Of Registered Owner	OCTOGON LOGISTICS PTE. LTD.
Co Reg No	201505427D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96682551
Alternative Phone No	OFFICE-68983828

Vehicle Particulars

Manufacturer	SCANIA
Model	PRIME MOVER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109137694
Cover Note Number	

Driver

Name of Driver	HAN BING
Work Permit No	G8306818W
Date Of Birth	10/03/1982
Occupation	OUTDOOR
Date Of Driving Pass	15/08/2011
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96682551
Fax Number	
Contact Number	OFFICE-68983828
Email Address	NOEMAIL

Address	1 #01-01 JALAN SAMULUN
Postcode	S629119
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7699H (behind)
Vehicle Make/Model/Colour	TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number	XD1357J
-----------------------------	---------

CH PLAN

A :

B :

C :




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02/7/19, @ about 10:55 hours, my vehicle was stationary along AYE towards Tuas (Before Exit 22) when suddenly, I was hit by behind vehicle, XD 7699H, which caused my vehicle to move forward and hit into the vehicle in front, XD 1357J.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

→ 
Policyholder's Signature
Date & Time:

 - 3 JUL 2019
Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 650545
Tel: 6360 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Denise

e-mail to Pascal (LKK) 29/7/19
 pick for final
 (1 week)

Reminded 5/8/19

Reminded 15/8/19

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Address : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : MSIG Insurance (Singapore) Pte Ltd
 Motor Claims Dept

Date : 12 Jul 2019

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR SCANIA P400 - XE891J
ACCIDENT INVOLVING XE891J & GXD7699H ON 02/07/2019

ITEMS	DESCRIPTION	QTY	PRICE
1	Front bumper (center) <i>bt</i>	1pc	\$ 1,950.00 ✓
2	Front bumper side @\$1450ea <i>LH-bt / RH-X su</i>	2pcs	\$ 2,900.00 <i>1450</i>
3	Front bumper side garnish @\$145ea <i>X su</i>	2pcs	\$ 290.00 X
4	Front panel. <i>cm</i>	1pc	\$ 2,410.00 ✓
5	Front panel lower/P400 (big) <i>repair</i>	1pc	\$ 1,930.00 X
8	Front panel absorber @\$195ea. <i>X su</i>	1pc	\$ 390.00 ✓
9	Front panel hinge @\$390ea. <i>X su</i>	1pc	\$ 780.00 X
10	Front panel meat @\$328.77ea. <i>X su</i>	1pc	\$ 657.54 ✓
11	Emblem. <i>new</i>	1pc	\$ 133.00 ✓
12	Front lower panel meat @146.78ea. <i>X su</i>	2pcs	\$ 293.56 X
13	Front corner panel @\$1073.32ea <i>LH-repair / RH-X su</i>	2pcs	\$ 2,146.64 X
14	SCAN. <i>new</i>	1pc	\$ 125.01 ✓
15	IA. <i>new</i>	1pc	\$ 78.01 ✓
16	Air con duct housing <i>cm</i>	1pc	\$ 650.00 ✓
17	Air con duct <i>X su</i>	1pc	\$ 950.00 X
18	Front wiper garnish center. <i>cm</i>	1pc	\$ 205.00 ✓
19	Front wiper garnish side @\$215ea. <i>cm</i>	2pcs	\$ 430.00 ✓
Sum Carried Forward			\$ 16,318.76

Sum Carried Forward**\$ 16,318.76**

20	Front wiper arm. <i>scu</i> ✓	1pc	\$	436.00 ✓
21	Roof top sunvisor wire. <i>X scu</i>	1pc	\$	350.00 X
22	Roof top sunvisor bracket. <i>bt</i> ✓	1pc	\$	320.00 ✓
23	Roof top sunvisor lower. <i>X scu</i>	1pc	\$	446.40 X
24	Roof top sunvisor top. <i>ca</i> ✓	1pc	\$	446.40
25	Front wiper blade @\$88ea. <i>X scu</i>	2pcs	\$	176.00 X
26	Front windscreen glass. <i>ca</i> ✓	1pc	\$	1,480.00

Less 10%

10,113.42
10%
9102.07

\$	19,973.56
\$	(1,997.35)
\$	17,976.21

27	Front number plate. <i>bt</i> ✓	1pc	\$	25.00
28	Front windscreen sealant. <i>ne</i> ✓	4pcs	\$	80.00 } <i>120</i>
29	Front ERP Bracket. <i>ne</i> ✓	1pc	\$	15.00

Labour Charge & Misc

To remove, repair, replace & install front damaged parts.

To R & R front windscreen glass

To repair & weld rear chassis.

To R & R wiring.

To putty & spray painting.

Total

R&R
Hp 90010068
8 days
L/S
09/07/19 @1725
Returning after repair

\$	1,800.00 <i>1100</i>
----	---------------------------------

\$	380.00 <i>300</i>
----	------------------------------

\$	1,000.00 <i>600</i>
----	--------------------------------

\$	60.00 <i>30</i>
----	----------------------------

\$	1,000.00 <i>800</i>
----	--------------------------------

\$	22,336.21
----	------------------

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

*9102.07**120.00**2830.00**12,052.07**20%**9641.65**9,650 8 days*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019		05 Jul 2019 15:59 Edit Adj Rpt	S\$9,650.00 Edit Estimates	S\$9,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HENG LIM TRANSPORT PTE LTD, Co. Reg. No.: 199602304E								
Main Claimant:	OCTOGON LOGISTICS PTE. LTD., Co. Reg. No.: 201505427D								
Vehicle Reg. No.:	XE891J	Date of Loss:	02/07/2019 11:00 - :59 [47 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598813	Policy/Cover Note No.:	28611451MKC (Comprehensive) Coverage: 20/09/2018 - 19/09/2019						
Vehicle Reg. No. (Insured):	XD7699H	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 06/07/2019]								
Driver/Custodian (Insured):	SONG XIANGJIA (), NRIC: G2786579N, Tel: +6596476993 Email:								
Adj Asg. Remarks:	on WP, URGENT, Liab: 100%, Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: 63161131 / 63161151.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE891J (598813)

[XD7699H]

TP

OCTOGON LOGISTICS PTE. LTD.

Jul 2 2019 11:00AM

[HENG LIM TRANSPORT PTE LTD]

Woon Meng Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/07/19 14:11	Accident Statement From:SC - Reg. No: XD7699H, Claimant: HENG LIM TRANSPORT PTE LTD	 Load HTM	☐
2	05/07/19 14:11	Addendum Sheet From:SC - Reg. No: XD7699H, Claimant: HENG LIM TRANSPORT PTE LTD	 Load TIF	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/19 11:51	General View	 Load JPG ☒	☒
2	27/12/19 11:51	General View	 Load JPG ☒	☒
3	27/12/19 11:51	General View	 Load JPG ☒	☒
4	27/12/19 11:51	General View	 Load JPG ☒	☒
5	27/12/19 11:51	General View	 Load JPG ☒	☒
6	27/12/19 11:51	General View	 Load JPG ☒	☒
7	27/12/19 11:51	General View	 Load JPG ☒	☒
8	27/12/19 11:51	General View	 Load JPG ☒	☒
9	27/12/19 11:51	General View	 Load JPG ☒	☒
10	27/12/19 11:51	General View	 Load JPG ☒	☒
11	27/12/19 11:51	General View	 Load JPG ☒	☒
12	27/12/19 11:51	General View	 Load JPG ☒	☒
13	27/12/19 11:51	General View	 Load JPG ☒	☒
14	27/12/19 11:51	General View	 Load JPG ☒	☒
15	27/12/19 11:51	General View	 Load JPG ☒	☒
16	27/12/19 11:51	General View	 Load JPG ☒	☒
17	27/12/19 11:51	General View	 Load JPG ☒	☒
18	27/12/19 11:51	General View	 Load JPG ☒	☒
19	27/12/19 11:51	General View	 Load JPG ☒	☒
20	27/12/19 11:51	General View	 Load JPG ☒	☒
21	27/12/19 11:51	General View	 Load JPG ☒	☒
22	27/12/19 11:51	General View	 Load JPG ☒	☒
23	27/12/19 11:51	General View	 Load JPG ☒	☒
24	27/12/19 11:51	General View	 Load JPG ☒	☒
25	27/12/19 11:51	General View	 Load JPG ☒	☒
26	27/12/19 11:51	General View	 Load JPG ☒	☒
27	27/12/19 11:51	General View	 Load JPG ☒	☒
28	27/12/19 11:51	General View	 Load JPG ☒	☒
29	27/12/19 11:51	General View	 Load JPG ☒	☒
30	27/12/19 11:51	General View	 Load JPG ☒	☒
31	27/12/19 11:51	General View	 Load JPG ☒	☒
32	27/12/19 11:51	General View	 Load JPG ☒	☒
33	27/12/19 11:51	General View	 Load JPG ☒	☒
34	27/12/19 11:51	General View	 Load JPG ☒	☒
35	27/12/19 11:51	General View	Load JPG ☒	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
36	27/12/19 11:51	General View	 Load JPG	☒
37	27/12/19 11:51	General View	 Load JPG	☒
38	27/12/19 11:51	General View	 Load JPG	☒
39	27/12/19 11:51	General View	 Load JPG	☒
40	27/12/19 11:51	General View	 Load JPG	☒
41	27/12/19 11:51	General View	 Load JPG	☒
42	27/12/19 11:51	General View	 Load JPG	☒
43	27/12/19 11:51	General View	 Load JPG	☒
44	27/12/19 11:51	General View	 Load JPG	☒
45	27/12/19 11:51	General View	 Load JPG	☒
46	27/12/19 11:51	General View	 Load JPG	☒
47	27/12/19 11:51	General View	 Load JPG	☒
48	27/12/19 11:51	General View	 Load JPG	☒
49	27/12/19 11:51	General View	 Load JPG	☒
50	27/12/19 11:51	General View	 Load JPG	☒
51	27/12/19 11:51	General View	 Load JPG	☒
52	27/12/19 11:51	General View	 Load JPG	☒
53	27/12/19 11:51	General View	 Load JPG	☒
54	27/12/19 11:51	General View	 Load JPG	☒
55	27/12/19 11:51	General View	 Load JPG	☒
56	27/12/19 11:51	General View	 Load JPG	☒
57	27/12/19 11:51	General View	 Load JPG	☒
58	27/12/19 11:51	General View	 Load JPG	☒
59	27/12/19 11:51	General View	 Load JPG	☒
60	27/12/19 11:51	General View	 Load JPG	☒
61	27/12/19 11:51	General View	 Load JPG	☒
62	27/12/19 11:51	General View	 Load JPG	☒
63	27/12/19 11:51	General View	 Load JPG	☒
64	27/12/19 11:51	General View	 Load JPG	☒
65	27/12/19 11:51	General View	 Load JPG	☒
66	27/12/19 11:51	General View	 Load JPG	☒
67	27/12/19 11:51	General View	 Load JPG	☒
68	27/12/19 11:51	General View	 Load JPG	☒
69	27/12/19 11:51	General View	 Load JPG	☒
70	27/12/19 11:51	General View	 Load JPG	☒
71	27/12/19 11:51	General View	 Load JPG	☒
72	27/12/19 11:51	General View	 Load JPG	☒
73	27/12/19 11:51	General View	 Load JPG	☒
74	27/12/19 11:51	General View	 Load JPG	☒
75	27/12/19 11:51	General View	 Load JPG	☒
76	27/12/19 11:51	General View	 Load JPG	☒
77	27/12/19 11:51	General View	 Load JPG	☒
78	27/12/19 11:51	General View	 Load JPG	☒
79	27/12/19 11:51	Reinspection Photo	 Load JPG	☒
80	27/12/19 11:51	Reinspection Photo	 Load JPG	☒
81	27/12/19 11:51	Reinspection Photo	 Load JPG	☒
82	27/12/19 11:51	Reinspection Photo	 Load JPG	☒
83	27/12/19 11:51	Reinspection Photo	Load JPG	☒
84	27/12/19 11:51	Reinspection Photo	Load JPG	☒
85	27/12/19 11:51	Reinspection Photo	Load JPG	☒
86	27/12/19 11:51	Reinspection Photo	Load JPG	☒
87	27/12/19 11:51	Reinspection Photo	Load JPG	☒
88	27/12/19 11:51	Reinspection Photo	Load JPG	☒

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
89	27/12/19 11:51	Reinspection Photo	1	Load JPG	✓
90	27/12/19 11:51	Reinspection Photo	1	Load JPG	✓
91	27/12/19 11:51	Reinspection Photo	1	Load JPG	✓
92	27/12/19 11:51	Reinspection Photo	1	Load JPG	✓
93	27/12/19 11:51	Reinspection Photo	1	Load JPG	✓
94	27/12/19 11:51	Reinspection Photo	1	Load JPG	✓
95	27/12/19 11:51	Reinspection Photo	1	Load JPG	✓

Documentation

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	05/07/19 14:11	Email - PRI	1	Load PDF	
2	05/07/19 14:13	XE891J - (NTUC)	1	Load PDF	
3	05/07/19 14:21	Agree on SJE	1	Load PDF	

Documents Checklist**DOCUMENTS CHECKLIST**
[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

 (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

 Our File No: CS/MSG19011940/R1TF3S2
 Date: 30/12/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28611451MKC
Claimant Vehicle No :	XE891J	Insured Vehicle No :	XD7699H
Date of Loss:	02/07/2019	Nature of Claim:	TP
		Claim No:	598813

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE891J		
Make & Model:	SCANIA P400LA, 12.7 D 4X2 MSZ (M)	Engine No:	6886534
Reg. Date:	30/07/2015 (Man. Year: 2015)	Chassis No:	YS2P4X20005392368
Colour:	White	Odometer:	157464 km
Engine Capacity:	12742 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	GoodTyre 8 mm	Rear Left Side:	GoodTyre 8/8 mm
Front Right Side:	GoodTyre 8 mm	Rear Right Side:	GoodTyre 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,096.20	9,222.08	8,874.12	49.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	2,830.00	1,410.00	33.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,336.20	12,052.08	10,284.12	46.04
Approved Total (Overridden) (S\$)		9,650.00		
(S\$)	22,336.20	9,650.00	12,686.20	56.80
+ GST 7.00/7.00% (S\$)	1,563.53	675.50	888.03	56.80
Nett Amount (S\$)	23,899.73	10,325.50	13,574.23	56.80

INSPECTION

Date of Assignment:	05/07/2019	
Date Inspected:	09/07/2019 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23., #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Dec 2019)	
Parts:	N/A	SCANIA P400LA 12.7 D 4X2 MSZ (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE891J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CENTER)	Bent	1,950.00 FL	*1,950.00 FL
2	1		*FRONT BUMPER SIDE	N/s Bent / O/s Serviceable	2,900.00 FL	*1,450.00 FL
3	2		*FRONT BUMPER SIDE GARNISH	Serviceable	290.00 FL	*- FL
4	1		*FRONT PANEL	Cracked	2,410.00 FL	*2,410.00 FL
5	1		*FRONT PANEL LOWER / P400 (BIG)	Repair	1,930.00 FL	*- FL
6	1		*FRONT PANEL ABSORBER	Serviceable	390.00 FL	*- FL
7	1		*FRONT PANEL HINGE	Serviceable	780.00 FL	*- FL
8	1		*FRONT PANEL MEAT	Serviceable	657.54 FL	*- FL
9	1		*EMBLEM	Necessary	133.00 FL	*133.00 FL
10	2		*FRONT LOWER PANEL MEAT	Serviceable	293.56 FL	*- FL
11	2		*FRONT CORNER PANEL	N/s Repair / O/s Serviceable	2,146.64 FL	*- FL
12	1		*SCAN	Necessary	125.01 FL	*125.01 FL
13	1		*IA	Necessary	78.01 FL	*78.01 FL
14	1		*AIR CON DUCT HOUSING	Cracked	650.00 FL	*650.00 FL
15	1		*AIR CON DUCT	Serviceable	950.00 FL	*- FL
16	1		*FRONT WIPER GARNISH CENTER	Cracked	205.00 FL	*205.00 FL
17	2		*FRONT WIPER GARNISH SIDE	Cracked	430.00 FL	*430.00 FL
18	1		*FRONT WIPER ARM	Scratched	436.00 FL	*436.00 FL
19	1		*ROOF TOP SUNVISOR WIRE	Serviceable	350.00 FL	*- FL
20	1		*ROOF TOP SUNVISOR BRACKET	Bent	320.00 FL	*320.00 FL
21	1		*ROOF TOP SUNVISOR LOWER	Serviceable	446.40 FL	*- FL
22	1		*ROOF TOP SUNVISOR TOP	Cracked	446.40 FL	*446.40 FL
23	2		*FRONT WIPER BLADE	Serviceable	176.00 FL	*- FL
24	1		*FRONT WINDSCREEN GLASS	Cracked	1,480.00 FL	*1,480.00 FL
25	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
26	4		*FRONT WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
27	1		*FRONT ERP BRACKET	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,093.56	10,233.42
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,997.36	1,011.34
Total Parts (\$\$)	18,096.20	9,222.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPAIR, REPLACE & INSTALL FRONT DAMAGED PARTS.	New	1,800.00	1,100.00
2	TO R&R FRONT WINDSCREEN GLASS.	New	380.00	300.00
3	TO REPAIR & WELD REAR CHASSIS.	New	1,000.00	600.00
4	TO R&R WIRING.	New	60.00	30.00
5	TO PUTTY & SPRAY PAINTING.	New	1,000.00	800.00
Gross Labour Cost (S\$)			4,240.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >