

22/03/2002

ASS. REC. BY:

REF:

Special Instruction:

Surveyor

Sava

ASSIGNMENT (Office)

5/7/2019.

From (Person):

ong li li

of

LPC

Date/Time:

9.5.19 2.25p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 7929H

Insured:

SLF 2011G

at Workshop m/s

One Motor Trading

Tel:

67430629

of

464 Macpherson Road

Policy No:

Claim No:

18/19/19/VP05/021734

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30.4.2019

(Client's Record)

10.5.2019

CA / REV / REP. / REV 24 HRS

"w.p."

H.O.D. Endorsement:

Date/Time:

9.5.19 3.00p.m

Person Contacted:

mr ong

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBM 7929H - X

SLF 2011G - X

20/5/19

Submit PRS report

10/7/19

Submit LS \$ 2100 (Red 3350, 6170), 3 days

RECEIVED 10 JUL 2019

Steve

REF: LPC

PRS

ASSIGNMENT

From

Date 10.5.2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 79294

at Workshop m/s One motor Trading
of 464 macpherson Road

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

"wp"

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBM 79294

Yr Regn

28/3/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Sniper T150

C.C

149 150

Colour

Green

A/C Insured / Std / NI / NA

Sp. Reading

27395

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH/34 G0740J0093931

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

70/80-17

R:

80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CORSA

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/4/19

D.O.I

10/5/19

Survey held at

One motor

10-21 am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 8K

RECEIVED 22 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

225- typist

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

450

Transportation:

) \$ + RS, \$

) Photos

) Others

)

TOTAL

450

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 5 July 2019 3:24 PM
To: Admin-D (LKKAuto); assignments; SUR
Cc: MT_Claim_SG
Subject: RE: Your Ref: BCC.FBM7929H.OM Our Ref: 18/19/19/VP05/021734 [External General]
Attachments: 21734 TPD SR.pdf

Lonpac External - General

Dear Nivitha

Attached is the TP survey report, please let us have your surveyor's review/report.

Thanks,
Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 9 May, 2019 3:59 PM
To: ONG LI LI; assignments; SUR
Cc: MT_Claim_SG
Subject: RE: Your Ref: BCC.FBM7929H.OM Our Ref: 18/19/19/VP05/021734 [External General]

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that repairer agreed to survey on 10/5/2019.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Thursday, 9 May, 2019 2:25 PM
To: BCCLAW <bcclaw@singnet.com.sg>; assignments@lkkauto.com; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Your Ref: BCC.FBM7929H.OM Our Ref: 18/19/19/VP05/021734 [External General]

Lonpac External - General

Dear Nivitha

Please see attached and arrange survey.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: BCCLAW [mailto:bcclaw@singnet.com.sg]

Sent: Thursday, 9 May, 2019 2:19 PM

To: ONG LI LI

Cc: MT_Claim_SG

Subject: RE: Your Ref: BCC.FBM7929H.OM Our Ref: 18/19/19/VP05/021734 [External General]

Dear Sir / Mdm

We enclose herewith our letter dated 9 May 2019 for your attention.

Thanks and Regards

BENEDICT CHAN & COMPANY

14 Fort Road Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

We do not accept service of Court documents by facsimile or email

CONFIDENTIALITY NOTICE

This email including any attachment (s) is confidential and may be privileged. Accordingly, if you are not the intended recipient, please notify us immediately, delete this email including any attachment (s) from your computer system and do not disclose or distribute it to any person or continue to read this email. Thank you.

From: ONG LI LI [mailto:llong@lonpac.com]

Sent: Thursday, May 9, 2019 12:50 PM

To: BCCLAW

Cc: MT_Claim_SG

Subject: RE: Your Ref: BCC.FBM7929H.OM Our Ref: 18/19/19/VP05/021734 [External General]

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We are not agreeable with your list of proposed surveyors, we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey. Please advise the location of your client's workshop.

Dear Nivitha

Please follow up and arrange survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: BCCLAW [mailto:bcclaw@singnet.com.sg]
Sent: Thursday, 9 May, 2019 12:44 PM
To: ONG LI LI
Cc: MT_Claim_SG
Subject: RE: Your Ref: BCC.FBM7929H.OM Our Ref: 18/19/19/VP05/021734 [External General]

Dear Sir/Mdm

We enclose herewith our letter dated 9 May 2019 for your attention.

Thanks and Regards

BENEDICT CHAN & COMPANY
14 Fort Road Singapore 439075
Tel : 6220 6088 Fax : 6220 6087

We do not accept service of Court documents by facsimile or email

CONFIDENTIALITY NOTICE

This email including any attachment (s) is confidential and may be privileged. Accordingly, if you are not the intended recipient, please notify us immediately, delete this email including any attachment (s) from your computer system and do not disclose or distribute it to any person or continue to read this email. Thank you.

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Thursday, May 9, 2019 11:43 AM
To: bcclaw@singnet.com.sg
Cc: MT_Claim_SG
Subject: Your Ref: BCC.FBM7929H.OM Our Ref: 18/19/19/VP05/021734 [External General]

Lonpac External - General

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to your fax of 9 May 2019.


We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor

surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Ong Hwee jie/Steve Chen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.



Virus-free. www.avast.com

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

HP 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Aziz Azizan Bin Ruslan
Apt Blk 166A Teck Whye Crescent #10-351
Singapore 681166

Our Ref : PA/FBM7929/0519/tpw
Date : 03 June 2019

REFERENCES

Claim Type	: Third Party	Date of Accident	: 30 April 2019
Vehicle No.	: FBM 7929 H	Date of Assignment	: 13 May 2019
Make	: Yamaha	Date of Inspection	: 13 May 2019
Model	: Sniper T150	Date of Re-inspn	: 14 May 2019
Reg. Date	: 28 March 2018	Date of Re-inspn	: 17 May 2019
Color	: Green	Chassis No	: MH3UG0740J0093934
Odometer	: 27395 km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Dunlop	110/70 -17	6mm
Rear	Dunlop	150/60 -17	8mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and left portion.

Please refer to photographs and assessment of repairs for details

Enclosed (68) photographs depicting damage and after repair

INSPECTION AND ADJUSTMENT

Original Quotation : \$7,143.51 Revised Assessment \$5,450.00 Lump sum

Survey conducted at

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Six (6) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICESVehicle No: **FBM 7929 H**

Our Ref: PA/FBM7929/0519/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Handle bar	1 pc	Bent	125.00	125.00 ✓
2	Handle balancer	1 set	Grazed	60.00	60.00 30 ✓
3	Handle grip	1 set	Usable	80.00	2 N/A
4	Clutch lever	1 pc	Cut/bent	28.60	28.60 ✓
5	Brake lever	1 pc	Usable	33.00	~
6	Mirror	1 set	Cut	130.00	130.00 30 ✓
7	Headlamp cowling	1 pc	Grazed	162.50	162.50 85 ✓
8	Headlamp cowling rear cover	1 pc	Deformed	93.60	93.60 X N/A
9	Handle bar rear cover	1 pc	Deformed	187.20	187.20 X N/A
10	Head light assy	1 pc	Cut	260.00	260.00 X N/A
11	Head light cowling bracket @ \$33/-	2 pcs	Distorted	66.00	66.00 X N/A
12	Fork complete @ \$380/-	2 pcs	Bent	760.00	760.00 X N/A
13	Fork under bracket	1 pc	Distorted	165.00	165.00 X N/A
14	Front mudguard	1 pc	Cut	96.00	96.00 X N/A
15	Front wheel assy	1 pc	Warped	420.00	420.00 350 ✓
16	Front centre panel	1 pc	Deformed	182.00	182.00 ✓
17	Front panel inner @ \$139/-	2 pcs	Cut/deformed	278.00	278.00 X N/A
18	Side panel outer upper @ \$196	1/2 pcs	Cut LH	392.00	196.00 ✓
19	Side panel lower @ \$103	1/2 pcs	Cut LH	206.00	103.00 ✓
20	Side lamp @ \$92/-	1 pc	Cut LH	184.00	92.00 ✓
21	Gear pedal	1 pc	Bent	56.00	56.00 ✓
22	Gear pedal shaft	1 pc	Bent	85.00	85.00 X N/A
23	Front footrest LH	1 pc	Bent	65.00	65.00 ✓
24	Front footrest bracket LH	1 pc	Bent	82.00	82.00 ✓
25	Tail board @ \$180	1/2 pcs	Cracked LH	360.00	360.00 180 ✓
26	Pillion seat bar	1 pc	Cut	120.00	120.00 80 ✓
27	Tail lamp assy	1 pc	Cut	262.00	262.00 X N/A
28	Rear signal lamp LH	1 pc	Cut/bent	75.00	75.00 X N/A
				5,013.90	4,509.90
List price less 10%				501.39	450.99
				4,512.51	4,058.91

1684.60
-10%
1516.14

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBM 7929 H**

Our Ref: PA/FBM7929/0519/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>Special Nett Items</u>					
29	Front panel emblem	1 pc	Necessary	53.00	53.00 20/
30	Side panel emblem @\$34/-	1/2 pcs	Necessary	68.00	68.00 20/
31	Steering cone & bearing	1 set	Necessary	220.00	110.00 /
32	Body sticker	1 set	Necessary	180.00	150.00 100/
33	Centre basket	1 pc	Deformed	50.00	50.00 X NN
34	Front tyre	1 pc	Cut 50%	160.00	80.00 X NN
35	Front wheel bearing	1 set	Necessary	150.00	75.00 50/
36	Rear box	1 pc	Cut	350.00	280.00 250/
37	Rear box bracket with base	1 pc	Bent	200.00	180.00 120/
				1,431.00	1,046.00 670

Labour Charges

Towing charges (2 trips)	150.00	120.00 30/
Body frame repair	550.00	450.00 200/
Remove & replace damage parts	500.00	400.00 200/
		1,200.00 970.00 430

Total Parts & Labours Concluded

P- 1516.14

M- 670

L- 430

7,143.51

6,074.91

Final lump sum repair adjustment

2616.14


5,450.00

4/5 - 2092.91

= 2100

3 days

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC19008202/Evd3e2-1		
300 BEACH ROAD		Date : 11-07-2019		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 2011G	Veh. Inspected	FBM 7929H	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021734	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	05/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA SNIPER T150	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3UG0740J0093934	Colour	GREEN	
Odometer	27395	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/80-17	CORSA	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/80-17	CORSA	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/04/2019	Inspection Date	10/05/2019	
Survey held at	464 MACPHERSON ROAD			
Repairer	ONE MOTOR PERFORMANCE [9756 6117]			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 7929H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	125.00	125.00
1	HANDLE BALANCER	GRAZED	60.00	30.00
1	HANDLE GRIP	NOT NECESSARY	80.00	-
1	CLUTCH LEVER	CUT / BENT	28.60	28.60
1	BRAKE LEVER	USABLE	33.00	-
1	MIRROR	CUT	130.00	30.00
1	HEADLAMP COWLING	GRAZED	162.50	85.00
1	HEADLAMP COWLING REAR COVER	NOT NECESSARY	93.60	-
1	HANDLE BAR REAR COVER	NOT NECESSARY	187.20	-
1	HEAD LIGHT ASSY	NOT NECESSARY	260.00	-
2	HEAD LIGHT COWLING BRACKET @\$33.00	NOT NECESSARY	66.00	-
2	FORK COMPLETE @\$380.00	NOT NECESSARY	760.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	165.00	-
1	FRONT MUDGUARD	NOT NECESSARY	96.00	-
1	FRONT WHEEL ASSY	WARPED	420.00	350.00
1	FRONT CENTRE PANEL	DEFORMED	182.00	182.00
2	FRONT PANEL INNER @\$139.00	NOT NECESSARY	278.00	-
2	SIDE PANEL OUTER UPPER @\$196.00	N/S CUT	392.00	196.00
2	SIDE PANEL LOWER @\$103.00	N/S CUT	206.00	103.00
2	SIDE LAMP @\$92.00	N/S CUT	184.00	92.00
1	GEAR PEDAL	BENT	56.00	56.00
1	GEAR PEDAL SHAFT	NOT NECESSARY	85.00	-
1	FRONT FOOTREST LH	BENT	65.00	65.00
1	FRONT FOOTREST BRACKET LH	BENT	82.00	82.00
2	TAIL BOARD @\$180.00	N/S CRACKED	360.00	180.00
1	PILLION SEAT BAR	CUT	120.00	80.00
1	TAIL LAMP ASSY	NOT NECESSARY	262.00	-
1	REAR SIGNAL LAMP LH	NOT NECESSARY	75.00	-
	LESS 10% DISCOUNT		-501.39	-168.46
			4,512.51	1,516.14

Report Ref No. CS3/LPC19008202/Evd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT PANEL EMBLEM (SN)	NECESSARY	53.00	20.00
2	SIDE PANEL EMBLEM @\$34.00 (SN)	NECESSARY	68.00	20.00
1	SET STEERING CONE & BEARING (SN)	NECESSARY	220.00	110.00
1	SET BODY STICKER (SN)	NECESSARY	180.00	100.00
1	CENTRE BASKET (SN)	NOT NECESSARY	50.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	160.00	-
1	SET FRONT WHEEL BEARING (SN)	NECESSARY	150.00	50.00
1	REAR BOX (SN)	CUT	350.00	250.00
1	REAR BOX BRACKET WITH BASE (SN)	BENT	200.00	120.00
			1,431.00	670.00
	<u>LABOUR</u>			
	TOWING CHARGES (2 TRIPS).		150.00	30.00
	BODY FRAME REPAIR.		550.00	200.00
	REMOVE & REPLACE DAMAGE PARTS.		500.00	200.00
			1,200.00	430.00
GRAND TOTAL			7,143.51	2,616.14

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CS3/LPC19008202/Evd3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.