

05/18

023/LPC19002648/Bgd301

023/LPC19002648/Bgd3

ASSIGNMENT (Object)

5/7/2019
B/2/19@9:47am

Mr Jim
Gerald Poh

LPC

Person Contacted

Phone No

OD / DRAWN / IP RES / COURTESY / EVA / INV / MV / CS

To Inspect Vehicle No. FBL 9936D

Insured SJB 56K

Workshop Name H.L. Cycle

Tel 9748 9940

Address 1 kaki Bkt Ave 6 #02-58/60

Claim No 19/19/19/vpus/021348

Sum Insured

Excess

Make of Veh
(Client's Record)

DOA 01/02/2019

CA / REV / REP. / REV. 24 HRS lup

HOV, Endorsed

Date/Time: 10:41am @ 13/2/19 Person Contacted

Mr. Tan

Vehicle (IP) 001

Date/Time Action/Instruction (X) Estimate

FBL 9936D - X

SJB 56K - X

27/2/19 inspect PRS

23/2/19 Submit US \$3850, 3 days.
(Red \$ 1950, 3x%)


22/7/2019

RECEIVED 23 JUL 2019

- No Bill
- By email
first

REF: **IPC**

ASSIGNMENT

PRS

Event:

Date: **13/2/19**

Vehicle No:

FBL 9936D

Page:

8/6/20A

Estimated Cost:

Type: M/Car / H/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / LVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

FBL 9936D

Make:

YAMAHA YZF-R3

cc: **321**

at Workshop no/s

H.L. Cycle

Colour:

BLUE

A/C: Insured / Std / NI / NA

of

**1 Kaki Bkt Ave 6 #02-58/60
Antobay**

Sp. Reading:

290 km/h

T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

HACZE 0047511

Policy No

C/No:

MH3RH071000065A7

Claims No

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: order / Jammed / Leaked / Burnt or

Make of Veh.

Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

Tyre Size:

F: **110/70R17**

R: **150/60R17**

IDAC Accident Report:

Consistent? Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

GIA / PR Seen:

Consistent? Yes or No

TOYO / YOKO or **Diablo**

Est. Repairs:

3 days Res: Yes or No

Front

Rear

Lump Sum:

% **3** Val: Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

CA / REV / REP. / 24 HRS **up**

Vehicle: IN / OUT

L/Bal.

mm

L/Bal.

mm

Date:

Person Contacted:

D.O.A.

1/2/2019

D.O.I.

13/2/19 2.01pm

Survey held at

H.L. Cycle

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time:

Action / Instruction

RECEIVED 23 FEB 2019

MV **9,000/2**

PV **5,051/2**

NV **3,950/2**

Date/Time, File Pass to?

Prel. Report

Days Of Repair:

13/2/19

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Add Fee:

Site Insp (\$

Interview (\$

Tech Insp (\$

Weekend (\$

Survey Fee:

Transportation:

1. S-PS \$

2. Photo

3. Other

TOTAL

Report Format:

PRS

Lump Sum / L.B.L. (\$

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 5 July 2019 1:57 PM
To: Admin-D (LKKAuto); assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: Your Ref: FBL9936D Our Ref: 19/19/19/VP05/021398 [External General]
Attachments: 21398 TP SURVEY REPORT 1.pdf

Lonpac External - General

Dear Nivitha

Attached is the TP survey report (part 1), please let us have your surveyor's review/report.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2019 13:26
Date Of Accident	01/02/2019 19:00
Exact Location Of Accident	BIDEFORD ROAD > CAIRHILL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL9936D
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD RIDZMAN BIN ABDUL GHANI
NRIC No	S8628822B
Email Address	RIDZSCARLET88@LIVE.COM.SG
Mobile Phone No	(LOCAL) +65-90170397
Alternative Phone No	OTHERS-90170397
Vehicle Particulars	
Manufacturer	YAMAHA
Model	YZF-R3 ABS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091788792-01
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD RIDZMAN BIN ABDUL GHANI
NRIC No	S8628822B
Date Of Birth	08/10/1986
Occupation	OUTDOOR
Date Of Driving Pass	07/10/2010
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90170397
Fax Number	
Contact Number	OTHERS-90170397
Email Address	RIDZSCARLET88@LIVE.COM.SG

Address BLK 363 #02-1570 YISHUN RING ROAD YISHUN GLORY
 Postcode 760363
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TANGLIN POLICE DIVISIONAL HQ ('E' DIVISION)
 Police Station Address ROAD: 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-3910000 - FAX NO: 63964900
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.E/20190202/7015;

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJB56K
 Vehicle Make/Model/Colour MERCEDES BENZ C 250
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver CHUA SWEE PING
 NRIC/Passport Number S1681850Z
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD RIDZMAN BIN ABDUL GHANI
Approximate Age	32
Injuries Sustain	
Injured person in which vehicle?	FBL9936D
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 363 #02-1570 YISHUN RING ROAD YISHUN GLORY
Postcode	760363

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time
19/02/2011
17:45:00



Driver's Signature
(If driver is not the policyholder)
Date & Time


09 FEB 2011

IDAC KAKI BUKIT (VAC)

Reporting to: 23 Kaki Bukit Ave 4
Name: Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars to be true in every respect.

[Signature]
Police Officer's Signature
Date & Time
05/02/2011

[Signature]
Driver's Signature
If driver is not the police officer
Date & Time

09 FEB 2011

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Reporting Centre For Road Accidents
Tel: 67416697 Fax: 67492305
Email: vockb@singnet.com.sg



speed when suddenly, the mentioned Mercedes Benz inch out and collided on my left side of the motorcycle. As a result from the impact, my motorcycle hit the curb on the right and after which, I was throw off from my motorcycle.

I was attended by the Mercedes Benz driver, Mr Chua Swee Ping (S1681850Z) and Certis Cisco Auxillary Police Corporal Serene. Apart from experiencing shock from the accident, at that point in time, I only suffer abrasion on my left elbow. The driver and the passenger of the Mercedes Benz did not suffer any injuries. The damage on my motorcycle was seen on the left side of the vehicle. The parts that was visibly damaged were the left handlebar barend, left fork protector, fork, the left body fairing, left headlamp, left gear shift, left rider footrest assembly, left pillion footrest, IU unit, left front and rear signal light. The visible damage on the car was only at the front right bumper. The assessment for damage cost on the motorcycle including repair work, labour and loss of mode of transportation to work range between \$2000 - \$2500.

I refused conveyance by ambulance because at that point, my injuries were not serious. Instead, traffic police assistance was require at scene due to a dispute from the Mercedes Benz driver and Auxillary Police Officer. Traffic police, Staff Sergeant Muhammad Ghazali, arrived at scene at 2000hrs and recorded the statement (E/20190201/0182) from all parties involved.

Later at approximately 2300hrs I experience pain radiating to the neck, left shoulder and left arm. The pain has impaired my ability to raise my left arm. I seek medical consultation at Sengkang General Hospital. I have to undergo x-ray scan and was given outpatient medical treatment accompanied with a 5 days MC. Doctor advice that I should return for further medical check up if the pain did not subside after 2

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In-Charge Of Case:

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 02/02/2019 18:03
Classification Of Case:

Authentication Stamp



weeks. I was also given a follow up to seek orthopedic should the condition worsen or did not subside.

This is to my best of knowledge of how the accident occur. I would not hesitate to provide photos and assistance if there is a need for further investigation. I do not have a onboard vehicle camera mounted on my motorcycle or helmet, however, the Mercedes Benz is equipped with a in-car camera and the driver have shown the video footage to the Traffic Police Officer.

Subjects Involved			
Victim			
Person Name	MUHAMMAD RIDZMAN BIN ABDUL GHANI		
ID Type	NRIC NO	ID No	S8628822B
Gender	Male	Age	32
Race	Malay	Language	English
Occupation	Fire-fighting and rescue officer	Address Type	
Address	APT BLK 363 YISHUN RING ROAD #02-1570 SINGAPORE 760363	Mobile No	90170397
Is Informant A Victim?	Yes		
Person Name	MUHAMMAD RIDZMAN BIN ABDUL GHANI (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 02/02/2019 18:03
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Tel : 6484 04842 / Fax : 6484 4342
Email : info@hlcycle.com.sg

28 February 2019

Accident Date : 1-Feb-19

Vehicle No : FBL 9936 D
Make / Model : Yamaha YZF R3

Owner : Muhammad Ridzman Bin Abdul Ghani
Address : C/o: H L Cycle Pte Ltd
No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Description	Amount (SGD\$)
Lump Sum Repair as per recommendation	\$ 5,800.00
TOTAL	\$ 5,800.00

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 20100228E

VEHICLE INSPECTION REPORT

To: Muhammad Ridzman Bin Abdul Ghani
C/o: H L Cycle Pte Ltd
No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Date : 28 February 2019
Our ref : HLC/02/1901/TP

Accident Date : 01 February 2019
Inspection Date : 13 February 2019
Repairer Name : H L Cycle Pte Ltd
No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FBL 9936 D
Make / Model : Yamaha YZF R3
Chassis No : MH3RH071000006547
Engine No : H402E0047511

Year / Capacity : 2017 / 321 cc
Colour : Blue
Mileage : 29044

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	: Pirelli	110/70 R17	5 mm	Sport
Rear	: Pirelli	150/60 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 106 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 5,800.00** on a contractual basis.

Under normal circumstances, the repair period would be about 9 (Nine) working days.

ELC L APPRAISER PTE LTD

Vehicle Registration No: FBL 9936 D

Our Ref No: HLC/02/1901/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front fender	Damage	\$ 145.00	\$ 145.00	CUT ✓	
2	Fork inner tubes	Damage	\$ 960.00	\$ 960.00	NNX	
2	Fork outer tubes	LH- Damage	\$ 760.00	\$ 380.00 750.00	CUT ✓	
1	Fork under bracket	Damage	\$ 450.00	\$ 450.00	NNX	
1	Front brake disc	Damage	\$ 288.00	\$ 288.00	NNX	
1	Front sport rim	Damage	\$ 90.00	\$ 90.00	NNX	
1	Front rim shaft	Necessary	\$ 90.00	\$ 90.00	NECV ✓	
1	N/s side mirror	Damage	\$ 95.00	\$ 95.00	SCR ✓	
1	Handle bar	Damage	\$ 155.00	\$ 145.00 155.00	BT ✓	
1	N/s handle bar end	Damage	\$ 28.00	\$ 28.00	SCR ✓	
1	Hand grip (1 set)	Necessary	\$ 60.00	\$ 60.00	NECV ✓	
1	Clutch lever	Damage	\$ 55.00	\$ 55.00	BT ✓	
1	Windshield	Damage	\$ 220.00	\$ 220.00	BR ✓	
1	Top fairing	Damage	\$ 480.00	\$ 480.00	CUT ✓	
1	Top fairing inner panel	Damage	\$ 85.00	\$ 85.00	CRA ✓	
1	Headlamp	Damage	\$ 320.00	\$ 320.00	CUT ✓	
1	Front n/s signal	Damage	\$ 75.00	\$ 75.00	DL ✓	
1	Lampstay	Damage	\$ 285.00	\$ 285.00	BT ✓	
1	N/s side panel	Damage	\$ 90.00	\$ 90.00	CUT ✓	
1	N/s side fairing	Damage	\$ 395.00	\$ 395.00	CUT ✓	
1	N/s side inner fairing	Damage	\$ 350.00	\$ 350.00	BR ✓	
1	N/s lower fairing	Damage	\$ 300.00	\$ 300.00	BR ✓	
1	Front n/s footrest	Damage	\$ 75.00	\$ 75.00	SCR ✓	
1	Gear pedal	Damage	\$ 150.00	\$ 150.00	BT ✓	
1	Rear n/s footrest	Damage	\$ 75.00	\$ 75.00	SCR ✓	
1	Rear n/s footrest bracket	Damage	\$ 70.00	\$ 70.00	SCR ✓	
1	N/s engine cover	Damage	\$ 380.00	\$ 350.00 380.00	SCR ✓	
1	Rear signal	Damage	\$ 75.00	\$ 75.00	BR ✓	
1	Side stand	Intact	\$ 75.00	\$ 75.00	NN	
			\$ 6,676.00	\$ 6,601.00	4393.00	
			Less 10%	\$ 667.60	\$ 660.10	439.30
Total Cost - List Items			\$ 6,008.40	\$ 5,940.90	3953.70	

L C L APPRAISER PTE LTD

Vehicle Registration No: FBL 9936 D

Our Ref No: HLC/02/1901/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
List Items Total c/f			\$ 6,008.40	\$ 5,940.90

SPECIAL NETT ITEMS

1	Front number plate	Necessary	\$ 15.00	\$ ✓ 15.00	NE C ✓
1	Swing arm slider (1 set) <i>N/S 1 pc</i>	Damage	\$ 150.00	\$ 75.00 150.00	CUT ✓
1	Fork slider (1 set) <i>N/S 1 pc</i>	Damage	\$ 150.00	\$ 75.00 150.00	CUT ✓
1	Rear tailboard protector	Damage	\$ 80.00	\$ ✓ 80.00	CUT ✓
1	Headlamp protector (1 set) <i>1 pc N/S</i>	Damage	\$ 80.00	\$ 40.00 80.00	CUT ✓
Total Cost - Special Nett items			\$ 475.00	\$ 475.00	

285.00

Total cost of parts

\$ 6,483.40 \$ 6,415.90

S&C L APPRAISER PTE LTD

Vehicle Registration No: FBL 9936 D

Our Ref No: HLC/02/1901/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,483.40	\$ 6,415.90

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00 N/A
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00 30 ✓
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00 300.00
4	To check , repair and straighten body frame to the original position.	\$ 350.00	\$ 350.00 250.00

GRAND TOTAL

\$ 7,443.40 \$ 7,265.90 580.00

Parts 3953.70
 SN 285.00
 Labour 580.00

 4818.70
 @ 20% 963.74

 3854.96

L/S 3850/2 with 3 repair days

TGM Hill
 22/7/19

C L APPRAISER PTE LTD

Vehicle Registration No: FBL 9936 D

Our Ref No: HLC/02/1901/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,800.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Muhammad Ridzman Bin Abdul Ghani
C/o: H L Cycle Pte Ltd
No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Invoice No: CL/190239
Ref No: HLC/02/1901/TP
Date: 28 February 2019

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>FBL 9936 D</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES <i>(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)</i>TRANSPORTATION	
GRAND TOTAL	SS 586.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC19002648/Bqd3s2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 23-07-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJB 56K	Veh. Inspected	FBL 9936D
Policy No.		Coverage (\$)	0.00
Claim No.	19/19/19/VP05/021398	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	05/07/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA YZF-R3	c.c	321
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MH3RH071000006547	Colour	BLUE
Odometer	29044	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/70 ZR17	DIABLO	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/60 ZR17	DIABLO	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/02/2019	Inspection Date	13/02/2019
Survey held at	HL CYCLE PL 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 9936D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	CUT	145.00	145.00
2	FORK INNER TUBES	NOT NECESSARY	960.00	-
2	FORK OUTER TUBES	N/S CUT	760.00	380.00
1	FORK UNDER BRACKET	NOT NECESSARY	450.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	288.00	-
1	FRONT SPORT RIM	NOT NECESSARY	90.00	-
1	FRONT RIM SHAFT	NECESSARY	90.00	90.00
1	N/S SIDE MIRROR	SCRATCHED	95.00	95.00
1	HANDLE BAR	BENT	155.00	145.00
1	N/S HANDLE BAR END	SCRATCHED	28.00	28.00
1	SET HAND GRIP	NECESSARY	60.00	60.00
1	CLUTCH LEVER	BENT	55.00	55.00
1	WINDSHIELD	BROKEN	220.00	220.00
1	TOP FAIRING	CUT	480.00	480.00
1	TOP FAIRING INNER PANEL	CRACKED	85.00	85.00
1	HEADLAMP	CUT	320.00	320.00
1	FRONT N/S SIGNAL	DISLUDGE	75.00	75.00
1	LAMPSTAY	BENT	285.00	285.00
1	N/S SIDE PANEL	CUT	90.00	90.00
1	N/S SIDE FAIRING	CUT	395.00	395.00
1	N/S SIDE INNER FAIRING	BROKEN	350.00	350.00
1	N/S LOWER FAIRING	BROKEN	300.00	300.00
1	FRONT N/S FOOTREST	SCRATCHED	75.00	75.00
1	GEAR PEDAL	BENT	150.00	150.00
1	REAR N/S FOOTREST	SCRATCHED	75.00	75.00
1	REAR N/S FOOTREST BRACKET	SCRATCHED	70.00	70.00
1	N/S ENGINE COVER	SCRATCHED	380.00	350.00
1	REAR SIGNAL	BROKEN	75.00	75.00
1	SIDE STAND	NOT NECESSARY	75.00	-
	LESS 10% DISCOUNT		-667.60	-439.30
			6,008.40	3,953.70
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NECESSARY	15.00	15.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SWING ARM SLIDER (SN)	N/S CUT	150.00	75.00
2	FORK SLIDER (SN)	N/S CUT	150.00	75.00
1	REAR TAILBOARD PROTECTOR (SN)	CUT	80.00	80.00
2	HEADLAMP PROTECTOR (SN)	N/S CUT	80.00	40.00
			475.00	285.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.	NOT NECESSARY	50.00	-
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		480.00	300.00
	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.		350.00	250.00
			960.00	580.00
GRAND TOTAL			7,443.40	4,818.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,850.00

Report Ref No. CS3/LPC19002648/Bqd3s2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.